

Coates Inspection Checklist

Tools & Equipment (Electric, Pneumatic, Hydraulic or Internal Combustion)		Photos
Asset # <u>1216295</u>		☒
General Information: *** Copy Data Plate information in this section *** Type of Tool: <u>1 Man Post Hole Digger</u> Make/Model: <u>STILL</u> Year: <u>2018</u> Serial Number: <u>85130</u> Engine / Motor - Make / Model: _____ Engine Serial Number: <u>515919123</u> Meter Reading: _____		☐ Data Plate
Comments: <u>Auger NEEDS Replacement: \$500 to Replace Auger</u> <u>Auger worn out on end where cutting Bit Attacks</u>		
Features: List features or options for the machine: Machine Type: _____ Frame Mount ☐ Trailer Mount ☐ AC / DC Range: _____ Engine Horsepower: _____ Auxiliary Power: _____ Leads: _____ Leads Length: _____ Yes ☐ No ☐		4-Corner Photos ☐ Left-Front Corner ☐ Left-Rear Corner ☐ Right-Front Corner ☐ Right-Rear Corner ☐ Damage ☐ Damage ☐ Damage
Overall Appearance: Switches/Controls: ☐ Good ☐ Fair ☐ Poor Sheet metal/Fiberglass Condition: ☒ Good ☐ Fair ☐ Poor Paint: ☒ Good ☐ Fair ☐ Poor R/t for Designed Purpose: ☐ Good ☐ Fair ☐ Poor		
Control Station Operates: Yes ☒ No ☐ N/A ☐ Operator Controls: ☒ Yes ☐ No ☐ N/A ☐ Gauges Operational?: ☒ Yes ☐ No ☐ N/A ☐ Safety Devices: ☒ Yes ☐ No ☐ N/A ☐ Comments: _____		☐ Hour Meter ☐ Operator Controls ☐ Safety devices ☐ Gauge ☐ Damage ☐ Damage
Engine or Electric Motor: Power: Diesel ☐ Petrol ☒ Hydraulic ☐ Electric ☐ Air ☐ Does it start? ☒ Yes ☐ No ☐ N/A ☐ Did it need to be jumped? ☐ Yes ☒ No ☐ N/A ☐ Acceptable Power: _____ Unusual Noises: _____ Comments: _____		☐ Right Side ☐ Left Side
Hydraulics Operates: Yes ☐ No ☐ N/A ☐ Leaks: Yes ☐ No ☐ N/A ☐ Pump: ☐ Yes ☐ No ☐ N/A ☐ Hoses: ☐ Yes ☐ No ☐ N/A ☐ Cylinders: ☐ Yes ☐ No ☐ N/A ☐ Drive Motors: ☐ Yes ☐ No ☐ N/A ☐ Brakes: ☐ Yes ☐ No ☐ N/A ☐ Parking Brakes: ☐ Yes ☐ No ☐ N/A ☐ Comments: _____		☐ Pump ☐ Cylinders ☐ Drive Motor ☐ Damage ☐ Damage ☐ Damage
Wiring & Lights Wiring: ☐ Yes ☐ No ☐ N/A ☐ Lights: ☐ Yes ☐ No ☐ N/A ☐ Comments: _____		
Chassis: Frame Condition: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Handles Condition: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Lift Points Condition: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Guards Condition: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Mounting Points: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Winching Cable: ☐ Good ☐ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A ☐ Comments: _____		☐ Frame condition ☐ Handles/Lifting points ☐ Guards condition
Tyre Condition: Left - Front: ☐ Brand- ☐ Size- ☐ Condition- Left - Rear: ☐ Brand- ☐ Size- ☐ Condition- Right - Front: ☐ Brand- ☐ Size- ☐ Condition- Right - Rear: ☐ Brand- ☐ Size- ☐ Condition-		Two pictures of a 45 degree angle showing the tread and side walls ☐ Left-Front ☐ Left-Rear ☐ Right-Front ☐ Right-Rear