



#### **DISCLAIMER: Second-Hand Plant Condition and Safety**

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

#### **Important Information**

##### **Condition of the Plant**

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report.

##### **Operational Safety Notice**

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

##### **Manufacturer Information and Records**

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

## Incoming Inspection Check

11/10/2024 / 90583304 / Sydney / UE / Battery Electric

Complete

Serial Number	90583304 12 - NH - KMS - LOW LEVEL ORDER PICKER
Hour Meter Read	1412 hr
Location	Sydney
Conducted on	11/10/2024 10:59 AM ACDT
Conducted By	Thomas Mullins
Truck Category	UE
Truck Make	Battery Electric
Equipment Exterior	
General Appearance / Paintwork	WEAR & TEAR

### Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4

Wheels/Tyres	
<b>Front Wheels / Tyres</b>	WEAR & TEAR
All wheels need replacing	
<b>Rear Wheels / Tyres</b>	WEAR & TEAR
<b>Wheel Bearings</b>	WEAR & TEAR
Chassis/Structure	
<b>Overhead Guard</b>	N/A
<b>Chassis</b>	WEAR & TEAR
<b>Battery Cover</b>	OK
<b>Driver Seat &amp; Fixing</b>	N/A
<b>Panels and Covers (Left &amp; Right)</b>	OK
<b>Accessories (Mirrors, Blue Lights)</b>	N/A
<b>Windscreen</b>	N/A
<b>Rear Screen</b>	N/A
<b>Arm Rest</b>	N/A
<b>Connection Elements</b>	OK
Drive Unit	
<b>Transmission Operation</b>	OK
<b>Transmission Noise &amp; Leaks</b>	OK
<b>Drive Motor Condition</b>	OK
Brake	
<b>Brake Function &amp; Adjustment</b>	OK
Steering	
<b>Steer Motor Operation/Noise</b>	OK
<b>Steering Cylinder</b>	OK
<b>Steer Axle</b>	OK
<b>Steering Wheel/Controls</b>	OK

Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	N/A
Forks & Fork Carriage	OK
Lift Chains Free & Secondary	N/A
Hydraulic Cylinder Free Lift	OK
Hydraulic Cylinders Secondary Light Right & Left	N/A
Hydraulic Hoses Conditions	OK
Reach Carriage & Cylinder	N/A
Sideshift Carriage & Cylinder	N/A
Tilt Function & Cylinders	N/A
Hydraulic System	
Valve Block	N/A
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK
Electric System	
Multi-pilot & Solo-pilot	N/A
Strobe & Working Lights / Alarms	N/A
Drive Display, Console & Instruments	OK
Main Contactor & Connectors	OK
Charger Condition & Operation	OK
Battery	
Battery Condition & Cables	WEAR & TEAR
BATTERY WAS OVERFILLED HAD TO REMOVE ACID SO COULD CHARGE Weak battery holds about 75%	
Battery Carriage	OK
Battery Lock System	OK

Additions or Attachments	
Any other related attachments	No
Was any wear & tear identified?	Yes
(Internal) Parts required	
Was any damage identified?	Yes
(External) Parts Required	
L/H SENSOR	
PAPER CLAMP	

## Media summary



Photo 1



Photo 2





Photo 3



Photo 4