

Work Order History

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0050783	1622	3861.09	4896.69	369355		PAINT CAB BACK TO RED FOR TRADE IN	31/03/2025	16/04/2025
R120-0050783	1622	763.20				STRIP FOR TRADE	31/03/2025	16/04/2025
R120-0050783	1622	272.40				REPLACE NEW TYRES. 6 x runout tyres pos 1 / 2 / 5 / 6 / 7 / 8	31/03/2025	16/04/2025
R140-0136601	1622	988.26	2529.41	368930		CARRY OUT B SERVICE	27/03/2025	28/03/2025
R140-0136601	1622	1777.55				NOX SENSOR NEEDS REPLACING	27/03/2025	28/03/2025
R140-0136573	1622	393.92	393.92	368923		REPLACE WINDSHEILD.	26/03/2025	27/03/2025
R140-0135886	1622	287.13	107.13	365010		BRAKE BOOSTER AIR LEAK	11/03/2025	12/03/2025
R154-0001394	1622	494.96	494.96	364245		K039 FIX TURBO EXHAUST FLANGE Inspected and found exhaust flange loose. \$259.88 Removed clamp and replaced exhaust gasket and clamp Started truck, confirmed fault rectified Part Number Part Description Quantity Total Cost 90-0013 CLAMP-5 V-BAND 1.00 52.80 2866337CUM GASKET EXHAUST 5 INCH 1.00 34.78 Parts Totals: 2.00 \$87.58 K046 FIX FUSE PANEL FROM FALLING Secured mounting panel \$87.50	6/03/2025	11/03/2025
R140-0135514	1622	61.92	10.32	363395		GOVERNOR VALVE EXHAUSTING NEEDS REPLACING	28/02/2025	28/02/2025
R154-0001379	1622	1403.60	1403.60	2961960		FTSD NUMBER: 2320766 LOCATION AND DATE: MACK DEPOT 10.02.2025 HUBO: 33241 WASHES NOT WORKING	10/02/2025	17/02/2025
R140-0133643	1622	657.35	534.95	2961960			18/01/2025	19/01/2025
R140-0133639	1622	275.62	165.22	2961960		BRAKE LINES & FITTINGS - HYDRAULIC & AIR	17/01/2025	18/01/2025
R140-0133195	1622	774.66	1235.18	2961960		GENERATOR/ALTERNATOR	9/01/2025	9/01/2025
R140-0133195	1622	348.92				FRONT ENGINE MOUNTS NEED REPLACING	9/01/2025	9/01/2025
R140-0133195	1622	144.66				LOOSE MOUNTING BOLTS FOR DIFF HEAD	9/01/2025	9/01/2025
R140-0133129	1622	309.60	69.60	2961960		BATTERY & CABLES	7/01/2025	8/01/2025
R140-0132675	1622	495.95	487.55	2961960		AIR CONDITIONING ASSEMBLY - COMPLETE	24/12/2024	27/12/2024
R154-0001332	1622	1595.69	1595.69	2961960		DATE: 23.12.2024 REPAIR ORDER NO. 913774 338,005 klms INSTALL CUSTOMER SUPPLIED SEAT - Removed old seat - Installed new seat but rails would not line up, found them to be bent - Removed rails from old seat and installed to new seat then installed seat to truck Fit new wiper blades - R&R drivers side wiper head - Found LHS wiper arm broken, requiring complete replacement - On removal of LHS wiper arm found damage to the mount - R&R wiper arm mount, R&R wiper arm - Tested operation , all ok	23/12/2024	2/01/2025
R140-0132197	1622	2263.33	0.00	2961960		SEAT WORN OUT	14/12/2024	14/12/2024
R140-0131813	1622	1123.17	1123.17	2961960		R/H WINDOW NOT ROLLING UP	6/12/2024	11/12/2024
R140-0129629	1622	49.30	9.70	2961960		AC NOT WORKING	17/10/2024	17/10/2024

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0128781	1622	5024.80	5024.80	2961960		SERVICE ON 19700486 BRIS DEPOT 27.09.2024 HUBO 1296196 05 11003134 - 11R22.5 148/145L BS M749II EC CC 3 Retread (recap) Customer Pull Point 06 11003134 - 11R22.5 148/145L BS M749II EC CC 3 Retread (recap) Customer Pull Point 07 11003134 - 11R22.5 148/145L BS M749II EC CC 3 Retread (recap) Customer Pull Point 08 11003134 - 11R22.5 148/145L BS M749II EC CC 3 Retread (recap) Customer Pull Point 09 11003134 - 11R22.5 148/145L BS M749II EC CC 6 Runout Held by Customer Match Tread Depth or Pattern 10 11003134 - 11R22.5 148/145L BS M749II EC CC	27/09/2024	4/10/2024
R142-0009215	1622	395.68	395.68	2961960		Invoice Number INV-1947 Invoice Date 30 Sep 2024 TRA Travel 1.00 70.00 10% 70.00 LAB Labour 2.00 121.00 10% 242.00 K301-354 Door Switch 1.00 83.68 10% 83.68 Vehicle: 2016 KENWORTH T409 PRIME MOVER Registration Number: XQ05BG Odometer: 32,420km Unit Number: 1622 27/09/2024 Travelled to site. Removed and replaced damaged door jamb switch. Tested and checked ok. A/C not working. Found no power getting to A/C blower fan. Traced fault to bad connection at fan relay. Tightened relay base pins and secured. Reassembled dash. Tested and checked ok. INCLUDES GST 10% 35.97	27/09/2024	1/10/2024

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R142-0009219	1622	61.60	61.60	2961960		SERVICE ON 2284496 BUND DEPOT 27.09.2024 HUBO 1	27/09/2024	4/10/2024
R140-0128651	1622	56.40	2548.64	2961960		Seat belt will not retract, bunk fridge not working, cracked windscreen	26/09/2024	1/10/2024
R140-0128651	1622	207.50				CRACKED WINDSCREEN	26/09/2024	1/10/2024
R140-0128651	1622	60.00				BUNK FRIDGE NOT WORKING	26/09/2024	1/10/2024
R140-0128651	1622	1518.84				B SERVICE E5 CUMMINS 60,000 KM	26/09/2024	1/10/2024
R140-0128651	1622	75.07				HEATER TAP BRACKET BROKEN	26/09/2024	1/10/2024
R140-0128651	1622	108.22				BOTH JETS TO BE REPLACED	26/09/2024	1/10/2024
R140-0128651	1622	254.93				SOLENOID VALVE CRACKED	26/09/2024	1/10/2024
R140-0128651	1622	175.92				GOVRNOR LINE LEAKING	26/09/2024	1/10/2024
R140-0128651	1622	91.76				TOP ROOF LIGHTS OUT	26/09/2024	1/10/2024
R140-0128651	1622	0.00				REPLACE STEER TYRES	26/09/2024	1/10/2024
R140-0128651	1622	60.00				STEERING COLUMN SURROUND MISSING	26/09/2024	1/10/2024
R154-0001267	1622	1099.24	1099.24	1517156		INV# 38437 DATE: 10/09/2024 Serviced Qty Description Unit Price Total 10/09/2024 Labour - The technician carried out checks to the air conditioner reported not to be running, after tests found the blower fan motor and fan speed resistor to be faulty. Carried out the removal and replacement of the faulty parts and test, all test ok. Left the unit operational and in service. 2 120.00 240.00 1 Controller Fan Speed 225.65 225.65 1 Fan Blower 533.65 533.65 Unit - 1622	10/09/2024	16/09/2024
R154-0001265	1622	198.00	198.00	1517156		INV# 38400 DATE: 04-09-2024 3/09/2024 Labour - The technician carried out checks to the cab air conditioner not cooling, removed the blower fan and was found to test ok, removed all plugs and refit back into position, checked voltage and all test ok. Refit all components back into place and test, all test ok. Left operational and in service. 1.5 120.00 180.00 Unit 1622 BALANCE: 198.00	4/09/2024	11/09/2024
R154-0001262	1622	45.76	45.76	1517156		SERVICE ON 756898 MACK DEPOT 26-08-2024 HUBO 1	26/08/2024	13/09/2024
R140-0124567	1622	166.23	64.23	1517156		REPLED MUDGUARD	24/06/2024	24/06/2024
R120-0046884	1622	446.55	446.55	1517156		DATE: 31/05/2024 INVOICE: PROFORMA COMPLAINT: FAULT COADES CAUSE: CRANKSHAFT POSITION SENSOR DAMAGED CORRECTION: GUIDANZ SO Number: 00911802 HRS/KM: 012277:20:46/846667.6 PLUG IN AND OBTAIN ECM DOWNLOAD - ACTIVE CODE 2321	31/05/2024	18/06/2024

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R154-0001178	1622	838.57	838.57	1517156		DATE: 29/05/2024 INVOICE: PROFORMA REPAIR EXHAUST PIPE INSPECT EXHAUST SEEN CLAMP COME OFF TRIED TO PUT I BACK ON BUR PIPE WAS TO SHORT ASKED CUSTOM IF SOMEONE HAS CUT THE EXHAUST THEY CUT THE PIPE TO SHORT WENT AND GOT A NEW BIT OF THE PIPE AND WELDED NEW PIECE ON PUT PIPE BACK ON.	29/05/2024	6/06/2024
R156-0020173	1622	263.33	341.33	1517156		GUARDIAN SYSTEMS	29/05/2024	29/05/2024
R156-0020173	1622	78.00				LEFT HAND TAIL LIGHT NOT WORKING	29/05/2024	29/05/2024
R154-0001170	1622	1458.47	1458.47	1517156		k051 steering ram broken Drove to Lindsay yard, knocked out pin on the steering ram because it was broken. Installed new ram and checked the operation. All ok no covers to replace as they were missing when i got there. Drove back home. \$408.96 Unable to get odometer reading as keys were not in truck. Part Number Part Description Quantity Total Cost 499080B TILT LOCK-GAS STRUT GEN 2.5 ST 1.00 799.67 CF Service Callout Fee 1.00 50.00 T TRAVEL PER KLM 27.00 47.25 Parts Totals: 29.00 \$896.92 PARTS \$896.92 LABOUR \$408.96 MISC. CONSUMABLES \$10.00 ENVIRONMENTAL LEVY \$10.00 SUBLET \$0.00 OTHER CHARGES \$0.00 TOTAL GST CHARGED \$132.59 TOTAL Incl. GST \$1,458.47	17/05/2024	23/05/2024
R140-0122629	1622	217.80	217.80	2130373		DATE: 24.04.2024 INVOICE NO. PT-13789 REMOVE 3G PHONE KIT. FIT 4G PHONE KIT. TESTED - OKAY.	29/04/2024	29/04/2024
R140-0122326	1622	24.31	21.91	2130373		VEHICLE FLUIDS, LUBRICANTS, GASES, & PARTICULATES	19/04/2024	19/04/2024

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R171-0003093	1622	1363.56	1363.56	2130373		SERVICE ON 18762832 LFL DEPOT 19.04.2024 HUBO 1000000 01 11006520 - 295/80R22.5 152/148M BS R154 CC 2 Retread (recap) Customer Pull Point 02 11006520 - 295/80R22.5 152/148M BS R154 CC 2 Retread (recap) Customer Pull Point Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 2 EA Tyre Removed - (Pos: 1, 2) -2 EA Case Credit 77000194 SIZE: CASE STOCK 295/80-22.5 (Pos: 1, 2) 2 EA	19/04/2024	30/04/2024
R140-0122286	1622	1117.77	947.37	2130373		UPGRADE TELEPHONE	18/04/2024	18/04/2024
R154-0001131	1622	899.33	899.33	2130373		DATE: 12.03.2024 CO NO. 6712071 WORK ORDER NO. 2876144 COMPLAINT: FUEL PRESSURE FAULTS. CAUSE: FAULTY FUEL PRESSURE ACTUATOR. CORRECTION: GUIDANZ NO. 00833160. 11,547 hrs 795,000 klms 404,972 ltrs FUEL BURN. - TRUCK CAME IN WITH COMPLAINTS OF DERATE AND FAULT CODES. - WHEEL TRUCK INTO BAY. - CAPTURE DOWNLOAD. - DOWNLOAD REVEALED FAULTS OF 1911 AND 0553. - PERFORM FUEL SYSTEM LEAKAGE TEST, (FUEL PRESSURE GOES ERRATIC AND SHUTS ENGINE DOWN) - INSPECT FUELING ACTUATOR, UPON INSPECTION, WAS FOUND THAT THE BODY WAS LOOSE FROM THE ACTUATOR HOUSING - REMOVE AND REPLACE ACTUATOR. - RE PERFORM FUEL SYSTEM LEAK TEST, FUEL PRESSURE READING ACCURATE. - CLEAR FAULT CODES.	19/03/2024	22/03/2024

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R154-0001118	1622	720.05	720.05	2130373		DATE: 29.02.2024 INVOICE NO. 37498 Labour - The technician carried out checks to the cab air conditioner reported not to be cooling. Carried out cleaning of the cab filter and connected the gauges, found the system to be short on refrigerant. Add refrigerant to the system and carried out the replacement of the gasket and clamp for the exhaust. Test run and all test ok, left the unit cooling and in service	1/03/2024	5/03/2024
R140-0120388	1622	230.14	76.54	2130373		WASHER JETS BLOCKED	23/02/2024	26/02/2024
R120-0045312	1622	2994.95	2994.95	2130373		CARRY OUT REPAIR LIST AND FIX TRUCK. CARRY OUT REPAIR LIST REPLACED 9KG FIRE EXTINGUISHER - J.B TIGHTEN COOLANT DRAIN FITTING - C.I RESECURE GREASE LINES UNDER GEARBOX - D.J REPLACE RHF J BRACKET - D.J RESECURE ECA COVER - D.J GREASE WHOLE TRUCK MANUALLY - C.I TENSION U BOLTS - J.B REPLACE 3 LEAKING PRESSURE PROTECTION VALVES - D.J REPLACE FOOT BRAKE VALVE AND RESEAL ALL FITTINGS - J.B CHECKED ALL DASH LIGHTS AND TELL TALES, REPLACED 10 TELL TALES AND 3 DASH LIGHTS - J.B REPLACE 2 DRIVER A/C VENTS - J.B FIT NEW FIRST AID KIT - J.B RESECURE BOTH INNER DOOR SEALS - J.B REPAIR AND RESEAL AIR LEAKS OVER THE TRUCK - D.J REPLACE WIPER STALK WITH SECOND HAND SPARE - J.B REPLACE WALK PLATE RUBBER - D.J	14/02/2024	15/02/2024
R120-0045275	1622	2014.57	2876.92	2130373		B SERVICE - CUMMINS E5. CARRIED OUT B SERVICE LHF STEER BOOSTER FAILED, REPLACED WITH 2ND HAND FIT NEW E-TAG CHANGED ALL TOP SHOCK BUSHES, CARRIED OUT DIFF SERVICE, CARRIED OUT GENERAL REPAIRS	10/02/2024	13/02/2024
R120-0045275	1622	402.05				REPLACE DIFF OILS AND FILTER	10/02/2024	13/02/2024
R120-0045275	1622	460.30					10/02/2024	13/02/2024
R140-0119771	1622	279.19	84.79	2130373		CLAMP BROKEN AND MISSING GASKET	6/02/2024	6/02/2024
R140-0119470	1622	29.95	59.90	2130373			25/01/2024	25/01/2024
R140-0119470	1622	29.95				TOP UP	25/01/2024	25/01/2024
R140-0119209	1622	90.58	6.58	2130373		WASHER JETS	18/01/2024	19/01/2024
R140-0119071	1622	2.40	0.00	2130373		PROCESSOR UPGRADE	12/01/2024	13/01/2024
R155-0023232	1622	549.35	549.35	2130373		A/C REPORTED NOT WORKING	10/01/2024	11/01/2024
R120-0044818	1622	426.56	426.56	2130373		EXHAUST FLEX NOT CHARGED OUT ON ORIGINAL JOB. REFER - R120-0044744.	5/01/2024	23/01/2024
R120-0044763	1622	320.40	320.40	2130373		WINDSHIELD WIPER & WASHER. FITTED 2ND HAND WIPERSTALK FITTED 2ND HAND IN CAB RIDE HEIGHT SWITCH	2/01/2024	4/01/2024
R120-0044744	1622	1103.63	1103.63	2130373		CHECK AFTER-TREATMENT FAULT. CHECKED FAULTS FOUND EXHAUST NOX SENSOR FAILED, REPLACED SENSOR AND MISSING WALK PLATE BRACKETS	29/12/2023	29/12/2023
R120-0044724	1622	623.22	623.22	2130373		REPAIR EXHAUST LEAK. REPLACED EXHAUST FLEX AND HEATER TAP	28/12/2023	28/12/2023
R120-0044711	1622	102.00	102.00	2130373		VT102 ALREADY INSTALLED AND VT103 WAS STILL IN THE TRUCK CONNECTED UP. REMOVED OLD IVU TRACKING UNIT REMOVED CAN CLIC AND RELOCATED TO CAN WIRES TO SUIT VALIDATED UNIT VIA PHONE APP CALIBRATED ODO AND HRS INTO APP TESTED OPERATIONS ALL IF FUNCTIONING CORRECTLY	27/12/2023	27/12/2023
R120-0044682	1622	33.02	9.02	2129307		REPLACE FEMALE ELECTRICAL SOCKET	22/12/2023	22/12/2023
R155-0022937	1622	80.06	80.06	2127908		TOP UP OIL & COOLANT	13/12/2023	14/12/2023
R140-0117133	1622	693.66	693.66	2127742		NOT STARTING	11/11/2023	13/11/2023
R140-0116747	1622	543.92	366.32	2116167		A/C NOT WORKING	31/10/2023	1/11/2023
R140-0116650	1622	2420.52	1774.92	2113552		B SERVICE E5 CUMMINS 60,000 KM	28/10/2023	30/10/2023
R140-0116344	1622	414.40	298.00	2105888		BATTERY CHECK SLOW STARTING	19/10/2023	20/10/2023
R140-0116229	1622	153.69	27.69	2102992		CHECK ENGINE LIGHT ON	16/10/2023	20/10/2023

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0115711	1622	225.50	225.50	2090227		DATE: 27.09.2023 REPAIR ORDER # 856136 Diagnose & rectify electronic fault Move truck into workshop. Hook up diagnostic laptop, download fault log & analyse data: found inactive fault 1911 [Injector Metering Rail 1 Pressure] logged. Start troubleshooting inactive 1911 but unable to complete full troubleshooting procedure as John Begeada elected to take vehicle to Brisbane. Erase inactive faults & return vehicle to service as requested.	28/09/2023	3/10/2023
R140-0115686	1622	103.76	52.16	2089244		TRANSMITTER - CB	27/09/2023	27/09/2023
R171-0001804	1622	5002.58	5002.58	2089021		SERVICE ON 17842229 LFL DEPOT 22.09.2023 HUBO 696,555 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 05 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 06 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 07 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 08 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 09 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 10 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 11 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point 12 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Retread (recap) Customer Pull Point Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2) 8 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 10, 11, 12, 5, 6, 7, 8, 9) 8 EA Tyre Removed - (Pos: 10, 11, 12, 5, 6, 7, 8, 9) -8 EA Case Credit 77000232 SIZE: CASE STOCK 11R22.5 ECOPIA (Pos: 10, 11, 12, 5, 6, 7, 8, 9)	22/09/2023	2/10/2023
R142-0006980	1622	115.00	115.00	2074434		DATE: 24.08.2023 INV # 1037 RIGHT INDICATOR DASH LIGHT NOT WORKING	25/08/2023	5/09/2023
R140-0114437	1622	0.00	277.40	2074027		FFC issues	24/08/2023	24/08/2023
R140-0114437	1622	2.40				VEHICLE NOT USING ADBLUE	24/08/2023	24/08/2023
R140-0114437	1622	803.00				INSPECT FFC	24/08/2023	24/08/2023

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R171-0001669	1622	35.20	35.20	2074027		SERVICE ON 17709600 LFL BRIS DEPOT 24-08-2023 HUBO 2068763 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 Runout Tyre 11R22.5 - RTD - 7.0mm RN 2.0 Retread (recap) Customer Pull Point 10 Runout Tyre 11R22.5 - RTD - 7.0mm RN 2.0 Retread (recap) Customer Pull Point 11 Runout Tyre 11R22.5 - RTD - 7.0mm RN 2.0 Retread (recap) Customer Pull Point 12 Runout Tyre 11R22.5 - RTD - 7.0mm RN 2.0 Retread (recap) Customer Pull Point Qty	24/08/2023	18/09/2023
R122-0062515	1622	963.21	611.61	2052515		B SERVICE	17/07/2023	17/07/2023
R122-0062523	1622	54.49	4.09	2052515		Guardian - FFC Streaming	17/07/2023	17/07/2023
R122-0062547	1622	134.20	134.20	2052515		SERVICE ON 17535135 SYDN DEPOT 17.07.2023 HUBO 2,028,625 10 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2, 12-5, 11-6, 9-7, 10-8, 8-9, 7-10, 6-11, 5-12) 2 EA Flip On Rim 33000540 - FLIP TRUCK TYRE OR RETREAD (Pos: 1, 2)	17/07/2023	14/08/2023
R120-0042254	1622	230.40	230.40	2043403		REPLACE WORN TYRES. swap steer tyres of 1390	5/07/2023	7/07/2023
R122-0061906	1622	90.64	90.64	2034264		REPLACE EXHAUST FLANGE	21/06/2023	22/06/2023
R122-0061844	1622	9470.59	9462.47	2034054		REPLACE CLUTCH	19/06/2023	22/06/2023
R130-0046101	1622	144.00	144.00	2018271		CHECKED AUTO GREASER AL SEEMS OK	24/05/2023	26/05/2023
R130-0045920	1622	456.76	456.76	2013706		replace speed sensor test drive	16/05/2023	17/05/2023
R155-0020678	1622	42.00	42.00	2011852		ADJUST DRIVER FACING CAMERA	11/05/2023	12/05/2023

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R155-0020486	1622	333.86	635.04	2006406		Air leak when the brakes on	21/04/2023	15/05/2023
R155-0020486	1622	138.00				AIR LEAK WHEN BRAKES APPLIED	21/04/2023	15/05/2023
R155-0020486	1622	163.18				REPLACED DAMAGED ABS LEAD	21/04/2023	15/05/2023
R155-0020335	1622	60.00	2773.86	2004304		TABLET REPORTED NOT WORKING	8/04/2023	16/05/2023
R155-0020335	1622	2.40				PHONE REPORTED NOT WORKING	8/04/2023	16/05/2023
R155-0020335	1622	2711.46				ENGINE BRAKE REPORTED INTERMITTANT	8/04/2023	16/05/2023
R155-0020129	1622	914.60	849.60	1997244		TABLET NOT POWERING UP	21/03/2023	23/03/2023
R155-0020111	1622	188.40	188.40	1996744		TRANSMISSION WILL NOT SHIFT	20/03/2023	20/03/2023
R155-0020053	1622	1835.16	1805.36	1995511		PM for 000-002 Last Done: 11/10/2022 Interval: 60000 Utilization: 54030	15/03/2023	16/03/2023
R155-0020027	1622	378.00	1522.64	1995342		SLOW TO TURN OVER -	14/03/2023	16/03/2023
R155-0020027	1622	1006.64				CAB AIR BAGS LEAKING	14/03/2023	16/03/2023
R155-0020027	1622	138.00				VEHICLE LOSING AIR PRESSURE	14/03/2023	16/03/2023
R155-0019931	1622	192.00	192.00	1990578		UNABLE TO SELECT FORWARD GEARS	2/03/2023	3/03/2023
R155-0019631	1622	458.87	664.07	1974316		SUZI COIL LEAKING AIR	1/02/2023	1/02/2023
R155-0019631	1622	205.20				AIR LEAK IN CAB	1/02/2023	1/02/2023
R155-0019606	1622	63.60	309.60	1972874		AIR LEAK FROM SUSPENSION DUMP SWITCH	28/01/2023	31/01/2023
R155-0019606	1622	123.60				FRONT STEER AXLE OIL LEAK	28/01/2023	31/01/2023
R155-0019606	1622	126.00				REPORTED BAD MATTRESS ODOUR	28/01/2023	31/01/2023
R155-0019582	1622	424.45	424.45	1970008		REPLACE SUZI COILS - BREAKDOWN @ HAY 1622 DATE: 25.01.2023 TAX INVOICE NO. 49281 Suzi Coil Long Tail 1.0000 156.50 EA 156.50 Coupler 1/2" N/S Female Thread 2.0000 29.83 EA 59.66 Nipple Air Adaptor 1/2" N/S Male Thread 2.0000 15.35 EA 30.70 Labour Phil Min 1.0000 139.00 Hr. 139.00 SUBTOTAL \$ 385.86	25/01/2023	3/05/2023

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0040187	1622	23267.40	40391.48	1963184		CARRY OUT MIDLIFE REPAIRS CHECK IDLE SHUTDOWN TIME. CHECK DIFF AND GEARBOX OIL. CHECK DAYTIME RUNNING LIGHTS. CHECK SPEED ALERT OPERATION. CHECK VIBRATION DAMPER. CHECK ABS LEAD. CHECK PHONE OPERATION. DOWNLOAD ENGINE ECM. DOWNLOAD AUTO SHIFT AND CHECK SETTINGS. CHANGE ADBLUE AIR FILTER. CHANGE ADBLUE IN TANK FILTER. SERVICE BUNK COOLER. CHANGE STEER OILS. ENGINE TUNE. KIT HORTON. A/C BEARING. KIT AIR DRIER. CHANGE POWER STEER OIL/FILTER. THERMOSTATS AND SEALS. REMOVE RADIATOR STRIP AND CLEAN INHOUSE. REPLACE COOLANT. REPLACE COOLANT FILTER. PRESSURE TEST INTERCOOLER. WHEEL ALIGNMENT. WATER PUMP. TURBO. OIL THERMOSTAT. ENGINE BRAKE KIT. STARTER. ALTERNATOR. COMPRESSOR - GOVERNOR VALVE. IDLERS AND TENSIONERS. TAILSHAFT UNI'S. SHIELD FFC WIRING. FIT NEW STYLE REVERSE BUZZER. UPDATE TO VT102. UPDATE GUARDIAN PROCESSOR TO 4G. CAB DETAIL CAB. CLEAN OUT FRIDGE. CLEAN AND CHECK DOG BOXES. POLISH FRONT BUMPER. POLISH ALL TANKS. POLISH GRILLE. NHVR STICKER FADED. NO MIBILE PHONE STICKERS. RH 1ST TANK STRAP RUBBER AND RH 4TH ONLY. REPLACE 2 X ADBLUE TANK STRAP RUBBERS. WEIGHT SCALE BOX - REPLACE WITH SECOND HAND. RESECURE ADBLUE TANK WIRING. RESECURE IN CAB FIRE EXTINGUISHER TAG. RESET GI LIGHT. ENGINE BRAKE LIGHT NOT COMING ON. LH/RH DOOR HANDLE SURROUNDS MISSING (INSIDE). TURBO TIMER INOP - SECOND HAND. REPLACE DRIVERS SIDE FLOOR MAT - SECOND HAND. LH DASH AIR VENT MISSING - SECOND HAND. ETAG HOLDER BROKEN - SECOND HAND. DRIVERS SIDE TWEETER BROKEN - SECOND HAND. DRIVERS VISOR SCREWS MISSING. CENTRE DASH PANEL SCREW MISSING. BUNK LIGHT COVER MISSING - SECOND HAND. PASSENGER IN CAB ROOF LIGHT INOP. PASSENGER SIDE IN CAB ROOF LENSE MISSING - SECOND HAND. BUNK ROOF X 2 GLOBES MISSING AND LENSES. DRIVERS DOOR CARD INSECURE. HORTON SOLENOID AIR FITTING LEAKING. CLEAN HEADLIGHT COVERS. RH CRACKED - SECOND HAND. LH 1DT/4TH TANK STRAP RUBBERS. FLIP LH BOTTOM STEP AROUND. COOLANT AND OIL BOTTLES EMPTY. FIRST AID KIT MISSING. PASSENGER SIDE DOOR CARD INSECURE. CAB SHOCKS LEAKING. EMERGENCY STICKER IN CAB UNREADABLE. WINDSCREEN CHIPPED. TACHO HEAD JUMPING AROUND. SPRAY DRIVERS WINDOW RUNNERS. FRONT BRAKE ADJUST. WHEEL ALIGNMENT. LEAKING INJECTOR NO. 2 & 5. ENGINE OIL FILL TUBE LEAKING. REPLACE HEATER HOSES AND RELOOM. FRONT ENGINE MOUNTS. TOP UP ENGINE OIL. POWER STEER SUCTION HOSE NEEDS REPLACING. ESOC FILL HOSE LEAKING. EXHAUST MANIFOLD LEAKING. TURBO DRAIN LEAKING. HARNESS RUBBING ON ROCKER COVER. TIN COVER LEAKING. DUMP PIPE RUBBERS. CHECK U-BOLTS. LH STEER HUBSEAL. CHECK KINGPIN GREASE OPERATION. HEAT EXCHANGE ORINGS LEAKING FRONT HALF. RELOOM GOVERNOR HOSES. POWER STEER HOSE FROM PUMP RUBBED THROUGH. RELOOM ALTERNATOR WIRING BOTTOM RADIATOR BUSHES. REPLACE EXHAUST CLAMP IN FRONT OF FLEX AND GASKET. RADIATOR TOP SHROUD FIT BIGGER WASHER RHS - FLAPPING AROUND. ENGINE NOISY CHECK ROCKERS/CAM ETC. KINGPINS NEED REPLACING - HAD NO GREASE. LH STEER MUDFLAP & RH NEED REPLACING. RADIATOR QUICK RELEASE FITTING. REPLACE 5/8 HEATER HOSE. FRONT CRANKSEAL LEAKING. TWO BOLTS MISSING FROM OIL COOLER. LOOM LHS ENGINE /ROCKER COVER. REAR	9/01/2023	20/01/2023
R120-0040187	1622	553.85				REPLACE DOSER PUMP AND FILTERS	9/01/2023	20/01/2023
R120-0040187	1622	50.60				SERVICE VIESA/PAINT KOOLKAT COVER RED	9/01/2023	20/01/2023
R120-0040187	1622	603.27				REPLACE POWER STEERING OIL & FILTER. REPLACE STEER HUB OILS. REPLACE PITMAN ARM PINCH BOLT AND TENSION	9/01/2023	20/01/2023
R120-0040187	1622	765.27				CARRY OUT ENGINE TUNE. REPLACE ENGINE BRAKE KIT. INSPECT ROCKER SHAFTS AND CAMSHAFT FOR WEAR	9/01/2023	20/01/2023
R120-0040187	1622	1166.45				REKIT HORTON FAN REPLACE ALL BELTS & TENSIONERS	9/01/2023	20/01/2023
R120-0040187	1622	28.72				REPLACE A/C COMPRESSOR	9/01/2023	20/01/2023
R120-0040187	1622	273.91				REKIT AIR DRYER	9/01/2023	20/01/2023
R120-0040187	1622	620.40				REPLACE OIL & COOLANT THERMOSTATS	9/01/2023	20/01/2023
R120-0040187	1622	585.33				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER	9/01/2023	20/01/2023
R120-0040187	1622	1073.99				REPLACE WATER PUMP	9/01/2023	20/01/2023
R120-0040187	1622	460.26				REPLACE STARTER MOTOR	9/01/2023	20/01/2023
R120-0040187	1622	312.51				REPLACE ALTERNATOR	9/01/2023	20/01/2023
R120-0040187	1622	2627.12				REPLACE AIR COMPRESSOR & D2 GOVERNOR VALVE	9/01/2023	20/01/2023
R120-0040187	1622	3865.34				REPLACE TURBO	9/01/2023	20/01/2023
R120-0040187	1622	224.88					9/01/2023	20/01/2023
R120-0040187	1622	1848.88					9/01/2023	20/01/2023

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0040187	1622	271.64					9/01/2023	20/01/2023
R120-0040187	1622	1842.26				POLISH WHEELS	9/01/2023	20/01/2023
R120-0039833	1622	2154.18	2154.18	1950304		INSPECT AFTER TREATMENT LIGHT, DIAGNOSE AND REPLACE DOSER PUMP	5/12/2022	6/12/2022
R140-0103574	1622	1112.40	715.83	1941124		Shudders when you accelerate once it goes in gear or reverse	10/11/2022	10/11/2022
R140-0103574	1622	106.49				RENEW EXH FLEX	10/11/2022	10/11/2022
R140-0103574	1622	345.34				B SERVICE E5 CUMMINS 60,000 KM	10/11/2022	10/11/2022
R140-0103610	1622	93.34	93.34	1941124		Fit Coles approved reverse alarm	10/11/2022	10/11/2022
R120-0039451	1622	148.80	56.40	1939491		INSPECT STEER TYRES	8/11/2022	9/11/2022
R120-0039369	1622	1100.10	1100.10	1933072		Aftertreatment light is on	2/11/2022	2/11/2022
R140-0103194	1622	2.40	2.40	1932468		Hard to start	31/10/2022	31/10/2022
R140-0102985	1622	410.39	2071.75	1928233		Aftertreatment light active	24/10/2022	26/10/2022
R140-0102985	1622	1279.00				Engine coolant system took 20 litres of coolant	24/10/2022	26/10/2022
R140-0102985	1622	382.36				R.H.R bonnet support rubber block broken off	24/10/2022	26/10/2022
R156-0016934	1622	131.25	131.25	1925768		LAMPS - TAIL, STOP, TURN & LICENSE, REAR	19/10/2022	19/10/2022
R140-0102491	1622	945.20	945.20	1920030		FLUSH SYSTEM	10/10/2022	12/10/2022
R140-0102293	1622	64.22	64.22	1917202		REPLACE ELECTRICAL LEAD	4/10/2022	4/10/2022
R140-0102215	1622	141.58	141.58	1916330		AFTERTREATMENT LIGHT ON DASH	30/09/2022	30/09/2022
R120-0038942	1622	12.00	0.00	1909469		CHECK SENTINEL DEVICE CHARGING	19/09/2022	20/09/2022
R120-0038902	1622	570.14	849.19	1906189		INSPECT AND TEST BATTERIES	14/09/2022	15/09/2022
R120-0038902	1622	0.00				FUEL PROBLEM, INSPECT	14/09/2022	15/09/2022
R120-0038902	1622	279.05				G/BOX OIL + FILTER	14/09/2022	15/09/2022
R120-0038902	1622	313.10				DIFF OILS + FILTER	14/09/2022	15/09/2022
R120-0038877	1622	526.90	526.90	1906085		WILL NOT START	12/09/2022	13/09/2022
R122-0054520	1622	15.60	0.00	1902470		If the truck shuts down on the idle timer it will not re start again	31/08/2022	31/08/2022
R122-0054553	1622	228.80	226.80	1902470		SERVICE ON 16348423 SYDN DEPOT 31-08-2022 HUBO 1899759 10 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2, 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Flip On Rim 33000540 - FLIP TRUCK TYRE OR RETREAD (Pos: 1, 2)	31/08/2022	9/09/2022
R140-0100871	1622	1803.71	1803.71	1895174		B SERVICE E5 CUMMINS 60,000 KM	20/08/2022	22/08/2022
R140-0100318	1622	248.40	248.40	1886723		INSPECT RTRANSMISSION FAU;LT	5/08/2022	5/08/2022
R140-0100135	1622	1.50	1.50	1882163		Sentinel is not working correct, keeps turning itself on and off	1/08/2022	2/08/2022
R140-0099719	1622	41.92	41.92	1867979		BREAKDOWN STAR TRACK GOLD COAST - SUPPLY COMPRESSOR TO BROWN & HURLEY	19/07/2022	27/07/2022

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R150-0000414	1622	2281.54	2281.54	1867979		VEHICLE LOCATE AT 99 MILLAROO DRIVE HELENSVALE. FARTRACK DRIVER NICK 04 5942 4387 BILLY CALLED IT IN 04 2838 3295. RECORD KMS ON VEHICLE KMS TRAVELED.....VEHICLE WONT BUILD UP AIR. Load tools, spoke to driver and decided what parts to take, load up parts, travel to Startrack yard, start truck, found not to be building air past 150KPA, check for air leaks, none present, remove discharge hose found compressor to not be pumping air out, remove intake hose, travel back to Yatala for ATF dex3 oil to follow Cummins procedure for freeing up one way vale in compressor head, travel back and carry out procedure, had no improvement, drain coolant and remove compressor head, found gasket broken, clean up surfaces and fit new head gasket kit, refit coolant hoses, fill back up with coolant, start and check operation of compressor, all okay, travel back to Yatala and unload tools and parts. \$960.00 Part Number Part Description Quantity Total Cost 4089238 KIT WABCO AIR COMP GSK 1.00 989.63 T TRAVEL PER KLM 53.00 79.50 Parts Totals: 54.00 \$1,069.13 PARTS \$1,069.13 LABOUR \$960.00 MISC. CONSUMABLES \$30.00 ENVIRONMENTAL LEVY \$15.00 SUBLET \$0.00 OTHER CHARGES \$0.00 TOTAL GST CHARGED \$207.41 TOTAL Incl. GST \$2,281.54	18/07/2022	21/07/2022
R191-0000299	1622	566.47	566.47	1860888		CALLOUT TO DUBBO 27.2.22 JOB DONE BY ISS FIRST RESPONSE SALES DOCKET: 73048186 ISS AFTER HOURS CALL OUT #113352 call out to Dubbo 27/02/2022 Caller Nick 1300546872 Driver Peter Gilbert 0478756270 98000120 ISS AFTER HOURS CALL OUT #113352 33000237 call out to Dubbo 27/02/2022 33000237 Caller Nick 1300546872 33000237 Driver Peter Gilbert 0478756270 33000237 1 x Puncture on Steer tyre 33000237 Right Hand side 33000237 Cracked Rim	12/07/2022	30/08/2022
R140-0098997	1622	4315.96	4315.96	1845799		WORK ORDER 4420226187 SERVICE ON 2105573 BRIS DEPOT 04.06.2022 11001472 11R22.5 148/145L BS M749 POS 5-12 33000084 FIT TYRE TBR X 8 77000232 CASE STCOK 11R22.5 ECOPIA X -8 33000188 PRESSURE CHECK X 2 POS 1 & 2 HUB 836007	24/06/2022	7/07/2022
R140-0098353	1622	941.76	5254.97	1836713		B SERVICE E5 CUMMINS 60,000 KM	4/06/2022	10/06/2022
R140-0098353	1622	2664.00				SEAT ADJUSTER FAULT	4/06/2022	10/06/2022
R140-0098353	1622	527.23				REPLACE SEAL DRIVE LHF	4/06/2022	10/06/2022
R140-0098353	1622	186.74					4/06/2022	10/06/2022
R140-0098353	1622	935.24				RENEW SHACKLE PINS AND BUSHES AS REQUIRED	4/06/2022	10/06/2022
R140-0098274	1622	595.57	941.11	1833870		RENEW LEAKING HUB SEAL	2/06/2022	3/06/2022
R140-0098274	1622	345.54				R/H STEER HUB LEAKING	2/06/2022	3/06/2022

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R191-0000291	1622	966.39	966.39	1833870		INLAND TRUCK CENTRE DUBBO RO115555 LABOUR NATIONAL FLEET CHECK AND REPAIR - R/H WINDOW NOT WINDING UP. . MOVE VEHICLE INTO THE WORKSHOP. REMOVE THE INNER DOOR PANEL & SKIN. INSPECTION FOUND THE WINDOW REGULATOR TO BE UNSERVICEABLE. REMOVE & REPLACE THE WINDOW REGULATOR. REFIT THE INNER DOOR SKIN & PANEL. TEST OPERATION - OK. RETURN VEHICLE TO SERVICE. COMPLETE PAPERWORK. . Labour LABOUR CHARGES FOR THE FOLLOWING WORK 288.26 Parts R21-1016 CONTROL-WINDOW REGULATO 1 566.78 Others WORKSHOP SUPPLIES 1 23.50 Sub Total ExGST: 878.54	2/06/2022	18/07/2022
R120-0037977	1622	0.00	0.00	1830854		DRIVE BAGS ARE GOING FLAT COMPLETED ON R140-0094220	31/05/2022	31/05/2022
R191-0000290	1622	263.66	263.66	1830854		INLAND TRUCK CENTRES DUBBO RO # R115539 KMS: 829,653 LABOUR NATIONAL FLEET - VEHICLE "SURGING", ENGINE WARNING LIGHTS "ACTIVE". . MOVE VEHICLE INTO THE WORKSHOP. HOOK UP LAPTOP. FAULT CODE 2322 & 0778 - ACTIVE. RAISE THE BONNET. TROUBLESHOOT FAULT CODES. FOUND BROKEN WIRE & DAMAGED PLUG FOR THE CAMSHAFT SPEED SENSOR. REPAIR THE DAMAGED WIRING. ADVISE CUSTOMER THE PLUG WILL NEED TO BE REPLACED. TEST VEHICLE OPERATION - OK. FAULTS INACTIVE. DISCONNECT THE LAPTOP. RETURN VEHICLE TO SERVICE. CLEAN WORK AREA & COMPLETE PAPERWORK. . Labour LABOUR CHARGES FOR THE FOLLOWING WORK 216.20 Others WORKSHOP SUPPLIES 1 23.50 Sub Total ExGST: 239.70 PARTS 0.00 LABOUR 216.20 OTHERS 23.50 GST 23.97 TOTAL 263.66	31/05/2022	9/06/2022
R140-0098056	1622	51.09	51.09	1826975		L.H spotter mirror broken	26/05/2022	26/05/2022
R140-0097007	1622	22.00	22.00	1813613		SERVICE ON 15841900 BRIS DEPOT 26.04.2022 HUBO 1813092 . Runout Tyre 11R22.5 - RTD - 7.0mm POS 09-12 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 33000370 - TYRE HELD FOR RUNOUT (Pos: 12) 77000180 SIZE: CASE STOCK 11-22.5 (Pos: 9, 10, 11)	26/04/2022	4/05/2022
R140-0095905	1622	23.48	23.48	1795667		R.H inner high beam headlight N/W	24/03/2022	24/03/2022
R122-0050307	1622	393.75	253.50	1790995		CHECK AFTERTREATMENT	16/03/2022	16/03/2022
R140-0095428	1622	283.22	283.22	1790160		CRACKED RIMS	15/03/2022	15/03/2022

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0095057	1622	803.54	803.54	1786312		Drivers side window is stuck up and won't go down, cruise control doesn't work, engine brake is stuck on high, no high beam flash, no interior lights working, heater doesn't work cant demist the windscreen	9/03/2022	10/03/2022
R154-0000706	1622	1223.83	1223.83	1784194		3/03/2022 Labour - The technician carried out checks to the cab air conditioner reported not to be cooling. Found the Tx valve was jammed closed. Carried out reclaiming of the gas and removed the evaporator coil from the cab. 3 105.00 315.00 4/03/2022 Labour - The technician carried out cleaning of the evaporator coil and fit the new TX valve into place, cleaned out the evaporator box and the blower wheel. Reassembled back into the cab. Vaced and charged the system with refrigerant. Test and left the unit cooling at +11.5 degrees. 4 105.00 420.00 1 TX Valve 284.07 284.07 1 O'Rings, Coil Cleaner, Consumables 38.50 38.50 1 Refrigerant R134A 55.00 55.00 Truck - 1622 1112.57 111.26	3/03/2022	17/03/2022
R140-0094793	1622	106.38	576.18	1782175		REPLACE MIRROW SWITCH MODULE	2/03/2022	3/03/2022
R140-0094793	1622	469.80				REPLACE A/C COMPRESSOR	2/03/2022	3/03/2022
R140-0094800	1622	581.63	581.63	1782175		SERVICE ON 15717923 BRIS DEPOT 01.03.2022 HUBO 1781070 11004496 - 295/80R22.5 152/148M BS R154 POS 2 33000051 - BALANCE TBR (Pos: 2) 33000084 - FIT TBR TYRE (Pos: 2) 33000270 - TYRE WELD FOR BLINDOUT (Pos: 2)	2/03/2022	4/03/2022
R140-0094748	1622	1340.58	1667.74	1782173		RENEW AIRBAGS AS REQUIRED	1/03/2022	2/03/2022
R140-0094748	1622	330.91				REPLACE TOP RADIATOR HOSE	1/03/2022	2/03/2022
R140-0094578	1622	926.74	547.99	1776153		Truck needs new wiper blades, steer wheel seal leaking, air leak from the drive area	24/02/2022	24/02/2022
R140-0094464	1622	1232.31	837.88	1773277		B SERVICE E5 CUMMINS 60,000 KM	22/02/2022	23/02/2022
R140-0094464	1622	291.82				REPLACE TURNTABLE WEAR RING	22/02/2022	23/02/2022
R140-0094380	1622	553.82	259.07	1770736		Ticking noise from steer wheels, truck is low on power and wont pull	19/02/2022	21/02/2022
R140-0094380	1622	41.25				GUARDIAN DFC MISALIGNED DUE TO DRIVER ABUSE	19/02/2022	21/02/2022
R140-0094371	1622	26.00	26.00	1769625		Supply 5 litres of top up engine oil	18/02/2022	18/02/2022
R140-0094220	1622	192.53	147.53	1767593		Washer bottle is leaking, air leak loosing air when connected to trailer when red button is in	16/02/2022	16/02/2022

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R142-0005070	1622	957.95	957.95	1767247		14.2.22 PROFORMA: 74271-## \$957.95 INC. GST KLMS: 760371 BREAKDOWN-SUSPENSION AIR BAG SYSTEMS LEAKS ATTEND PRIME MOVER ONSITE AT L.B.T. DEPOT. FOUND LEFT SIDE FIRST DRIVE AXLE AIR BAG LEAKING. ALSO FOUND AIR BAG AT RIGHT SIDE FIRST AXLE LEAKING ALSO. TRAVEL TO WSHOP COLLECT PARTS. RETURN TO L.B.T. DEPOT. DISCONNECT AND REMOVE LEAKING AIR BAGS, SWAP OVER FITTINGS AND FIT THE NEW AIR BAGS. BUILD UP AIR PRESSURE AND RETEST FOR LEAKS. RETURN P/MOVER TO SERVICE. RETURN TO WORKSHOP. AIRBAG-AIRGLIDE K/W [W013589541] 2.00 555.86 WORKSHOP SUPPLIES 15.00 Labour 300.00 Parts 555.86 Products 15.00 Sublet Other GST 87.09 TOTAL 957.95	14/02/2022	23/02/2022
R140-0093979	1622	355.00	635.00	1762708		ACCELERATOR PEDAL SEEMS VERY HARD TO PUSH - MIRROR HEAT LIGHT NOT WORKING	10/02/2022	12/02/2022
R140-0093979	1622	280.00				REPLACE TORQUE ROD BUSHES	10/02/2022	12/02/2022
R141-0000959	1622	641.55	641.55	1758531		Rego: XQ05BG 2016 KENWORTH T409 PRIME MOVER VIN: 6F5000000GA456339 Klms: 754 619 Turn Table Pads Remove Broken Bolts / Remove Plates / Clean / Fit New Plates and Bolts 21/01/2022 Labour 1 110.00 GST 10.00 110.00 Top Plate Insert Repair Kit - 12 Bolts / Each 1 486.65 GST 44.24 486.65 Freight to Store 1 20.70 GST 1.88 20.70 Consumables 1 16.50 GST 1.50 16.50	31/01/2022	31/01/2022
R141-0000963	1622	216.70	216.70	1758531		Rego: XQ05BG 2016 Kenworth T409 Prime Mover VIN: 6F5000000GA456339 Klms: 753 417 Starts and Then Cuts Out Connect To Scan Tool / Check Fault Codes / Ad Blue Faults / Check Water and Oil Levels / Clear Faults / Test 19/01/2022 Labour 1.75 110.00 GST 17.50 192.50 Consumables 1 16.50 GST 1.50 16.50	31/01/2022	31/01/2022
R140-0093237	1622	598.13	598.13	1756890		SERVICE ON 15597334 BRIS DEPOT 24.01.2022 HUBO 1756561 11004496 - 295/80R22.5 152/148M BS R154 POS 1 33000051 - BALANCE TBR (Pos: 1) 33000084 - FIT TBR TYRE (Pos: 1) 33000241 - SCRAP TYRES TBR (Pos: 1)	25/01/2022	27/01/2022

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R122-0047152	1622	195.80	195.80	1733193		SERVICE ORDER 15467497 SYDN DEPOT 11.12.2021 ODO 1720648 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2, 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000051 - BALANCE TBR (Pos: 1, 2) 33000540 - FLIP TRUCK TYRE OR RETREAD (Pos: 1, 2)	13/12/2021	15/12/2021
R140-0091667	1622	37.60	13.60	1728864		LOSING AIR QUICKLY WHEN PRKD - LOW BEAM ADJUSTED TOO HIGH	8/12/2021	8/12/2021
R140-0091685	1622	31.20	31.20	1728864		Send replacement parts to Mundubbera for breakdown that Mark Ford attended too	8/12/2021	8/12/2021
R140-0091499	1622	21.03	21.03	1724028		DIELECTRIC GREASE AS PER CAMERON	3/12/2021	3/12/2021
R140-0091482	1622	1528.70	2538.83	1723496		Transmission fault light stuck on	2/12/2021	6/12/2021
R140-0091482	1622	1010.13				Active fault code for low voltage at NOX sensor	2/12/2021	6/12/2021
R140-0091232	1622	131.25	0.00	1723496		AFTER TREATMENT LIGHT ON	27/11/2021	27/11/2021
R122-0046474	1622	38.50	38.50	1723496		SERVICE ORDER 15409353 SYDN DEPOT 26.11.2021 ODO 1703538 33000096 - PUNCTURE REPAIR TBR (Pos: 12)	26/11/2021	30/11/2021
R150-0000159	1622	3513.43	3513.43	1723496		BREAKDOWN ROADSIDE DOF VEHICLE REGO MAKE/MODEL MILEAGE/HRS ESN ENG MODEL ORDER NO. 23/11/2021 XQ-05BG KENWORTH T409 716343KMS E5 PI50-0000116 TRAILER REGO VIN CHASSIS UNIT Packed ute travelled to and from vehicle to inspect for truck not selecting gear. Connected the laptop - T/S active faults for ECA found faulty ECA. Remove and replace and tested - all ok. Return vehicle to service. NB: Core charge will be returned once we received the credit. Notes: ITEM DESCRIPTION QTY RATE NET GST AMT TOTAL AMT K4252 ECA KIT GEN 2 ULTRASHIFT 1 ea \$2,042.30 \$204.23 \$ 2,042.30 K4252.CORE CORE CHARGE K4252 1 ea \$700.00 \$70.00 \$ 700.00 KM KILOMETERS TRAVELLED 80 km \$1.30 \$10.40 \$ 104.00 LAPTOP LAPTOP 1 ea \$50.00 \$5.00 \$ 50.00 LABORD LABOUR ORD 1.5 hr \$109.09 \$16.36 \$ 163.64 LABOT1 LABOUR O/T1 1 hr \$134.09 \$13.41 \$ 134.09 Total: Paid: Balance Due: Subtotal: GST: \$3,513.43 \$3,194.03 \$0.00 \$319.40 \$3,513.43	24/11/2021	8/12/2021
R140-0090907	1622	62.89	62.89	1718884		Electrical suzie lead damaged	18/11/2021	18/11/2021
R140-0090847	1622	1849.87	2279.79	1718078		B SERVICE E5 CUMMINS 60,000 KM	17/11/2021	18/11/2021
R140-0090847	1622	154.50					17/11/2021	18/11/2021
R140-0090847	1622	32.67				REPAIR CRACK @ ADBLUE INJECTOR - STAND OFF BRACKET BROKEN	17/11/2021	18/11/2021
R140-0090847	1622	0.00				RENEW L/H WINDSCREEN	17/11/2021	18/11/2021
R140-0090847	1622	242.75				RENEW TORQUE ROD BUSHES AS REQUIRED	17/11/2021	18/11/2021
R140-0090847	1622	2.25				INVESTIGATE ABS FAULT CODES	17/11/2021	18/11/2021

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R122-0044165	1622	1251.25	1251.25	1689604		SERVICE ORDER 15158067 SYDN DEPOT 23.09.20212 ODO 1684294 11004496 - 295/80R22.5 152/148M BS R154 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000085 - ROTATE TBR TYRE (Pos: 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000084 - FIT TBR TYRE (Pos: 1, 2)	24/09/2021	28/09/2021
R140-0088173	1622	32.25	0.00	1681295		it appears to have a power issue and wont reboot.	9/09/2021	9/09/2021
R140-0087866	1622	183.82	91.67	1674337		REPLACE SUZI COIL AND FITTINGS	2/09/2021	3/09/2021
R140-0087866	1622	20.35					2/09/2021	3/09/2021
R140-0087387	1622	0.00	0.00	1668732		Emerald. Boost gauge is not working	21/08/2021	21/08/2021
R122-0043042	1622	599.83	461.08	1666202		REPLACE BATTERIES	19/08/2021	19/08/2021
R122-0042963	1622	264.75	0.00	1664276		NOT COMMUNICATING	17/08/2021	17/08/2021
R122-0042795	1622	913.98	921.58	1660459		B SERVICE	11/08/2021	12/08/2021
R122-0042795	1622	97.60				REPLACE TRAILER SOCKET	11/08/2021	12/08/2021
R140-0086840	1622	516.91	516.91	1659685		Please replace indicator stalk	10/08/2021	10/08/2021
R122-0042333	1622	1.50	1.50	1651968		Truck is only doing 97	29/07/2021	29/11/2021
R122-0041744	1622	305.25	0.00	1639608		Sentinel keeps turning off	12/07/2021	13/07/2021
R140-0085058	1622	(115.27)	(115.27)	1628101		CLAIM 00844 WARRANTY CLAIM 02301RT2905	28/06/2021	28/06/2021
R140-0084652	1622	264.82	32.32	1621102		AFTERTREATMENT LIGHT ON DASH	18/06/2021	19/06/2021
R140-0084444	1622	291.58	228.90	1618457		Vehicle won't start Load test batteries	14/06/2021	15/06/2021
R140-0084444	1622	8.57				Drive hub cap missing	14/06/2021	15/06/2021
R140-0083955	1622	1.50	0.00	1611709		IAP CHECKUP	3/06/2021	4/06/2021
R120-0034226	1622	76.50	0.00	1610774		SENTINEL NOT POWERING UP	1/06/2021	1/06/2021
R140-0083425	1622	6.32	2077.80	1602169		9AM, headlights need to be adjusted	22/05/2021	24/05/2021
R140-0083425	1622	1412.99				B SERVICE E5 CUMMINS 60,000 KM	22/05/2021	24/05/2021
R140-0083425	1622	278.07				REPLACE GEARBOX OILS AND FILTERS	22/05/2021	24/05/2021
R140-0083425	1622	374.42				REPLACE DIFF OILS AND FILTERS	22/05/2021	24/05/2021
R140-0083425	1622	6.00				GUARDIAN DFC MISALIGNED DUE TO DRIVER ABUSE	22/05/2021	24/05/2021
R140-0083080	1622	243.75	0.00	1595364		GUARDIAN NOT COMMUNICATING	14/05/2021	15/05/2021
R140-0083000	1622	4202.00	4202.00	1592798		SERVICE ORDER 14595756 BRIS DEPOT 12.05.2021 ODO 1611543 11001472 - 11R22.5 148/145L BS M749 05-12 33000084 - FIT TBR TYRE (Pos: 5, 6, 7, 8, 9, 10, 11, 12) 33000370 - TYRE HELD FOR RUNOUT (Pos: 5, 6, 7, 8) 77000222 SIZE: CASE STOCK 11R22.5 ECORIA (Pos: 9, 10, 11, 12)	12/05/2021	13/05/2021
R140-0082350	1622	38.50	38.50	1582404		SERVICE ORDER 14530322 BBRIS DEPOT 27.04.2021 ODO 1579265 33000096 - PUNCTURE REPAIR TBR (Pos: 11)	27/04/2021	29/04/2021
R140-0082374	1622	68.78	584.27	1582404		Truck won't build air up	27/04/2021	28/04/2021
R140-0082374	1622	388.50				Pos 4 air bag leaking	27/04/2021	28/04/2021
R140-0082374	1622	126.99				ABS lead missing, (Driver Barry Ireland) failed to report missing ABS lead	27/04/2021	28/04/2021
R140-0081856	1622	354.44	337.94	1575766		CHECK ENGINE FAULT CODES	15/04/2021	16/04/2021

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0033700	1622	1110.91	978.16	1575765		CHECK ENGINE FOR HARD STARTING	14/04/2021	15/04/2021
R120-0033675	1622	283.85	8.60	1575742		Truck keeps cutting out	12/04/2021	12/04/2021
R122-0038418	1622	0.00	0.00	1574527		CHECKED TYRES	10/04/2021	10/04/2021
R140-0081295	1622	82.50	0.00	1569346		GUARDIAN NOT COMMUNICATING	1/04/2021	1/04/2021
R140-0081140	1622	18.00	1.50	1566422		GPS NOT WORKING CORRECTLY	30/03/2021	31/03/2021
R140-0080893	1622	42.75	0.00	1562870		GUARDIAN NOT COMMUNICATING	25/03/2021	25/03/2021
R140-0080721	1622	271.12	435.94	1560270		RENEW T/TABLE PAD	22/03/2021	23/03/2021
R140-0080721	1622	164.82				steering column won't tilt	22/03/2021	23/03/2021
R120-0033354	1622	48.75	0.00	1552105		NOT COMMUNICATING	9/03/2021	9/03/2021
R140-0079861	1622	123.75	0.00	1548379		KEEPS TRIPPING THE BRAKE LIGHT FUSE BE THERE AT 9AM	4/03/2021	4/03/2021
R140-0079609	1622	124.54	36.04	1546243		RENEW OIL PRESSURE SWITCH	1/03/2021	1/03/2021
R140-0079470	1622	7.09	7.09	1543551			25/02/2021	17/03/2021
R122-0037087	1622	252.07	149.32	1540768		REPLACED SPLIT CONTROLLER	19/02/2021	26/02/2021
R140-0079075	1622	1056.00	1056.00	1539259		SERVICE ORDER 14241352 BRIS DEPOTT 18.02.2021 ODO 536843 11001553 - 295/80R22.5 152/148M BS R150 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 77000104 - FIT CASE STOCK 295/80-22.5 (Pos: 1, 2) B-SERVICE E5 CUMMINS	18/02/2021	23/02/2021
R122-0036927	1622	728.63	728.63	1536262			15/02/2021	17/02/2021
R122-0036859	1622	24.00	0.00	1534465		REPLACED GPS AERIAL AND CHANGED APN	12/02/2021	13/02/2021
R122-0036813	1622	162.79	71.29	1533524		air leak under bonnet	11/02/2021	13/02/2021
R122-0036325	1622	513.95				REPLACED FAN MOTOR	28/01/2021	29/01/2021
R122-0036177	1622	106.03	106.03	1517856		CHECKED PHONE OPERATION WITH BILL HORDERN.	21/01/2021	29/01/2021
R140-0077363	1622	1471.54	1471.54	1517156		RENEW POWER STEERING PUMP AND SUCTION FITTING	16/01/2021	3/05/2024
R140-0077264	1622	170.95	170.95	1516063		RENEW POWER STEERING PUMP AND SUCTION FITTING	14/01/2021	16/01/2021
R120-0032688	1622	125.25	6.75	1515358		TRUCK STARTS BUT WONT STAY RUNNING	13/01/2021	13/01/2021
R120-0032564	1622	449.38	6.88	1512487		RE-ALIGN WIPERS, REPLACE LH SUNVISOR CLIP	31/12/2020	31/12/2020
R120-0032571	1622	396.33	326.58	1512487		FLIP STEER TYRE ON RIM	31/12/2020	31/12/2020
R140-0076465	1622	107.25	0.00	1509897		REPAIR AUTO GREASER	21/12/2020	21/12/2020
R155-0012906	1622	608.25	608.25	1496600		REPLACE TRANSTECH AERIAL	28/11/2020	30/12/2020
R122-0034667	1622	66.00	0.00	1490043		Overspeed buzzer isn't working	19/11/2020	20/11/2020
R122-0034574	1622	9.00	0.00	1486675		Overspeed buzzer is not working, sentinel is not working	16/11/2020	17/11/2020
R140-0074956	1622	1.50	1.50	1484140		Overspeed buzzer isn't working, sentinel doesn't go off either	12/11/2020	12/11/2020
R140-0074690	1622	443.29	443.29	1477138		No wipers, no over speed buzzer, sentinel doesn't show the speed	4/11/2020	5/11/2020
R156-0010886	1622	971.58	971.58	1475685		inspect service and repair	2/11/2020	6/11/2020
R140-0074455	1622	158.14	158.14	1471149		No lights on trailers working	27/10/2020	28/10/2020
R140-0074199	1622	111.05	111.05	1468103		Bundy. Needs a new left hand indicator	21/10/2020	21/10/2020
R140-0073448	1622	37.50	37.50	1451843		Speedo is jumping around, sentinel isn't working	28/09/2020	28/09/2020
R140-0073375	1622	92.25	180.00	1447172		GUARDIAN GPS FAULT	24/09/2020	25/09/2020
R140-0073375	1622	87.75				GPS FAULT	24/09/2020	25/09/2020
R140-0072751	1622	216.00	216.00	1435234		GUARDIAN NOT COMMUNICATING	8/09/2020	8/09/2020
R140-0072292	1622	1292.98	1292.98	1426255		Dash lights flashing, abs light on Dash lights flashing	26/08/2020	31/08/2020
R120-0031164	1622	0.00	0.00	1420289		Guardian Camera Misaligned	19/08/2020	19/08/2020

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0071942	1622	562.64	562.64	1423353		RENEW TURBO TIMER	17/08/2020	22/08/2020
R140-0071848	1622	2110.51	2110.51	1417699		B SERVICE E5 CUMMINS 60,000 KM	12/08/2020	13/08/2020
R140-0071668	1622	78.64	78.64	1411301		Vehicle keeps on switching off once the key has been released	5/08/2020	6/08/2020
R140-0071384	1622	101.25	101.25	1407367		ENGINE SHUTTING DOWN AFTER STARTING	28/07/2020	29/07/2020
R140-0071284	1622	1239.55	1239.55	1407364		STEERING COLUMN FAULTY	27/07/2020	28/07/2020
R122-0032226	1622	13838.52	13838.52	1403974		APPROVED BH 22.7.20 DOSER PUMP, FUEL PUMP, THERMOSTAT-#2 PISTON PIN BROKEN	22/07/2020	27/07/2020
R140-0071153	1622	86.38	86.38	1402789		Check engine operation.	21/07/2020	22/07/2020
R122-0032164	1622	1325.94	1325.94	1402397			20/07/2020	23/07/2020
R140-0071118	1622	126.40	126.40	1402397		Regas a/c system.	20/07/2020	21/07/2020
R122-0032148	1622	166.33	166.33	1401485		REPLACE BUSTED EXHAUST CLAMP	18/07/2020	18/07/2020
R122-0032045	1622	170.50	170.50	1401445			14/07/2020	29/07/2020
R122-0031992	1622	5043.70	5043.70	1401445		SUPPLY PARTS & FLUIDS TO CUMMINS FOR ENGINE REPLACEMENT	11/07/2020	13/07/2020
R122-0031980	1622	3195.50	3195.50	1401445		APPROVED ML 10.7.20 FAILED ENGINE \cf0\fs20 Proceed to MANTON and assess situation afterhours on Saturday Front lift vehicle Remove Tail Shaft. Supply air. Interconnect brakes. Interconnect lights. Supply & fit "Vehicle in Tow" sign. Tow to CUMMINS, WETHERILL PARK Position as requested then drop. \cf1\fs16	10/07/2020	13/07/2020
R140-0070741	1622	24640.82	24640.82	1401445			10/07/2020	10/07/2020
R122-0031728	1622	115.71	115.71	1397650		secure l/h spotter mirror	29/06/2020	30/06/2020
R122-0031751	1622	1001.00	1001.00	1397650		SERVICE ORDER 13295326 SYDN DEPOT 29.06.2020 ODO 396463 11001553 - 295/80R22.5 152/148M BS R150 POS \lang1033\fs0 1- 2 33000051 - BALANCE TBR\lang1033\fs0 1-2 33000084 - FIT TBR TYRE - POS \lang1033\fs0 1- 2 77000194 SIZE: CASE STOCK 295/80-22.5 - POS \lang1033\fs0 1- 2	29/06/2020	30/06/2020
R122-0031124	1622	75.00	75.00	1376230		TRUCK FRIDGE NOT WORKING - SPEEDO ERRATIC	2/06/2020	4/06/2020
R122-0031135	1622	1195.11	1195.11	1376230		GEARBOX NOT SELECT GEAR	2/06/2020	3/06/2020
R122-0030694	1622	75.00	75.00	1363284		Pyro isn't workingPyro isn't working	13/05/2020	15/05/2020
R122-0030438	1622	485.26	614.95	1356786		1620 AIR DRYER CONTINUOUSLY EXHUASTING AIR, REKIT AIR DRYER AND REPLACE D-2 GOVENOR VALVE	1/05/2020	30/06/2020
R122-0030438	1622	129.69				REPLACE INTERCOOLER HOSE	1/05/2020	30/06/2020
R122-0030291	1622	757.70	757.70	1356786		B-SERVICE E5 CUMMINS	24/04/2020	30/04/2020
R122-0030301	1622	1958.00	1958.00	1356786		SERVICE ON 13041206 SYDN DEPOT 24.04.2020 ODO 351033 POS 5-8	24/04/2020	29/04/2020
R140-0067354	1622	1936.00	1936.00	1353892		SERVICE ON 13019492 BRIS DEPOT 18.04.2020 ODO 347277 POS 9-12	20/04/2020	22/04/2020
R120-0029746	1622	1254.92	1920.76	1349741		TRUCK WONT START	14/04/2020	16/04/2020
R120-0029746	1622	665.84				REPLACE ENGINE FAN	14/04/2020	16/04/2020
R156-0008460	1622	946.00	946.00	1326424		2 X 295/80R22.5 R150 POSITION 1,2 2 X RETORQUE 2 X FIT 2 X TRADES FTSD-12707583	14/01/2020	15/01/2020
R120-0027749	1622	259.75	259.75	1301949		CAB SAYING POWERED UP - ABS LED DAMAGED	18/11/2019	27/11/2019
R122-0027307	1622	122.25	122.25	1300027		REBUILD AIR AFTER PUTTING PARK BRAKE ON, OVERSPEED ALARM DOESN 'T WORK 80% OF TIME\fs0	14/11/2019	15/11/2019
R120-0027681	1622	753.82	753.82	1298810		B SERVICE - CUMMINS E5	12/11/2019	14/11/2019
R120-0027589	1622	902.50	3286.84	1292003		BONNET DAMAGED, HEADLIGHT HOUSING FALLEN OUT.	4/11/2019	14/11/2019
R120-0027589	1622	2206.59				REPLACE BONNET	4/11/2019	14/11/2019
R120-0027589	1622	177.75				WELD FRONT BUMPER.	4/11/2019	14/11/2019
R140-0060544	1622	37.50	37.50	1275383		STEERING COLUMN KEEPS MOVING CANT LOCK IN	17/10/2019	17/10/2019
R140-0060375	1622	37.50	37.50	1271695		CHECK ENGINE FAULT CODES- AFTERTREATMENT LIGHT ON	14/10/2019	14/10/2019
R140-0060175	1622	63.00	63.00	1267368		SLIGHT AIR LEAK BETWEEN WHEEL & FUEL TANK, SENTINEL DEVICE NOT WORKING - NO POWER	9/10/2019	9/10/2019
R122-0026445	1622	52.50	52.50	1265427		A.C NOT WORKING - CAB BUMP STOP MISSING REPLACE DRIVERS SEAT	2/10/2019	2/10/2019

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0027046	1622	10778.77	31686.47	1274390		CARRY OUT SERVICE.CHECK IDLE SHUTDOWN TIME (CUMMINS),CHECK DIFF & G/BOX OIL,CHECK DAYTIME RUNNING LIGHTS,CHECK SPEED ALERT OPERATION,CHECK CRANKCASE FILTER,CHECK VIBRATION DAMPER,CHECK ABS LEAD,CHECK PHONE OPERATION,FIT LED HEADLIGHTS,DOWN LOAD ENGINE ECM & AUTO SHIFT & CHECK SETTINGS,CHANGE ADBLUE AIR FILTER,CHANGE ADBLUE IN TANK FILTER,CHECK FOR CAMPAIGNS,SERVICE VIESA,CHANGE STEER OILS,ENGINE TUNE.A/C BEARINGS(NEW),KIT AIR DRYER,CHANGE POWER STEER OIL/FILTER,REMOVE RADIATOR STRIP & CLEAN INHOUSE.REPLACE COOLANT,REPLACE COOLANT FILTER,PRESSURE TEST INTERCOOLER,REPLACE DOSER PUMP,WHEEL ALIGNMENT,WATER PUMP,TURBO,OIL THERMOSTAT,ENGINE BRAKE KIT,COMPRESSOR-GOVERNOR VALVE,IDLERS & TENSIONERS,PAINT KOOLKAT COVER RED.CLUTCH,UPGRADE MUFFLER,DASH LOOSE,STEER COLUMN,STEER WHEEL,DRIVERS SEAT BASE WORN.DRIVERS SEAT ARM REST LOOSE.WIPER BLADES,WIPER ARM RHS REPLACE.RH SUNVISOR CLIP,CENTRE A/C VENT,DETAIL CAB,CLEAN DOG BOXES,LOADLIGHT VISOR INSECURE,CHECK ALL TAIL LIGHTS,TANK STRAP RUBBERS,STEER MUD F;LAPS CRACKED,STEER HUB CAPS MISSING,POLISH BUMPER,CAB MOUNTS,HEAT EXCHANGE O,RINGS,REPLACE HEATOR HOSES,RESECURE INLET ESOC,EXHAUST MANIFOLD GASKETS LEAKING,BONNET CRACKING ,HEADLIGHTS,LOW PRESSURE FUEL PUMP LEAK,CAB SUSPENSION BUMP STOP,HEATER TAPS LEAKING,FRONT CRANK SEAL,REAR ENGINE MOUNTS,ADBLUE INJECTOR CRACKED.LH & RH FRONT J BRAKES,GREASE CLUTCH,TREADLE VALVE FITTING LEAKING,CHECK STARTING-SLOW TO WIND.ROTATE ABS PLUGS,7 PIN FEMALE PLUG BROKEN,CHECK WALK PLATE RUBBERS,GUARDS & MUDFLAPS,KIT TURNTABLE & FOOT BUSHES,TAIL LIGHTS WATER DAMAGE,RXHAUST FACE MISSING AT OUTLET,FRONT DIFF RESEAL,LOWER SHOCK BUSHES,REAR DIFF RESEAL,REPLACE DRIVE HUB CAPS,BATTERY BOX TRAY SEIZED.	26/09/2019	21/10/2019
R120-0027046	1622	2123.49				REPLACE DOSER PUMP AND FILTERS	26/09/2019	21/10/2019
R120-0027046	1622	2165.88				CARRY OUT ENGINE TUNE. REPLACE ENGINE BRAKE KIT. INSPECT ROCKER SHAFTS AND CAMSHAFT FOR WEAR	26/09/2019	21/10/2019
R120-0027046	1622	725.02				REKIT HORTON FAN REPLACE ALL BELTS & TENSIONERS	26/09/2019	21/10/2019
R120-0027046	1622	198.75				REPLACE A/C COMPRESSOR	26/09/2019	21/10/2019
R120-0027046	1622	262.51				REKIT AIR DRYER	26/09/2019	21/10/2019
R120-0027046	1622	226.44				REPLACE OIL & COOLANT THERMOSTATS	26/09/2019	21/10/2019
R120-0027046	1622	744.77				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER	26/09/2019	21/10/2019
R120-0027046	1622	1154.06				REPLACE WATER PUMP	26/09/2019	21/10/2019
R120-0027046	1622	2662.36				REPLACE AIR COMPRESSOR & D2 GOVERNOR VALVE	26/09/2019	21/10/2019
R120-0027046	1622	3784.32				REPLACE TURBO	26/09/2019	21/10/2019
R120-0027046	1622	1225.36					26/09/2019	21/10/2019
R120-0027046	1622	532.59				POLISH WHEELS	26/09/2019	21/10/2019
R120-0027046	1622	1037.88				REPLACE TANK STRAP RUBBERS	26/09/2019	21/10/2019
R120-0027046	1622	274.75				REPLACE MUDGUARDS AND MUDFLAPS	26/09/2019	21/10/2019
R120-0027046	1622	3789.52				REPLACE CAB MOUNTS, STEERING COLUMN, STEERING WHEEL	26/09/2019	21/10/2019
R120-0026800	1622	389.24	611.60	1243612			11/09/2019	23/09/2019
R120-0026800	1622	81.00				REPLACE HORTON SOLENOID AND FILTER, REPAIR TREADLE VALVE FITTINGS THAT ARE LEAKING	11/09/2019	23/09/2019
R120-0026800	1622	141.36				REPLACE ROOF LIGHTS, REPLACE MALE TRAILER PLUG	11/09/2019	23/09/2019
R120-0026756	1622	766.37	766.37	1240240		B SERVICE - CUMMINS E5	7/09/2019	12/09/2019
R120-0026639	1622	140.41	140.41	1227949		REPLACE WIPER ARM AND BLADE ASSY RH. NOT CHARGED ON ORIGINAL JOB. REFER - R120-0026385	29/08/2019	31/08/2019
R140-0058611	1622	11.27	11.27	1227469		A/C REPAIRS	28/08/2019	29/08/2019
R140-0058538	1622	1100.38	1100.38	1226600		A/C NOT WORKING	27/08/2019	28/08/2019
R120-0026385	1622	939.71	939.71	1207683		REPLACE EXHAUST DUMP PIPE FROM TURBO	10/08/2019	12/08/2019
R120-0026357	1622	0.00	0.00	1204590		EXHAUST LEAK AT TURBO FLANGE	8/08/2019	8/08/2019
R122-0025386	1622	358.22	358.22	1201156		replace r/h bonnet strut	5/08/2019	7/08/2019
R122-0025190	1622	578.87	578.87	1190334		A/HOURS CALLTO YARD T/TABLE WILL NOT LOCK IN REPAIR T/TABLE	26/07/2019	26/07/2019
R120-0025949	1622	803.35	803.35	1174866		B SERVICE - CUMMINS E5	13/07/2019	13/07/2019
R120-0025949	1622	0.00				LEAKING COOLANT AT REAR OF ENGINE, NO BRAKE LIGHTS, WORK LIGHT ON MIRROR NEEDS TO BE TIGHTEND	13/07/2019	13/07/2019

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0056700	1622	544.50	544.50	1170283		SERVICE ON 12108976 BRIS DEP 10.7.19 HUBO 169004 POS 1	10/07/2019	16/07/2019
R120-0025850	1622	0.00	0.00	1164706		CHECK ENGINE LIGHT COMING ON - SMELLS OF BURNING COOLANT	5/07/2019	5/07/2019
R120-0025509	1622	488.76	488.76	1134330		CAB AIR BAGS FLAT	11/06/2019	17/06/2019
R120-0025489	1622	16.50	16.50	1131918		IFACE NOT CHARGING	8/06/2019	8/06/2019
R120-0025381	1622	4983.46	4983.46	1123534		DRIVE TYRES	1/06/2019	1/06/2019
R122-0024190	1622	439.41	506.91	1119530		PRYO NOT WORKING - HEATER NOT WORKING -WIND COMING THROUGH L.H DOOR - VIBRATION THROUGH THE STEERING WHEEL	28/05/2019	28/05/2019
R122-0024190	1622	67.50				ADJUST L/H DOOR STRIKER	28/05/2019	28/05/2019
R120-0025273	1622	671.44	1039.72	1111030		B SERVICE - CUMMINS E5	23/05/2019	25/05/2019
R120-0025273	1622	315.47					23/05/2019	25/05/2019
R120-0025273	1622	52.81					23/05/2019	25/05/2019
R122-0024135	1622	121.50	121.50	1113143		STEERING WHEEL HAS A LOT OF PLAY - VIBRATION THRU STEERING WHEEL - A LOT OF WIND COMING THRU THE L.H DOOR - HEATER NOT WORKING	23/05/2019	23/05/2019
R122-0023696	1622	200.93	200.93	1084194		REPLACE L/H DOOR WINDOW MODULE	29/04/2019	30/04/2019
R140-0053685	1622	23.35	23.35	1076293		ENGINE OIL TOP UP	23/04/2019	23/04/2019
R120-0024769	1622	739.20	739.20	1067269		AFTER HOURS CALLOUT TO COOLONGOLOOK TO CHECK PROBLE WITH AIR SYSTEM-BYPASS FAULTY AIR DRIER REGO: X005BG KLMS: 57,645	15/04/2019	15/04/2019
R120-0024707	1622	189.75	189.75	1062625		ROTATION WHEELS	11/04/2019	12/04/2019
R120-0024643	1622	0.00	0.00	1059995		Need to check batteries out had to jump start	9/04/2019	9/04/2019
R120-0024616	1622	543.60	1458.50	1058785		REPLACE STARTER MOTOR	6/04/2019	6/04/2019
R120-0024616	1622	405.01				AIR DRYER BYPASSED REKIT AND TEST	6/04/2019	6/04/2019
R120-0024616	1622	509.89				LOAD TEST AND REPLACE WORN OUT BATTERIES	6/04/2019	6/04/2019
R122-0023240	1622	621.49	939.08	1051907		E5 SERVICE TO SUIT 604	1/04/2019	2/04/2019
R122-0023240	1622	205.09				REPLACE GOVERNOR AIR LINES	1/04/2019	2/04/2019
R122-0023240	1622	112.50				REPLACE TANK STRAP RUBBER	1/04/2019	2/04/2019
R120-0024414	1622	126.00	126.00	1019000		INSPECT AND ADJUST GUARDIAN REPAIR MOTOR HARNESS	23/03/2019	23/03/2019
R120-0024398	1622	18.75	101.25	861803		INSPECT DRIVE TYRES	22/03/2019	22/03/2019
R120-0024398	1622	82.50				1\fbidis\ansi\deff0{\fonttbl{\f0\fswiss\prq2\fcharset0 Calibri; \viewkind4\uc1d\ltrpar\f0\fs22 GUARDIAN VIBRATION MOTOR IS NOT WORKING	22/03/2019	22/03/2019
R120-0024392	1622	37.50	37.50	861803		AIR LEAKS UNDER BONNET	21/03/2019	21/03/2019
R140-0052373	1622	1359.14	1359.14	861803		AFTERTREATMENT LIGHT ON DASH	19/03/2019	20/03/2019
R140-0052391	1622	38.50	38.50	861803		SERVICE ON 11742652 BRIS DEP 19.3.19 HUBO 1037544 POS 12	19/03/2019	20/03/2019
R120-0024223	1622	405.67	2292.82	861803	11530.00	INSPECT TURBO CHARGER FOR NOISE	11/03/2019	13/03/2019
R120-0024223	1622	906.10				HORTON FAN WORN OUT	11/03/2019	13/03/2019
R120-0024223	1622	602.12				REPLACE COOLANT THERMOSTAT	11/03/2019	13/03/2019
R120-0024223	1622	378.93				INSTALL GUARDIAN SYSTEM	11/03/2019	13/03/2019
R120-0024200	1622	205.70	205.70	861803		AFTERTREATMENT LIGHT COMES ON/OFF	9/03/2019	9/03/2019
R120-0024152	1622	146.34	347.58	861803		EXHAUST LEAK UNDER CAB	6/03/2019	6/03/2019
R120-0024152	1622	201.24				NO LIGHTS TO TRAILER FITTING SEIZED ON PRIME MOVER	6/03/2019	6/03/2019
R120-0024025	1622	392.22	392.22	861803		BLOWN FLEX TUBE	27/02/2019	28/02/2019
R122-0022416	1622	677.39	929.89	861803	11213.00	B-SERVICE E5 CUMMINS	18/02/2019	19/02/2019
R122-0022416	1622	252.50				REPLACE R/H TORQUE ROD BUSHES	18/02/2019	19/02/2019
R120-0023697	1622	516.30	516.30	861803		AIR LEAKING AT AIR DRYER	2/02/2019	4/02/2019
R122-0021818	1622	946.00	946.00	861803		2 X 295/80R22.5 R150 POSITION 1,2 2 X FIT 2 X TRADES FTSD-11558532	15/01/2019	16/01/2019
R122-0021790	1622	0.00	0.00	861803		COOLANT LEAK AT THE HEATER CONTROL	14/01/2019	15/01/2019
R122-0021585	1622	603.16	1087.06	861803	10482.00	B-SERVICE E5 CUMMINS	31/12/2018	2/01/2019

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R122-0021585	1622	483.90				REPLACE WORN OUT ALTERNATOR	31/12/2018	2/01/2019
R122-0021516	1622	41.25	41.25	861803		DRIVERS SIDE WEATHER SHIELD NEEDS SOME BOLTS IN IT	24/12/2018	27/12/2018
R120-0023103	1622	84.75	84.75	861803		ROTATE DRIVE TYRES	22/12/2018	24/12/2018
R140-0048260	1622	2.25	2.25	861803		SENTINEL DEVICE IS NOT WORKING	7/12/2018	7/12/2018
R140-0048333	1622	(22.00)	(22.00)	861803		SERVICE ON 11463138 BRIS DEP 7.12.18 HUBO 925208 POS 1	7/12/2018	12/12/2018
R120-0022858	1622	517.82	517.82	861803		REPLACE WIPER SWITCH	6/12/2018	11/12/2018
R120-0022703	1622	16.61	16.61	861803		SENTINEL TABLET IS NOT WORKING, SHROUD NEAR GEAR STICK HAS COME AWAY FROM GEAR STICK AREA	28/11/2018	30/11/2018
R122-0021006	1622	15.00	101.25	861803		GEARSHIFT CONSOLE IS LOOSE, VIBRATION IN STEER, PULLING TO LEFT, NEEDS STEERING WHEN CENTREING	26/11/2018	27/11/2018
R122-0021006	1622	86.25				SECURE G/SHIFT CONSOLE	26/11/2018	27/11/2018
R122-0021021	1622	778.25	778.25	861803			26/11/2018	26/11/2018
R120-0022450	1622	117.25	117.25	861803			10/11/2018	10/11/2018
R140-0046891	1622	198.75	198.75	861803		AUTO GREASER NOT WORKING	6/11/2018	7/11/2018
R122-0020642	1622	1548.55				B-SERVICE E5 CUMMINS	5/11/2018	5/11/2018
R122-0020274	1622	383.13	383.13	897355		COOLANT LEAK AT HEATER TAP	15/10/2018	16/10/2018
R120-0021812	1622	67.50	67.50	834574		SPEED CHECKS	29/09/2018	29/09/2018
R120-0021609	1622	1025.00	1025.00	825028		ROTATE STEER TYRES	15/09/2018	17/09/2018
R120-0021519	1622	1645.17	1645.17	821734	7108.00	B SERVICE - CUMMINS E5	11/09/2018	14/09/2018
R122-0019581	1622	30.00	30.00	811585		CUMMINS WARRANTY COOLANT PIPE	3/09/2018	3/09/2018
R122-0019573	1622	3301.50	3301.50	810327		SHIFTER TOWER FALLING OFF	1/09/2018	3/09/2018
R140-0043634	1622	44.00	44.00	790442		SERVICE ON 11069580 BRIS DEP 1.8.18 HUBO 777226 POS 5-12 ** fitted Michelin**	17/08/2018	20/08/2018
R120-0021138	1622	106.50	106.50	790442		FIT NEW TYRES - 8 ACROSS THE DRIVE	16/08/2018	20/08/2018
R120-0021103	1622	19.80	19.80	789329		10 X PRESSURE CHECK STEER & DRIVE TYRES 2 X CALLOUT G K DENNY	13/08/2018	14/08/2018
R120-0021079	1622	245.85	832.22	787939		PULLS RIGHT UNDER BRAKES	11/08/2018	11/08/2018
R120-0021079	1622	167.25				DRIVELINE VIBRATION	11/08/2018	11/08/2018
R120-0021079	1622	176.25				REPLACE ALL DRIVE TYRES	11/08/2018	11/08/2018
R120-0021079	1622	242.87				REPLACE CRACKED RH REAR ENGINE MOUNT	11/08/2018	11/08/2018
R140-0043353	1622	573.25	573.25	784223		STEERING TIGHT NOT GETTING GREASE - VIBRATION THROUGH THE STEERING WHEEL	8/08/2018	9/08/2018
R122-0019127	1622	1361.74	1399.24	782113		VIBRATION IN CAB - STEERING AL OVER THE ROAD	6/08/2018	8/08/2018
R122-0019127	1622	37.50				SEND TO BIG WHEELS FOR WHEEL ALIGNMENT	6/08/2018	8/08/2018
R122-0019133	1622	418.53	418.53	782113		6.8.18 1622 REGO QV12HP WHEEL ALIGNMENT	6/08/2018	7/08/2018
R122-0019069	1622	47.25	47.25	776233		DRIVE LINE VIBRATION	1/08/2018	1/08/2018
R122-0019070	1622	1.50	1.50	776233		BAD DRIVE LINE VIBRATION, STEERING ALL OVER THE PLACE NEEDS A WHEEL	1/08/2018	1/08/2018
R140-0043132	1622	342.95	4119.99	776233		R/H/R HUB SEAL LEAKING	1/08/2018	2/08/2018
R140-0043132	1622	3777.04				1.8.18 FITTED OWN STOCK (MICHELIN)	1/08/2018	2/08/2018
R122-0019043	1622	37.50	37.50	775931		ELECTRIC MIRROR SWITCH ONLY WORKS ONE WAY, WORK LIGHTS ON MIRRORS NEED TIGHTENING UP	31/07/2018	31/07/2018
R122-0019044	1622	20.25	20.25	775931		TANSTECH HAS NO POWER GOING TO IT	31/07/2018	31/07/2018
R120-0020777	1622	114.75	114.75	764956		BALANCE WHEELS	21/07/2018	23/07/2018
R122-0018806	1622	727.38	727.38	758058		BAD VIBRATION THOUGH THE STEERING WHEEL	16/07/2018	17/07/2018
R120-0020641	1622	751.16	751.16	756472		B SERVICE - CUMMINS E5	12/07/2018	12/07/2018
R122-0018373	1622	250.25	307.50	729127		NEEDS A NEW SPOTTER MIRROR, AFTER TREATMENT LIGHT IS ON	18/06/2018	18/06/2018
R122-0018373	1622	57.25				REPLACE SPOTTER MIRROR	18/06/2018	18/06/2018
R120-0020110	1622	110.25	110.25	722195			12/06/2018	12/06/2018

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0019835	1622	551.50	1939.76	700281	5552.00	1 X PUNCTURE REPAIR	24/05/2018	26/05/2018
R120-0019835	1622	1388.26				B SERVICE - CUMMINS E5	24/05/2018	26/05/2018
R120-0019697	1622	204.75	204.75	689376		SPEEDO INOP	15/05/2018	15/05/2018
R122-0017841	1622	38.50	38.50	689376		1 X PUNCTURE REPAIR POSITION 1 FTSD-10878918	15/05/2018	17/05/2018
R122-0017702	1622	946.00	946.00	680451		2 X 295/80R22.5 R150 POSITION 1,2 2 X FIT 2 X TRADES FTSD-10863856	8/05/2018	9/05/2018
R140-0038722	1622	39.75	39.75	651399		REINSTALL BUNK FRIDGE	13/04/2018	13/04/2018
R120-0018985	1622	66.00	66.00	643916		NO DASH LIGHTS	6/04/2018	6/04/2018
R120-0018915	1622	658.62	658.62	636875		B SERVICE - CUMMINS E5	31/03/2018	31/03/2018
R140-0037370	1622	259.09	259.09	611499			9/03/2018	9/03/2018
R140-0037120	1622	75.00	75.00	602473		INSPECT TRANSMISSION NOISE	2/03/2018	2/03/2018
R120-0018348	1622	468.75	480.13	596237		gearb/clutch issues grease clutch and check fault codes	23/02/2018	24/02/2018
R120-0018348	1622	11.38					23/02/2018	24/02/2018
R122-0016497	1622	19.80	19.80	596237		SERVICE ORDER NO 10552750 SYD DEP 7.2.18 HUBO NA POS 1,2,5-12	22/02/2018	23/02/2018
R120-0017805	1622	638.87	1650.37	574615		B SERVICE - CUMMINS E5	27/01/2018	27/01/2018
R120-0017805	1622	1011.50				REPLACE STEER TYRES	27/01/2018	27/01/2018
R120-0017547	1622	84.75	84.75	555170		GEARBOX IS PLAYING UP HARD TO GET THE TRUCK TO SELECT GEARS	13/01/2018	15/01/2018
R122-0015683	1622	2.25	2.25	550122		CAB FRIDGE NOT WORKING	8/01/2018	9/01/2018
R122-0015685	1622	41.25	41.25	550122		FRIDGE IS NOT WORKING	8/01/2018	9/01/2018
R120-0017252	1622	37.50	90.00	537457		IFACE NOT CHARGING	27/12/2017	27/12/2017
R120-0017252	1622	11.25				A/C NOT COLD	27/12/2017	27/12/2017
R120-0017252	1622	41.25				STEERING WANDERING	27/12/2017	27/12/2017
R120-0016917	1622	14207.56	25274.20	525077	3276.00	C-SERVICE	7/12/2017	18/12/2017
R120-0016917	1622	1772.26				REMOVE RADIATOR AND CLEAN HEATER TAPS + HOSES	7/12/2017	18/12/2017
R120-0016917	1622	24.00				REPLACE THERMOSTAT	7/12/2017	18/12/2017
R120-0016917	1622	91.50				REPLACE WATER PUMP OIL THERMOSTAT	7/12/2017	18/12/2017
R120-0016917	1622	66.49				REPLACE DOSER PUMP AND FILTERS	7/12/2017	18/12/2017
R120-0016917	1622	689.12				REPALCE TURBO DUMP PIPE RUBBERS EXHAUST FLEX	7/12/2017	18/12/2017
R120-0016917	1622	119.91				A/C BEARING SERVICE VIESA	7/12/2017	18/12/2017
R120-0016917	1622	291.51				REPLACE STEER OILS REPLACE POWER STEER OIL + filter ster unis	7/12/2017	18/12/2017
R120-0016917	1622	0.00				ENGINE TUNE WARRANTY- REPLACE SHAFTS AND TUNE	7/12/2017	18/12/2017
R120-0016917	1622	388.17				KIT AIR DRIER	7/12/2017	18/12/2017
R120-0016917	1622	196.50				REPLACE STARTER MOTOR	7/12/2017	18/12/2017
R120-0016917	1622	548.75				ALTERNATOR	7/12/2017	18/12/2017
R120-0016917	1622	176.78				AIR COMPRESSOR	7/12/2017	18/12/2017
R120-0016917	1622	0.00				REPLACE TENSIONERS + BELTS	7/12/2017	18/12/2017
R120-0016917	1622	485.27				CAB MOUNTS	7/12/2017	18/12/2017
R120-0016917	1622	0.00				WARRANTY- FRONT CRANK SEAL	7/12/2017	18/12/2017
R120-0016917	1622	126.00				FUEL TANK STRAPS	7/12/2017	18/12/2017
R120-0016917	1622	778.48				DRIVE GAURDS	7/12/2017	18/12/2017
R120-0016917	1622	96.92				INSPECT AND REPAIR LIGHTS TIDY SUZI COILS AND TEST	7/12/2017	18/12/2017
R120-0016917	1622	0.00				WARRANTY- RESEAL FRONT DIFF	7/12/2017	18/12/2017
R120-0016917	1622	386.25				POLISH BUMPER	7/12/2017	18/12/2017
R120-0016917	1622	4136.67				replace drive tyres balance steer + polish rims	7/12/2017	18/12/2017

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0016917	1622	521.93				DASH LIGHTS DOOR SEAL INSECURE RELOCATE IFACE WEATHER SHIELD CLIPS WIPER BLADES DETAIL + STICKERS UNH HANDLE LOOSE CALIBRATE SPEEDO NO SPEED ALERT	7/12/2017	18/12/2017
R120-0016917	1622	170.13				REPLACE FRONT ENGINE MOUNTS	7/12/2017	18/12/2017
R122-0015157	1622	81.00	81.00	515712		GEARBOX IS PLAYING UP GETTING CONFUSEDDefault Plan	4/12/2017	5/12/2017
R140-0033340	1622	980.88	1099.38	508148		B SERVICE E5 CUMMINS	28/11/2017	28/11/2017
R140-0033340	1622	118.50				AIR CONDITIONING ASSEMBLY - COMPLETE	28/11/2017	28/11/2017
R140-0032830	1622	813.71	813.71	492684		AS PER JUSTIN EMAIL 15.11.17 INPUT SHAFT REPLACEMENT PROFORMA INVOICE 15.11.2017 REPAIR ORDER NO: 532352 ENGINE HOURS 6405 ODO: 487459	15/11/2017	15/11/2017
R140-0032577	1622	(49.50)	(49.50)	485100		B/STONE 1X 11R22.5 R/O 1X FIT 1X TRADE FTSD 1555713	8/11/2017	10/11/2017
R122-0014604	1622	165.12	165.12	484077		SENTINEL DEVICE WILL NOT TURN ON	6/11/2017	6/11/2017
R140-0031801	1622	69.86	69.86	468860		REPLACE RADIATOR CAP	24/10/2017	24/10/2017
R140-0031401	1622	1111.00	1111.00	459849		B/STONE FIT 2X 295/80/22.5 R150 POS 1/2 AND BALANCE 2X HELD FOR RUN OUT FTSD 1523410	16/10/2017	20/10/2017
R140-0031141	1622	19.80	19.80	451184		B/STONE PRESSURE CHECK X12	10/10/2017	16/10/2017
R122-0013983	1622	530.24	530.24	451184	2318.00	B SERVICE	9/10/2017	10/10/2017
R120-0015424	1622	5.50	5.50	424265		1 X 11R22.5 RUNOUT POSITION 7 2 X CALLOUT 1 X FIT G.K DENNEY	18/09/2017	21/09/2017
R120-0015402	1622	114.00	114.00	424265		GEARBOX/CLUTCH ISSUES- NOT SELECTING GEARS ON HILLS SEND TRUCK TO B&H FOR WARRANTY	16/09/2017	16/09/2017
R120-0015281	1622	180.00	355.86	414799		REPLACE BROKEN GAURDS STRAIGHTEN REAR BAR	8/09/2017	8/09/2017
R120-0015281	1622	160.86				REPLACE SUZI COILS	8/09/2017	8/09/2017
R120-0015281	1622	15.00				INSPECT TURNTABLE OPERATION DUE TO DRIVERE DROPPING TRAILER	8/09/2017	8/09/2017
R120-0014917	1622	602.90	602.90	392055	1546.00	B SERVICE - CUMMINS E5	19/08/2017	21/08/2017
R120-0014829	1622	22.50	245.23	386147		REPLACE RH WINDSCREEN WALK PLATE LOOSE	15/08/2017	16/08/2017
R120-0014829	1622	222.73				REPLACE R/H WINDSCREEN-CITY AUTO GLASS	15/08/2017	16/08/2017
R120-0014538	1622	37.50	37.50	370630		BREAKDOWN-REPLACE LHR OUTTER TIRE WITH RO	31/07/2017	31/07/2017
R122-0012108	1622	935.00	935.00	329002		REPLACE STEER TYRES WITH 295 'R150, TRADE-IN x 2 FTSD- 1406570	27/06/2017	29/06/2017
R122-0012081	1622	1206.12	1206.12	327770		B SERVICE + DIFF & TRANS OILS	26/06/2017	26/06/2017
R120-0013678	1622	109.37	109.37	313471		replace wiper blades	14/06/2017	14/06/2017
R120-0013230	1622	54.75	54.75	285104		DRIVE TYRES NEED SORTING OUT	22/05/2017	22/05/2017
R140-0023553	1622	587.41	587.41	263697		B SERVICE E5 CUMMINS	3/05/2017	3/05/2017
R140-0023313	1622	2158.63	2785.55	267928		REPLACE HORTON KIT	27/04/2017	6/05/2017
R140-0023313	1622	626.92				B SERVICE E5 CUMMINS	27/04/2017	6/05/2017
R122-0010830	1622	65.25	65.25	253701		CHECK DRIVE TYRES AS THEY ARE MISS MATCHED	24/04/2017	26/04/2017
R120-0012461	1622	0.00	37.50	245971		CHECK FRONT SHOCKS	15/04/2017	15/04/2017
R120-0012461	1622	37.50				REPLACE STEER TYRES	15/04/2017	15/04/2017
R140-0022692	1622	2288.00	2288.00	240123		B/STONE FIT 4X 11R/22.5 M749 POS 9-12 4X HELD FOR R/O FTSD 1335020	11/04/2017	13/04/2017
R120-0011826	1622	817.74	817.74	192170		B SERVICE - CUMMINS E5	11/03/2017	11/03/2017
R140-0020977	1622	36.00	43.50	183940		SPEED ALERT IS NOT WORKING,	3/03/2017	3/03/2017
R140-0020977	1622	7.50				LIGHT IN OIL PRESSURE GAUGE IS NOT WORKING	3/03/2017	3/03/2017
R140-0020714	1622	77.25	77.25	183940		SPEED ALERT IS NOT WORKING	28/02/2017	3/03/2017
R120-0011242	1622	18.75	18.75	172167		SPEED ALERT QUIET	11/02/2017	13/02/2017
R120-0011017	1622	315.68	315.68	159133		INSPECT AFTER TREATMENT SYSTEM	31/01/2017	1/02/2017
R120-0011017	1622	0.00				PHONE NOT WORKING	31/01/2017	1/02/2017
R140-0019110	1622	28.86	28.86	150825		SUPPLIED DRIVER WITH WHEEL NUT COVERS	24/01/2017	24/01/2017
R140-0019129	1622	1115.84	1115.84	150825		B/STONE FIT 2X 295/80/R22.5 R150 POS 1/2 AND BALANCE 2X SENT TO COFFS FTSD 1327838	24/01/2017	27/01/2017

Work Order ID	Equipment ID	Section Total Cost	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R140-0018417	1622	800.64	807.74	136330		B SERVICE E5 CUMMINS	7/01/2017	9/01/2017
R140-0018417	1622	7.10				REPLACE LEAKING R/H/R DRIVE AXLE GASKET	7/01/2017	9/01/2017
R140-0018041	1622	68.80	68.80	125945		RENEW REAR AXLE GASKETS	29/12/2016	29/12/2016
R120-0010177	1622	536.80	536.80	116556		CALLOUT TO TWELVE MILE REST AREA TO CHECK PROBLEM WITH CLEARANCE LIGHTS NOT WORKING ON B TRAILER. UPON ARRIVAL ALL LIGHTS WERE WORKING CORRECTLY. CHECK ELECTRICAL PLUGS ETC TO TRY TO LOCATE FAULT. UNABLE TO LOCATE.	21/12/2016	22/12/2016
R140-0017423	1622	63.75	63.75	108622		VEHICLE TAKEN TO BROWN AND HURLEY FOR TRANSMISSION FAULTS	13/12/2016	13/12/2016
R120-0009876	1622	0.00	0.00	104079		LHR HUB GASKET	8/12/2016	8/12/2016
R120-0009876	1622	0.00				WARRANTY- WONT ENGAGE GEARS	8/12/2016	8/12/2016
R120-0009738	1622	258.75	258.75	97882		FIRST TUNE	2/12/2016	2/12/2016
R122-0007858	1622	58.50	58.50	88378		GEARBOX ISSUES	23/11/2016	24/11/2016
R122-0007859	1622	22.50	22.50	88378		TURBO TIMER PLAYING UP	23/11/2016	24/11/2016
R122-0007727	1622	18.75	18.75	83034		OVERSPEED BUZZER NOT WORKING	17/11/2016	18/11/2016
R122-0007728	1622	46.50	46.50	83034		SPEED LIMITER NOT WORKING	17/11/2016	18/11/2016
R122-0007482	1622	580.25	580.25	71528	957.00	DUE FOR B \f0 SERVICE	7/11/2016	8/11/2016
R122-0007483	1622	72.75	72.75	70804		TRASSMISSION SERVICE LIGHT IS ON TAKE TO G & R FOR WARRANTY 71250 KM \f0	7/11/2016	8/11/2016
R120-0008970	1622	114.00	114.00	65148		REPLACE TURNTABLE PULL CORD	31/10/2016	31/10/2016
R120-0008970	1622	0.00				GREASE CLUTCH	31/10/2016	31/10/2016
R120-0008166	1622	71.50	71.50	39065		FIT UP SPEED ALARM	29/09/2016	29/09/2016
R120-0007906	1622	180.00	180.00	32073		TINT ALL WINDOWS	21/09/2016	22/09/2016
R140-0013975	1622	75.00	75.00	30942		VEHICLE TAKEN TO BRISKAIR FOR AUTO GREASER REPAIRS	20/09/2016	20/09/2016
R120-0007676	1622	0.00	0.00	25794		WARRANTY-B&H REPLACED X-Y SHIFTER	13/09/2016	13/09/2016
R122-0005975	1622	20.25	20.25	20053		GEARBOX ISSEUES	7/09/2016	7/09/2016
R122-0005976	1622	42.75	42.75	20053		ENGINE BRAKE NOT WORKING ALL THE TIME	7/09/2016	7/09/2016
R140-0013315	1622	112.50	112.50	19209		VEHICLE TAKEN TO BROWN AND HURLEY DARRA FOR FIRST SERVICE	6/09/2016	6/09/2016
R120-0007284	1622	637.68	637.68	11460		B SERVICE - CUMMINS E5 FIRST SERVICE	30/08/2016	30/08/2016
R120-0006932	1622	(5110.00)	(5110.00)	1		PUT TYRES INTO SYSTEM FROM PD JOB	11/08/2016	11/08/2016
R120-0006911	1622	660.00	660.00	1		INSTALL GPS	10/08/2016	12/12/2016
R120-0006837	1622	4497.25	4497.25	1		PD CHANGE ALL TYRES TO MICHELINS	6/08/2016	8/08/2016
R120-0006814	1622	3912.83	6187.83	11460	94.00	PRE DELIVERY K200- SUPPLY & FIT- PHONE AERIAL EBS LEAD EBS BLANK PLIG SUZI COIL LED HEADLIGHTS CIRCUIT BREAKER SPARE JOINERS CHANGE DIFF OILS SPARE COOLANT 5 L SPARE OIL 5 L	5/08/2016	6/09/2016
R120-0006814	1622	2275.00				INSTALLL NEW TRANSTECH UNIT	5/08/2016	6/09/2016
R130-0003898	1622	48.14	195.44	1		MAKE AND FIT NEW ELECT LEAD	28/07/2016	28/07/2016
R130-0003898	1622	147.30				FIT NEW ABS LEAD	28/07/2016	28/07/2016