



Crane**Safe**®

Div of The Crane Industry Council of Australia ABN 73 002 565 773

PO Box 136 MOUNT WAVERLEY VIC 3149 Phone: +61 (03) 9501 0078 Email: assessments@cranesafe.com.au

AC A 153036-11

Initial Inspection Date: 20/11/2020

Reassessment Date: 30/03/2021

Conforms to Checklist: Yes

Issued Date: 31/03/2021

Expiry Date: 30/03/2022



**RedLine Mechanical Pty Ltd** 

ABN 68 070 729 983

PO BOX 3054 MIDLAND WA 6056

REPRESENTATIVE

Mr Michael Verhulst Phone: 0450 695 239 Email: redlinemechanical@hotmail.com

ASSESSED BY

Sean Chinnery

**Reg No:** WA1083

**Phone:** 0408 502 735

Email: sean@onsiteinspections.com.au

COMPANY

**Onsite Inspection and Training** 

PO Box 383 WILLETON

WA 6955



### Franna 4WD-MAC14

LOWER HOURS

12779

KILOMETERS

10313

SERIAL NUMBER

MC14015

PLANT NUMBER

MC14015

ΥОМ

1996

MAX LOAD 14000 KG

NUMBER OF AXLES

No

2

design registration number 14/11/96

PLANT REGISTRATION NUMBER

WC19810

ROAD REGISTRATION

NOT ROAD REGISTERED

### **Assessment**

Country Where Assessed

Australia

State

WA

Operators Manual in English OK

Log Book OK

Maintenance Records OK

Major Inspection Report Sighted Yes



## **Actions Required**

N/A

Crane Safety Manual

This report is confirmation that the crane has undergone an annual inspection to the appropriate standard and is considered safe for continued operation at time of inspection.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

All CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia and may not be use without The Crane Industry Council of Australia's prior written consent.

Boom and Attachments			
Base Section	ОК	Machinery Hook	ОК
No. 1 Section	ОК	Boom Lift Cylinders	ОК
No. 2 Section	ОК	Lock Valve(s)	ОК
No. 3 Section	REMEDIED	Extension Cylinders	ОК
No. 4 Section	N/A	Lock Valve(s)	ОК
Length Markings	N/A	Extend Ropes / Chains	ОК
Rope Compensation System	ОК	Retract Ropes / Chains	ОК
Hook Lift Lugs and Tonnage Decals	ОК	Boom Length Recoil Drum(s)	ОК
Head Sheaves and bearings	ОК	Boom Angle Indicator	ОК
Idler Sheave and Bearing	ОК	Extension / Fly Jib	N/A
Rooster Sheave and Bearing	N/A	Extension Sheaves and Bearings	N/A
Extension / Fly Jib Mounts	N/A		
ANTI-TWO BLOCKS			
Boom Head	N/A		
Rooster Sheave	N/A		
	N/A		
Extension / Fly			
HOOK BLOCKS - WITH CRANE			
	Disale		OV
Description	Block	Manufacturers Identification	OK
	OK	BP11060996	N/A
Branded WLL (kg)	OK	Safety Latches	OK
7500kg		Sheaves and Bearings	OK
	N/A	1	ОК
Swivel	N/A	Branded with Tare Weight (kg)	OK .
		71kg	
HOOK BLOCKS - WITH CRANE No. 2			
Description	Swivel hook	Manufacturers Identification	ОК
•		CCE 2071	
Branded WLL (kg)	ОК	Safety Latches	ОК
15000kg		Sheaves and Bearings	N/A
		0	
Swivel	ОК	Branded with Tare Weight (kg)	N/A
		0kg	
		ong	

### HOOK BLOCKS - WITH CRANE No. 3

 Description
 Rhino hook
 Manufacturers Identification
 OK

 175917

 Branded WLL (kg)
 OK
 Safety Latches
 OK

 10000kg
 Swivel
 N/A

 Branded with Tare Weight (kg)
 N/A

0kg

### Frame and Cabin

Frame	ОК	Control Cables / Pilot Hoses	ОК
Counterweight Attachment - Security	ОК	Heater	N/A
Counterweight Hazard Striping	REMEDIED	Air Conditioner	ОК
Boom Mounting Lugs	ОК	Gauges	ОК
Boom Mounting Pins	REMEDIED	Anti-Two block Alarms	N/A
Lift Cylinder Lugs	ОК	Horn	ОК
Lift Cylinder Pins	ОК	Access Steps	ОК
Cab Glass and Mirrors	ОК	Doors and Locks	ОК
Sheet Metal / Guards	ОК	Crane Level Indicator	ОК
Seat and Assembly including Seat Belts	ОК	Front Wiper	ОК
Decals / Signs - In English	ОК	Roof Wiper	N/A
Load Charts in English as per AS1418	ОК	Windscreen Wiper / Washer	ОК
Side Slope Deration Chart	REMEDIED	Switches and Relays	ОК
Control Levers - Clearly Marked	ОК	Rotating Beacon(s)	ОК

## **Drive Systems**

Radiator & Coolant level	OK	Engine Mounts	OK
Water Temperature Gauge	ОК	Power Transmission Belts	REMEDIED
Radiator Hoses / Heater Hoses	ОК	Exhaust Brake	N/A
Fan / Fan Shaft Assembly	ОК	Muffler / Spark Arrestor	ОК
Fan Guard	ОК	Abnormal Engine Noises	ОК
Oil Filter & Oil Level	ОК	Fuel Tank & Diesel Level	ОК
Water Pump and Conditioner	ОК	Drive Coupling	ОК
Oil Cooler(s)	N/A	Transmission Noise / Leaks	OK
Fuel Lines	ОК	Filter and Housing	ОК
Throttle	OK	Pump Drives (PTO)	OK

### Chassis Inspection

Frames	ОК	Rear Brake(s)	ОК
Suspension System	ОК	Holding / Parking Brake	ОК
Axle Lock Outs (if fitted)	N/A	Emergency Brake Release	ОК
Steering Components - Lugs / Pins etc	ОК	Front Wheels and Tyres	ОК
Front Axle(s)	ОК	Rear Wheels and Tyres	ОК
Rear Axle(s)	ОК	Spare Wheel	N/A
Differentials / Planetary Drives	ОК	Engine Cowls	ОК
Transfer Case	ОК	Articulation Joint	ОК
Drive Lines	ОК	Tackle Boxes	ОК
ABS Brakes	N/A	Fire Extinguisher	ОК
Front Brake(s)	ОК		

## Hydraulic System

Hydraulic Reservoir & Oil Level	ОК	Emergency Steering Pump	OK
Return Filters and Housing	ОК	Steering Cylinder	OK
Suction Lines and Hoses	ОК	Relief Valves	OK
Oil Cooler(s)	N/A	Flow Control Valves	REMEDIED
Main Pump(s)	ОК	Pressure Filter and Housing	ОК

## ADDITIONAL ITEMS

Steering Pump

Hoses REMEDIED

ОК

## Air Systems

Compressor	OK	Brake Valves	OK
Air Reservoirs	ОК	Air Cylinders	N/A
Drain Valves	ОК	Gauges	ОК
Air Lines	ОК	Air Dryer	N/A
Brake Chambers	ОК		

### **Electrical Systems**

ОК ОК **Battery Box Hazard Lights** ОК OK **Battery Cables Work Lights** REMEDIED ОК **Battery Isolator Clearance Lights** OK OK **Head Lights** Switches and Relays ОК ОК **Tail Lights** Back-up Alarm ОК ОК Stop Lights Horn for Road Travel ОК **Directional Indicators** 

ADDITIONAL ITEMS

**REMEDIED** Number plate light

### Main Winch

Winch Condition & Oil Level	OK	Drum Turn Indicator	N/A
Leaks	ОК	Wire Rope	ОК
Rope Spooling	ОК	Rope Anchor and Pin	ОК
Winch Attachment, Pins / Bolts	ОК	Correct Assembly and Connection of Hoist Rope Anchor	ОК
Brake Operation	OK		

Brake Operation

### Functional Tests - Main Winch

Rated Capacity Indicator (RCI)

**Load Chart Reference Number** 

Printed Chart - No Load

MCC1087AA

ОК

	Printed Chart	RCI
Boom Angle, deg	30.00°	30.00°
Boom Length, m	10.00m	10.00m
Radius, m	6.61m	6.60m
Load, kg	3200kg	3100kg

Rated Capa	acity Limite	er (RCL)
------------	--------------	----------

**Load Chart Reference Number** 

Rated Load - Boom Fully Extended

MCC1087A

OK

	RCI	Measured
Radius, m	5.30m	5.30m
Load, kg	3600kg	3510kg

Rated Load in Stability

ОК

	RCI	Measured
Radius, m	5.30m	5.30m
Load, kg	3600kg	3510kg

Line Pull Test

ОК

	RCI	Measured
Load, kg	2700kg	2700kg

Winch Brake Test

OK

	RCI	Measureu
Load, kg	2700kg	2700kg

Overload Warning Lights and Alarms

OK

Rated Capacity Limiter Fitted (Overload Limiter)

ОК

Moscurod

### Crack Inspection

No Cracks Detected

ОК

Any third party testing is not included in the Crane**Safe** NATA accreditation.

Manufacturer Additional
N/A
Site Requirements

N/A


### Crane



Serial Number



**Lower Hours** 



Kilometers



Model

### Assessment



Log Book



Maintenance Records



Description



Manufacturers Identification



Description



**Manufacturers Identification** 



Description



Manufacturers Identification



**Retract Ropes / Chains** 



No. 3 Section



Lift Cylinder Pins

Mac 14 Cranesafe.pdf

**Counterweight Hazard Striping** 



**Boom Mounting Pins** 


Mac 14 Cranesafe.pdf

Side Slope Deration Chart

### **Drive Systems**



Transmission Noise / Leaks



Power Transmission Belts

### Chassis Inspection



Rear Wheels and Tyres



**Articulation Joint** *No movement* 




Front Wheels and Tyres

## Hydraulic System



**Return Filters and Housing** 



Flow Control Valves



Additional

All CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia and may not be use without The Crane Industry Council of Australia's prior written consent.

### Air Systems



Gauges

### **Electrical Systems**



**Battery Isolator** 



Additional



**Clearance Lights** 



**Brake Operation** 



Correct Assembly and Connection of Hoist Rope Anchor

### Functional Tests - Main Winch




**Load Chart Reference Number** 



Rated Load - Boom Fully Extended - Load Measured



Rated Load - Boom Fully Extended



Rated Load - Boom Fully Extended - Load RCI



Line Pull Test - Load Measured



Line Pull Test - Load RCI



Y - Y Measurement





PO Box 136
MOUNT WAVERLEY VIC 3149
P: +61 (03) 9501 0078
E: assessments@cranesafe.com.au

Accreditation no. 19898

## ARTICULATED MOBILE CRANE

Maintenance List

RedLine Mechanical Pty Ltd P O Box 3054 MIDLAND 9509 WA Company Postcode Address State

4WD Mac 14 NOT ROAD WC19810 MC14015 MC14015 14/11/96 14000kg Franna 12779 1996 **Design Registration Number** Year of Manufacture Plant Registration Road Registration Number of Axles Serial Number Plant Number Lower Hours REGISTERED Max. Load Model Make

10313 Kilometers

Company Postcode Address State State Sean Chinnery 0408 502 735 Australia WA1083 Country where assessed seanonsite@amnet.net.au Assessed By Reg. No. Phone Email

Onsite Inspection and Training

PO Box 383 WILLETON

6955

WA

WA

Crane Safety Manual

redlinemechanical@hotmail.com Mr Michael Verhulst 68 070 729 983 0450 695 239 Representative Phone Email ABN



NATA is a signatury to the ILAC Butual Recognition Arrangement for compliance with BONEC 17020

© The Crane Industrial 2009

All CraneSafe forms, Checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia 2009

Maximum Period Allowed Before Re-assessment Initital Inspection Date

Conforms to Checklist

ŝ

20/11/2020

## CRANE

## ASSESSMENT

8 8 8 Operators Manual in English Maintenance Records Log Book

## **BOOM AND ATTACHMENTS**

Item

No. 3 Section

NOT OK -

Remedied By

No. 3 Section Push bar is bent



## FRAME AND CABIN

Counterweight Hazard Striping

Boom Mounting Pins

Side Slope Deration Chart

NOT OK . \

NOT OK - V

NOT OK - Not in the crane

Remedied By





Counterweight Hazard Striping Faded



Boom Mounting Pins Noisy when booming up

all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consert,

## DRIVE SYSTEMS

Item

Power Transmission Belts

NOT OK -

Remedied By





Power Transmission Belts /

## CHASSIS INSPECTION

Item

Front Wheels and Tyres

NOT OK -

Front Wheels and Tyres Low pressures

Remedied By



all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consent.

## HYDRAULIC SYSTEM

Item

Flow Control Valves

Hoses

NOT OK -

NOT OK -





Flow Control Valves Oil leak from valve bank under cabin



Additional



## **ELECTRICAL SYSTEMS**

Item


Clearance Lights

Number plate light

NOT OK -

NOT OK -







Additional

# ADDITIONAL ANNUAL INSPECTIONS STIPULATED BY THE MANUFACTURER





PO Box 136
MOUNT WAVERLEY VIC 3149
P: +61 (03) 9501 0078
E: assessments@cranesafe.com.au

Accreditation no. 19898

## ARTICULATED MOBILE CRANE

Maintenance List

RedLine Mechanical Pty Ltd P O Box 3054 MIDLAND 9509 WA Company Postcode Address State

4WD Mac 14 NOT ROAD WC19810 MC14015 MC14015 14/11/96 14000kg Franna 12779 1996 **Design Registration Number** Year of Manufacture Plant Registration Road Registration Number of Axles Serial Number Plant Number Lower Hours REGISTERED Max. Load Model Make

10313 Kilometers

Company Postcode Address State State Sean Chinnery 0408 502 735 Australia WA1083 Country where assessed seanonsite@amnet.net.au Assessed By Reg. No. Phone Email

Onsite Inspection and Training

PO Box 383 WILLETON

6955

WA

WA

Crane Safety Manual

redlinemechanical@hotmail.com Mr Michael Verhulst 68 070 729 983 0450 695 239 Representative Phone Email ABN



NATA is a signatury to the ILAC Butual Recognition Arrangement for compliance with BONEC 17020

© The Crane Industrial 2009

All CraneSafe forms, Checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia 2009

Maximum Period Allowed Before Re-assessment Initital Inspection Date

Conforms to Checklist

ŝ

20/11/2020

## CRANE

## ASSESSMENT

8 8 8 Operators Manual in English Maintenance Records Log Book

## **BOOM AND ATTACHMENTS**

Item

No. 3 Section

NOT OK -

Remedied By

No. 3 Section Push bar is bent



## FRAME AND CABIN

Counterweight Hazard Striping

Boom Mounting Pins

Side Slope Deration Chart

NOT OK . \

NOT OK - V

NOT OK - Not in the crane

Remedied By





Counterweight Hazard Striping Faded



Boom Mounting Pins Noisy when booming up

all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consert,

## DRIVE SYSTEMS

Item

Power Transmission Belts

NOT OK -

Remedied By





Power Transmission Belts /

## CHASSIS INSPECTION

Item

Front Wheels and Tyres

NOT OK -

Front Wheels and Tyres Low pressures

Remedied By



all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consent.

## HYDRAULIC SYSTEM

Item

Flow Control Valves

Hoses

NOT OK -

NOT OK -





Flow Control Valves Oil leak from valve bank under cabin



Additional



## **ELECTRICAL SYSTEMS**

Item


Clearance Lights

Number plate light

NOT OK -

NOT OK -







Additional

# ADDITIONAL ANNUAL INSPECTIONS STIPULATED BY THE MANUFACTURER





PO Box 136
MOUNT WAVERLEY VIC 3149
P: +61 (03) 9501 0078
E: assessments@cranesafe.com.au

Accreditation no. 19898

## ARTICULATED MOBILE CRANE

Maintenance List

RedLine Mechanical Pty Ltd P O Box 3054 MIDLAND 9509 WA Company Postcode Address State

4WD Mac 14 NOT ROAD WC19810 MC14015 MC14015 14/11/96 14000kg Franna 12779 1996 **Design Registration Number** Year of Manufacture Plant Registration Road Registration Number of Axles Serial Number Plant Number Lower Hours REGISTERED Max. Load Model Make

10313 Kilometers

Company Postcode Address State State Sean Chinnery 0408 502 735 Australia WA1083 Country where assessed seanonsite@amnet.net.au Assessed By Reg. No. Phone Email

Onsite Inspection and Training

PO Box 383 WILLETON

6955

WA

WA

Crane Safety Manual

redlinemechanical@hotmail.com Mr Michael Verhulst 68 070 729 983 0450 695 239 Representative Phone Email ABN



NATA is a signatury to the ILAC Butual Recognition Arrangement for compliance with BONEC 17020

© The Crane Industrial 2009

All CraneSafe forms, Checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia 2009

Maximum Period Allowed Before Re-assessment Initital Inspection Date

Conforms to Checklist

ŝ

20/11/2020

## CRANE

## ASSESSMENT

8 8 8 Operators Manual in English Maintenance Records Log Book

## **BOOM AND ATTACHMENTS**

Item

No. 3 Section

NOT OK -

Remedied By

No. 3 Section Push bar is bent



## FRAME AND CABIN

Counterweight Hazard Striping

Boom Mounting Pins

Side Slope Deration Chart

NOT OK . \

NOT OK - V

NOT OK - Not in the crane

Remedied By





Counterweight Hazard Striping Faded



Boom Mounting Pins Noisy when booming up

all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consert,

## DRIVE SYSTEMS

Item

Power Transmission Belts

NOT OK -

Remedied By





Power Transmission Belts /

## CHASSIS INSPECTION

Item

Front Wheels and Tyres

NOT OK -

Front Wheels and Tyres Low pressures

Remedied By



all CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia's prior written consent.

## HYDRAULIC SYSTEM

Item

Flow Control Valves

Hoses

NOT OK -

NOT OK -





Flow Control Valves Oil leak from valve bank under cabin



Additional



# **ELECTRICAL SYSTEMS**

Item


Clearance Lights

Number plate light

NOT OK -

NOT OK -







Additional

# ADDITIONAL ANNUAL INSPECTIONS STIPULATED BY THE MANUFACTURER



# Crane**Safe**

# **Wire Rope Certificate**

Certificate No: AC R.1 153036-11.1

Accreditation no. 19898

**Company Name:** RedLine Mechanical Pty Ltd **Crane Make & Model:** Franna 4WD-MAC14

Length of Rope: 60.00m

**Rope Construction:**  $35 \times 7$  non rotating

Wire Finish: Uncoated

**Direction of Rope Lay:** Lang Right Hand Lay

**Sheave Wear:** Pass **Crane Serial No.:** MC14015 Year of Manufacture: 1996

Wire Rope Application: Main Hoist

Rope Termination (End 1): Swaged End Fitting Rope Termination (End 2): Wire Rope Clamps

**Rope Diameter:** 13.00mm **Minimum Diamter Wear:** 12.4mm





	pected (approx. etres)	10	20	30	40	50	60	8
Number of Visible Wire Breaks (over a length of 6x the rope's dia) AS2759-2004 Clause 14.4		0	0	0	0	0	0	0
Degree of Damage and Deformation of Rope AS2759-2004 Clause14.13		0	0	0	0	0	0	0
Abrasion of Outer Wires AS2579-2004 Clasue 14.9	Degree of Deterioration	0	0	0	0	0	0	0
Corrosion AS2759-2004 Clause14.8	Degree of Deterioration	0	0	0	0	0	0	0
Reduction of Rope	Measurement (mm)	13.00	13.00	13.00	13.00	13.00	13.00	13.00
Diameter AS2759-2004 Clause14.9	Measurement 90° (mm)	13.00	13.00	13.00	13.00	13.00	13.00	13.00
Additional Comments			_				_	

Degree of Deterioration:

1 = slight, 2 = medium, 3 = high, 4 = very high, 5 = discard

At time of inspection, the rope measurements and construction was in accordance with the requirements of AS2759 - 2004 Section 13 and the operators manual supplied with the crane.

Date Inspected: 30/03/21 Date Issued: 31/03/2021

Sean Chinnery CraneSafe Assessor No: WA1083





# **Supporting Documents**



# **Original Rope Certificate**



# Crane**Safe**®

Certificate No: AC HB.1 153036-11.1

# **Fall Block Certificate**

Accreditation no. 19898

**Company Name: Crane Make & Model:**  RedLine Mechanical Pty Ltd Franna 4WD-MAC14

Crane Serial No.: Year of Manufacture: MC14015 1996

Item Inspected AS1418.5-2013 Annex K.1				
	MANUFACTURERS ID no.	BP11060996		
Fall Block	NOMINAL LIFTING LOAD	7500kg		
	MASS	71kg		
AS1418.5-2013 Annex K.3				
Sheave	NUMBER OF SHEAVES	1		
	ROPE DIAMETER	13mm		
	KIND OF MATERIAL	Metal		
	GROOVE WEAR	¥		
	BRUISING	✓		
	ROTATING / BEARING	✓		
	CRACKS	₹		
	CHIPS	✓		



At time of Inspection, the hook block was in accordance with the requirements of AS1418 Part 5 2013 and the load charts supplied with the crane.

Date Inspected: 30/03/21 Date Issued: 31/03/2021

Sean Chinnery CraneSafe Assessor No: WA1083







# Crane**Safe**®

**Hook Block Certificate** 

Certificate No: AC HB.2 153036-11.1

Accreditation no. 19898

**Company Name: Crane Make & Model:**  RedLine Mechanical Pty Ltd Franna 4WD-MAC14

Crane Serial No.: Year of Manufacture: MC14015 1996

Item Inspected AS1418.5-2013 Annex K.1			
	MANUFACTURERS ID no.	CCE 2071	
Hook	FORM OF HOOK	Single	
Block	NOMINAL LIFTING LOAD	15000kg	
	MASS	0kg	
AS1418.5-2013 Annex K.2			
	WEAR	ightharpoons	
	CRACKS	$\mathbf{Z}$	
	DEFORMATION	$\mathbf{Z}$	
Lifting	SAFETY LATCH	$\mathbf{Z}$	
Hook	SWIVEL	$\mathbf{Z}$	
	BEARING	$\mathbf{Z}$	
	HOOK BRUISING	ightharpoons	
	Y - Y MEASUREMENT	100mm	
AS1418.5-2013 Clause 4.2.13			



At time of Inspection, the hook block was in accordance with the requirements of AS1418 Part 5 2013 and the load charts supplied with the crane.

Date Inspected: 30/03/21 Date Issued: 31/03/2021

Sean Chinnery CraneSafe Assessor No: WA1083







**Certificate No: WA153036** 



# CERTIFICATE OF ANNUAL INSPECTION AND TESTING Articulated Mobile Crane

**Inspection Date:** 30/03/21 **Renewal Date:** 30/03/2022 **Issued Date:** 31/03/2021

Location of Inspection: Redline mechanical

Crane Owner: RedLine Mechanical Pty Ltd

Address: PO BOX 3054 MIDLAND, 6056, WA, Australia

Crane Make: Franna

Crane Model: 4WD-MAC14

**Crane Serial Number: MC14015** 

**YOM:** 1996 **Hours:** 12779



Inspection in accordance with: ✓ AS2550.1 & AS2550.5 EN (FEM&ISO) JIS
✓ Codes of Practice ✓ Manufacturer's Instructions.
Inspection Comments:
This certificate is confirmation that the crane has undergone an annual inspection to the
appropriate standard and is considered safe for continued operation at time of inspection.

Signed:

**Printed Name:** Sean Chinnery

CraneSafe Assessor No:: WA1083

CraneSafe Assessment No: AC A 153036-

11

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

© The Crane Industry Council of Australia 2009



**Certificate No: WA153036** 



Accreditation no. 19898

# LOAD INDICATOR CERTIFICATION Articulated Mobile Crane

Annual Inspection Date: 31/03/2021 Crane Owner: RedLine Mechanical Pty Ltd

Address: PO BOX 3054 MIDLAND, 6056, WA, Australia

Crane Make: Franna Crane Model: 4WD-MAC14
Crane Serial Number: MC14015 YOM: 1996 Hours: 12779

Rated Capacity Indicator (RCI)
Load Chart Reference Number

MCC1087AA

**Printed Chart - No Load** 

	Printed Chart	Rated Capacity Indicator
Boom Angle, deg	30.00	30.00
Boom Length, m	10.00	10.00
Radius, m	6.61	6.60
Load, kg	3,200.00	3,100.00

## Rated Capacity Limiter (RCL)

**Load Chart Reference Number** 

Rated Load - Boom Fully Extended

MCC1087A

### **Rated Load in Stability**

	Rated Capacity Indicator	Measured
Radius, m	5.30	5.30
Load, kg	3,600.00	3,510.00

	Rated Capacity Indicator	Measured
Radius, m	5.30	5.30
Load, kg	3,600.00	3,510.00

### **Line Pull Test**

# Rated Capacity Measured Load, kg 2,700.00 2,700.00

# **Winch Brake Test**

	Rated Capacity Indicator	Measured
Load, kg	2,700.00	2,700.00

At the time of test, the load indicator was reading in accordance with the requirements of AS1418.1 & AS1418.5 and the load charts supplied with the crane

Signed:

**Printed Name:** Sean Chinnery

**CraneSafe Assessor No:**: WA1083

CraneSafe Assessment No: AC A 153036-11

**Issued Date:**: 31/03/2021

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

© The Crane Industry Council of Australia 2009

All CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia and may not be used without The Crane Industry Council of Australia's prior written consent.

# **SUPPORTING INFORMATION**



P Spearwood LPO, PO Box 7272, SPEARWOOD WA 6163

A 25 Quarimor Rd, Bibra Lake WA 6163

T +61 8 9499 6500

F +61 8 9418 4160

E admini/amlequip.com.au

# 10 YEAR ASSESMENT REPAIR INSPECTION REPORT ARTICULATE MOBILE CRANE

Section 1.0 Crane Particulars	REPORT No AML - 42984-
Owner: Civmec	
Location: Perth Workshop	
Contact: Mark Cockshott	
Plant ID: CR4	Worksafe No:WC19810
Make: Terex	Serial No: 14015
Model: MAC 14	Design Code:
Year of Manufacture: 1996	Max SWL: 14t
Machine Hours: 12066	Machine Kms: 10313
Section 1.1 Paperwork & Accurate Records	
Operators Manual: Located in Cab	
Log Book: Located in Cab Last Entry:	
Service Repair History:	
Inspections History: 14/07	7/2016
The following inspection was carried out under the gui Inspection Guidelines.	idelines on AS1418/ 2550 and CICA Major
Inspection Date: 14/07/2016	Repair Date: 14/07/2016
INSPECTOR SIGNATURE:	DATE: 14/7/16
CUSTOMER SIGNATURE:	DATE:
10 YEAR INSPEC	TION REPORT









P Spearwood LPO, PO Box 7	

- A 25 Quarimor Rd, Bibra Lake WA 6163
- T +61 8 9499 6500
- F +61 8 9418 4160
- E admin@amlequip.com.au

Machine in good condition	
Damage:	
Section 1.3 Engine	
Oil Condition Oil Pressure Exhaust System Exhaust Smoke Air Intake System Engine Mountings Radiator Radiator Mounts/ Guards/ Hoses Correct Coolant Engine Fan/ Mounting V Belt Fuel Line/ Security Engine Breather Fuel Tank Throttle Linkages Exhaust Brake Loose/ Broken Bolts Unusual Noises Comments;	Satisfactory Unsatisfactory   N/A   Notes:
Engine oil and filters changed , and cleaned , replace exhaust fl	, engine front crankshaft seal replaced , Radiator removed and flush ex
Oil Condition Oil Pressure Oil Leakage Oil Cooler Hoses/ Security Play in shift mechanism Clutch & Operation Shift/ Kick Down	Satisfactory Unsatisfactory N/A   Notes:



P Spearwood LPO, PO Box 7272, SPEARWOOD WA 616	), PO Box 7272, SPEARWOOD WA 6163
--	-----------------------------------

A 25 Quarimor Rd, Bibra Lake WA 6163

T +61 8 9499 6500

F +61 8 9418 4160

E adminitramlequip.com.au

ABN 43 101 150 663				
Torque Converter Operation Transfer case (T/C) Oil Condition T/C Condition T/C Leakage T/C Cooler/ Hoses T/C Bearing Movement T/C Mountings Unusual Noises Comments:				
Oil and filter changed				
Section 1.5 Driveline/ Differentials				
Uni-Joints Centre Bearing Movement in splines Propeller shaft run out Differential Oil Oil Leaks Backlash Loose/ Broken Bolts Unusual Noises Comments:  Wheel bearings replaced and hub seal 16P14008/003, rear drive shaft univers		le quills	NDT as	
Section 1.6 Steering Group				
Steering Wheel Play/ Backlash Steering Wheel Operation/Condition Turning Force Orbital Oil Leak Orbital Mounting End Play Oil leaks Hose Condition Joint Condition Correct Pressures Priority Valve Steering Cylinder Oil Leaks Steering Cylinder Mountings Emergency Steer Function Steering Lock/ Stops Function Test Comments:	Satisfactory U	Insatisfacto	× 000000000000000000000000000000000000	Notes:









10	e.	ini	in	m	nn	Di.	5	PO	B	-	7	27	9	cp	F	SER	W	ďά	505	M	VA.	E	36	ŧ
		~~				г. ъ			-					-at-	Bes 17				~~			- 164		

A 25 Quarimor Rd, Bibra Lake WA 6163

T +618 9499 6500

F +61 8 9418 4160

E adminipamlequip.com.au

Steer pins and bearings inspected al reset, emergency steer pressure swi		1.700 14.74 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19.44 19
reset, emergency steer pressure swi	terrepraced , reset main block re	ilei
Section 1.7 Brake Systems		
	Satisfactory Unsatisfactory N/A	Notes:
Brake Test		-
Park Brake Test		
Air Leakage		0.75
Treadle Valve Function		-
Control Valve Function		•
Dump Valve Function		-
Low Air Alarms		
Mounting Booster/ Function		1.43
Compressor Cycle Time		<ul> <li>checked with in spec</li> </ul>
Pressure Test		
Brake Shoes/ Pads		270
Brake Drums/ Disks		- see notes
Hose/ Mounting Condition		3.73
Emergency Brake Control		2.40
Comments:		
Brake drums and shoes visual inspe-	ction, all with in spec, emergenc	y brake knob replaced
Section 1.8 Wheel Group		
	Satisfactory Unsatisfactory N/A	Notes:
Tyre Pressure		- see notes
Tyre Crack/ Pressure		•
Tyre Condition		- see notes
Loose/ Broken Bolts/ Studs		*
Wheel Spacers		
Spare Tyre		•
Tyre Ratings		
Comments:		
4 x front tyres replaced, all wheel s	pacers replaced	
Section 1.9 Suspension Group		Notes
Leaf Spring Condition	Satisfactory Unsatisfactory N/A	Notes:
Misalignment among leaves		100
Looseness/ Damage to Harness	M H H	
	M H H	
Torque Arm Bush Condition	8 8 8	0.53
Spring Lock Out Condition	님 님 띯	•
Spring Lock Out Switching	님 님 띯	
Spring Lock Out Cylinder Leaks	닗 님 띰	•
4WD Operation		*
Axle Lock Operation		
Comments:		









	P Spearwood	PO PO Box 7	272 SPEARW	OOD WA 6163
--	-------------	-------------	------------	-------------

A 25 Quarimor Rd, Bibra Lake WA 6163

T +618 9499 6500

F +61 8 9418 4160

E admin@amlequip.com.au

Oil Condition Oil Leaks Hydraulic Tank Mounting/ Condition Hydraulic Tank Sight Glass Filter/ Housing Pressure Hoses Return Hoses Hydraulic Pump Condition/ Mounting Steer Pump Condition/ Mounting Emergency Steer Motor/ Mounting Hydraulic Oil Cooler Pump Flow Efficiency Control Valve Condition/ Mounting Control Lever Operation/ Condition Correct Pressures Dash Gauge Operation Comments:	Satisfactory Unsatisfactory	\$0000000000000000000000000000000000000	Notes:
Hydraulic pump flow test completed as tank filter housing ,  Section 2.1 Frame/ Panel Group  Centre Pivot Movement Door Seals Door Locks Panel Rust Panel Damage Comments:	Satisfactory Unsatisfactory	N/A	Notes:







P Spearwood LPO, PO Box 7272, SPEARWOOD WA 6163
---

A 25 Quarimor Rd, Bibra Lake WA 6163

T +61 8 9499 6500

F +61 8 9418 4160

E adminigramlequip.com.au

Section 2.2 Boom Group			
	Satisfactory Unsatisfactory	N/A	Notes:
Base Section			•
No. 1 Section	$\boxtimes$		
No. 2 Section			
No. 3 Section	$\boxtimes$		
No. 4 Section		$\boxtimes$	- N/A
Lift Cylinder Pivot Pins/Bushes	$\boxtimes$		- Inspected
Hose Condition			- Changed as required
Lift Cylinder Leaks			Tellin Floor of the second
Rear boom Pivots			- Pins and bearings replaced
Lock Valve Operation	$\boxtimes$		- Over centre valves replaced
Wear Pad Condition			- with in spec, reshim
Wear Pad Lubrication			- Regreased on assembly
Telescopic Cylinder Mountings			
Telescopic Cylinder Leaks			
Telescopic Cylinder Condition			- Resealed
Telescopic Cylinder Counterbalance Valve			
Rear Guide Sheave			
Rear Guide Motor			
Length Indicator			- Recalibrate 3B6
Angle Indicator			- Recalibrate 3B6
Guide Sheaves			1 = 1
Head Sheaves			
Winch Rope Roller/ Guide			
Extend/ Retract Rope Sheaves			
Boom Extension/ Retraction Ropes:	2007		
a) Breakage			
b) Wear			
c) Kinks			
d) Corrosion			*
e) Lubrication			
f) Adjustment			- see notes
Comments:			

NDT completed as per report 16P14008/001, Boom Survey as per report CR0386, 3B6 Recalibrated, motion cut system installed, transducers replaced, new decal install on manual for pin location holes, compensator sheave boss replaced NDT as per report 16P14057/001, deflector shave replaced, retract rope replaced cert attached D8961, retract sheave bearings replaced, extension ropes replaced, as per cert D8630, Manual push bar replaced, lower boom roller on head section replaced, hook pin replaced, Winch mounts replaced NDT as per report 16P14008/004, Hook Block recertified as per attached BP11060995.2, Hook recertified as per report BP11060995.1, Rhino Rectified BVII1060995.3,









Section 2.3 Winch Group

ABN 43 101 150 663

P Spearwood LPO, PO Box 7272, SPEARWOOD WA 6163
---

A 25 Quarimor Rd, Bibra Lake WA 6163

T +618 9499 6500

F +61 8 9418 4160

E adminitramlequip.com.au

	Satisfactory Unsatisfactory	N/A	Notes:
Hose/ Fitting Security			- Replaced
Hose/ Fitting Leaks			
Winch Mounting			-
Oil Condition			- Changed
Oil Leaks			3
Brake Function			- New
Brake Efficiency			- New
Drum Condition			
Rope Anchors/ Points			-
Hook Block			-
Hook Rotation			-
Hook Deformation			
Rope Guards			-
Sheave Condition			-
Manufacturer Identification			-
Branded SWL/ Tare Weights			-
Winch Rope:			
a) Correct Diameter			- Replaced
b) Deformation			

Winch assembly replaced see attached serial number , winch rope replaced asper certificate

# Section 2.4 Electrical

c) Weard) Kinks

g) Eyelet h) Lubrication i) Correct Length Comments:

e) Broken Wires f) Bull Dog Grips

	Satisfactory Unsatisfactory	N/A	Notes:
Battery Box			
Battery Security			
Battery Isolator/ Lock Out			A company
Lights			- Repaired as required
Hazard Lights			
Reverse Alarm			
Reverse Light/s			
Switches/ Relays			
Horn			
Dash Gauges			- replaced globes
Neutral Start Operation			
Interior Light			
Warning Light	<b>X</b> I		-
Harness Condition/ Security	<b>X</b> I	П	_









P	Spearwood LP	O. PO Box 7272, 5	SPEARWOOD WA. 6163
1	war on the same of the	A STATE OF THE PARTY.	STATE OF THE PARTY

T +618 9499 6500

F. +618 9418 4160

E admini⊞amlequip.com.au

Condenser Condition/ Mounting Evaporator Condition/ Mounting Hose/ Fitting Security Heater Operation Core Condition/ Mounting Heater Hose Condition/ Mounting Comments:				- Serviced cable reconnected
Air con compressor replaced, system p system re gassed and tested operation . headlight switch , replace indicator ala	Brake pressure	e switch	replaced	i, Beacon replaced, replace
Section 2.5 Crack Inspection				
NDT Test carried out to 10% on high str repair procedure will be carried out as p Comments:		er attach	ed repor	t. If faults have been identified the
As per reports attached				
As per reports attached  Section 2.6 Safety Documentation				









P Spearwood LPO	PO Box 7272, SPE	ARWOOD WA 6163
-----------------	------------------	----------------

A 25 Quarimor Rd. Bibra Lake WA 6163

T +61 8 9499 6500

F +61 8 9418 4160

E admin@amlequip.com.au

### Section 2.7 Operational Testing

	Satisfactory Unsatisfactory	N/A	Notes:	
Winch Hoisting/ Lowering	Ø O	П	•	
Boom Raising/ Lowering	<b>⋈</b> □	$\Box$		
Boom Telescoping		$\Box$	-	
Slewing Under Load				
Road Test			2	
Lights/ Indicators			2	
Rated Load at Full Extension				
Rated Load Stability				
Line Pull Test at 110%				
Winch Brake Test				
Overall Performance				
Comments:				
All systems tested and operated, fu	Il 110% SWL structural, sta	bility a	and line pull tests completed	

### Overall Additional Comments:

 Machine has had a full major 10 year mechanical inspection completed, all main systems were tested, repaired and replaced as required, this machine is considered safe for use and complies to AS1418/2550









P Spearwood LPO, PO Box 7272, SPEARWOOD WA 6163

A 25 Quarimor Rd, Bibra Lake WA 6163

T +618 9499 6500

F +61 8 9418 4160

E administrantequip.com.au

# INSPECTION CERTIFICATE

# 10 YEAR MAJOR INSPECTION

CLIENT CIVMEC

CONTACT MARK COCKSHOTT

INSPECTOR ANTHONY GROSSER

TEST LOCATION PERTH WORKSHOP

Plant Number Road Registration NA

Plant Registration WC19810 Serial Number 14015

Make Terex Franna Model MAC14

Year of Manufacture 1996

Axles 2 Maximum Load 14t

(Tonne)

Hours 12066 hrs Kilometres 10313 km

CraneSafe Report Number AC A 067128-2 Refer to attached report

Inspection Date July 16

This machine has completed its statutory inspection requirements and at the time of inspection was found to be in a safe working condition and complies with AS1418/ AS2550 major inspection guidelines and industry standards.

ANTHONY GROSSER: @9905569.

MACHINE IS CONSIDERED SAFE FOR USE AT THE TIME OF INSPECTION AND IS TO BE OPERATED AS PER THE MANUFACTURERS SPECIFICATIONS.









# WorkSafe Western Australia

Government of Western Australian

# EVIDENCE OF PLANT REGISTRATION

The item of the plant described below has been registered to:	Plant Registration Number	
CIVMEC CONSTRUCTION & ENG. PTY LTD	WC19810	
PO BOX 202 BELMONT WA 6104	Date Registered	
	14/11/96	
LOCATION OF PLANT		
ITINERANT FROM 85 ABERNETHY ROAD, B	ELMONT WA 6104	
DESCRIPTION OF PLANT		

CAPACITY

14 TONNES

FRANNA MOBILE CRANE MODEL MAC14

HAZARD LEVEL (as per AS3920.1)

N/A

and pursuant to Regulation 4.17 of the Occupational Safety and Health Regulations 1996, is subject to compliance with the following conditions:

LIFT AND CARRY LOADS AS PER MANUFACTURERS LOAD CHART MCC1087A MAXIMUM SAFE WORKING LOAD 14.0 TONNES, INCLUDING OPERATING INSTRUCTIONS PAGES 1 - 13

Issued by the WorkSafe Western Australia Commissioner

This Evidence shall be exhibited in a conspicuous place on or near the Plant.

This Registration remains valid until:

- There is a change to the plant such that it no longer complies with the registered design;
- For normally fixed plant, there is a change in location; or
- There is a change of ownership of the plant.

It is the responsibility of the owner to ensure that the plant is inspected and that documents / records are kept in accordance with the requirements of the Occupational Safety and Health Regulations 1996.

(cranelevida)



WESTCENTRE 1260 Hay Street West Perth.

Postal Address: P.O. Box 294 West Perth Western Australia 6872, Telephone: (09) 327 8777. Facsimile: (09) 321 8973. Internet Address: http://www.wt.com.au/soletyline Email Address: safety@wt.com.au TTY: (09) 327 8838



# Equipment Logistics & Consultancy Pty Ltd

Address: 5/84 Forsyth Street, O'Connor WA Postal Address: PO Box 4484, Myaree BC WA 6960 Phone: 0437518891 Email: robstelcinspect.com.au

# INSPECTION CERTIFICATE ANNUAL STATUTORY INSPECTION

CLIENT CIVMEC CONSTRUCTION & ENGINEERING

CONTACT MARK COCKSHOTT

INSPECTOR ROB CLARKE WA1073
TEST LOCATION MADDINGTON )W.A

MACHINE SPECIFIC DETAILS

Plant Number CR4 Road Registration 036-KKI

Plant Registration WC 19810 Serial Number MC14015

Make Franna Model 4WD MAC 14

Year of Manufacture 1996

Axles 2 Maximum Capacity (Kg) 14,000Kg

Hours 12066 Km 10313

Australian Design Compliance (If Applicable) Q15419

INSPECTION SPECIFIC DETAILS

Report Number ACa 067128-2 Refer to attached report

Inspection Date 14th July 2016

Re-inspection Date 13th July 2017

THIS MACHINE HAS COMPLETED ITS STATUTORY INSPECTION REQUIREMENTS AND AT THE TIME OF INSPECTION WAS FOUND TO BE IN A SAFE WORKING CONDITION AND COMPLIES WITH AS1418/ AS2550 REQUIREMENTS.

ROB CLARKE: SPEZZASCRE WA1073

SIGNED ON BEHALF OF EQUIPMENT LOGISTICS & CONSULTANCY PTY LTD

MACHINE IS CONSIDERED SAFE FOR USE AT THE TIME OF INSPECTION AND IS TO BE OPERATED AS PER THE MANUFACTURERS SPECIFICATIONS.

Lifting Equipment Inspections • Condition Reports • Incident Investigations • Fleet management systems • CraneSafe endorsed assessor