	A189572 TY 23/05/21	ENG NO WARRAN	1NL3PP 8 810,704	Tag #: Kilometers	TXF105	TTXF105	2017 DAF F
Total C	Employee		endor	V	Notes	Kilometers	Date
\$0.0		,			CARRY OUT 20,000KM SER SERVICE SHEET RS CHANGED ENGINE OIL AN COOLANT -42	614,726	5/10/2021
	Cost \$0.00					nance Performed E	<i>Mainter</i> SERVIC
	\$0.00	Total:					
\$0.0		,		E OIL AND	CARRY OUT 20,000KM SER SERVICE SHEET RS DID NOT CHANGE ENGINE FILTERS COOLANT -41 REPLACED RH BULLBAR L	635,859	25/11/2021
	Cost					nance Performed	
	\$0.00 \$0.00	Total:				E	SERVIC
40	ψ0.00	i otai.				050 705	20/01/2022
\$0.0		,		S AL ERS AND RESEALED	CARRIED OUT 20,000KM S PER SERVICES SHEET ZS REPLACED OIL AND FILTE COOLANT -42DEG REPLACED RADIATOR REPLACED FRONT SEAL A FRONT COVER REPLACED SUMP GASKET	658,765	20/01/2022
	Cost					nance Performed	Mainter
	\$0.00					E	SERVIC
	\$0.00	Total:					
\$0.0		,		JI	REPLACED MUFFLER	674,809	17/03/2022
	Cost \$0.00					nance Performed	<i>Mainter</i> REPAIR
	\$0.00	Total:					11217111
\$0.0		,		RS, JI, AL E OIL OR DEG BOLTS FRONT R/H	CARRIED OUT 20,000KM S PER SERVICE SHEET DID NOT CHANGE ENGINE FILTERS CHECKED COOLANT -42DE TIGHTENED TURNTABLE E TIGHTENED REAR AXLE FI LOWER AIR BAG NUT REPLACED REAR R/H SLA	679,725	31/03/2022
	Cost					Maintenance Performed	
	\$0.00 \$0.00	Total:				E	SERVIC
	40.00	i Otal.			CARRIED OUT 100000KM S	700,718	13/05/2022

16/10/2024 1:37:37 PM Page 1 of 3

COOLANT -44 DEG
REPLACED RH FRONT MUDGUARD AND
FLAP AL JS
REPLACED OIL FILL HOSE AL JS
REPLACED HEATER HOSES ZS JS
REPLACED RH FRONT BOTTOM
SHOCKER RUBBER ZS JS
TOOK TRANSMISSION OIL SAMPLE AL
DRIVERS FAULT #28220
ADJUSTED HEADLIGHTS AL

	ance Performed	d		Cos	_
SERVICE	=		То	\$0.00 tal: \$0.00	_
21/06/2022	721,149	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, JS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -44DEG REPLACED FRONT DRIVE S-CAM BUSHES REPLACED FRONT R/H DRIVE SLACK ADJUSTER	,		\$0.00
	ance Performed	d		Cos	
SERVICE	=		T -	\$0.00	_
			10	tal: \$0.00	
30/11/2022	743,435	CARRIED OUT 20,000KM SERVICE AS PER SHEET CHANGED ENGINE OIL AND FILTERS COOLANT@-43DEG REPLACED HIGH PRESSURE POWER STEERING HOSE REPLACED FRONT RH DRIVE LOWER SHOCKER RUBBER	,		\$0.00
Maintena	ance Performed	d		Cos	t
SERVICE				\$0.00	_
			То	tal: \$0.00	
21/02/2023	762,629	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS DID NOT CHANGE OIL OR FILTERS COOLANT@-42 DEG	,		\$0.00
Maintena	ance Performed	d		Cos	t
SERVICE				\$0.00	_
			То	tal: \$0.00	
12/04/2023	762,629	REPAIRED LH UPPER AND LOWER MIRROR GLASS AND OUTERS . USED OLD HOUSINGS	,		\$0.00
	ance Performed	d		Cos	
REPAIRS	5			\$0.00	_
			То	tal: \$0.00	
21/07/2023	783,263	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC CHANGED ENGINE OIL AND FILTERS COOLANT @-42DEG REPLACED BOTH ENGINE MOUNTS REPLACED BELTS REPLACED TURN TABLE JAWS REPLACED TURN TABLE SLIDES POWER STEERING HAD LEAK CHECK	,		\$0.00
16/10/2024 1	:37:37 PM				Page 2 of 3

FLUID NEXT SERVICE ===JOBS TO BE DONE=== COOLANT BUNG ABOVE OIL FILTER NEEDS REPLACING

nce Performed	1		Cost	
		Total:	\$0.00	
788,913	REPLACED TOP HEATER HOSE JS	,		\$0.00
	1		Cost	
		Total		
		i Otai.	ψ0.00	
804,189	CARRIED OUT 100,000KM SERVICE AS PER SHEET JS DW DID NOT CHANGE OIL OR FILTERS COOLANT @-35DEG REPLACED L/H BTAKE AND INDICATOR TAIL LIGHT REPLACED ADBLUE TANK FILLER CAP TIGHTEND ALL TURBO CLAPMS	,		\$0.00
nce Performed	1		Cost	
			\$0.00	
CHECK		Total	*	
		i Otal.	Ψ0.00	
809,663	GEARBOX STUCK IN MANUAL SHIFT REPLACED IGNITION BARREL BC REPLACED HOUSE BATTERIES BC REPLACED START BATTERIES BC REPLACED DRIVERS WINDOW PANEL SWITCH BC REPLACED RELAY AND FIXED CODES BR BC	,		\$0.00
	ce Performed		Cost	
		l otal:	\$0.00	
810,704	REPLACED FOLLOWING CLUTCH PARTS FRICTON DISK SPIGOT PRESSURE PLATE THROW OUT BEARING AND FORK CLEANED ENGINE BAY	,		\$0.00
			Cost	
			\$0.00	
		Total:	\$0.00	
	788,913 nce Performed 804,189 nce Performed CHECK 809,663	REPLACED TOP HEATER HOSE JS nce Performed 804,189 CARRIED OUT 100,000KM SERVICE AS PER SHEET JS DW DID NOT CHANGE OIL OR FILTERS COOLANT @-35DEG REPLACED L/H BTAKE AND INDICATOR TAIL LIGHT REPLACED ADBLUE TANK FILLER CAP TIGHTEND ALL TURBO CLAPMS nce Performed CHECK 809,663 GEARBOX STUCK IN MANUAL SHIFT REPLACED IGNITION BARREL BC REPLACED HOUSE BATTERIES BC REPLACED START BATTERIES BC REPLACED DRIVERS WINDOW PANEL SWITCH BC REPLACED RELAY AND FIXED CODES BR BC nce Performed 810,704 REPLACED FOLLOWING CLUTCH PARTS FRICTON DISK SPIGOT PRESSURE PLATE THROW OUT BEARING AND FORK CLEANED ENGINE BAY nce Performed	Total: 788,913 REPLACED TOP HEATER HOSE JS *** ** ** ** ** ** ** ** ** ** ** **	Total: \$0.00

16/10/2024 1:37:37 PM Page 3 of 3

\$0.00

Grand Total: