

All Maintenance

Filters applied:

Asset Maintenance Status	Closed
Maintenance Type	A Service, B Service, Brake Test, C Service, D Service, Hydro/Hatch & Vent
Asset	HV2261/039 Tristar Water Tanker YQ89GD
Asset Status	Active

Id	Created At	Type	Asset Id	Description	Sub-type	Maintenance Type	Asset Maintenance Status	Description	Notes
5646	11/08/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed		
5188	07/07/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service	
5187	07/07/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service	
5186	07/07/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service	
5185	07/07/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service	

3955	05/04/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	B Service	Closed	B Service	Removed ring feeder due to being seized in housing. Strip and inspect. Carry out overhaul of ringfeeder. Paint test & reinstall. Remove and replace all rocker box bushes and pins. Extra time taken to remove due to being seized in housings. Remove and replace 2x spring pack due to leafs being broken. Install with new hardware and tension to oem spec. Remove and replace Pos 6 brake booster due to leaking air. Checked lights, found 3 broken - 1 tail light, rear indicator and an amber clearance light on right side. Remove and replace lights, test all ok. Signage bracket broken. Repair bracket and paint. Install new marker and DNOT
3241	02/03/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service - 22/2	
2831	10/02/2022	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	A Service	Closed	A Service	
2361	06/12/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	Repair	Closed	check operation of rear lights	
2192	29/11/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	B Service	Closed	B Service	
1772	26/11/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	Repair	Closed	Travel to site, check operation of rear lights, no signal to lights get access to junction box signals ok, chase harness found corrosion in several spots chop out and repaired. Test all light function ok	Travel to site, check operation of rear lights, no signal to lights get access to junction box signals ok, chase harness found corrosion in several spots chop out and repaired. Test all light function ok

1708	22/11/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	B Service	Closed	B Service as per service sheet, Adjusted wheel bearings POS 1,2,4 and 1 clearance, 1 indicator out ordered	B Service as per service sheet, Adjusted wheel bearings POS 1,2,4 and 1 clearance, 1 indicator out ordered
1163	01/10/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	Brake Test	Closed	Brake Test	
1162	01/10/2021	Heavy Vehicles	HV2261/039	Tristar Water Tanker	Water Tanker	D Service	Closed		