

LINE	PART NUMBER	DESCRIPTION	QUANTITIES		BIN LOC	NETT PRICE	GST VALUE	EXT PRICE
			ORD	SUP				
1	RM2S1	REAR MARKER L/H STICKER	1	1	GON-2	18.42	1.84	18.42
2	RM1S1	REAR MARKER R/H STICKER	1	1	GON-2	18.42	1.84	18.42
3	FR	INWARD FREIGHT	0	0		0.00	0.00	0.00

Fault Information

Equipment Type: Vehicle

Fault Type: Tipper Body

Fault Level: Minor

Odometer: 460870

Comment:

Tailgate air ram has an air leak.

Registration: XO32UO

Id: XT105

Date: 05:34, 02/07/2024

Fault History

Renew the registration on or before the due date.
It is an offence to drive an unregistered vehicle.

Registration Notice

21
SEP

UD GKB4D 0415287170
X032U0 26000 70000
JNBGWB4DA00H00976 22-09-2023
Config. SP3 Cond. G096

Expiry Date: 21-09-2024

VIN: JNBGWB4DA00H00976
Plate: X032U0

- **Important:** If you change the registration term, an inspection may or may not be required. Contact Service NSW on 13 22 13, or visit nsw.gov.au/topics/vehicle-registration/renew/short-term for more information.
- Compulsory Third Party (CTP) insurance policies for six month registration on light vehicles have a use-by date of 21 days after the registration expiry date.
- **Hearing or speech impaired?** Call us on the National Relay Service: TTY users phone 133 677 then ask for 13 22 13. Speak and Listen users phone 1300 555 727 then ask for 13 22 13.



Transport for NSW Certificate of Registration

Record the Transport for NSW receipt number here if required.

Rec: 0415287170 \$7,860.20
Payment Date: 22-09-2023

This certificate of registration identifies the registered operator of this vehicle, it is not proof of vehicle ownership. The garage address is shown below.

Payment Details

Plate Number	Expiry Date	Use
X032U0	21-09-2024	B BUSG

REGISTRATION FEE	\$70.00
ROADUSE CHGE(SP3)	\$4,572.00
NHVR REGULATORY CHGE	\$401.00
HVIS INSPECTION FEE	\$217.27
GST ON HVIS INSPECTI	\$21.73
HVIS INSPECTION FEE	\$217.27
GST ON HVIS INSPECTI	\$21.73
NATIONAL HEAVY VEHIC	\$29.20
STAMP DUTY	\$2,310.00
TOTAL	\$7,860.20

Cond. G096
SHORT COMB P/MOVER-HAUL ONE TRAILER ONLY

Insurer : 36
Insurer A/c: 103560855

Year	Make	Model	Variant	Shape	Engine Capacity	VIN/Chassis Number
2014	UD	GKB4D	GKB4D	PMV	13000.0	JNBGWB4DA00H00976
Tare Weight	GVM	GCM	Seating Capacity	Engine Number	Axle Code	
8420	26000	70000	2	GE13340290D	R14	

VCC: Modified as per Compliance Cert. 1100062300369MPv01

Conditions and Information:

USAGE: BUSINESS - GENERAL.
SUBJECT TO CONDITIONS: HR, HV, 87

QTY/ UNITS	ITEM NO.	DESCRIPTION	UNIT	EX AMOUNT	CODE
	1	Work completed 21/08/24 Repairs to UD tipper truck XO32UO 465989 km Tipper controls not working, and body not going up and down, and tailgate not opening and closing. Found that ECU control module had failed and needed replacing. Also repaired wiring.			
1	Parts	Complete tipper control module		\$1,342.00	GST
9	LabC	Labour Hours		\$900.00	GST

QTY/ UNITS	ITEM NO.	DESCRIPTION	UNIT	EX AMOUNT	CODE
40 2	1 Mileage LabC	Work completed 12/08/24 Repairs to UD tip truck XO32UO 465781 km On-site at Clayton yard for tarp not closing - found that heavy duty fuse needed to be reset. Test Ok km Travel to site Labour Hours		\$30.00 \$200.00	GST GST

QTY/ UNITS	ITEM NO.	DESCRIPTION	UNIT	EX AMOUNT	CODE
	1	Work completed 01/10/24 Repairs to UD tipper XO32UO (new Vic rego XW47SD) 471467 km Complete roadworthy repairs for registration transfer to Vic. Replace windscreen, welding repairs to body. Replace fuse box and battery cover. Suspension repairs. Top up hydraulic oil. Replace rear mud flaps and retro signs.			
1	Parts	Replacement windscreen		\$740.00	GST
1	Misc	Welding repairs		\$280.00	GST
1	Parts	Fuse box and battery cover		\$297.00	GST
1	Parts	Battery clamps		\$68.00	GST
1	Parts	Mudflaps and retro signs		\$242.00	GST
1	Parts	Suspension bushes		\$236.00	GST
40	Hyd	Litres Hydraulic Oil	Litre	\$320.00	GST
1	Misc	Roadworthy fee		\$900.00	GST
1	Misc	Vicroads registration fee		\$2,243.50	GST
19	LabC	Labour Hours		\$1,900.00	GST

Description	Quantity	Unit Price	GST	Amount AUD
Supply only pull tarp 26.3.24 ORDER NO:XT105	1.00	0.00		0.00
Pull tarp in black mesh 1735 wide inc ring. 5.2M tarp at max width. Pull tube to suit gates 1850 wide. Eyelets 500mm apart both sides.	1.00	1,150.00	10%	1,150.00
Rope cleats small	4.00	8.50	10%	34.00
			Subtotal	1,184.00
			TOTAL GST 10%	118.40
			TOTAL AUD	1,302.40

Product	Description	Quantity	Price Excl.
CARRY OUT MINOR SERVICE AS REQUIRED			
01	CARRY OUT MINOR SERVICE AS REQUIRED ***** RESET VEHICLE SERVICE INTERVAL DISPLAY *****		925.00
VC	V.C.A.D.'s CONNECTION FEE	1	50.00
CC	CONSUMABLES	1	88.80
VDS4	VGA CAL85121795 ENGINE OIL	33	291.06
UD99999FK025	KIT FILTER BASIC CWB-GE 13LITRE TD UD Carried out 'UD' Minor Service	1	247.32
		Sub Total:	<u>1,602.18</u>
CHECK ADVISE GEARBOX FAULTS			
	***** Road tested and confirmed issues. Truck needs to go to heavy auto shop for further diagnosis/checks		
		Sub Total:	<u>0.00</u>
CHECK ADVISE RADIO SCREEN N/W			
	***** Checked and confirmed screen barely readable. Requires new screen		
		Sub Total:	<u>0.00</u>
REFIT SEALS TO DOORS			
74	REFIT SEALS TO DOORS ***** Cleaned surfaces of old sealant/adhesive. Resecured seals to door		185.00
		Sub Total:	<u>185.00</u>

Parts: \$247.32

Labour: \$1,110.00

Others: \$429.86

Sub Total: \$ 1,787.18

Total GST: \$ 178.72

Rounding: 0.00

INVOICE TOTAL 1,965.90

