Service History

STOCK NO: D524 VEHICLE: 2019 Komatsu HM300-5 Dump Truck

SERIAL NO: Purchase Hours: 7956

<u>DATE</u>	<u>DESCRIPTION</u>
	Lukeash Transport - pick up truck from Sydney & deliver to yard
12/11/2021	Purchase copy of operators manual
12/11/2021	GM Risk Assessment - risk assessment
3/12/2021	Labour-Graeme- take off stickers
3/12/2021	Labour-Stan- clean up & remove stickers
6/12/2021	Labour-Graeme - wash exterior
4/02/2022	Labour-Graeme- sanding parts at Patt Trak
7/02/2022	Body Shop - yellow paint - 20 litres
11/02/2022	Labour-Graeme - parts run to Winchelsea
15/02/2022	Haymes Paint Shop - grey primer
10/03/2022	Enzed - hose assembly made to order
10/03/2022	Patt Trak - complete 500 hr service @ 7963 hrs as per checklist
	replace engine oil - 40 litres
	replace fuel filter
	top up transmission oil - 5 litres
	top up diff oil
	check tyre pressures - all 80 PSI
	check/adjsut park brakes - 1400 RPM
	replace seat belt
	drain & refill ad blue as it had diesel in it
	fill auto greaser with grease
	fit fire extinguisher
	blow out intercooler
	fit seat cover
	M&R Oil - various oil
	Komatsu - filters
10/03/2022	Chris Reilly - blast, prime & top coat - chassis grey - tipper yellow - rear
	wheels yellow
16/03/2022	Maxiparts - fire extinguisher
17/03/2022	Signs on the move - supply & fit "KOMATSU" stickers to body
23/03/2022	Labour-Stan- check over @ 7965 hrs as per checklist
	check air con - 7 deg
	check/adjust park brake 1400 RPM
	make sure reverse camera is clear
	fit emergency hammer
	fit brake pedal rubber
23/03/2022	Labour - Paul - install & connect new UHF radio & aerial - repair electrical
	junction behind battery box - check auto greaser
	Maxiparts - UHF radio
	Komatsu - brake pedal rubber
23/03/2022	Labour-Ben- fit hi vis tape - fit nut indicators - fit safety stickes - fit Drews
	stickers -

23/03/2022				
	Labour-Jye- filled auto greaser - fitted seat cover - assist with removal &			
	fitting of intercooler cover - assist with drain & refill ad blue			
23/03/2022	William Adams - GP seat belt			
25/03/2022	Komatsu - seat cover			
25/03/2022	Maxiparts - emergency hammer			
7/04/2022	Labour-Alan- wash exterior			
11/04/2022				
	Patt Trak complete following repairs from 9/12/21 to 11/3/22 - panel			
	repair, remove & straighten - remove battery boc lid - drill holes in			
	bottom and clean - remove handrails and step panesl - straighten front			
	grille - modify, weld and strengthen cabin step - sand panels & handrails			
	for paint - straighten & weld RH cabin steps - remove body and straighten			
	headboard - paint & panel repairs - jack up & remove rear wheels - get			
	ready for sand blasting & paint - remove battery box, burpes & handrails -			
	sandblast rear - paint with primer - paint 1/2 topcoat - paint wheels and			
	nuts - sand & paint lift cyliners - fit wheels - sandblast & paint rear of truck			
	- sandblast & paint body, muffler, handrails & paint handrails - sanded			
	panels - cleaned windows & mirrors - bogged hole on battery box - blast			
	paint RH front under guard, front bumper, side wheel etc - weld			
	headboard - blast LH inner guard - remove wheel - clean & paint - refit			
	exhaust & paint handrails - paint inner LH wheel hub - fit wheels - move			
	body out for blast & paint - paint underbody and assembly - wash & clean - final check			
16/05/2022	Labour-Stan- complete checkover @ 8035 hrs as per checklist			
10/03/2022	park brake adjusted 1500 RPM			
	repaired fire extinguisher bracket stay			
	check air con - 7 deg			
16/05/2022	Labour-Michael - clean cabin & wash			
	Labour - Stan - check over @ 8131.9 hrs as per checklist			
, , , , ,	blow out cab air cleaner			
	seat belt dated Feb 18			
	check air con - 8 deg & heater 37 deg			
	check park brake 1500 RPM			
	refit battery hold down			
	clean trans oil sight glass tube			
	set graco grease pump			
	Labour Paul - checklist			
29/06/2022	Labour-Paul- top up grease tank - grease front LHS & RHS drive shafts -			
	blow out cab - clean dash			
12/07/2022	Labour-Paul - travel to site & check faults on machine @ 8198 hrs			
	check transmission oil			
	check engine oil			
	check & replace hydraulic breather cap			
	check hydraulic oil - oil leak at hydraulic cap - due to being overfull			
	check cab air cleaner			
	check & tighten wheel nuts			
	remove & replace park brake switch			
	lubricate & adjust bonnet catch			

C	check fire system fault - no fault at time
19/07/2022 E	ETA Mechancial - travel to site - adjust handbrake to spec
4/08/2022 L	abour-Michael - clean cabin & wash
11/08/2022 L	abour-Zac- check over @ 8233 hrs as per checklist
c	check air con min 6 deg - max 28 deg
f	it clip to steering lock pin
11/08/2022 L	abour-Baz - tighten battery box latch catch
26/08/2022 N	Maxiparts - ad blue
21/09/2022 E	Enzed - hose assembly made to order
21/09/2022 P	Patt Trak - replace 2 hoses in articulated area of truck - drive to Enzed to
g	get item made
28/09/2022 L	abour-Alan- washed & detailed
4/11/2022 L	abour-Paul - completed 500 hr service @ 8452 hrs as per checklist
r	replace engine oil & filters - 35 litres
t	op up transmission oil - 4 litres
С	checked air con vent temp 15 deg - add 288 grams R134A
r	e check air con - min 4 deg - max 31 deg
a	add leak guard
С	check tyre pressures - all 70 PSI
r	replaced seat belt
r	eplaced missing bolts in guard under exhaust at rear of cabin
N	M&R Oil - various oil
7/11/2022	
N	Maxiparts - fuel water seperator, fuel water bowl seperator, fuel filter
11/11/2022	
	GPER - travel to site - 8478.9 hrs - remove covers around DEF - found
lt	proken exhaust clamp - call Komatsu to make sure they have parts - travel
	to Komatsu get parts and travel back to site - remove more panels around
	exhaust and fit new clamp - refit all panels - test machine - all good
	Komatsu - clamp and gasket
	GM Risk Assessment - risk assessment
	Komatsu - v-belt
	Patt Trak - check over machine @ 8864 hrs as per checklist
	plow out air cleaners
t	op up engine oil - 5 litres
t	op up transmission oil - 3 litres
	check air con - 5 deg
	replaced grease line on rear strut
	Komatsu - lamp
	abour-Daniel - exterior clean & detail interior
	abour - Corey - complete 1000 hour service @ 8892 hrs as per list
r	replace engine oil & filters - 35 litres
	replace fuel filter
	check air con - min 6 deg - max 30 deg
	check park brake 1500 RPM
	M&R Oil - various oil
	Komatsu - filters as required
l 18/07/2023 L	abour - Corey - complete check over @ 8934 hrs as per checklist
С	check air con 7 deg min - 32 deg max Dark brake adjusted 1400 RPM

fit new fire extinguisher fit new seat belt install new door switch Patchy Auto Elec - wire in new seat belt catch Maxiparts - fire extinguishe and bag 18/07/2023 Labour-Daniel - exterior clean & detail interior Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM replaced LH side indicator globe		refilled auto greaser
install new door switch Patchy Auto Elec - wire in new seat belt catch Maxiparts - fire extinguishe and bag 18/07/2023 Labour-Daniel - exterior clean & detail interior Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM		fit new fire extinguisher
Patchy Auto Elec - wire in new seat belt catch Maxiparts - fire extinguishe and bag 18/07/2023 Labour-Daniel - exterior clean & detail interior Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM		fit new seat belt
Maxiparts - fire extinguishe and bag 18/07/2023 Labour-Daniel - exterior clean & detail interior 18/07/2023 Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM		install new door switch
18/07/2023 Labour-Daniel - exterior clean & detail interior 18/07/2023 Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM		Patchy Auto Elec - wire in new seat belt catch
Patt trak- install GPS tracker behind seat in fuse panel and diagnose komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM		Maxiparts - fire extinguishe and bag
komtrax system - found fault with aerial 19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	18/07/2023	Labour-Daniel - exterior clean & detail interior
19/07/2023 Labour-Daniel - finished detailing & helped Corey fit clamps 20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	10/07/2022	Patt trak- install GPS tracker behind seat in fuse panel and diagnose
20/07/2023 Komatsu - antenna 31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	10/0//2023	komtrax system - found fault with aerial
31/07/2023 Labour-Corey - complete check over @ 8966 hrs as per checklist seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	19/07/2023	Labour-Daniel - finished detailing & helped Corey fit clamps
seat belt dated 7/23 check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	20/07/2023	Komatsu - antenna
check air con - 6 deg min - 30 deg max adjust park brake - 1500 RPM	31/07/2023	Labour-Corey - complete check over @ 8966 hrs as per checklist
adjust park brake - 1500 RPM		seat belt dated 7/23
		check air con - 6 deg min - 30 deg max
replaced LH side indicator globe		adjust park brake - 1500 RPM
		replaced LH side indicator globe