

Work Order History Report

26-May-2023

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
CB EME SCP 637E#7		ClearyBros. Earthmoving Workshop Scraper 637E #7						
	5517	Blow injector line rear engine	19/05/2017	25310	Hours	0.0	0.0	\$0.00
	73	250 Hour Earthmoving service	19/05/2017	25333	Hours	0.0	0.0	\$0.00
	11399	hyd oil leak.Steering hose blown under cab.replace steering hose & add oil - test ok.	10/02/2018	25440	Hours	0.0	6.5	\$0.00
	11432	air cond not cold, check system, compressor not engaging check wiring found broke wire to compressor positive, repaired wiring at compressor thermostat and pressure switch, clutch engaged check pressures found to be low 80psi on high side recover gas, pressure test, found both charge ports leaking replaced valves, replace receiver dryer, pressure test again tested fine at 350psi, vac down, charge system test.	13/02/2018	25455	Hours	0.0	0.0	\$0.00
	11680	LH front brake sticking.Replace booster, grease all brakes.	20/02/2018	25494	Hours	0.0	0.0	\$0.00
	12703	seat broken Replace washers on seat shock (remove 637#8) check oil leaks< replace hoses on grease unit,weld up center pin on seat	05/03/2018	25556	Hours	0.0	0.0	\$0.00
	12237	500 Hour Earthmoving Service	19/03/2018	25622	Hours	0.0	0.0	\$0.00
	11977	Blown RHR tyrePremiums sent to job	12/04/2018	25625	Hours	0.0	0.0	\$0.00
	16219	Remove broken bolts and fit apron to trunnion	24/05/2018	25644	Hours	0.0	0.0	\$0.00
	13666	Blown hose assist pirtek to r&r hose ass	31/05/2018	25675	Hours	0.0	0.0	\$0.00
	11534	Needs routers / r&r routers and plow bolts	05/06/2018	25699	Hours	0.0	0.0	\$0.00
	14130	Diff lock not working no reverse alarm and horn not workingReplaced blown fuse for diff lock Repair broken wire for rev alarmClean debris from inside horn	22/06/2018		Hours	0.0	0.0	\$0.00
	14079	leaking apron cylinderRnR apron cylinder Wash area down	25/06/2018	25736	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		install new seals on pipes and hoses tested ok						
	16053	No4 piston valve failure piston meltedRemove power pack and refit X637#8 power pack with trans, fuel pump, turbo and harness reused from 637#7Drain and refill trans and engine oil, fill coolant level Turn cutting edges and refit rebuilt air dryer	16/08/2018	25769	Hours	0.0	0.0	\$0.00
	15968	water leak	24/08/2018		Hours	0.0	0.0	\$0.00
	15833	Front engine oil leakReplaced blown hose under cab	27/08/2018		Hours	0.0	0.0	\$0.00
	14104	water in rear engineRemoved rear engine Removed sump and pressurized to see were it was leaking into the motor was leaking through water pump Fitted OR water pump Replaced turbo gasket on front motor and both turbo pipes on RHS6 New injectors fitted.Replaced 2 hoses on tranyFixed door latch Replaced LHS rear booster Replaced rear motor governer hoseFitted 2 new unis Fitted new fire extinguisher bracket Fitted new turbo to rear motor OR turboGot new pipe welded in were it was rusted through on the 3 pipes in the hitch closest to the bowl Adjusted all brakes	13/09/2018		Hours	0.0	0.0	\$0.00
	16499	Bad fuel leak Removed and fitted new injector line on rear motor cylinder 3	14/09/2018	25827	Hours	0.0	0.0	\$0.00
	16471	250 Hour Earthmoving service	21/09/2018	25844	Hours	0.0	0.0	\$0.00
	16907	RnR door cab strap brace RnR broken door control arm	27/09/2018	25844	Hours	0.0	0.0	\$0.00
	16159	Blown hoseCalled pirtek	02/10/2018		Hours	0.0	0.0	\$0.00
	13727	stuck in gear rear motorFound broken wire in harness up at the rear computer and repaired wire tested OK	11/10/2018		Hours	0.0	0.0	\$0.00
	20052	Prep machine for bypassFit 2x new extinguisher Turn full set of cutting edges Wireless reverse camera fitted RnR seals on steering cylinder	13/03/2019	25853	Hours	0.0	0.0	\$0.00
	20061	No reverse alarm Replace blown fuse Locate and repair short circuit Locate and repair open circuit	18/03/2019	25855	Hours	0.0	0.0	\$0.00
	20309	Rear motor blowing major amounts of smoke and looks like it's on fire.	02/04/2019		Hours	0.0	0.0	\$0.00
	20534	Rear motor over heating Washed rear radiator	08/04/2019		Hours	0.0	0.0	\$0.00
	21599	oil leak dug clay from guards and replaced injector lineCameron Buck	02/05/2019		Hours	0.0	0.0	\$0.00
	21179	Oil leak under front belly guardoil feed for air compressor	07/05/2019	25987	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		blown linefit hose assemblyrefill engine oil to correct levelBrad Wise					
	21505	blown hose Pirtek made and fitted hose	18/05/2019	Hours	0.0	0.0	\$0.00
	25076	Tyre repair pos1&2Premium tyresSee attach	30/05/2019	26098 Hours	0.0	0.0	\$0.00
	22296	front motor wont startbatteries failed due to banging on battery box lid,dig out battery box & repair battery bracketfit new batteries & start ok Glen Windle	14/06/2019	26137 Hours	0.0	0.0	\$0.00
	22263	wont start SEE WORK ORDER 22296	14/06/2019	Hours	0.0	0.0	\$0.00
	21319	500 Hour Earthmoving Service	22/06/2019	26164 Hours	0.0	0.0	\$0.00
	22675	loosing coolant from radiator pressure relief check cooling system,small bubbles in rad,top up coolant ,advise operator to monitor temp,refer pkwsGlen Windle	01/07/2019	26168 Hours	0.0	0.0	\$0.00
	23126	Horn u/sr&r cat horn ass. test okBrad Wise	02/07/2019	26174 Hours	0.0	0.0	\$0.00
	22953	Needs rear blinkers brake lights	10/07/2019	Hours	0.0	0.0	\$0.00
	23162	oil leakdropped belly guards ,tightened all bolts that hold torque converter in as they were looseCameron Buck	12/07/2019	Hours	0.0	0.0	\$0.00
	24157	Start front motorJump started to move machine	29/08/2019	Hours	0.0	0.0	\$0.00
	25941	Check over machine for use A/park bypass,leaksR&R bearing pin ass. for bowl lift cylinderR&R oring seals on supp steer hose for steering filter/screenR&R RHS pin in bowl lift cylinderR&R oring on trans pipe over front trans,Repair steering screen mounting bracketR&R 1x sealed beam head light,R&R seals on rear engine,fit fuel ratio control valveR&R narve LED tail lights on rear,R&R LHR brake booster,adjust brakesR&R LHSmanifold to turbo exhaust elbows,clamps,R&R rear brake relay control valveR&R blown trans cooler hose on rear transB Wise	15/10/2019	26184 Hours	0.0	0.0	\$0.00
	26125	Front diff lock not workingRemove diff,trans ass.,air line to diff lock blown,R&R air line (internal) axle tube seals,planetary seals;Install trans seal,refit diff,trans ass. test diff lock & gears okB Wise	26/10/2019	26184 Hours	0.0	0.0	\$0.00
	26437	Seat belt u/sRemoved and replaced seat belt with a new oneR Latham	05/11/2019	26198 Hours	0.0	0.0	\$0.00
	26487	Air cond recharge see air cond sheet #1871B Patrick	08/11/2019	26221 Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	26741	Tyre repair pos4Premium tyres se attach	12/11/2019	26248	Hours	0.0	0.0	\$0.00
	26632	Rattle in front engine pressuring water ,routers wornRemove all injectors,turn engine over No8 cylinder full of waterRemove & replace head gasket on RHS bank,repair muffler mount bracket,R&R engine oil,R&R rear engine governor shaft seal,plate & throttle diaphragm, R&R 2x routers & boltsB Wise	20/11/2019	26295	Hours	0.0	0.0	\$0.00
	26757	UHF not workingReplaced Ariel fitting into UHFC Buck	25/11/2019		Hours	0.0	0.0	\$0.00
	27497	Tyre replacement pos 3&4Premiums	27/11/2019		Hours	0.0	0.0	\$0.00
	26969	Blown hose/ fuel lineInstall hose(supplied),install #2 fuel line (spare) on rear engineB Patrick	27/11/2019	26328	Hours	0.0	0.0	\$0.00
	26951	250 Hour Earthmoving service	07/12/2019	26359	Hours	0.0	0.0	\$0.00
	27235	Flat front left tyrePumped tyre up front leftC Buck	16/12/2019		Hours	0.0	0.0	\$0.00
	28040	rear engine oil leak Removed air fuel ratio from fuel pump and time serted mounting bolts,replaced oringsR Latham	24/01/2020		Hours	0.0	0.0	\$0.00
	28777	Rear turbo U/SReplaced with Cat O-R turbo, replaced seals and gaskets.	30/01/2020	26500	Hours	0.0	0.0	\$0.00
	29072	Fan bearingsChange fan bearings on rear motor	15/02/2020		Hours	0.0	0.0	\$0.00
	28399	seat Shock leaking on the floor, rear engine fan wobbling,Hook bolts need tighteningOrdered new cylinder for seat.Ordered new fan Bearings.Changed and tightened bolts on hook	20/02/2020		Hours	0.0	0.0	\$0.00
	29816	Rear engine KnockingCheck filter for metalPut away parts to allow use of frontReeve	16/03/2020		Hours	0.0	0.0	\$0.00
	30023	Linkage "gone limp"Remove missing nut off 637#8and installed nut on to 637#7Reeve	21/03/2020	26609	Hours	0.0	0.0	\$0.00
	29865	500 Hour Earthmoving Service	20/04/2020	26679	Hours	0.0	0.0	\$0.00
	31722	check over machineMore to do-carried over,replaced rear power pack o-ring for yoke,replaced leaking trans filter o-ringreplaced all lights with LEDs,fitted LED to rearR Farquhar	12/05/2020	26679	Hours	0.0	0.0	\$0.00
	32246	FRS tyre needs air and leaks oil Pumped up RHS front tyre and changed o-ring on hose in hitch areaR Latham	25/05/2020		Hours	0.0	0.0	\$0.00
	32660	Brake booster locked on Replaced left rear brake boosterC Buck	04/06/2020		Hours	0.0	0.0	\$0.00
	32604	2000 Hour earthmoving service	11/06/2020	26679	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	33490	Seat inspection,brakes locking onTested and could not reproduce fault,checked operation of booster-all working correctly under foot and park brakemay have had low air,checked seat for report-okReeve F	23/06/2020	26692	Hours	0.0	0.0	\$0.00
	33561	No hornReplaced air horn with electric hornC Buck	24/06/2020	26697	Hours	0.0	0.0	\$0.00
	33850	Seat tornReplaced back and base seat cushionsReeve F	25/06/2020	26703	Hours	0.0	0.0	\$0.00
	33856	Turbo line on power packChanged turbo oil pipe to a braided hose,new filler capC Buck	30/06/2020		Hours	0.0	0.0	\$0.00
	35259	Check hour meterCheck operation of hour meters,working OKPump up RHF tyreB Wise	13/08/2020	26716	Hours	0.0	0.0	\$0.00
	36137	Loosing air pressureReplace broken fitting on front L/H brake booster & test OKG Windle	07/09/2020		Hours	0.0	0.0	\$0.00
	36072	Rear bail hook and stepsWeld in rear bar finish 8/9/20Swap steps over so driver has access,need to fab bottom step for L/H sideS Rodgers	08/09/2020	26733	Hours	0.0	0.0	\$0.00
	37814	Pump up pos 2 tyrePremium tyre's(see attach)	16/10/2020		Hours	0.0	0.0	\$0.00
	40444	Tyre off bead Could not pump upPremium tyre's(see attach)	21/01/2021		Hours	0.0	0.0	\$0.00
	41283	Tyre repairs pos#2Premium tyres (see attachment)	25/02/2021		Hours	0.0	0.0	\$0.00
	43107	Defect repairs Reseal ejector cylinder, apron hoses R&R ejector frame rollers and all oil leaks repaired BPM (see all attachments)	31/03/2021		Hours	0.0	0.0	\$0.00
	36389	Needs edges, routers, also push pad broken offTidy up machine ready for work all repairs carried out at PKWS (see attachment)	12/04/2021	26761	Hours	0.0	0.0	\$0.00
	43350	No A/C workingTest a/c diagnose compressor faulty, R&R compressor and drier, pressure test vacuum and regasBAE (see attachment)	15/04/2021		Hours	0.0	0.0	\$0.00
	42859	No A/C fans, rear trans playing upCheck rear trans oil, sink light, upshift , downshift-no faults found @ time of inspectionA/C fan breaker tripped 1 x fan motor shorted to ground, needs 1x fan motor parts orderedB wise	21/04/2021		Hours	0.0	0.0	\$0.00
	42838	Transmission problemRemove guards around harness visually inspect plugs etc, test drive for 2hrs then had issue on front controller with position sensorRemove sensor check-ok, remove all plugs and clean out and put back test-ok no	23/04/2021	26781	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		issuesBen P						
	43189	Oil leak Replaced blown hoseC Buck	28/04/2021	26795	Hours	0.0	0.0	\$0.00
	43111	Rear engine getting hotBlow out radiator(note no warning lights working on front or rear engine)Reeve F	30/04/2021		Hours	0.0	0.0	\$0.00
	43226	Water in engine oil, gauges broken oil leaksremove sump-water in #7 LH back cylinder, R&R head gasket, R&R sump gasketR&R starter motor, gasket and boltsB WiseReplaced head gasket left side, R&R head, removed sump and resealedC Buck	11/05/2021	26822	Hours	0.0	0.0	\$0.00
	43799	Air leakReplaced brake valve for pedal, rear fan beltsC Buck	21/05/2021		Hours	0.0	0.0	\$0.00
	43803	Trans gauge not workingRear engine fault light not workingchecked out plugs and cleaned out sinc box working ok nowReeve F	26/05/2021	26863	Hours	0.0	0.0	\$0.00
	43926	Rear motor not pairing upFixed broken wireC Buck	27/05/2021		Hours	0.0	0.0	\$0.00
	44140	Coolant hose on rear motorReplaced hose and gasket, filled with coolant-okReeve F	28/05/2021		Hours	0.0	0.0	\$0.00
	43778	250 Hour Earthmoving service	02/06/2021	26897	Hours	0.0	0.0	\$0.00
	44219	Coolant leakMoved hose on rear engine up and added extra clamps: may be weeping from oil coolerReeve F	02/06/2021		Hours	0.0	0.0	\$0.00
	44914	Fit 2 X new tyre's on Pos 1&2Premium tyre's (see attachment)	02/06/2021	26900	Hours	0.0	0.0	\$0.00
	44366	blown hoseReplaced blown suction hose, topped up oil, washed machine as oil all over machine windows etc, test-okReeve F	08/06/2021	26913	Hours	0.0	0.0	\$0.00
	44788	Grease line Replaced broken grease lineReeve F	09/06/2021	26917	Hours	0.0	0.0	\$0.00
	44789	Hydraulic oil lowOil was low due to previous breakdown topped up oilReeve F	10/06/2021	26925	Hours	0.0	0.0	\$0.00
	44771	Replaced fan top air box plateReeve F	18/06/2021	26930	Hours	0.0	0.0	\$0.00
	45525	Rear trans gauge not working.Diagnose & rectify elec. problem with rear trans gauge. Replace wiring & bypass damaged plug.	24/06/2021	26930	Hours	0.0	0.0	\$0.00
	45486	General repairsRepaired grease line leak & desiezed pin & greased .Capped off unused, leaking grease line. tightened up loose clamps on hyd. suction line. Replaced rear eng. top rad. hose clamp. Replaced pump top O ring.	28/06/2021	26930	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost	
	45569	Rear wiper not working.Checked power & earth to rear wiper & speeds Ok. Found rear wiper arms loose. tightened & tested Ok	09/07/2021	26931	Hours	0.0	0.0	\$0.00	
	45542	Pre-start faults.Replaced rear eng. flow sw. EMS fault light for rear on order. Replaced wiring to rear eng. trans. gauge sensor. Checked all gauges in cab-Ok	15/07/2021		Hours	0.0	0.0	\$0.00	
	50757	A/C dumped gasPressure tested and found leak from condenser and hose to compressorsent hose to be matched by pirtekReeve F	01/12/2021	26932	Hours	0.0	0.0	\$0.00	
	52009	Fire extinguisher replaced	11/02/2022		Hours	0.0	0.0	\$0.00	
	54317	Inspection to go to site	29/04/2022	26934	Hours	0.0	0.0	\$0.00	
	54255	Trans oil topped upFlow sensor ordered	10/05/2022	26954	Hours	0.0	0.0	\$0.00	
	54806	Seat shock assembly repaired	19/05/2022	26970	Hours	0.0	0.0	\$0.00	
	54854	Built up air to release park brake = Inspected/OK	26/05/2022	26982	Hours	0.0	0.0	\$0.00	
	44194	Gauge and light wiring repaired	10/06/2022		Hours	0.0	0.0	\$0.00	
	54834	Bad oil leak # Pirtek replaced hose	27/06/2022		Hours	0.0	0.0	\$0.00	
No of W/O for 637E#7 :			101		Asset Total:	637E#7	0.0	6.5	\$0.00
No of W/O for CB :			101		Parent Total:	CB	0.0	6.5	\$0.00
Grand Total			101			0.0	6.5	\$0.00	