

**RECEIVED**

19/10/23

1/6 Raceway Place
Eastern Creek NSW 2766
1300 292 646
www.outrite.com.au
ABN: 59 632 942 584

TAX INVOICE**Invoice No: 17730**

7 - 9 George Place Artarmon NSW 2064		Site: 7 - 9 George Place Artarmon NSW 2064	
Job No: 2678 Account No: E008		Invoice Date: 19-Oct-23	
		Order No: EAU-PO117421	
Details	Stock No	Qty	Unit Price per Cost

2.5 forklift	EAU-EM41419			
Labour Charge		3	120.00 hour	\$360.00
Checked over unit, Found metal shavings in hydraulic filter from hydraulic pump letting go. Replaced filter and checked system found shavings in valve block , needs to be replaced. Ordered new valve block and fitted. Flushed hydraulic oil and system. Tested all ok all working fine. Replaced broken mirror. Full function test all ok.				
Valve assembly oil control valve		1	5,000.00	\$5,000.00

GST No. 59 632 942 584

Payment Terms: Strictly 30 days from end of month
Account Name - Outrite Hire and Sales
BSB - 082-330 Acc Number - 85-228-3813
Please send remittance advice to:
Accounts@outrite.com.au

Sub-Total	\$5,360.00
GST at 10%	\$536.00
TOTAL	\$5,896.00



1/6 Raceway Place
Eastern Creek NSW 2766
1300 292 646
www.outrite.com.au
ABN: 59 632 942 584

Invoice Date: 26-May-2023

Invoice No: 14836

Note: 5641

TAX INVOICE

Customer:

Customer name 7 - 9 George Place
Artarmon
NSW 2064

Site: 7-9 George Place
Artarmon
NSW 2064

Account No: E008

Order No: EAU-PO115085

<u>Equipment</u>	<u>Stock No</u>	<u>Qty</u>	<u>List Price per</u>	<u>Amount</u>
Parts to Repair Forklift		1	\$1,594.82	\$1,594.82
Labour		1	\$120.00	\$120.00
Pump for Toyota Forklift		1	\$995.00	\$995.00

Major Service.

Checked over forklift , mast chains and rollers worn and need to be replaced.

Removed Mast assembly stripped down and removed and replaced all bearing shims and replaced chains.

Refitted Mast and continued with major service.

Remove and replaced all hydraulic filters.

On removal found metal shaving in hydraulic oil.

Removed and replaced oil flushed system.

Hydraulic pump was the issue, removed and replaced pump and seal.

All Ok,

Continued with Major service.

Removed and replaced engine oil and filters, Spark plugs and flushed cooling system.

Topped up all fluid levels and lubricant unit.

Payment Terms: Strictly 30 days from end of month

Account Name - Outrite Hire and Sales

BSB - 082-330 Acc Number - 85-228-3813

Please send remittance advice to:

Accounts@outrite.com.au

Sub-Total \$2,709.82

GST \$270.98

TOTAL \$2,980.80

Balance

Date: 21/02/2022

Make: Toyota

Model: 32-8FG25

Serial Number: 16607

Hour Meter : 10010

INSPECTION REPORT

1. Takeover job and inspect. Noted raise and lower spool switches intermittently high resistance when operating and new switches ordered.
2. Replace switches and noted spool spring jamming up. Disassemble spool and repair spring and spring cup. Found also main inlet hose split, ordered new hose.
3. Test drive Unit & found the mast functions worked correctly if Rev's were up & would not lower if at idle. Check wiring, hosing etc & found nothing obvious.
4. Remove control valve & check micro switches & solenoids on bottom, found swarf in poppet valve for the lift/lower solenoid.
5. Clean control valve & check for more swarf, reassemble ready for install
6. Reinstall control valve & check operation, still had some fault. Try to adjust pressure relief valve & made no difference. Recheck all wiring & plugs, after some research it sounds like the lift/lower solenoid is failing. Placed new solenoid on order & remove control valve again.
7. Fit new solenoid, reinstall control valve & clean up wiring.
8. Connect hosing & test hydraulics ALL OK.
9. Refit Panels & clean unit.
10. Ready to customer

Labour	10.5 hours	\$1,155.00
Labour	9 hours	\$720.00
Brake Cleaner	1	\$10.50
Hydraulics Oil 68	2	\$19.94
Workshop Consumables	1	\$21.00
Floor Mat	1	\$224.35
Solenoid Lift/Lower	1	\$895.80
	Subtotal	\$3,046.59
	GST Total	\$304.65
	Total	\$3,351.24