

W/O No	Asset No	Asset Description	Due Start	Job Type	Description	Downtime	Repair Time	Component Code	Department	Parent Asset	Labour Costs	Material Costs	Other Costs	Account Code
8805	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	19/2/2018 8:16 am	Break	Hino Dutro Truck (BM27643) - Installed 2 x new batteries & terminals	0	2		Maintenance	POB_LVH	\$240.00	\$0.00	\$381.00	P020
4062	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	5/6/2015 5:27 am	Correct	HINO DUTRO TRUCK (1BYI236) - NEW REAR NUMBER PLATE REQUIRED	0	6		Maintenance	POB_LVH	\$360.00	\$0.00	\$0.00	P026
11453	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	15/12/2020 11:41 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (6 Monthly) *** iPad Inspection ***	0	0		Stevedore	POB_LVH	\$90.00	\$0.00	\$0.00	P020
17478	POB_LVH	Motor Vehicles	31/3/2025 12:00 am	Request	Reviewed G.Bronca Completed as per inspection check list KPA FBT Vehicle Reporting (12 Monthly)	0	0		Stores	POB_P&E	\$360.00	\$0.00	\$0.00	
11496	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/11/2020 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - serviced as reqd, noted that front brakes need a full service due to corrosion. Helper pads in rear suspension need replacing. Tax invoice with job info in docs.	0	4.8		Stores	POB_LVH	\$672.00	\$0.00	\$522.40	P020
5928	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	27/5/2016 11:52 am	Break	Hino Truck (BM27643) - Replaced faulty starter motor. Job info in docs	0	3		Maintenance	POB_LVH	\$330.00	\$0.00	\$678.00	P020
15632	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	3/7/2024 12:00 am	PM	Truck, Hino 300 Series (BM27643) - Vehicle Inspection (3 Monthly) *** iPad Inspection ***	0	0		Stevedore	POB_LVH	\$115.00	\$0.00	\$0.00	P020
10697	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	8/3/2020 10:00 pm	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) - Completed as reqd.	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020

7102	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	9/3/2017 10:00 pm	Correct	Hino Dutro Truck (BM27643) - New pintle hook required for towbar due to old one being bent at 45deg. New hook purchased from Broome Diesel & installed as reqd.	0	2		Maintenance	POB_LVH	\$120.00	\$0.00	\$0.00	P020
14479	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	9/6/2023 12:00 am	Correct	Truck, Hino 300 Series (BM27643) - Clutch not working correctly. Clutch does not fully engage causing truck to stay in gear. - Could not replicate clutch problem.	0	0.5		Maintenance	POB_LVH	\$0.00	\$0.00	\$0.00	P020
1203	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	9/6/2012 5:00 am	Correct	HINO TRUCK (1BYI236) - TAIL GATE REPAIRS	0	6		Fabrication	POB_LVH	\$360.00	\$0.00	\$0.00	P026
11026	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	19/5/2020 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - service carried out as reqd, noted missing body mount bolts replaced and rest of them torqued to spec. Tax invoice with job info in docs.	0	4.58		Maintenance	POB_LVH	\$641.20	\$0.00	\$257.90	P020
10519	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	19/11/2019 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - Service completed, noted A/C requires service, RHR brake cylinder leaking and spring bushes badly worn. invoice with job info in docs.	0	5.5		Maintenance	POB_LVH	\$770.00	\$0.00	\$251.95	P020
15054	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	23/1/2024 12:00 am	PM	Truck, Hino 300 Series BM27643 - Vehicle Inspection (3 Monthly) *** iPad Inspection *** completed as requested	0	0		Stevedore	POB_LVH	\$35.06	\$0.00	\$0.00	P020

3015	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	31/7/2014 11:05 am	Correct	HINO TRUCK (1BYI236) - ELECTRIC WINDOWS NOT WORKING	0	2		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
13192	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	5/8/2022 12:00 am	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** service completed as reqd, tax invoice with job info in docs.	0	3.33		Stores	POB_LVH	\$466.20	\$0.00	\$222.45	P020
4176	POB_LVH	Motor Vehicles	1/12/2015 10:00 pm	PM	VEHICLES - INSPECTIONS (MONTHLY) - Finally completed as required	0	14		Stevedore	POB_P&E	\$840.00	\$0.00	\$0.00	
11002	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/5/2020 10:00 pm	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Full Detail (12 Monthly) - completed	0	2		Stevedore	POB_LVH	\$240.00	\$0.00	\$0.00	P020
18307	POB_FRE	First Response Equipment	20/8/2025 2:00 am	PM	Reviewed M.Gibbs Completed by St Johns on the 30th of July Invoice in doc's	0	0		HSE	POB_P&E	\$0.00	\$2,220.02	\$0.00	P254
7312	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	12/7/2017 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - Serviced as reqd, see doc's for invoice.	0	3		Maintenance	POB_LVH	\$639.80	\$0.00	\$270.10	P020
3492	POB_LVH	Motor Vehicles	3/11/2014 11:34 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	12		Maintenance	POB_P&E	\$720.00	\$0.00	\$0.00	
15689	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	10/4/2024 12:00 am	Correct	Truck, Hino 300 Series (BM27643) - Supply & fit new tyre as reqd. Tax invoice in docs.	0	1		Maintenance	POB_LVH	\$0.00	\$436.00	\$0.00	P020
11968	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	27/5/2021 8:33 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection *** - completed by Gen	0	2		Stevedore	POB_LVH	\$0.00	\$0.00	\$0.00	P020
1194	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	10/5/2012 5:00 am	Correct	HINO TRUCK (1BYI236) - HORN NOT WORKING	0	1		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026

16628	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/10/2024 9:46 am	Correct	Brake lights not working Completed in previous work order by Brad Tribbick	0	0		Maintenance	POB_LVH	\$0.00	\$0.00	\$0.00	P020
11580	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	1/12/2020 10:00 pm	Correct	Hino Dutro Truck (BM27643) - Front brakes required full strip down service. Have quite a bit of surface corrosion and noisy. Rear spring helper pads are cracked and require replacement. - Completed as reqd, tax invoice with job info in docs.	0	7.07		Maintenance	POB_LVH	\$989.80	\$0.00	\$1,022.10	P020
9662	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	11/12/2018 10:00 pm	Correct	Hino Dutro Truck (BM27643) - Replaced 2 x front & 1 x spare tyre as they were worn, perished and 1 x had 300mm split in sidewall. Tax invoice in docs.	0	2		Maintenance	POB_LVH	\$180.00	\$0.00	\$1,182.00	P020
3995	POB_LVH	Motor Vehicles	3/6/2015 6:50 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	17		Stevedore	POB_P&E	\$1,020.00	\$0.00	\$0.00	
10601	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	20/11/2019 10:00 pm	PM	Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection *** - completed the day after vehicle had been serviced	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
1645	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	5/2/2013 5:00 am	PM	HINO TRUCK (1BYI236) - *** 10000 KM SERVICE ***	0	6		Mechanical	POB_LVH	\$782.40	\$0.00	\$0.00	P026
19446	POB_LVH	Motor Vehicles	13/5/2026 12:00 am	Request	KPA FBT Vehicle Reporting (12 Monthly) Completed as required.	0	0		Finance	POB_P&E	\$90.00	\$0.00	\$0.00	
7022	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	3/4/2017 10:00 pm	PM	Hino Dutro Truck (BM27643) - Vehicle Detail (3 Monthly) - Completed as reqd, no polish.	0	3		Stevedore	POB_LVH	\$180.00	\$0.00	\$0.00	P020
5455	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	19/4/2016 9:00 am	PM	Hino Truck (BM27643) - *** 6 Month/10,000km Service *** - Serviced as required, job info in docs.	0	3		Maintenance	POB_LVH	\$1,470.00	\$0.00	\$764.75	P020

10133	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	19/6/2019 5:31 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection ***	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
7271	POB_LVH	Motor Vehicles	30/5/2017 10:00 pm	PM	Vehicle Inspections (Monthly) - Finally completed as reqd. Completed checklists in docs.	0	18		Stevedore	POB_P&E	\$1,080.00	\$0.00	\$0.00	
10437	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	21/11/2019 5:53 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (6 Monthly) *** iPad Inspection *** - completed as reqd	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
3014	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	31/7/2014 10:59 am	Correct	HINO TRUCK (1BYI236) - EXHAUST BRAKE NOT WORKING	0	1		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
9650	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	12/12/2018 7:45 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection *** completed as required	0	2.5		Stevedore	POB_LVH	\$0.00	\$0.00	\$0.00	P020
7542	POB_LVH	Motor Vehicles	23/7/2017 10:00 pm	PM	Vehicle Inspections (Monthly) - Completed as reqd	0	17		Stevedore	POB_P&E	\$1,020.00	\$24.65	\$0.00	
14026	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	24/3/2023 12:00 am	PM	Truck, Hino 300 Series (BM27643) - *** 6 Month/10,000km Service *** - Service completed as reqd, tax invoice with job info in docs.	0	3		Maintenance	POB_LVH	\$0.00	\$740.72	\$0.00	P020
16542	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	9/10/2024 12:00 am	PM	Truck, Hino 300 Series (BM27643) - Vehicle Inspection (3 Monthly) *** iPad Inspection ***	0	0		Stevedore	POB_LVH	\$70.00	\$0.00	\$0.00	P020
2961	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/3/2014 6:33 am	Correct	HINO TRUCK (1BYI236) - REVERSE BEEPER NOT WORKING	0	0.5		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026

16627	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	11/10/2024 11:59 am	Correct	replaced brake lamps rest all good	0	0		Stores	POB_LVH	\$0.00	\$0.00	\$0.00	P020
6873	POB_LVH	Motor Vehicles	15/2/2017 10:00 pm	PM	Vehicle Inspections (Monthly) - Completed as required, inspections in docs.	0	19		Stevedore	POB_P&E	\$1,140.00	\$0.00	\$0.00	
1214	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	8/6/2012 5:30 am	Break	HINO TRUCK (1BY1236) - STARTING DIFFICULTIES (FLAT BATTERY)	0	0.5		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
17033	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	4/7/2025 12:25 pm	PM	Reviewed M.Gibbs Truck, Hino - 300 Series - SCC 4x2 - BM27643 - Vehicle Inspection	0	0		Stevedore	POB_LVH	\$0.00	\$0.00	\$0.00	P020
3713	POB_LVH	Motor Vehicles	13/4/2015 7:27 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	20		Maintenance	POB_P&E	\$1,200.00	\$0.00	\$0.00	
7531	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	17/8/2017 10:00 pm	PM	Hino Dutro Truck (BM27643) - Vehicle Detail (3 Monthly) - Completed as reqd	0	4		Stevedore	POB_LVH	\$240.00	\$0.00	\$0.00	P020
13486	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/8/2022 6:25 am	Correct	Truck, Hino 300 Series (BM27643) - Replaced faulty slave cylinder due to loss of clutch. Tax invoice with job info in docs	0	3.24		Maintenance	POB_LVH	\$453.60	\$0.00	\$276.20	P020
6591	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	23/11/2016 10:00 am	PM	Hino Truck (BM27643) - Vehicle Detail (3 Monthly) - Detailed as required.	0	4		Stevedore	POB_LVH	\$240.00	\$0.00	\$0.00	P020
12805	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	27/1/2022 12:00 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection ***	0	0		Stevedore	POB_LVH	\$240.00	\$0.00	\$0.00	P020
9518	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	30/10/2018 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - Service completed, tax invoice and job info in docs. *** Noted to repack wheel bearings and adjust valve clearances at next service ***	0	3.5		Maintenance	POB_LVH	\$490.00	\$0.00	\$206.00	P020

11731	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	20/1/2021 1:10 pm	Correct	Hino Dutro Truck (BM27643) - Clutch not working correctly. Replaced leaking slave cylinder and master cylinder assembly as reqd. Tax invoice in docs with job info.	0	4.56		Maintenance	POB_LVH	\$638.40	\$0.00	\$288.65	P020
15395	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	27/2/2024 12:00 am	Request	Truck, Hino 300 Series (BM27643) - A/C system not working 100% - System pressure checked & re-gassed, all working good at present, please monitor going forward. Tax invoice with job info in docs.	0	1.5		Maintenance	POB_LVH	\$0.00	\$396.36	\$0.00	P020
2692	POB_LVH	Motor Vehicles	20/1/2014 11:20 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	6		Maintenance	POB_P&E	\$360.00	\$0.00	\$0.00	
5271	POB_LVH	Motor Vehicles	2/8/2016 11:30 am	PM	Vehicle Inspections (Monthly) - Completed as required, all vehicle check sheets in docs. Noted that all bus tyres require replacing.	0	7		Stevedore	POB_P&E	\$420.00	\$0.00	\$0.00	
10390	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	30/11/2020 9:54 am	Correct	Hino Dutro Truck (BM27643) - Driver seat requires canvas seat cover ASAP	0	0		Maintenance	POB_LVH	\$120.00	\$0.00	\$0.00	P020
10585	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	13/2/2020 10:00 pm	Correct	Hino Dutro Truck (BM27643) - RHR Brake wheel cylinder leaking brake fluid and suspension spring bushes flogged out. - All repairs carried out as reqd, tax invoice with full job description in docs.	0	16.1		Maintenance	POB_LVH	\$2,254.00	\$0.00	\$1,635.40	P020
8313	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	28/11/2017 8:14 am		Replace damaged mirror. Completed as Required. Job info and invoice in Doc's.	0	1		Maintenance	POB_LVH	\$0.00	\$0.00	\$408.95	P020
2616	POB_LVH	Motor Vehicles	18/12/2013 11:30 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	3		Maintenance	POB_P&E	\$180.00	\$0.00	\$0.00	

15335	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	15/2/2024 12:00 am	Break	Truck, Hino 300 Series (BM27643) - Belt is out of adjustment and can't be tightened any more. Order replacement belt and fit. Picture of belt in doc's new belt fitted and adjusted	0	0		Maintenance	POB_LVH	\$120.00	\$0.00	\$0.00	P020
3844	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	12/2/2016 6:30 am	PM	HINO TRUCK (1BYI236) - DETAIL VEHICLE (6 MONTHLY) - Completed as required	0	5.5		Stevedore	POB_LVH	\$330.00	\$0.00	\$0.00	P026
7784	POB_LVH	Motor Vehicles	7/12/2017 10:00 pm	PM	Vehicle Inspections (Monthly) Completed as Required.	0	16		Stevedore	POB_P&E	\$0.00	\$0.00	\$0.00	20220
2988	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	8/5/2014 9:17 am	Correct	HINO TRUCK (1BYI236) - NEW EXHAUST MUFFLER REQUIRED	0	2		Mechanical	POB_LVH	\$180.00	\$0.00	\$0.00	P026
3027	POB_LVH	Motor Vehicles	8/5/2014 6:23 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	5.5		Maintenance	POB_P&E	\$330.00	\$0.00	\$0.00	
5959	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	2/8/2016 10:00 am	PM	Hino Dutro Truck (BM27643) - Vehicle Detail (3 Monthly) - Completed as required. Good job done.	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
2134	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	28/8/2013 11:42 pm	Request	HINO TRUCK (1BYI236) - TYRES NEED REPLACING	0	2		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
14233	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	12/4/2023 9:34 am	Correct	Truck, Hino 300 Series (BM27643) - Accelerator peddle loose, falls off lever Repaired pedal hinge	0	0		Maintenance	POB_LVH	\$120.00	\$0.00	\$0.00	P020
14865	POB_FRE	First Response Equipment	1/11/2023 12:00 am	PM	First Aid Kits - Inspection & Restocking (6 Monthly)	0	0		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	SAFETY
5055	POB_LVH	Motor Vehicles	2/2/2016 8:09 am	PM	Vehicle Inspections (Monthly) - Completed as required	0	16		Stevedore	POB_P&E	\$960.00	\$0.00	\$0.00	
3585	POB_LVH	Motor Vehicles	15/1/2015 7:02 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	0		Maintenance	POB_P&E	\$840.00	\$0.00	\$0.00	

134	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	25/5/2011 6:36 am	Correct	HINO TRUCK (1BY1236) - REPLACE STARTER MOTOR	0	8		Mechanical	POB_LVH	\$195.60	\$0.00	\$719.58	P026
12482	POB_FRE	First Response Equipment	4/10/2021 8:52 am	PM	First Aid Kits - Inspection & Restocking (6 Monthly)	0	8		Maintenance	POB_P&E	\$720.00	\$0.00	\$0.00	SAFETY
7163	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	14/3/2017 10:00 pm	Correct	Hino Dutro Truck (BM27643) - Replaced wiper blades as required.	0	2		Maintenance	POB_LVH	\$120.00	\$0.00	\$0.00	P020
11154	POB_FRE	First Response Equipment	19/8/2020 10:00 pm	PM	First Aid Kits - Inspection & Restocking (6 monthly) - completed as reqd	0	12		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	
15660	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	2/5/2024 12:00 am	PM	Truck, Hino 300 Series (BM27643) - *** 6 Month/10,000km Service *** - Service completed, tax invoice with job info in docs.	0	3		Mechanical	POB_LVH	\$0.00	\$840.77	\$0.00	P020
19090	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	6/1/2026 11:28 am	Correct	REVIEWED S . MOONEY . BM27643 - Truck, Hino - 300 Series - SCC 4x2 - Replaced 2 x 12V batteries for the 24V system. Tax invoice in docs.	0	1		Maintenance	POB_LVH	\$60.00	\$420.00	\$0.00	P020
10584	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	2/12/2019 10:00 pm	Correct	Hino Dutro Truck (BM27643) - Service A/C system. Evaporator is blocked. - Full A/C service with install of new evaporator due to corrosion of old one. Tax invoice with job info in docs.	0	3.5		Maintenance	POB_LVH	\$350.00	\$0.00	\$778.75	P020
16634	POB_FRE	First Response Equipment	31/1/2025 2:00 am	PM	Reviewed G.Bronca First Aid Kits - Inspection & Restocking (6 Monthly)	0	0		HSE	POB_P&E	\$128.00	\$1,346.84	\$0.00	
10022	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	9/5/2019 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - Service completed as reqd, tax invoice with job info in docs.	0	5.3		Maintenance	POB_LVH	\$742.00	\$0.00	\$297.00	P020

11175	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	22/7/2020 10:36 am	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection ***	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
12026	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	13/5/2021 10:00 pm	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - serviced as reqd, tax invoice with job info in docs.	0	3.28		Stores	POB_LVH	\$459.20	\$0.00	\$216.00	P020
12151	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/6/2021 6:15 am	Correct	Hino Dutro Truck (BM27643) - Batteries replaced in 24V cranking system. Tax invoice in docs.	0	1		Maintenance	POB_LVH	\$60.00	\$0.00	\$0.00	P020
13055	POB_FRE	First Response Equipment	12/4/2022 9:23 am	PM	First Aid Kits - Inspection & Restocking (6 Monthly)	0	1		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	
5186	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	10/2/2016 6:01 am	Correct	Hino Truck (BM27643) - Replaced LH side mirror as required. Parts invoice in docs.	0	2		Maintenance	POB_LVH	\$120.00	\$0.00	\$503.60	P020
14139	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	11/4/2023 10:00 pm	PM	Truck, Hino 300 Series (BM27643) - Vehicle Inspection (3 Monthly) *** iPad Inspection ***	0	0		Stevedore	POB_LVH	\$6,000.00	\$0.00	\$0.00	P020
15671	POB_FRE	First Response Equipment	27/7/2024 12:00 am	PM	First Aid Kits - Inspection & Restocking (6 Monthly) Completed by Stjohn's July 24 Invoice in Doc's	0	0		HSE	POB_P&E	\$128.00	\$0.00	\$2,706.02	SAFETY
11739	POB_FRE	First Response Equipment	22/3/2021 10:00 pm	PM	First Aid Kits - Inspection & Restocking (6 Monthly)	0	6		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	
63	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	20/5/2011 5:00 am	Request	HINO TRUCK (1BYI236) - HORN NOT WORKING	0	1		Electrical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
6525	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	2/11/2016 11:00 am	PM	Hino Dutro Truck (BM27643) - *** 6 Month/10,000km Service *** - Service completed, A/C belt & idler pulley replaced as required. Job info in docs.	0	5		Maintenance	POB_LVH	\$630.00	\$0.00	\$364.80	P020

14262	POB_FRE	First Response Equipment	21/4/2023 12:00 am	PM	First Aid Kits - Inspection & Restocking (6 Monthly)	0	0		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	
195	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	28/6/2011 12:03 pm	Request	HINO TRUCK (1BYI236) - SPONGY CLUTCH	0	8		Mechanical	POB_LVH	\$0.00	\$0.00	\$0.00	P026
6527	POB_LVH	Motor Vehicles	2/11/2016 11:30 am	PM	Vehicle Inspections (Monthly) - Completed as reqd, all KPA vehicles inspected.	0	27		Stevedore	POB_P&E	\$1,620.00	\$0.00	\$0.00	
11791	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	1/3/2021 10:00 pm	PM	Hino Dutro Truck (BM27643) - Vehicle Inspection & Clean (2 Monthly) *** iPad Inspection *** - completed	0	2		Stevedore	POB_LVH	\$120.00	\$0.00	\$0.00	P020
4091	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	4/8/2015 12:25 pm	Correct	HINO DUTRO TRUCK (BM27643) - A/C NOISEY	0	1		Mechanical	POB_LVH	\$60.00	\$0.00	\$0.00	P026
3303	POB_LVH	Motor Vehicles	19/8/2014 11:05 am	PM	VEHICLE - INSPECTION (MONTHLY)	0	3		Maintenance	POB_P&E	\$0.00	\$0.00	\$0.00	
7984	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	23/12/2017 10:00 pm	Correct	Hino Dutro Truck (BM27643) - Truck tray flooring has rusted thru in a number of spots. Replace whole floor with new tread plate. Blast and Painting of Tray required.	0	1		Maintenance	POB_LVH	\$0.00	\$150.89	\$0.00	P020
11875	POB_LVH	Motor Vehicles	30/3/2021 10:00 pm	Request	KPA FBT Vehicle Reporting (12 Monthly) - completed as reqd	0	2		Maintenance	POB_P&E	\$120.00	\$0.00	\$0.00	

9053	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	13/8/2018 6:53 am	Correct	Hino Dutro Truck (BM27643) - Undertake following repairs to items as highlighted during last service (April 2018 - BDHS ordering reqd parts) ADDITIONAL REPAIRS NOTED - * DIFF PINION SEAL LEAKING. * EXHAUST FLEX JOINT RUSTED AND FAILING. * GEAR SELECTOR OIL LEAK. * REAR SPRING BUMP STOP MISSING RH SIDE. Completed as Required	0	4		Maintenance	POB_LVH	\$0.00	\$0.00	\$0.00	P020
17909	POB_LVH001	*BM27643 - Truck, Hino - 300 Series - SCC 4x2	18/6/2025 2:00 am	PM	Reviewed M.Gibbs Truck, Hino 300 Series (BM27643) - *** 6 Month/10,000km Service *** - Completed as reqd. Tax invoice with job info in docs. - ADJUSTED ALL BRAKES - WELDED EXHAUST BROKEN UNDERNEATH - Note: KING PINS HAVE WEAR ONCE GREASED THE PLAY IS TAKEN UP BUT WILL NEED RE BUSHING AND PINS AT SOME STAGE - OK FOR NOW.	0	0		Mechanical	POB_LVH	\$420.00	\$136.74	\$0.00	P020