

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

Cat: DTRK45

Year: 2017

Provisional?:

Supplier:

Model: Bell Dump Truck

Under Repair?

Log

<i>Date</i>	<i>Type</i>	<i>Description</i>	<i>Meter</i>	<i>Labour</i>	<i>Parts</i>
26/07/2024	REPAIR	Harris Heavy Mechanical: Change out heater core and tap. Test operation		\$360.00	
16/07/2024	OTHER	Hitachi: Supply heater coil			\$579.40
16/07/2024	OTHER	Hitachi: Supply motor valve			\$224.83
11/07/2024	SERVICE	Harris Heavy Mechanical: Complete 250hr service. Diagnose coolant leak. Run auto greaser through multiple cycles (@ 7628 Hours)	7628	\$757.00	
10/07/2024	SERVICE	HHM: Completed Service Onsite, Heater Core will need to be replaced, slight leak, also new electronic heater tap (@ 7899 Hours)	7899	\$757.00	
10/07/2024	OTHER	Road Runner: 3 x 20Litre Drums of 10W-40 Engine oil			\$524.88
26/06/2024	OTHER	Blatchs: Wix air filters, fuel/water separator, fuel lube			\$842.27
16/05/2024	REPAIR	TG: Blew out cab, element air and a/c filters. Tagged and replaced 1 x fire extinguisher, fixed wiring for lower work light and got working. Replaced globes in 2 x cabin works lights (@ 7628 Hours)	7628	\$125.00	
14/05/2024	REPAIR	Tyrepower: Earthmover tyre service		\$200.00	
14/03/2024	REPAIR	Harris Heavy Mechanical: Travel to Temora. Inspect faults. Put alternator wiring bank to original. Test & fault cleared.		\$720.00	
8/03/2024	REPAIR	TG: Fit new tipping multicolour signal light, wire up and tested. Worked fine		\$60.00	

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

5/03/2024	REPAIR	Acemec: Test a/c, tighten stoder valve and clean cab filters		\$137.00	
4/03/2024	REPAIR	Harris Heavy Mechanical: Reseal hydraulic brake oil tank & inspect for leaks. Go through error code list & fix. Drain engine oil to correct level. Gas front struts to level machine. Pump & check tyres.		\$600.00	
1/03/2024	REPAIR	DC: Top up brake cooling tank (10 litres). Leak on top of tank (@ 7463 Hours)	7463	\$150.00	
29/02/2024	OTHER	Hitachi - Supply OBW Load light			\$1,160.30
22/02/2024	REPAIR	Acemec: Diagnose and repair start fault		\$230.00	
24/01/2024	REPAIR	A1 Earthworx: DIAGNOSE LOSS OF ELETRICAL POWER - INSPECT BATTERY CABLES & CONNECTORS - TERMINALS CORRODED OFF, STRIP BACK & JOIN TOGETHER, CABIN POWER RESTORED, DIAGNOSE ACTIVE & START FAULT CODES		\$450.00	
15/11/2023	REPAIR	GB Auto: Diagnose and repair air con issues		\$715.00	\$206.00
3/11/2023	SERVICE	JB Mechanical: Carry out engine service, full check over, check oils and fluids, replaced all filters, inspect grease issue. Supply engine oil (@ 7236 Hours)	7236	\$440.00	\$500.00
14/09/2023	OTHER	Hitachi: Supply Motor actuator			\$90.63
11/09/2023	REPAIR	Acemec: Travel to/from Ulan Mine 11/9/23. Diagnose a/c leak. Attempt to repair. Replace alt circuit breaker. Travel to/from Ulan Mine 18/9/23. Replace a/c compressor. Diagnose & repair heater tap fault.		\$1,000.00	\$3,460.00
6/09/2023	OTHER	Hitachi: Supply motor actuator			\$90.63

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

1/09/2023	REPAIR	Acemec: Travel to / from site. Diagnose alternator fault and other electrical faults	\$1,540.00
24/08/2023	OTHER	Filtermax: Supply filter kit	\$629.46
24/08/2023	OTHER	Filtermax: Lube filter, fuel filter, air filters,	\$629.46
12/08/2023	OTHER	Westrac: Supply 2 x 18Litres of engine coolant	\$276.64
11/08/2023	REPAIR	Harris Heavy Mechanical: Travel to/from Mudgee 7/8/23. Inspect why coolant hose blew off & inspect for damage. Found water pump to be noisy. Travel to/from Mudgee 7/8/23. Inspect why coolant hose blew off & inspect for damage. Found water pump to be noisy.	\$2,640.00
10/08/2023	REPAIR	GB Auto: Investigate no heater. Removed dash and tested power at heater tap. Found tap inop. Need new control module unit. Remove motor from tap and opened valve to allow for heat	\$390.00
9/08/2023	REPAIR	Quantum Fire Technology: Description of Works - Replace hosing as required - Replace labels - Replace gauges as required - Replace Piston in Valve - Service & lubricate activation points - Replace nozzles & caps as required TESTING - Conduct discharge test - Conduct clear passage test - Conduct Electrical test - Conduct 30 minute pressure test - Detection Network Provide commission report - AS5062	\$1,440.30

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

8/08/2023	OTHER	Hitachi: Supply ribbed v-belts, tensioner belt and water pump	\$2,923.28	
7/08/2023	OTHER	Hitachi - Supply water pump	\$868.28	
20/07/2023	REPAIR	A1 Earthworx: TRAVEL TO SITE, FOUND BURST HEATER HOSE HAS SPRAYED COOLANT ON EXHAUST MANIFOLD CAUSING SMOKE, SHORTEN HOSE & RECONNECT, FILL WITH WATER & COOLANT, BRIDGE E- STOP CIRCUIT, START ENGINE & MOVE OUT OF THE WAY	\$675.00	
19/07/2023	OTHER	Hitachi: Subscription of Airtime, classic for 3 months	\$461.68	
27/06/2023	REPAIR	A1 Earthworx: Diagnose low/no charge light and alarm, test charge rate, alternator bearings starting to squeal	\$270.00	
22/06/2023	REPAIR	GB Auto: Replace single pole isolator with dual pole Fit alternator circuit breaker Remove old isolator and fit two pole replace battery as old one had bad terminal fit alt circuit breaker Parts: battery, circuit breaker, bracket circuit, lockout isolator, lug boot, cable battery, conduit, terminal battery	\$780.00	\$1,116.22
14/06/2023	REPAIR	A1 Earthworx: Diagnose no heater	\$90.00	
6/06/2023	REPAIR	Acemec: Repair fuel gauge fault. Repair fuel gauge fault	\$330.00	
6/06/2023	OTHER	CoolDrive: Supply wheel nuts and wheel nut indicator	\$212.60	
5/06/2023	OTHER	Advance Global: Supply and install Lagging	\$300.00	\$2,639.00
2/06/2023	OTHER	Advance Global: Supply reverse alarm	\$157.60	
30/05/2023	OTHER	DCT: Supply receptacle jump start	\$158.00	

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

8/02/2023	REPAIR	Tye Engineering: Remove, rebuild and replace tailgate open/closer linkage on LH side of Dump truck		\$450.00
24/01/2023	SERVICE	Harris Heavy Mechanical: Complete 500hr service. Gas up lefthand side front strut. Park Brake Test Completed, Due at Next Service 7,000 Hours. Emergency Steering Test Completed, Due at Next Service 7,000 Hours. All Final Drives Checked (@ 6593 Hours)	6593	\$550.00
24/10/2022	SERVICE	Westrac Completed 500 Hour Service, as per manufacture specs (@ 6588 Hours)	6588	
7/10/2022	OTHER	Hitachi: Element, oil filters, air filter assembly, brake filter, breather, air dryer filter, transmission filter kit, transfer case filter, fuel filter		\$2,034.84
11/08/2022	REPAIR	Westrac: Troubleshoot transmission. Cause: Transmission overfull. Correction: Run machine to heat up transmission, wait for machine to fault, investigate fault, found transmission to be overfull. Drained approx 8 Kitres of oil from Transmission. Run machine again to check for fault. All OK		\$1,320.57
22/07/2022	REPAIR	Harris Heavy Mechanical: Check over machine & active error codes. Drain trans oil to level. Top up hydraulic oil & coolant. Repair leak on brake tank & test.		\$412.50
21/07/2022	OTHER	Tyrepower: 2 x Maxam 15.5/80-24 tyres 6 x 29.5 R25 TL Maxam		\$29,727.30

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

11/07/2022	REPAIR	Acemec: Test a/c faults, leak test. Trace leaking fitting and repair. Vacuum, gas and test. Turn off foward and reverse beepers through computer		\$660.00	\$175.00
30/06/2022	REPAIR	Axiom: Long term report / Services of Stuart Wilson		\$2,250.00	
20/06/2022	REPAIR	Acemec: Travel to/from CVO. Fit supplied UHF kit		\$385.00	
25/05/2022	REPAIR	Acemec: Wire up door alarm to Bell specifications, wire up and mount 2 way. Supply module-park brake		\$660.00	\$285.00
11/05/2022	REPAIR	JB: Fit new brake pressure switch and check for faults (all ok), adjust fuel overflow hose to fit under the bonnet. Fit helicoils to hydraulic tank cover and refit covers for accumulators. Drain out excessive engine oil (@ 6095 Hours)	6095	\$200.00	
10/05/2022	REPAIR	JB: Fit fuel tank overflow hose and clampts for MDG pan out (@ 6095 Hours)	6095	\$100.00	
10/05/2022	OTHER	Hitachie: Supply Sensor, pressure			\$368.89
5/05/2022	REPAIR	O'Connell DFC: Travel to site and fit alternator. Jump start and test operation. Check coolant warning lamp. No issue found after battery reset. Machine running OK (@ 6109 Hours)	6109	\$240.00	
4/05/2022	REPAIR	O'Connell DFC: Travel to site. Machine not charging. Carry out checks on alt belt and wiring. Found alternator to be faulty. Sourced and ordered new alternator. Remove old alternator and return to workshop (@ 6109 Hours)	6109	\$120.00	
4/05/2022	OTHER	Dailmer Trucks: Supply 1 x alternator			\$2,052.49

Stock No: APH00863

Bell B45E Articulated 45T Dump Truck

Serial No: AEBA845EA01205984

Reg No:

3/05/2022	REPAIR	JB: Diagnose brake fault - U/S pressure switcch. Carry on with MDG15 list (@ 6095 Hours)	6095	\$250.00	
3/05/2022	OTHER	SCH: hose and clamps			\$254.92
2/05/2022	REPAIR	Acemec: Program prestart through truck, program seat belt alarm		\$330.00	
29/04/2022	REPAIR	JB: Jack up cabin, connect pressure gauges, run and check pressures to diagnose brake fault (@ 6094 Hours)	6094	\$225.00	
				<hr/>	
				\$22,919.37	\$53,039.60