

Finished Date/Time Description

Aztech Gunnedah

Repairs

FA103 placed reverse alarm

26/09/2023 Re First Aid Kit replaced -
Aztech Gunnedah

Carry out 160K service.

Air filter

26/09/2023 Cabin filter

2/05/2023 UF33 - Tyre puncture repair

6/12/2022 Rego & CTP renewal - eSafety Check (Brake Test)

Repairs required as part of 150000km service - Aztech Replaced fuel filter as U/S, Adjusted hand brake, Replaced wiper

4/10/2022 blades as U/S, Topped up front diff oil, Sent for tyres, Refit rear mud flaps (supplied)
Carried out 150,000km service - Aztech

Fire Extinguisher: FE379

Tag - 09/22

Built - 12/21

4/10/2022 First Aid: FA003

Replace 4 tyres - Tyrepower

30/09/2022 Toyo 265/65R17 120R OPEN COUNTRY AT2

8/12/2021 Pink Slip

27/08/2021 Install new side step (Right)

27/08/2021 movement. Replaced transfer output seal and flange as leaking, adjusted oil level.

27/08/2021 Carried out 130,000k Service INV# 17971

3/08/2021 wheel alignment INV#307111

2/11/2021 mudguards and clips INV#1984544B

27/04/2021 DPF Replaced & Air Filter replaced

17/03/2021 Uninstall minebar, uhf radio

Replace Battery
18/02/2021 DIN65LH MF BOSS
Check clutch operation
Removed gearbox, propeller, cross member and re fit. Removed and replaced clutch components. Removed fly wheel send
away for resurface, Carried out road test. Clean dirt underneath and in gear box area, Carried out check over. Replaced
3/12/2020 missing rear inner guards and mud flaps.
Carried out 120,000km service.
Adjusted hand brake.
Fit rear mudguards as missing.
23/09/2020 Assemble and fit side steps as missing.
110,000KM Service
replaced front brake and rotars
replaced air and pollen filters
cleaned outside of vehicle for service
9/06/2020