



Vehicle History Detail



Fleet #	XO21AJ
Registration	XO21AJ
Make	DAF
Model	XF105
VIN / Chassis #	XLRTT47MSGG136160

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1809	13/12/2022	0	0	Elec Windows				\$574.55
R-1792	05/12/2022		0	Callout	Jack			\$480.09
S-2670	02/11/2022	1008816	0	A - Fortnightly				\$473.00
R-1779	25/10/2022	0	0	Power Steering				\$13,044.64
S-2639	25/10/2022	1007438	0	C - 150k		Replaced Battery Terminals		\$1,891.34
R-1796	14/10/2022	0	0	Power Steering				\$10,668.64
S-2619	20/09/2022	9970450	0	B - 50k	Jack			\$1,054.30
S-2624	20/09/2022	0	0	A - Fortnightly				\$711.04
R-1687	06/09/2022			Brakes	Tony Madden	fit new brake shoes and drums fit new wheel bearing kits and seals		\$4,168.87
R-1711	22/08/2022			Power Steering		REMOVE POWER STEERING HOSES TAKE TO HARDEN BEARING TO BE REPAIRED THEN REFIT HOSES		\$561.42
T-544	07/07/2022	0	0	New		2x Hankook	107604	\$1,396.00
T-543	30/06/2022	0	0	Second hand tyre		1x second hand tyre 1x truck tyre disposal	107535	\$290.00
R-1657	21/06/2022			Oil Leak				\$207.38
R-1583	17/05/2022			Heater Tap				\$1,675.92

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1585	17/05/2022			Wiper Stalk				\$741.79
S-2567	11/05/2022	0	0	B - 50k				\$1,197.30
R-1570	10/05/2022			Electronic Diary		NAVMAN REMOVED		\$35.75
R-1503	03/05/2022	0	0	Radiator	Jack	waiting on radiator UP DATE::: REPLACED RADIATOR- NEW RADIATOR WAS FOUND TO BE CRACKED-REMOVED- NEW RADIATOR ORDERED AND ANOTHER ONE FITTED REPLACED CONDENSOR AND OIL FILTER HOSE JR1081		\$6,287.65
R-1510	03/05/2022	0	0	Battery		JR 1072 CANBERRA TRUCK = HEADER TANK Received Invoice 1193784 JR1073 HDT= 2X BATTERIES.. Received Invoice No 1584		\$1,542.87
S-2534	08/04/2022	885183	0	B - 50k	Dylan			\$768.30
S-2535	08/04/2022	935183	0	B - 50k	Dylan			\$768.30
S-2536	08/04/2022	885183	0	C - 150k + RTA Insp.	Dylan			\$1,098.26
S-2509	28/03/2022	939387	0	A - Fortnightly	Yard			\$473.00
R-1487	17/03/2022	0	0	Cab				\$468.67
O-186	16/02/2022	0	0	Registration	Transport NSW (Service NSW)			\$4,703.61

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1440	06/01/2022	0	0	warning lights		REPAIR 01 TRUCK PRESENTED WITH NO SPEEDO FOUND PLUG DAMAGED AND MULTIPLE WIRES DAMAGED REPLACED PLUG AND SECTION OF LOOM RESECURED LOOM AND CLEARED CODES ROAD TESTED ALL OK.		\$475.88
T-462	20/12/2021	0	0	New		4x aeson tyres 4x truck tyre disposal	105405	\$1,868.00
R-1425	13/12/2021			Air Conditioner		Air conditioner repair-regassed removed cross member and replaced chackles repaired multiple air leaks recalibrated the departure system road tested all ok checked out transmissionDT codes found internal failure in range change, and engine does not respond correctly both dtc's result being locked in manual mode found exhaust brake leaking air when engaged tighten, all is ok this was fault for engine carried out static and dynamic shift rail position test and clutch position test, found range change out of spec in dynamic test drained trans oil and found full of metal shavings replace gearbox reflashed software for TCM on new gearbox. checked over, all good	1185067	\$23,486.32
S-2408	18/09/2021	0	0	A - Fortnightly				
S-2400	06/09/2021	0	0	A - Fortnightly				
R-1331	29/08/2021	0	0	Trailer Plug	Kobi	REPLACE TRIALER PLUG		\$0.00
R-1330	27/08/2021	0	0	A/C, Drive belts	Jack, Kobi			\$0.00
S-2388	25/08/2021	0	0	A - Fortnightly				

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-395	20/08/2021	0	0	New		2x bridgestone 1x truck tyre disposal	104182	\$1,586.50
S-2325	11/08/2021	804176	0	B - 50k	Dylan, Jack, Kobi	rear brakes are low		
R-1335	11/08/2021	0	0	deck lid	Jack	replaced missing bolts and tightened remaining bolts		\$115.50
S-2322	09/08/2021	800262	0	A - Fortnightly	Dylan			
S-2298	05/07/2021	782478	0	A - Fortnightly	Kobi			\$473.00
S-2274	17/06/2021	773056	0	A - Fortnightly	Kobi	retighten exhaust solenoid		\$154.52
S-2195	21/05/2021	757409	0	A - Fortnightly	Dylan	added 4Ls of engine oil		\$205.04
R-1207	19/05/2021	757200	0	Defect, Differential Oil Leak, Torque Rod	Kobi	replace torque rod bushes replace jackshaft seal DEFECT CLEARED		\$1,809.75
S-2117	12/04/2021	735183	0	D - 300k	Dylan, Zane			\$1,545.65
R-1058	26/03/2021	712476	0	Dash - Gauges, Oil Leak	Jack	replaced coolant lvl sensor part no:1850746		\$189.45
R-1054	03/03/2021			Electrical	Jack	Lane departure camera remounted		\$46.75
S-1960	19/02/2021	706402	0	A - Fortnightly		Replace two coolant hoses back of motor		\$529.03
O-122	16/02/2021	0	0	Registration				\$4,599.15
R-943	20/01/2021	687354		Air Conditioner		checked belts belts okay		\$35.75
R-930	14/01/2021	685367	0	body	Zane			\$379.50
R-923	14/01/2021	685367	0	Windscreen Washers	Kobi	wiper blades x3, washer nozzle fitted witnessed by workshop Manager		\$255.58
R-928	14/01/2021	685317	0	Mirrors	Jack			\$240.70

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-929	14/01/2021	685367	0	Engine Oil leaks		Clutch and gearbox hot washed and degreased by workshop.		\$5,104.77
R-907	08/01/2021	0	0	Defect, Fuel Tank		tank removed from truck, and sent to Spinafex welding Cootamundra. Tank refitted to truck. DEFECT CLEARED by Riverina Truck Centre Wagga.		\$275.50
S-1829	07/01/2021	681002	0	A - Fortnightly				\$330.00
R-844	24/12/2020	0	0	Drivers Seat		New seat cover supplied		\$278.31
T-221	23/12/2020			New - Drives, New - Steers		2x bridgestone 4x goodyear 4x truck tyre disposal	101601	\$3,936.00
R-779	22/12/2020	672278		Fuel Tank	Steve T	Thread taped drain plug		\$46.75
S-900	30/11/2020	655369	0	A - Fortnightly	Zane			\$165.00
R-644	13/11/2020	642965	0	Fuel Tank	Steve T	Fix fuel leak coming from fuel tank New fuel cap fitted. new copper washer to be fitted at next service ,Drivers side fuel tank.		\$148.93
S-719	17/10/2020	632540	0	A - Fortnightly	Yard			\$187.00
S-612	22/09/2020	620030	0	B - 50k	Yard			\$699.39
T-145	15/09/2020	0	0	Balance , Strip & Fit, Tyre Pressures		2x strip fit, balance steers plus pressure	100411	\$220.00
S-647	13/09/2020	617101	0	A - Fortnightly	Yard	8lt oil headlight globe		\$529.28
R-501	05/09/2020			Speed Alert	Jack	Install Hummingbird Speed alert device .		\$224.85
R-722	26/08/2020			Headlights	Jack			\$142.12
R-436	14/08/2020	583581		Engine		See document attached for all work carried out		\$1,891.33
R-465	12/08/2020			Body Repairs		Repair bullbar Remove and replace N/S door extension and lower step housing	7155	\$2,229.84

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-271	24/06/2020	576710	0	C - 150k		Completed "C" service		\$1,109.90
R-345	23/06/2020			Electrical	Jack			\$432.57
R-273	12/06/2020	568430	0	Electrical		parts ordered 29/07/20		\$419.82
R-264	10/06/2020	5669380	0	Door Lock, Ignition Barrel		Supply & fit ignition barrel & both exterior door handles.	0388740	\$2,401.94
S-202	18/05/2020	538903	0	D - 300k		duplicated job card		
T-75	14/05/2020	0	0	New, Rotate		4 New Goodyear tyres 4 tyre disposal POS 3, 4, 5, 6 rotated to axle 7, 8, 9, 10	140879	\$2,366.00
R-196	14/05/2020	523668	0	Defect, Headlights, Self Clearing	Dylan	Dylan 0.5 hour , supply and fit H7 headlight globe DEFECT HVN0548689 CLEARED (self clearing).		\$63.46
S-183	04/05/2020	0	0	A - Fortnightly		3 litres engine oil added		\$159.50
T-57	24/04/2020	0	0	New		2 Goodyear 2 Tyre disposal	140683	\$1,313.00
R-176	24/04/2020	538157	0	Drive belts		Replace drive/fan belt at Marulan Replace alternator/aircon belt, tensioners & idler pulleys in workshop 1 x 1942517 tensioner asm. 1 x 1695242 tensioner asm. 1 x 1811819 idler pulley Steer tyres replaced by HTS 1 x 1884148 fan belt 1 x 1812162 alternator belt Marulan done by Tony, Jack, Gus Workshop done by Michael, Dylan, Jack		\$1,193.20
R-163	16/04/2020	0	0	Engine Light		Link to job R436 Truck taken to Inland Truck Centre - Wagga, for diagnosis & repair. Found faulty ECU caused by leaking windscreen		
S-158	13/04/2020	0	0	A - Fortnightly				\$159.50

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-38	10/04/2020	0	0	Puncture		puncture repair	140227	\$77.00
R-143	31/03/2020	530578	0	Fuel Tank	Yard	R/h fuel tank bung resealed		\$204.63
S-84	31/03/2020	530578	0	B - 50k	Dylan, Gus, Mick	R/h fuel tank bung resealed Done by Gus, Michael, Dylan Check parts used - dafs use 2 x fuel filters		\$553.89
S-461	25/02/2020	0	0	A - Fortnightly	Yard			\$473.00
S-9	10/02/2020	490478	0	B - 50k				\$602.33
O-7	07/02/2020	0	0	CTP				\$1,957.13
S-708	14/01/2020	477118	0	A - Fortnightly				\$165.00
S-332	09/01/2020	475198	0	A - Fortnightly	Yard			\$165.00
S-958	24/12/2019	465663	0	A - Fortnightly				\$154.00
S-976	17/12/2019	459458	0	A - Fortnightly				\$118.25
S-49	04/12/2019	451541	0	C - 150k	Yard	Replace 2 x wiper blades. Replace bolts. Solenoid RH side Gearbox top		\$1,196.28
S-1085	19/11/2019	440112	0	A - Fortnightly		Replace LR hub seal (no entered) LH inner fog light globe. Add 6ltrs engine oil		\$201.69
O-45	04/11/2019	0	0	Non Repair (Cosmetic)		Wash exterior of truck	314900	\$160.00
S-1087	16/10/2019	418219	0	A - Fortnightly		1x 1914691 tail light lens LH		\$204.25
S-1088	30/09/2019	406152	0	B - 50k		change gearbox oil		\$847.02
R-481	30/09/2019			Defect, Self Clearing		Windscreen was replaced DEFECT CLEARED		\$484.00
S-1086	05/09/2019	0	0	A - Fortnightly		1x 186249 wiper arm. 1x H7 headlight globe. 2x 03.01568 hub gasket. 2x wiper blades		\$403.46
S-1399	21/08/2019	378682	0	A - Fortnightly				\$330.00
S-1398	16/08/2019	376210	0	A - Fortnightly				\$236.50

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-1624	11/07/2019	362555	0	B - 50k				\$847.02
S-1625	01/07/2019	356305	0	A - Fortnightly				\$165.00
S-1668	11/06/2019	344506	0	A - Fortnightly		Tighten front right u-bolts (could not get to outer LHS) 1x ad blue filter & ad blue filler cap		\$579.73
S-1623	04/04/2019	304180	0	A - Fortnightly				\$187.00
S-1667	29/03/2019	300509	0	A - Fortnightly		2.5ltr oil		\$176.28
R-896	27/03/2019			Headlights		Changed LH head light - roo damage		\$737.33
S-1669	11/03/2019	289036	0	A - Fortnightly				\$165.00
104 Records							TOTAL:	\$130,697.51