

W/O No	Asset No	Asset Description	Description	Job Type	Finished Date/Time	Downtime	Repair Time	Component Code	Department	Parent Asset
11587	MS12	TUFF LOW LOADER	Flat Tyre. 09.10.2023_MWR_WA - Remove inside tyre. Repair damaged valve stem and inflate tyre. (SM)	Repairs	10/10/2023	1	3		GRV	MSS Other Assets
11490	MS12	TUFF LOW LOADER	General maint. 24.09.2023_MWR_WA - Pick up truck and float from GRV. Check over and adjust tyre pressures. (SM)	Repairs	24/09/2023	2	2		GRV	MSS Other Assets
11253	MS12	TUFF LOW LOADER	Hyd Oil Leak. 20.08.2023_MWR_ES - WHEN NORTH WERE LOWING THE RAMPS, OIL POURED OUT OF LH SIDE, FOUND 6 OUT OF 8 HYD HOSES BUSTED OFF COUPLINGS UNDER NEATH THE LH SIDE RAMP, LOOKS LIKE TRAILER WASN'T RASIED OR TOOK IT OFF A BANK WHEN LAST USED. REMOVED ALL 8 HOSES, RETURNED TO MHF, GOT THEM TO REMOVE THE FITTINGS IN THE MIDDLE AND MAKE 4 LONG COMPLETE HOSES FROM VALVE BANK TO CYL. RETURNED TO MNM, FITTED & TESTED. TOPPED UP HYD OIL (SM)	Repairs	20/08/2023	4	4		MNM	MSS Other Assets
10923	MS12	TUFF LOW LOADER	General maintenance. 01.07.2023_MWR_WA - Wash out deck widening slides. Repair bent control access door. Grease ramps pivots. (SM) 30.06.2023_MWR_WA - Set up trailer on wash pad for cleaning deck widening guides and greasing ramps. (SM)	Repairs	1/07/2023	3	3		Workshop Mbh	MSS Other Assets
10857	MS12	TUFF LOW LOADER	Check Over. 19.06.2023_MWR_WA - Check and replace 1x Pirelli ST01 tyre on new rim. Adjust all tyre pressures. (SM)	Repairs	19/06/2023	2	2		Workshop Mbh	MSS Other Assets
10856	MS12	TUFF LOW LOADER	Float Move 19.06.2023_MWR_WA - Onsite float move for MNM job no 2420 (SM)	General	19/06/2023	0	2.5		MNM	MSS Other Assets
10528	MS12	TUFF LOW LOADER	Replace Battery & install DC-DC charger. 03.05.2023_MWR_WA - Fabricate stabilizer for solar panel and mount for dc/dc charger. Modify wiring at front of trailer for charger operation. Fit new battery and clamp. Replace cables for battery and power pack. (SM) Clean out rear control compartment. Wash out deck spread guides 28.04.2023_MWR_SP - Fit new toolbox latch to RHS tool box. Fabricated mount for solar panel on front of trailer and fit solar panel. Greased and inspected trailer while it was on wash pad. (SM) 26.04.2023_All parts in stock (SM) 19.04.2023_Parts ordered from 4wd Supercentre, TOLL Tracking #8868520062705 and 8868490062927. (SM)	Repairs	3/05/2023	0	13		Workshop Mbh	MSS Other Assets
10432	MS12	TUFF LOW LOADER	Needs 4x new Wheel Rims. 14.04.2023_MWR_SP - Received new wheels and tyres to work shop, Fitted 2x tyres to wheels and fit to trailer as spares, other two wheels are in stock without tyres and all tyres purchased for trailer are fitted. (SM) 13.04.2023_Parts in stock. (SM) 05.04.2023_Ordered from Truckline (SM)	Repairs	14/04/2023	2	2		Workshop Mbh	MSS Other Assets
10390	MS12	TUFF LOW LOADER	Fit new flag holders. 10.04.2023_MWR_WA - Fabricate and fit new wide load flag holders. Replace broken poles to wide load flags. Close up float and park up. (SM)	Repairs	10/04/2023	2.5	2.5		Workshop Mbh	MSS Other Assets
10383	MS12	TUFF LOW LOADER	Wash out deck slides. 09.04.2023_MWR_WA - Wash out deck slides. (SM)	Repairs	9/04/2023	0.5	0.5		Workshop Mbh	MSS Other Assets
10375	MS12	TUFF LOW LOADER	Fit up tyres. 07.04.2023_MWR_SC - Fit up new tyres to spare rims for changeout. (SM)	Tyre/Track	9/04/2023	2	2		Workshop Mbh	MSS Other Assets
10306	MS12	TUFF LOW LOADER	Battery for Ramps(MS12) not working. MRF Request No 7383_MS4_GRV_02.03.2023. 25.03.2023_MWR_WA - Repair wiring to power pack solenoid control. (SM)	Repairs	25/03/2023	0	5.5		GRV	MSS Other Assets
10303	MS12	TUFF LOW LOADER	Tyre carrier loose. 25.03.2023_MWR_SC - Tyre carrier loose, cut of existing bolts, cleaned up mounts, re-bolted. (SM)	Repairs	25/03/2023	1	1		Workshop Mbh	MSS Other Assets

9726	MS12	TUFF LOW LOADER	Both side folding ramp pivot pins seizing up need to remove pins and clean lube. 25.03.2023_MWR_SP - Set up trailer. Drill out and fit grease nipples to ram and pivot pins. (SM) 04.12.2022_MWR_RC - Clean around ramp pins remove 3x pins, pins are very seized in r/h top pin would not press out with our small pressing equipment. will need larger ram or oxy lance. (SM)	Repairs	25/03/2023	0	10		Workshop Mbh	MSS Other Assets
10154	MS12	TUFF LOW LOADER	Flat Tyres. 02.03.2023_MWR_SC - Set up and replace 1 tyre. Re-inflate 1 tyre. (SM)	Repairs	2/03/2023	2	2		GRV	MSS Other Assets
10083	MS12	TUFF LOW LOADER	COI due , booked for 21/02/2023 8:45am 21.02.2023_MWR_WA - Carry out COI inspection. (SM) 21.02.2023_COI attached, Passed inspection but noted starting to get movement in suspension swing arms and suggested straightening bent R/H tie rail. (SM) 20.02.2023_MWR_WA - Rewire R/H rear lights and rear side lights. Replace 2 tyres. Wash and clean trailer. (SM) 19.02.2023_MWR_WA - Set up trailer. Grease and adjust brakes. Repairs to trailer lights. (SM)	Repairs	21/02/2023	10	10		GRV	MSS Other Assets
10020	MS12	TUFF LOW LOADER	Blown Tyre. 09.02.2023_MWR_SC - Tyre blown when trailer returned from site. R+R tyre. (SM)	Tyre/Track	9/02/2023	1	1		GRV	MSS Other Assets
9909	MS12	TUFF LOW LOADER	New chains required for MS12. 20.01.2023_Chains received by Wayne (SM) 06.01.2023_Ordered from Truckline (SM)	Repairs	25/01/2023	0	0		GRV	MSS Other Assets
9774	MS12	TUFF LOW LOADER	Chains Missing. 16.12.2022_Seán found more chains in the workshop, no need to order more at this time. (SM) 09.12.2022_MWR_WA - Trailer is missing tie down chains? We will need 2x load binding chain kits. I think 8mm please check previous orders (SM)	Repairs	16/12/2022	0	0		MNM	MSS Other Assets
9745	MS12	TUFF LOW LOADER	Deck Expansion not working. 15.12.2022_MWR_RC - Found deck slides and deck jammed and very dry and rusty. Freed up deck all the way out and cleaned and lubricated slides worked slides in and out a few times all ok. Tested pump pressure - 2900psi stall. Tested all rams for bypassing, oil didn't bypass. Battery was only six volts and circuit breaker was tripping out when pump stalled out. Battery came good with truck running and deck sliding good. (SM) 13.12.2022_MWR_WA - Replace power pack battery. Replace Anderson plug at front of trailer. (SM) 10.12.2022_MWR_WA - Set up trailer to work deck widening. Lift/pull and maneuver deck to spread. Clean and diesel lube deck guides. Temporary fit ms75 battery. Widening still not working effectively. Set up deck at 3.5m for MNM to complete required task. This trailer is basically out of service. Hydraulic power pack needs replacing. We will need to separate extender decks from trailer assess slides and wear plates if any. Try to determine if there is a problem with slides and guides. Whilst deck is removed will definitely need to reseal/replace hydraulic cylinders possibly add extra cylinders. (SM)	Repairs	15/12/2022	0	9		MNM	MSS Other Assets
9743	MS12	TUFF LOW LOADER	Air Leaks. 09.12.2022_MWR_WA - Repair air leaks at brake connections. (SM)	Tyre/Track	9/12/2022	1	1		Workshop Mbh	MSS Other Assets
9742	MS12	TUFF LOW LOADER	Repair Oversize Flag mounts. 09.12.2022_MWR_WA - Repair oversize flag mounting. (SM)	Tyre/Track	9/12/2022	1	1		Workshop Mbh	MSS Other Assets
9741	MS12	TUFF LOW LOADER	2x Flat Tyres. 09.12.2022_MWR_WA - Set up trailer. Replace 2x tyres. (SM)	Tyre/Track	9/12/2022	2	2		Workshop Mbh	MSS Other Assets
9661	MS12	TUFF LOW LOADER	Deck not closing. 27.11.2022_MWR_WA - Wash out Deck slides. (SM)	Repairs	27/11/2022	0.5	0.5		Foxleigh	MSS Other Assets
9660	MS12	TUFF LOW LOADER	2x Flat Tyres. Replace two tyres on float	Tyre/Track	27/11/2022	2	2		Foxleigh	MSS Other Assets
9529	MS12	TUFF LOW LOADER	Flat Tyre. 13.11.2022_MWR_WA - Remove old blown tyre and replaced with new. (SM)	Tyre/Track	13/11/2022	0	0		Foxleigh	MSS Other Assets
9517	MS12	TUFF LOW LOADER	Deck not widening. 10.11.2022_MWR_WA - Clean and test deck widening/retract operation. (SM)	Repairs	10/11/2022	1	1		Foxleigh	MSS Other Assets

9376	MS12	TUFF LOW LOADER	GRV Brake Test due. 19.10.2022_MWR_SC - Perform brake test, complete, scan and submit paperwork. To keep inline with MS4 (SM)	External	19/10/2022	1	1		GRV	MSS Other Assets
9318	MS12	TUFF LOW LOADER	Leaking Hyd Hoses. 17.10.2022_MWR_WA - Travel to site remove two hyd hoses for R/H fold out ramp. Return to town get hoses made return to site and refit. Need to replace all other hyd hoses for ramps. Both side folding ramp pivot pins seizing up need to remove pins and clean lube. (SM)	Repairs	17/10/2022	2	2		MNM	MSS Other Assets
9265	MS12	TUFF LOW LOADER	6M Service, Grease & adjust brakes due 03/10. 03.10.2022_MWR_WA - Carry out 6mth inspection. Grease and adjust brakes. Minor repairs to weld cracks. Replace 3x tyres. Replace over size flag poles. (SM) 02.10.2022_MWR_WA - Set up trailer in work shop on ramps. Check over for cracks in frame and welds. Adjust ride height valve. (SM)	Service	3/10/2022	8	8		Workshop Mbh	MSS Other Assets
9160	MS12	TUFF LOW LOADER	Damaged Anderson plug. 13.09.2022_MWR_SC - When operating float yesterday noticed that Anderson plug to support float battery was smashed. Drove to site, replaced Anderson plug, test, ok. (SM)	Repairs	13/09/2022	1	1		GRV	MSS Other Assets
9149	MS12	TUFF LOW LOADER	GRV Brake Test due 30/08. 11.09.2022_MWR_SC - Perform brake test, complete, scan and submit paperwork. (SM)	External	11/09/2022	0	1		GRV	MSS Other Assets
9066	MS12	TUFF LOW LOADER	Repair Oversize flags. 06.09.2022_Flags repaired by Wayne (SM)	Repairs	6/09/2022	0	0		Workshop Mbh	MSS Other Assets
8874	MS12	TUFF LOW LOADER	Check over: 03.08.2022_MWR_WA - Carry out trailer and tyre checks pump up tyres (SM)	Repairs	3/08/2022	0	2		GRV	MSS Other Assets
8759	MS12	TUFF LOW LOADER	Remove worn and fit new tyre to rear left outer: 12.07.22_MWR_SCR_RC_cut away old jagged mud guard steel plate causing damage to tyres; find and repair corroded wiring for side clearance lights and rear tail lights, make and replace rear wiring loom.	Tyre/Track	15/07/2022	12	12		Workshop Mbh	MSS Other Assets
8777	MS12	TUFF LOW LOADER	Wiring for side clearance lights: 15.07.2022_MWR_RC_complete wiring for side clearance lights. (KD)	Repairs	15/07/2022	0	0		Workshop Mbh	MSS Other Assets
8512	MS12	TUFF LOW LOADER	GRV Brake Test; 03.06.2022_MWR_SC - Perform brake test, complete, scan and submit paperwork (SM)	External	3/06/2022	0	1		GRV	MSS Other Assets
8463	MS12	TUFF LOW LOADER	Damaged Tyres; 25.05.2022_MWR_RC - Fold up, clean and pack away chains for float after ms 77 move. Collect 4x tyres from Tyrepower fit 3x tyres to wheels ready for spares. (SM) 09.05.2022 - 4x tyres ordered through Tyrepower ex Brisbane (SM)	Damage	25/05/2022	0	1.5		GRV	MSS Other Assets
8456	MS12	TUFF LOW LOADER	Clean Slides; 23.05.2022_MWR_RC - Check and clean slides ready for ms15 transport. Free up 2x chain dogs (SM)	Repairs	23/05/2022	0	0.5		Workshop Mbh	MSS Other Assets
8179	MS12	TUFF LOW LOADER	Tyre Change; 18.03.2022_MWR_RC - Change out rear r/h tyre on trailer for new tyre and rim from spares on trailer. complete (SM)	Tyre/Track	18/03/2022	0	1		Workshop Mbh	MSS Other Assets
8154	MS12	TUFF LOW LOADER	GRV Brake test due, 13.03.2022_MWR_SC - Perform GRV brake test, scan and submit paperwork. (SM)	External	13/03/2022	0	1		GRV	MSS Other Assets
8105	MS12	TUFF LOW LOADER	Cracks in Ramps & RH Extender Hyd Cylinder has a bent rod. 13.03.2022_MWR_RC - Replace r/h tip cylinder on ramps , completed. (SM) 11.03.2022 - Part now in stock (SM) 04.03.2022_MWR_WA - Inspect and identify required hyd cyl. (SM) 02.03.2022_MWR_WA - Locate trailer in work shop. Extend and support ramps into position to carry out cracking repairs to R/H main ramp and extender ramp. Grind out and re-weld cracking as required. (SM)	Repairs	13/03/2022	0	11		Workshop Mbh	MSS Other Assets
8131	MS12	TUFF LOW LOADER	Inspection: 09.03.2022_MWR_RC - grease all point under float and inspect trailer for damage. topup rear l/h tyre , slow leak wet with detergent not found, complete (SM)	PM	9/03/2022	1.5	1.5		Workshop Mbh	MSS Other Assets

8117	MS12	TUFF LOW LOADER	Ramp power pack going flat. 06.03.2022_MWR_WA - Test charging to trailer battery (SM) 05.03.2022_MWR_WA - Fit and connect direct power supply through Anderson plug at turn table. (SM)	Repairs	6/03/2022	4	4		Workshop Mbh	MSS Other Assets
8095	MS12	TUFF LOW LOADER	Checkover/clean/grease: 28.02.2022_MWR_SC/RC - Reversed float onto wash pad, spread deck, cleaned out all slides and pockets of dirt and debris, sprayed slides with anti-seize/dry lube, tested function, ok. Greased float, adjusted all tyre pressures, cleaned out control cabinet, fully washed float. (SM)	PM	28/02/2022	2	3.5		Workshop Mbh	MSS Other Assets
7965	MS12	TUFF LOW LOADER	Defected on its COI for some cracks at the 4th Axle, both sides in front of the trailing arm. 06.02.2022_MWR_WA - Remove from stands. Close up trailer reposition in yard. After welding repairs have been carried out (SM) 04.02.2022_MWR_WA - Set up trailer in yard for welding repairs by Metal Professionals. Jack up and remove wheels (SM) 01.02.2022 - Metal Professionals inspected and quoted on the repair. (SM) 01.02.2022 - COI Defect. (SM)	Repairs	6/02/2022	70	3		Workshop Mbh	MSS Other Assets
7954	MS12	TUFF LOW LOADER	Defected on COI, Brake imbalance all axles, Boosters overstocking.	Repairs	1/02/2022	0	2.5		Workshop Mbh	MSS Other Assets
7953	MS12	TUFF LOW LOADER	Defected on COI, Wheel bearing movement, 1st Axle: 01.02.2022_MWR_SC - Adjusted 2 front axle wheel bearings 1 Hr (SM)	Repairs	1/02/2022	0	1		Workshop Mbh	MSS Other Assets
7926	MS12	TUFF LOW LOADER	COI booked 01/02/2022 at 8:45am ay Hornery's: 01.02.2022_MWR_SC - Drove trailer to Hornery's, Inspection performed, failed on 4 minor components. (SM) 29.01.2021_MWR_SC/RC - grease and checks under float wash float and wash out float slides (SM)	QLD Tpt	1/02/2022	0	3		Workshop Mbh	MSS Other Assets
7818	MS12	TUFF LOW LOADER	Damaged Tyre: 11.01.2022_MWR_WA - Replace pos 14 tyre, 1x new tyre and new rim from store. (old rim can be reused), Pirelli ST01-215/75R17.5 (SM)	Tyre/Track	11/01/2022	0	1		Workshop Mbh	MSS Other Assets
7778	MS12	TUFF LOW LOADER	Flat Tyres: 16.12.2021_MWR_WA - Check tyre pressures. Replace 1x damaged tyre from store. (SM) 15.12.2021_MWR_WA - Set up truck/trailer for tyre repairs. (SM)	Tyre/Track	16/12/2021	0	4		Workshop Mbh	MSS Other Assets
7765	MS12	TUFF LOW LOADER	Flat Tyre: 10.12.2021_MWR_WA - Remove and repair flat tyre pos 5. Fit puncture plug. (SM)	Tyre/Track	10/12/2021	0	1		Workshop Mbh	MSS Other Assets
7671	MS12	TUFF LOW LOADER	Adjust Tyre Pressures: 08.12.2021_MWR_WA - Refit 2x tyre valve extensions (SM) 26.11.2021_MWR_WA - Adjust tyre pressures. Need to set up with tyre valve extensions for missing from inside tyres. (SM)	Repairs	9/12/2021	0	0.6		Workshop Mbh	MSS Other Assets
7764	MS12	TUFF LOW LOADER	Damage to Oversize Sign: 08.12.2021_MER_SC - Repair bent oversize signs mrf 5259 complete. (SM)	Damage	8/12/2021	0	0.5		MSM	MSS Other Assets
7758	MS12	TUFF LOW LOADER	Needs 4 new rims: 08.12.2021_MWR_WA/SC - Fit new tyres to rims mfr 5028 complete. 4x new tyres/rims. Replace pos 13 tyre with spare. 1x new tyre to spare rim. Refit 2x tyre valve extensions. (SM) 27.10.2021 - Sean confirmed parts arrived. (SM) 26.10.2021 - ordered from Truckline. (SM)	Repairs	8/12/2021	0	6.5		Workshop Mbh	MSS Other Assets
7703	MS12	TUFF LOW LOADER	GRV Site Intro due 01/12/2021: 02.12.2021_MWR_SC - Perform GRV annual inspection and paperwork. Scan and place in the GRV tray. 0.5 Hrs (SM)	Compliance	2/12/2021	0	0.5		GRV	MSS Other Assets
7702	MS12	TUFF LOW LOADER	MNM Site Intro due 01/12/2021: 02.12.2021_MWR_SC - Perform MNM annual inspection and paperwork. Scan and place in the MNM tray. 1.5 Hrs (SM)	Compliance	2/12/2021	0	1.5		MNM	MSS Other Assets
7670	MS12	TUFF LOW LOADER	Cracked L/H extender ramp hyd cyl mount: 26.11.2021_MWR_WA - Finish weld repair on l/h extender ramp. (SM) 25.11.2021_MWR_WA - Repairs to hyd cylinder mounting bracket L/H extender ramp. (SM)	Repairs	26/11/2021	0	4		Workshop Mbh	MSS Other Assets

7669	MS12	TUFF LOW LOADER	Needs new Power Pack (to spread deck): 25.01.2022 - Wayne advised to close out (SM) 26.11.2021_MWR_WA - Wash out deck slides. (SM) 25.11.2021_MWR_WA - Carry out hydraulic pressure tests on power pack. (SM) 17.10.2021_MWR_WA - Power pack battery was replaced a few weeks ago. Im sure a MWR was sent. The system operation and power pack was used today and appears to be working correctly. (SM) 07.09.2021 - Need to discuss replacement options with Sean. (SM)	Repairs	26/11/2021	0	2		Workshop Mbh	MSS Other Assets
7540	MS12	TUFF LOW LOADER	Tyre with Low Tread (Monitor): 04.11.2021_MWR_SC - Swapped tyre off of rack onto pos 8 outer tyre. 0.5 Hrs (SM)	Corrective	4/11/2021	0	1		Workshop Mbh	MSS Other Assets
7539	MS12	TUFF LOW LOADER	Requires More Hi-Vis Tape along the sides: 04.11.2021_MWR_SC - Removed existing tape, fitted new hi-vis tape to trailer. 1 Hr (SM)	Corrective	4/11/2021	0	1.5		Workshop Mbh	MSS Other Assets
7437	MS12	TUFF LOW LOADER	Replace 4 tyres: 21.10.2021_MWR_SC - Noticed 4 X tyres with wire sticking out and 1 has had sidewall failure. R+R Tyres, rotated others to suit wear. (SM)	Tyre/Track	21/10/2021	0	2.5		Workshop Mbh	MSS Other Assets
7196	MS12	TUFF LOW LOADER	Oversize Sign Damaged: 17.10.2021_MWR_WA - Fabricate mountings and replace rear oversize signs. Mrf 4309 wa-2hr (SM) 07.09.2021 - Clay - still usable at the moment, left is fine, right is bent, hold off until worse?. (KD) 01/09/2021 - Ordered from Truckline, ex Brisbane, MEX Po 687. (SM) 14.07.2021 - Sean - need to look at redesigning system, it's a continual issue. Will think about it this swing. (KD)	Damage	17/10/2021	0	2		Workshop Mbh	MSS Other Assets
7159	MS12	TUFF LOW LOADER	Trailer Inspection: 17.10.2021_MWR_WA - Replace oversize flags mrf 4619 wa-1hr (SM) 08/09.2021 - SC confirmed parts in stock. (SM) 07.09.2021 - Clay - hasn't arrived. (KD) 01/09/2021 - Ordered from Truckline, MEX Po 687. (SM) 18.08.2021_MWR_SC/WA - Performed weekly inspection on trailer, Found 4 Clearance lights not working, repaired. Requires 2 X sets of Oversize flags. (SM) 18.08.2021_MWR_SC/WA - Performed weekly inspection on trailer, Found 4 Clearance lights not working, repaired. Requires 2 X sets of Oversize flags. (SM)	PM	17/10/2021	0	5		Workshop Mbh	MSS Other Assets
7415	MS12	TUFF LOW LOADER	Change 2 Tyres: 16.10.2021_MWR_WA - Remove and fit new tyres pos 4 WA-2hr (SM) 14.10.2021_MWR_WA - Remove spare tyres from rack. Fit two new strip and replace tyres. Ready to replace on truck. (SM)	Tyre/Track	16/10/2021	0	5		Workshop Mbh	MSS Other Assets
7395	MS12	TUFF LOW LOADER	Broken Cylinder Mount: 11.10.2021_MWR_SC - Received call from Scott Doogan that MS12 ramp has a broken cylinder mount. Trailer has arrived back in yard, prepped and welded mount back in place. Test function, perfect. We need to keep an closer eye on the cracks/wear on MS12 When Possible. (SM)	Repairs	11/10/2021	0	2.5		Workshop Mbh	MSS Other Assets
7336	MS12	TUFF LOW LOADER	GRV Brake Test Due 26/09 02.10.2021_MWR_CD - complete brake test for GRV, complete paperwork. (SM)	External	2/10/2021	0	0.5		GRV	MSS Other Assets
7335	MS12	TUFF LOW LOADER	MNM Brake Test Due 26/09: 11.10.2021 - Shane advise stickers received. (SM) 07.10.2021 - Nikki - MS12 Brake Test submitted 4/10/21 (SM) 02.10.2021_MWR_CD - complete brake test for MNM, complete paperwork. (SM)	External	2/10/2021	0	1		MNM	MSS Other Assets
7168	MS12	TUFF LOW LOADER	Trailer ramps and deck close not working: 22.08.2021_MWR_WA - Pick up and replace battery to hydraulic power pack. (SM) 21.08.2021_MWR_WA - Inspect loss of power to electric power pack. Found battery faulty. (SM)	Repairs	22/08/2021	0	2.5		Workshop Mbh	MSS Other Assets
7158	MS12	TUFF LOW LOADER	Split Deck won't close. 18.08.2021_MWR_SC/WA - Greased, washed and tested spread action, once cleaned out, trailer would spread and retract fine. (SM)	Repairs	18/08/2021	0	1		MNM	MSS Other Assets

6983	MS12	TUFF LOW LOADER	Trailer won't extend on RHS: 14.07.2021 - needs regular washing, Gilly gave it a clean while he was here so can close out. Any issue with trailer not extending are generally due to mud, make sure operators clean it. (KD)	Repairs	14/07/2021	0	0.1		MNM	MSS Other Assets
6953	MS12	TUFF LOW LOADER	GRV Brake Test due 14/07: 10.07.2021_MWR_CD - Complete 3 monthly brake test for MNM and GRV. (SM)	External	10/07/2021	0	0.5		GRV	MSS Other Assets
6952	MS12	TUFF LOW LOADER	MNM Brake Test due 14/07: 10.07.2021_MWR_CD - Complete 3 monthly brake test for MNM and GRV. (SM)	External	10/07/2021	0	1		MNM	MSS Other Assets
6446	MS12	TUFF LOW LOADER	Turntable has lots of play in it. 26.05.2021_MWR_CD/WA - Prep skid plate ready to be mounted, fit new bushed into skid plate mounts onto trailer, cut down pin retainer bolts, fit skid plate to trailer. Fit and tension mounting pins, refit all other removed components (SM) 25.06.2021_MWR_WA - Santrax- carry out build up and line boring of turn table pivot point mounts. 8hr on delivery note 16007. SJ welding- pick up turn table pad to carry out pivot point mounting repairs. (SM) 23.06.2021 - Simon Texted, "all good for Lineboring Friday, will pick up the turntable Friday and have. it back to the workshop Saturday afternoon." (SM) 22.06.2021 - Conformed the work with Simon, scheduled for Friday 25/06. (SM) 21.06.2021 - Simon form SJ Welding phoned, \$2470+ gst for the line boring etc. (SM) 16.06.2021_MWR_SC - Cleaned, inspected and reported turntable pivot issue. (SM) 15.06.2021_MWR_CD/WA - Set up for SJ welding to lance turntable pin out . SJ's carry out pin lancing and removal. (SM) 10.06.2021 - SJ Welding booked for Tuesday 15/06 pm. (SM) 09.06.2021 - Wayne, will liaise with Steve to get SJ out to lance the pins. (KD) 03.06.2021 - Approved quote from SJ welding to Lance pins. 29.05.2021_MWR_WA - Attempt to remove both front and rear skid plate pins, find that both pins seized into trailer boss, apply heat to assist with removal, could not free up seized pins. both pins will need to be lanced. (SM) 19.05.2021 - Sean - might get it in this swing. (KD) 27.04.2021 - Sean, depends how hard the bushes are to get out, 4 hr job. Not an issue at the moment so schedule in when MS81 done. (KD) 17.04.2021 - WA advised parts arrived (SM) 13.04.2021 - Pin & Bushes ordered from Tuff Trailers. (SM) 10.04.2021_MWR_ES - Inspected turn table for movement/wear. found the skid plate pivot bushes worn & will need to be replaced. (SM) 10.04.2021 - MPF Ordered for MS4 but the fault is with the trailer (MS12) (SM)	Repairs	26/06/2021	0	13.5		MNM	MSS Other Assets
6821	MS12	TUFF LOW LOADER	Brake Slack adjusters worn: 16.06.2021_MWR_SC - Remove POS1+2 Slack adjusters, replace with new, grease and adjust brakes. (SM) 15.06.2021_MWR_WA/CD - Set up trailer in shop remove prime mover jack and support trailer change out slack adjusters. Need to replace 1st axel slack adjusters (parts here). (SM) 14.06.2021 - WA confirmed parts in stock. (SM) 10.06.2021 - Ordered from Multispares (part# G22-5020BENDIX). (SM)	Repairs	16/06/2021	0	6		Workshop Mbh	MSS Other Assets
6743	MS12	TUFF LOW LOADER	3 Month Service Due now: 29.05.2021_MWR_CD/WA - Fabricate hub nut sockets, adjust wheel bearings on pos, 7,8 and 3. Prep and weld crack at pos 7. (SM) 28.05.2021_MWR_CD - Back trailer into workshop, jack up and place on stands. Insect trailer for faults. Found multiple cracks from metal fatigue. Also find 2x bearing to be adjusted and 1 tyre with major side wall crack. (SM)	PM	29/05/2021	0	6		Workshop Mbh	MSS Other Assets
6624	MS12	TUFF LOW LOADER	Replace/Rotate Tyres: 29.05.2021_MWR_CD - Strip and fit new tyre to pos 4 outer due to major side wall spit, strip and fit x2 new tyres to pos 3 (SM) 18.05.2021 - Tyres ordered from Freedom (SM) 11.05.2021 - Sean requested 8x new tyres be ordered for this. (SM) 11.05.2021_MWR_SC/ES - Removed Pos 7+8 inner and outer tyres, replaced tyres on rims, fitted runout tyres to pos 6 Torqued wheels. Truck had a blowout on return from Poitrel, will use a spare off the rack to replace. (SM)	Tyre/Track	29/05/2021	0	8		Workshop Mbh	MSS Other Assets

6718	MS12	TUFF LOW LOADER	(Done)Tyre Audit - complete an MWR with the the tyre size, quantities (steer/drive, specifying tyres fitted and any spares stored on the vehicle) and brand / model: 25.05.2021_MWR_SC - Tyre Audit, P1 to P8 I+O- Pirelli ST01 X 215/75R17.5. Spares 4 X Pirelli ST01 X 215/75R17.5 onboard. (SM)	Tyre/Track	25/05/2021	0	0.5			MSS Other Assets
6720	MS12	TUFF LOW LOADER	Oversize Signs need fixing. 25.05.2021_MWR_ES - Installed new oversize signs, reason old ones are damaged is due to leaving them folded down when dropping the ramps which causes it to get caught on the hoses then rips the sings. Had to fab up brackets so the signs release from the magnet when lowering the ramps. Painted & installed with hose clamps from MHF invoice. Tested ramp function. Cleaned up work area, parked trailer back up. (SM) 17.05.2021 - Parts ordered and shipped today from Multispares. (SM) 07.05.2021 - Signs ordered from Multispares. (SM) 06.05.2021 - Sean advised new signs needed. (SM)	Repairs	25/05/2021	0	4		MNM	MSS Other Assets
6499	MS12	TUFF LOW LOADER	GRV Brake Test due 22/04. 20.04.2021_MWR_CD - Complete break test complete all paper. (SM)	External	20/04/2021	0	0.5		GRV	MSS Other Assets
6493	MS12	TUFF LOW LOADER	MNM Brake Test due 22/04. 20.04.2021_MWR_CD - Complete break test complete all paper. (SM)	External	20/04/2021	0	1		MNM	MSS Other Assets
6447	MS12	TUFF LOW LOADER	RH Side Lights on float not working. 10.04.2021_MWR_ES - Front half of the RH side trailer clearance lights were out. investigated found broken wiring. repaired. tested working. (SM) 10.04.2021 - MRF Raised for MS4 but the fault is with the trailer (MS12) (SM)	Repairs	10/04/2021	0	1		Workshop Mbh	MSS Other Assets
6343	MS12	TUFF LOW LOADER	Re-glue Deck Rubber. 29.03.2021_MWR_SC - Deck rubber has partially come unstuck after MS81 move, lifted up rubber, cleaned and glued down rubber. (SM)	Repairs	29/03/2021	0	0.5		Workshop Mbh	MSS Other Assets
6342	MS12	TUFF LOW LOADER	RH Sidelights on float out. 29.03.2021_MWR_ES - RH Clearance light are not working, were on MS4 mrf # 3765, repaired wire feed at rear of trailer, test lights, ok. (SM)	Repairs	29/03/2021	0	1		Workshop Mbh	MSS Other Assets
6271	MS12	TUFF LOW LOADER	Cracks around Pos #4 & #8 suspension arm brackets. 19.03.2021_MWR_WA - Remove pos 8 wheels. Grind out where possible cracks in suspension brackets clean surfaces and re-weld. Prep and re-weld (previously welded) cracks at frame where air bag suspension mounts. (SM) 18.03.2021_MWR_WA - Position trailer in shed on ramps. Identify cracks grind out and weld cracking area as best as possible in 1 to 4 axles. Identify and grind/weld cracks in trailer support frame (SM) 17.03.2021_MWR_CD - Thoroughly wash down trailer and inspect all suspension for cracks and fatigue signs. (SM)	Repairs	19/03/2021	0	13.5		Workshop Mbh	MSS Other Assets
6266	MS12	TUFF LOW LOADER	Replace tyre & adjust pressures. 16.03.2021_MWR_ES - Found flat tyre on float, Remove and replaced with runout tyre off rack. Adjusted pressures in 2 X doey tyres. (SM)	Tyre/Track	16/03/2021	0	1		Workshop Mbh	MSS Other Assets
6160	MS12	TUFF LOW LOADER	Cracks in loading ramp. 03.03.2021_MWR_WA/CD - Set up trailer in W/Shop remove, hyd hoses and wiring to access cracked framing and welds at L/H ramp hinge point on trailer. Grind out cracks, prep and weld framing and gussets for hinge point. Repaint and reassemble hoses/wiring. Remove 1 hinge pin to inspect wear in pin and bearing. (SM)	Repairs	4/03/2021	0	11.5			MSS Other Assets
6169	MS12	TUFF LOW LOADER	Deck Slides. 04.03.2021_MWR_CD - Clean out all deck slides to allow deck to open and close freely. (SM)	Wash	4/03/2021	0	0.5		Workshop Mbh	MSS Other Assets
6118	MS12	TUFF LOW LOADER	Remove Verizon Tracker. 27.02.2021_MWR_ES - Remove Tracker (SM)	Verizon	27/02/2021	0	0.5			MSS Other Assets
6052	MS12	TUFF LOW LOADER	RH bottom tail light in/op. 15.02.2021_MWR_ES/WA - Inspected wiring, found broken wires, cut out bad wiring & connected. tested all working. (SM)	Repairs	15/02/2021	0	1		Workshop Mbh	MSS Other Assets

5972	MS12	TUFF LOW LOADER	Float Deck will not spread, slides blocked. Battery Flat. 06.02.2021_MWR_CD - Spread float to max width, wash out all deck slides, retract float deck multiple times and wash out again. Test ok (SM) 05.02.2021_MWR_CD - Travel to MNM and locate machine onsite 1.0hr. Find that trailer batter that powers hydraulic power pack had boiled and popped, replace battery with deep cycle battery (N70T) out of C32, assist trailer widening process with crowbar. Will need to wash out deck slides 1.0hr (SM)	Repairs	6/02/2021	0	4.5		MNM	MSS Other Assets
5845	MS12	TUFF LOW LOADER	COI 13 January 20201 (due 10 January 2021): 27.01.2021 - MTC have signed off, new defect notice attached. Emailed to central compliance and requested COI. COI issued attached. (KD) 25.01.2021 - Steve is going to follow up with Black. Got no response so arranged for MTC to do it. 22.01.2021 - compliance emailed back to say BDS are not a registered AIS and we have to take it somewhere else. Looked online - Black diesel services in Moranbah can do them, phoned and left a message for Andrew Black. (KD) 22.01.2021 - emailed defect notice to central compliance and requested COI ne emailed. 21.01.2021 - Ben from BDS has signed off on the Defects (SM) 20.01.2021 - I called Ben from BDS, he'll swing past the workshop tomorrow afternoon to sign off on the COI Defect repairs (SM) 15.01.2021_MWR_ES - Set up trailer on wash pad, inspect brakes & adjust, grease slack adjusters & scams. Inspect lights, no brake lights, inspected & found incorrect wiring on trailer plug, brake light wire was in the wrong pin. Corrected the wiring, reinstalled trailer plug. tested. RH side clearance light not working, found broken wiring, repaired. 3rd axle brake lines have been rubbing & one had been joined, travelled to MHF for new hose & clamps. fitted & tested. (SM) 12.01.2021_MWR_CD - Pre COI check, grease, adjust brakes, check lights, general check over 1.5hrs (SM) 08.01.2021 - Booked QLD COI inspection for Mackay, 1.15 pm. Zac is flying in on Tuesday so will take it to Mackay (emailed Toby to confirm OK), need to communicate with him. Phoned QLD transport - no need to seek an extension of time, only necessary if we want payment details, because it's booked within the 2 months of original date and there is an inspection due it's AOK. (KD)	QLD Tpt	27/01/2021	0	6.5		Workshop Mbh	MSS Other Assets
5896	MS12	TUFF LOW LOADER	Both Position 3 tyre blew. 23.01.2021_MWR_CD - Strip blown tyres off rims, fit 2 new tyres to rims and put back on spare tyre rack on gooseneck. 1.5hrs (SM) 22.01.2021_MWR_CD - Both tyres on pos3 blew while leaving MNM, get trailer off site to parking bay at from of mine. Replace both tyres with spares on gooseneck of trailer, travel back to workshop 2.0 (SM)	Tyre/Track	23/01/2021	0	3.5		MNM	MSS Other Assets
5898	MS12	TUFF LOW LOADER	Annual Inspection (to be done by 22/01/2021). 22.01.2021_MWR_CD - Complete brake test and annual inspections for MNM and GRV complete all paperwork, submit and scan. (SM)	Compliance	22/01/2021	0	1.5		GRV	MSS Other Assets
5897	MS12	TUFF LOW LOADER	Annual Inspection (to be done by 22/01/2021). 22.01.2021_MWR_CD - Complete brake test and annual inspections for MNM and GRV complete all paperwork, submit and scan. (SM)	Compliance	22/01/2021	0	1.5		MNM	MSS Other Assets
5846	MS12	TUFF LOW LOADER	11.01.2021 - Clay said flat tyre on float. (KD) : 12.01.2021_MWR_CD - Replace pos7 inner tyre 1.0hr (SM) 12.01.2021 - Clay fixing today. (KD)	Tyre/Track	12/01/2021	0	1		Workshop Mbh	MSS Other Assets
5664	MS12	TUFF LOW LOADER	3 month /125Hr Service: 29.11.2020_MWR_CD - Spread trailer deck and clean deck slides, grease trailer and adjust brakes, general check over, 2hrs. (SM)	Service	29/11/2020	0	2		Workshop Mbh	MSS Other Assets
5504	MS12	TUFF LOW LOADER	Replace 2 Tyres (RHS, front axle), General Check over trailer, Grease & adjust brakes. 01.11.2020_MWR_CD - Replace 2 Tyres (RHS, front axle), General Check over trailer, Grease & adjust brakes.(SM)	Tyre/Track	2/11/2020	0	3		Workshop Mbh	MSS Other Assets
5488	MS12	TUFF LOW LOADER	29.10.2020_MWR_CD: Asses and replace x4 tyres on LHS of trailer with new tyres in stock 2.0hrs	Tyre/Track	29/10/2020	0	2		Workshop Mbh	MSS Other Assets

5490	MS12	TUFF LOW LOADER	MNM & GRV 3mth Brake Test due 03/11/2020. 29.10.2020 - MS12_MWR_CD - complete 3 monthly brake test for MNM and GRV, complete and submit all paperwork 1.5hrs (SM) 20.10.2020 - MNM work order attached, also emailed to Sean direct. Emailed Nikki to ask due date. (KD)complete 3 monthly brake test for MNM and GRV, complete and submit all paperwork 1.5hrs	External	29/10/2020	0	1.5		Workshop Mbh	MSS Other Assets
5197	MS12	TUFF LOW LOADER	RHS ramp is jamming when sliding out: 02.09.2020_MWR_spread trailer deck to max width, pressure wash all slides and frame of trailer. rear ramp slides particually full of mud and gravel. 2.0 test deck after all slides had been cleaned, trailer returning and widening without fault. prep multipul suspension and frame cracks founds after cleaning trailer. repair cracks and paint after completion 3.5 27.08.2020 - Sean advised still needs to be looked at and will get Clay to look at it and report on in (MW) 15.08.2020 - Sean advised: schedule for Thursday 20/08 (Clay) (MW)	Repairs	2/09/2020	0	5.5		Workshop Mbh	MSS Other Assets
5157	MS12	TUFF LOW LOADER	Welds are cracking on trailer near ramps: 21.08.2020_MWR_prep and weld all visible cracks around rear of trailer 20.08.2020 - scheduled for tomorrow. Emailed Clay to confirm. (KD) 17.08.2020 - Sean advised: schedule for Friday 21/08 (Clay) (MW)	Repairs	21/08/2020	0	1.5		Workshop Mbh	MSS Other Assets
5084	MS12	TUFF LOW LOADER	Pos 3 air bag is leaking: 18.08.2020_MWR_Moved trailer to wash pad, washed down POS3 area. moved the trailer into the workshop, replaced pos 3 airbag. inspected for leaks. parked truck up. 06.08.2020_MWR_meanure airbags, get part number from all bags 06.08.2020 - Clay advised: 7 out of the 8 air bags are goodyear 566-24-3-038 (MW) 05.08.2020 - Mel to contact tuff. Only leaking at one position, should get a couple so we have one spare. (KD) 04.08.2020_MWR_Seansaid he will size them up.	Repairs	18/08/2020	0	4.5		Workshop Mbh	MSS Other Assets
5125	MS12	TUFF LOW LOADER	Rear over size sign damaged on rear the (size) sign: 16.08.2020_MWR_Modified sign mounting, fitted 2 magnets to sign to enable release when pressure gets too much. 05.08.2020 - Sean will put on the list. (KD) 30.07.2020 - Sean - has an idea about fixing with magnets so wouldn't bend. Will see if gets time this swing. (KD) 08.07.2020 - Sean - same old story, leave signs down when they lower the ramps, just bent, not need to be replaced or repaired. (KD)	Damage	16/08/2020	0	1		Workshop Mbh	MSS Other Assets
5091	MS12	TUFF LOW LOADER	Repair cracks and clean up air lines: 08.08.2020_MWR_prep multiple chassis and suspension cracks, weld up cracks and paint when cool 2.5 secure brake air hoses 5 06.08.2020 - Scheduled to repair at yard on Saturday, 08.08 - emailed Paul to confirm. (KD) 04.08.2020_MWR_Multiple Chassis cracks, marked with yellow paint.	Repairs	8/08/2020	0	3.5		Workshop Mbh	MSS Other Assets
5079	MS12	TUFF LOW LOADER	GRV and MNM brake test due 28/08/2020: 05.08.2020_MWR_perform 3 monthly brake test for MNM and GRV, complete and submit all paperwork 30.07.2020 - sent Sean the MNM work order. Also attached in MEX (MW) 30.07.2020 - Sean -will wait for MNM work order. (KD)	External	5/08/2020	0	1.5		Workshop Mbh	MSS Other Assets
5060	MS12	TUFF LOW LOADER	3 monthly service due on the 04/08/2020: 04.08.2020_MWR_Carried out 3 month service, Swapped out POS 4 tyres with new spare ones. carried out full chassis inspection for cracks. NOTES FOR FUTURE: Fire Extinguisher is missing its date stamp tag, Pos 3 air bag is leaking, Sean said he will size them up. Multiple Chassis cracks, marked with yellow paint. 03.08.2020_MWR_3 month service - Started 3 monthly service 1hr. Gave trailer a full clean down 1hr 30.07.2020 - Sean - Eddie will do this one. Will probably be a few MRFs come in on this one. 30.07.2020 - Sean -will get Eddie to do it, will also be some more repairs on that. (KD)	Service	4/08/2020	0	6		Workshop Mbh	MSS Other Assets

4965	MS12	TUFF LOW LOADER	<p>Electric motor for HYD on back of trailer not working properly: 03.08.2020_MWR_Electric motor, removed old motor & cleaned area. prepped & installed new one. had to modify the valve bolts to suit. added oil, tested 23.07.2020 - Sean confirmed part has arrived so this work can now be scheduled (KD). Eddie can do that one - 2 hrs. (KD) 22.07.2020 - Part has been sent with TNT on tracking number: 940322390 (MW) 21.07.2020 - Sean - schedule for Edward, will just give him a couple of tips. Not urgent but will fail eventually. 2hrs. (KD) 16.07.2020 - quote from Tuff \$1,001 sent to Kate/Craig for approval on Teams App. PO approved and sent to Tuff (MW) 14.07.2020 - sent reminder to Tuff that we have not received quote yet (MW) 09.07.2020 - added task to Teams App (MW). Asked Mel to talk to Tuff and get quote if possible on Powerpack. (KD) 08.07.2020 - Sean - it is working but need to look at in next couple of months. No identifiers on the motor at all - Sean has taken to MHF. Will need to talk to Tuff trailers. Sent email yesterday with images (attached). Reservoir is cracking as well, the pump and the reservoir os called a "powerpack" and come together. If we can get the same one it will save a lot cause won't need to change the vavles over. Only identifier is 0450 stamped on the base.</p>	Repairs	3/08/2020	0	2		Workshop Mbh	MSS Other Assets
4884	MS12	TUFF LOW LOADER	<p>Inspect ramp motor for slow operation: 29.07.2020_MWR_fitted solar panel, wired up & tested. 1.5hrs Helped load ms17 onto float 1hr 28.07.2020_MWR_Started to install the solar panel onto the trailer, installed wiring. had to stop and pack up due to the float being needed. Panel just needs to be bolted on & connected up then tested. 07.07.2020_MWR_Maneuvered trailer into workshop. Pulled apart ramp components, Charged and load tested battery- failed as expected. Removed ramp hydraulic powerpack, disassembled, found contamination/rust in commutator and bushes, cleaned up as best as possible, recommended new powerpack. Made a new mounting for the float battery, used the 1 good battery out of MS48. Reassembled and installed powerpack, made new cabling for battery. Test, ok. Still requires a solar panel for trickle charging. Power pack is certain to fail, still recommend a new powerpack 06.07.2020_MWR_Back trailer onto washpad, Spread and wash trailer, as covered in oil and dirt. 1.5 Hrs. Began inspecting wiring/hydraulic motor, removed battery, placed on charge, will test tomorrow morning. Found leaking airbag. Will continue works tomorrow. 27.06.2020_MWR_Inspect for ramp slow operation , found battery at rear failed load test, charged battery & tested again no good, will need to be replaced, i don't think they have been plugging in the power wire from cab to trailer. Which will cause the battery to full drain which over time kills them. I've placed stickers at multiple places to remind drivers to plug the wire in before use. or we look at a solar setup for that battery? 24.06.2020 - Scheduled for Ed while Sean on break. Estimate 4 hours with R2211 (KD)</p>	Repairs	29/07/2020	0	13		Workshop Mbh	MSS Other Assets
4885	MS12	TUFF LOW LOADER	<p>Left clearance lights not working on trailer: 07.07.2020_MWR_Replaced Trailer LHS park light harness, repairing other wiring that showed signs of fatigue. Fitted new trailer plug and Clearance light LHS. 27.06.2020_MWR_Inspected wiring on trailer, found between pos 5 & 7 broken wires that need repairing, also hanging wires under the IH ramp which need tidied up. ran out of time to finish repair.</p>	Corrective	7/07/2020	0	4.5		MNM	MSS Other Assets
4877	MS12	TUFF LOW LOADER	<p>Mount 175A Anderson plug to front of trailer, rewire if necessary: 27.06.2020_MWR_Made up mount for anderson plug for the front of the trailer, ended up having to rewire and extend wire & replacing anderson plug 24.06.2020 - Scheduled for Ed while Sean on break. Estimate 4 hours with R2212 (KD)</p>	Repairs	27/06/2020	0	1.5		Workshop Mbh	MSS Other Assets

4852	MS12	TUFF LOW LOADER	<p>Dogs missing for smaller chains: 24.06.2020_MWR_Supplied 4 X 10MM chain dogs, and 2 X 10MM chains to MS12. 24.06.2020 - Sean confirmed parts arrived and he will schedule this work today (MW) 23.06.2020 - PO sent to Truckline and parts should arrive into the workshop 24/06 (MW) 23.06.2020 - Approved quote. (KD) 22.06.2020 - Truckline quote is \$457.42 and readily available in Mackay so could them same day to our workshop. Sent Kate the quote for approval (MW) 22.06.2020 - sent email to Truckline asking to quote (MW) 17.06.2020 - Craig - will need them cause MS4 and MS12 will be used as operational kit so will need them. (KD) 21.05.2020 - Clay advised they are in MS64 which is in Toowoomba so we may need to get some for MS12 (MW) 23.04.202 - Clay is sure they are in MS64, he is pretty sure when Zac went to Toowoomba he put them in MS64. (KD) 17.04.2020 - emailed Blake to ask if they may have been moved to the other trailer with the new truck driver started. (KD)</p>	Repairs	24/06/2020	0	0		MNM	MSS Other Assets
4756	MS12	TUFF LOW LOADER	<p>Install Verizon GPS tracker: 06.06.2020_MWR_Installed wireless tracker onto frame of trailer, test, ok. (TRACKER NO. 3163136664)</p>	Verizon	6/06/2020	0	0.5		MNM	MSS Other Assets
4723	MS12	TUFF LOW LOADER	<p>MNM and GRV brake test due 12/06: 01.05.2020 - Clay completed on 29/05 - emailed to confirm that he scanned and emailed it to nikki and gave original to paul this morning. (KD) 29.05.2020_MWR_Complete 3monthly brake test for MNM and GRV 25.05.2020 - MNM work order added to request (MW) Rubber on deck has pulled out from bolts and torn after dozers load: 28.05.2020_MWR_Cut down RHS deck rubber 27.05.2020_MWR_Trim deck rubber on LHS of trailer 26.05.2020_MWR_Move trailer onto wash pad, wash mud and rocks off, degrease, steam clean. Move into yard. 2 Hrs Fit rubber to deck, wash rubber, use contact adhesive on both surfaces, allowing 5 minutes prior to pressing together. Use weights to press rubber down to deck. 5 Hrs Cut out chain holes in rubber once it has adhered. Begin trimming inside sheets. 2.5 Hrs 21.05.2020 - Sean advise we can do this on site so let's book it in but when not raining (MW) 20.05.2020 - spoke to Sean he will stop in at Bunnings to buy these items he needs for this job and will call from the trade desk to pay via credit card (MW) 20.05.2020 - Mel said link Sean sent through is only available at Bunnings Brisbane. Available in Mackay - Mel will call Sean and ask him to grab it on the way of he's ok with that. (KD) 08.05.2020 - Sean emailed link to contact adhesive from Bunnings, need degreaser and brushes for roller application. (KD) 27.04.2020 - parts added to the work order (MW) 24.04.2020 - parts being picked up today by Dan (MSS truck driver) and taken back to Workshop on Monday (MW) 23.04.2020 - asked supplier to call me to arrange the order (MW) 09.04.2020 - Craig definitely wants it done, will order rubber for next time truck is on TBA. (KD) 26.03.2020 - on hold cause not essential. (KD) 23.02.2020 - Craig has asked Sean to go ahead with rubber. Emailed Craig and he said do it in March when Spotto brings the machines down to Cameby, it can go on the backload to Moranbah. Emailed Mel to advise. (KD) 20.02.2020 - emailed quote to Sean to ask if he thinks it will work. Craig doesn't want it</p>	External	29/05/2020	0	1.5		Workshop Mbh	MSS Other Assets
4559	MS12	TUFF LOW LOADER	<p>3 Month service - grease, check tyre pressure, adjust brakes; check wheels and tyres; check lights; and anything else needed: 04.05.2020_MWR_Rotate numerous tires for longgeperity. Replace x2 tires 1.0. Tension all wheel nuts 1.0. Grease and adjust brakes check lights 05.02.2020 - scheduled for 02.05.2020 if time permits. (KD)</p>	Repairs	28/05/2020	0	13.25		Workshop Mbh	MSS Other Assets
4586	MS12	TUFF LOW LOADER	<p>3 Month service - grease, check tyre pressure, adjust brakes; check wheels and tyres; check lights; and anything else needed: 04.05.2020_MWR_Rotate numerous tires for longgeperity. Replace x2 tires 1.0. Tension all wheel nuts 1.0. Grease and adjust brakes check lights 05.02.2020 - scheduled for 02.05.2020 if time permits. (KD)</p>	Service	4/05/2020	0	3		Workshop Mbh	MSS Other Assets

4308	MS12	TUFF LOW LOADER	Valve extensions for inside wheels: 04.05.2020_MWR_Remove out outer tires and fit tyre valve extensions 10.03.2020 - followed up with another email to Craig. (KD) 26.02.2020 - emailed to Craig for approval: "This is the quote for Valve extensions for inside wheels on MS12. Approve or not? Sean said they have plastic ones in stock which he could use but Spotto doesn't like them and he's learnt that if Spotto doesn't like something he just breaks it so that's what will probably happen if we fit the plastic ones!" (KD) 25.02.2020 - Hoses24 quote for parts \$364.58 and stock will take 2-3 days. Quote sent to Kate for approval (MW) 25.02.2020 - asked Brad at Hoses24 to send through a quote (MW). 20.02.2020 - Sean says it is a reasonable request and hoses 24 has them, asked Mel to get quote. (KD)	Repairs	4/05/2020	0	3		Workshop Mbh	MSS Other Assets
4483	MS12	TUFF LOW LOADER	Extendable deck not working: 12.04.2020_MWR_Inspected deck, all slides are full of mud/grit. Drove onto washe pad, spread deck. Washed clean, lubricated slides. Tested, opens and fully closes. 1.5 Hrs	Repairs	12/04/2020	0	1.5		MNM	MSS Other Assets
4335	MS12	TUFF LOW LOADER	8 x tyres in rack need replacing and 2 x new rims: 12.04.2020_MWR_Checked pressures, loaded up spare tyres into rack, MRF Completed. 0.5 Hrs 07.04.2020 - order placed with Wises stock should be in be the end of the week (MW) 18.03.2020 - they can just put the rims with tyres on rack. 16.03.2020 - parts added to work order (MW) 13.03.2020 - Followmont Toowoomba depot (Eric) advised that the freight is sitting on a truck in Moranbah ready for delivery today (MW) 13.03.2020 - asked Mel to track. (KD) 11.03.2020 - Followmont tracking number for the 2x rims and tyres is: F4155541 (MW) 11.03.2020 - chased Wises Tyres for tracking number (MW) 11.03.2020 - asked Mel to get Followmont tracking number. (KD) 10.03.2020 - Wises are shipping the rims Wirth 2 tyres fitted today. (KD) 04.04.2020 - one tyre fitted and ready to ship, waiting for second tyre to arrive, should be there today. (KD) 02.03.2020 - order for 2 x rims and 2 x tyres to go onto rims placed with Wises, stock should arrive to their depot 03/03 (MW) 28.02.202 - quote comparison - Samios Tyres quote (Rims \$125 each and available, tyres Michelin \$506 but not available for up to a couple of weeks) Wises - \$482 inc for Michelin, rims \$168. \$320 pirellis. MTM - \$220 rims; \$540 michelins. Truckline - \$168 per rim. 27.02.2020 - Samios Tyres quote (Rims \$125 each and available, tyres Michelin \$506 but not available for up to a couple of weeks) =. Quote sent to Kate for approval (MW) 28.02.202 - quote comparison - Samios Tyres quote (Rims \$125 each and available, tyres Michelin \$506 but not available for up to a couple of weeks)Wises - \$482 inc for Michelin; rims \$168. \$320 pirellis. MTM - \$220 rims; \$540 michelins. Truckline - \$168 per rim. Asked Mel to get quote from Samios and Woods. Pretty Pleeaaaaaaase. (KD) 26.03.2020 - Truckline rim quote \$410.10 / compare price of Wises - \$168 per rim plus \$50	Tyre/Track	12/04/2020	0	0.5		Workshop Mbh	MSS Other Assets
4273	MS12	TUFF LOW LOADER	QLD Transport Inspection - 9.45am, 4 March 2020: need to rectify the following items by the 20/03/2020 (COI attached) - Brakes: adjust all brakes correctly to make operate equal and effective and no overstroking and slack adjusters at 90 deg to booster push rods when brake applied. 17.03.2020 - COI issued. 17.03.2020 - emailed signed defect notice too central.compliance.admin@tmr.admin.qld.gov.au and requested that COI be provided. (KD) 15.03.2020_MWR_Reversed trailer onto ramps, lifted up, adjusted brakes. 0.5 Hr 04.03.2020_MWR_Take to hornerys yard for coi. Wait in line for inspection. Inspect trailer. Return to workshop	Inspect	16/03/2020	0	2		Workshop Mbh	MSS Other Assets
4334	MS12	TUFF LOW LOADER	MNM site introduction: 15.03.2020_MWR_Perform brake test and complete MNM inspection 1.5 Hr	Corrective	15/03/2020	0	1.5		Workshop Mbh	MSS Other Assets
4333	MS12	TUFF LOW LOADER	GRV site introduction: 15.03.2020_MWR_Perform brake test and complete GRV inspection 1 Hr	Corrective	15/03/2020	0	1		Workshop Mbh	MSS Other Assets

4083	MS12	TUFF LOW LOADER	King pin needs inspection to check for movement: 25.02.2020_MWR_Remove old kingpin. Clean up old boss. Fit new kingpin and test hitch. ok 31.01.2020 - Mel got quote for new kingpin, \$730.57. Just a drop in job, 1/2 hour. Need to use a truck MS4 or MS45 to adjust turntable. 26.01.2020_MWR_Inspected kingpin, excess movement. Removed kingpin. Measured, shows signs of wear and damage. Recommend replacement, until we can get a new "Boss" welded into the skid plate.	Repairs	25/02/2020	0	2		Workshop Mbh	MSS Other Assets
4272	MS12	TUFF LOW LOADER	Trailer cracks in deck: 16.02.2020 - MSS arranged for SBSSE to repair as per attached invoice_Clean, prep & welkd up cracks in truck & float. 14.02.2020 - MSS arranged for SBSSE to repair as per attached invoice_Clean up work area & tools to move to another site. Travel to site to inspect D8 dozer & float for cracks. Move dozer to work area & move truck & float to suitable area to commence repairs.	Tyre/Track	16/02/2020	0	0		Workshop Mbh	MSS Other Assets
4172	MS12	TUFF LOW LOADER	LH deck widener lever not working all the time: 14.02.2020 - Clay - was just full of dirt, can close out. (KD) 31.01.2020 - could be electrical or hydraulic so 1/2 hour to assess. (KD)	Repairs	14/02/2020	0	0.01		Workshop Mbh	MSS Other Assets
4157	MS12	TUFF LOW LOADER	30000 KM service due and needs to be greased: 09.02.2020_MWR_complete 30000klm service, would recommend greasing trailer on a more regular basis	Service	9/02/2020	0	1		Workshop Mbh	MSS Other Assets
4156	MS12	TUFF LOW LOADER	Inox for dogs: 09.02.2020_MWR_supply tin of lubricant and parts for chain dogs	Repairs	9/02/2020	0	0		Workshop Mbh	MSS Other Assets
4155	MS12	TUFF LOW LOADER	LHS tail lights U/S again: 09.02.2020_MWR_find and repair wiring issues causing tail lights not to work	Corrective	9/02/2020	0	1		Workshop Mbh	MSS Other Assets
4154	MS12	TUFF LOW LOADER	New hub meter needed as current one is cracked; 09.02.2020_MWR_fit new hubmeter	Repairs	9/02/2020	0	1		Workshop Mbh	MSS Other Assets
4153	MS12	TUFF LOW LOADER	Plug for trailer lights needs replacing (photo attached): 09.02.2020_MWR_fit new trailer light socket	Repairs	9/02/2020	0	1		Workshop Mbh	MSS Other Assets
4152	MS12	TUFF LOW LOADER	Marker light RHS facing forward flickering: 09.02.2020_MWR_replace forward facing marker light	Repairs	9/02/2020	0	1		Workshop Mbh	MSS Other Assets
4151	MS12	TUFF LOW LOADER	Fit winch: 09.02.2020_MWR_Fit new spare tyre winch CM3000 blue	Capital	9/02/2020	0	2		Workshop Mbh	MSS Other Assets
4140	MS12	TUFF LOW LOADER	LHS tail lights U/S: 07.02.2020_MWR_Repair wiring fault for l/h rear tail lights	Corrective	7/02/2020	0	0.5		Workshop Mbh	MSS Other Assets
4139	MS12	TUFF LOW LOADER	Fit mud flaps x 2: 07.02.2020_MWR_Replace x2 mudflaps	Repairs	7/02/2020	0	1		Workshop Mbh	MSS Other Assets
4096	MS12	TUFF LOW LOADER	2 x rims need tyres: 02.02.2020_MWR_Strip 3 X tyres from rims, inspect rims, 1 rim is U/S as per previous MWR. Fitted 2 new Tyres to ok rims. Discarded other worn rim. 31.01.2020_MWR_Inspected tyres that had gone flat, causing excess wear on other tyres. Found excess wear / corrosion in rim. Causing tyre to go flat and put excess load onto other paired tyre. This causes blow outs and excess wear.	Tyre/Track	2/02/2020	0	2.5		Workshop Mbh	MSS Other Assets
4094	MS12	TUFF LOW LOADER	Tyre pressures need checking: 31.01.2020 - Sean - very simple job, Tools are at the workshop, any operator could do it (KD). Quote 1 hr - 3hrs depending on inflation for us to do. Sent text to Blake and asked if he wanted us or Spotto to do it, Blake responded he will ask Spotto to do. (KD)	Tyre/Track	31/01/2020	0	0		Workshop Mbh	MSS Other Assets

3132	MS12	TUFF LOW LOADER	Two strips of rubber to be fitted on each deck of the float and bolted down: 21.01.2020_MWR_Clean deck of trailer. Lay out new rubber matting. Cut to length. Mark and cut in all deck tie down points. Bolt rubber to deck 26.06.2019 - Sean - pirate brought some rubber in, but not a roll, it's in strips, so when we have some time we will deal with it. (KD) 07.06.2019 - Craig still wants it done, pirate has some smaller rubber, will schedule it on when the workshop has some time, all it needs is two strips cut, they won't be glued they'll sit on top of the deck, ratchet strapped on. (KD) 06.06.2019 - emailed Craig to see if still wants it done. (KD) 31.05.2019 - Adam - Craig said not doing it, Kate to check. 08.05.2019 - Adam will schedule - Pirate got right size rubber. Need to consider whether it will be glued. Grease at same time. 02.05.2019 - To be schedule in during May if time permits, low priority. Pirate got some but too wide. Craig is going to see if can get smaller rubber. Adam looking at whether it can be glued. Pirate is organising some conveyor rubber from MNM - two strips to be fitted on each deck of the float and bolted down.	PM	21/01/2020	0	4.5		Workshop Mbh	MSS Other Assets
4302	MS12	TUFF LOW LOADER	Recommendation - Trailer is in need of a wheel alignment: 09.01.2020 - wheel alignment done by Big Wheels in Toowoomba. 28.11.2019 - Wheel alignment not done because Big wheels found issues with suspension, they have given quote and need to book work in when back in Toowoomba. MSS has issued purchase order to Big Wheels. (KD) 26.11.2019 - Wheel alignment booked at Big Wheels in Toowoomba at 8am 28.11.2019. (KD)	Tyre/Track	9/01/2020	0	0		Workshop Mbh	MSS Other Assets
4095	MS12	TUFF LOW LOADER	Big Wheels Toowoomba Invoice: Repairs: replace front right hanger; repair S-cam tubes fit on front axle; replace front left hanger; had to remove both hangers to rebush axle; rebush front axle TMC bush's; replace bearings 1 side due to burn marks on bearings. Power down shock. Remove and replace shock absorbers - remove ad replace all shocks and safety straps; heat and cut frozen shock bolts; replace missing catch strap clips. Wheel alignment.		9/01/2020	0	0			MSS Other Assets
3914	MS12	TUFF LOW LOADER	Tyres - large chunks missing, metal showing: 24.11.2019 - Clay - changed 1 x new tyre, no new tyres on spare rack now so need to order 6 more. (KD) 22.11.2019: checked records and Sean changed one tyre on 16.11.2019 and did a service on 17.11.2019. Asked Clay to check whether this is a valid request. (KD)	Tyre/Track	24/12/2019	0	0		Workshop Mbh	MSS Other Assets
3906	MS12	TUFF LOW LOADER	Hook up float and prime mover: 02.12.2019_MWR_Requires to hook up float to prime mover, due to float operator Turbo running out of hours. Float is required first job in the morning to bring a digger back to site that has been booked in for a week....	General	2/12/2019	0	0.5		Workshop Mbh	MSS Other Assets
3818	MS12	TUFF LOW LOADER	LH tool box lock unserviceable: 17.11.2019_MWR_Welded LH toolbox lock, to enable closing of toolbox.	Repairs	17/11/2019	0	0.5		Workshop Mbh	MSS Other Assets
3817	MS12	TUFF LOW LOADER	20,000KM service due and greasing needs to be completed: 16.11.2019_MWR_Greased, adjusted brakes and inspected trailer. Repaired sidelight wiring, tightened loose leg bolt.	Service	17/11/2019	0	1		Workshop Mbh	MSS Other Assets
3813	MS12	TUFF LOW LOADER	Make tyre crane work - finish wiring: 16.11.2019_MWR_Made removable wiring loom for Tyre crane, to enable it to be used with both prime movers. Could not test, as control is in MS45.	Repairs	16/11/2019	0	1.5		Workshop Mbh	MSS Other Assets
3812	MS12	TUFF LOW LOADER	Tyres need changing: 16.11.2019_MWR_Replaced 1 X Tyre, completed.	Tyre/Track	16/11/2019	0	1		Workshop Mbh	MSS Other Assets
3811	MS12	TUFF LOW LOADER	Repair rear oversize sign: 16.11.2019_MWR_Repaired oversize sign by straightening out and reattaching to trailer, completed.	Repairs	16/11/2019	0	0.5		Workshop Mbh	MSS Other Assets

3773	MS12	TUFF LOW LOADER	Trailer not retracting correctly after being spread: 09.11.2019_MWR_drive to quarico to use pit, inspect for cracks and damage before traveling to cameby No major structural cracks found, cracks found in spread frames and slides, dirt built up in spread frames making float hard to close	Repairs	9/11/2019	0	2.5		Workshop Mbh	MSS Other Assets
3720	MS12	TUFF LOW LOADER	Flat tyre on float: 26.10.2019_MWR_Jack up float. Remove rim and flat tire. Replace with run-out tire. Retorque	Tyre/Track	26/10/2019	0	1		Workshop Mbh	MSS Other Assets
3677	MS12	TUFF LOW LOADER	Remove kingpin: 15.10.2019_MWR_Removed kingpin from trailer to enable easier hitching.	PM	15/10/2019	0	0.5		Workshop Mbh	MSS Other Assets
3667	MS12	TUFF LOW LOADER	Hub Meter not working: 11.10.2019. - Must be for MS12 - getting readings now. 10.10.2019 - Clay confirmed no hub meter installed. (KD)	Repairs	11/10/2019	0	0		Workshop Mbh	MSS Other Assets
3661	MS12	TUFF LOW LOADER	Clearance light out: FIXED in WORKORDER 3562 02.10.2019 - emailed Clay to check to see if he remembers doing it. (KD) 24.09.2019 - Sean - check with Clay, he may have fixed. (KD) 22.08.2019 - Clay / Sean low priority but needs to be done. Schedule in for service.	Repairs	2/10/2019	0	0		Workshop Mbh	MSS Other Assets
3598	MS12	TUFF LOW LOADER	Tyre/Track - Tyre/Track: REPLACE TYRE 24.09.2019_MWR_Removed tire off rack, replaced tire with stock. Needs 2 x tyres	Tyre/Track	24/09/2019	0	1		Workshop Mbh	MSS Other Assets
3525	MS12	TUFF LOW LOADER	Spare tyres for trailer needed: 15.09.2019_MWR_rotate and replace tyres. Fit up 3 knew spares and 1 runout 03.09.2019_MWR_Trailer dropped off with worn out tyres pos 4 axle. Replaced tyres with run outs and will wait to fit new tyres when time allows. Diagnosed fault with electrical power to deck widening solenoid. Repaired old wiring, test, ok.	Tyre/Track	15/09/2019	0	7		Workshop Mbh	MSS Other Assets
3562	MS12	TUFF LOW LOADER	Light not working 12.09.2019_MWR_find wiring fault for causing left hand side lights to not be working, assist crowy load machine	Repairs	12/09/2019	0	2		Workshop Mbh	MSS Other Assets
3503	MS12	TUFF LOW LOADER	Mudflap missing passenger side. 23.08.2019_MWR_do up list of things needed needed for site inspection, fit wheel nut indicators, Fit mud flap to L/H side -502 mrf, put new flags in toolbox -504 mrf, modify new over size signs to fold in middle fit to trailer, new landing legs fitter -502 mrf, fit new reflection tape to rear	Repairs	23/08/2019	0	6.5		Workshop Mbh	MSS Other Assets
3494	MS12	TUFF LOW LOADER	22.08.2019_DAY WORKS SHEET_fitted air bags, changed flat tyre 21.08.2019_MWR_back float into workshop, jack up and put on stands, go through jsea ans swi with Dave, remove air bag ready to fit new bag when it arrives 20.08.2019_MWR_jack up and place float on stands, find air leak (blown air bag),Remove and kink supply air hose Air bag	Repairs	22/08/2019	0	7		Workshop Mbh	MSS Other Assets
3479	MS12	TUFF LOW LOADER	14.08.2019_MWR_replace landing legs, weld on bottom support for side ways movment Legs on trailer have possibly been dragged/damaged on last use; LHS Landing leg bent, needs replacing	Damage	14/08/2019	0	4.5		Workshop Mbh	MSS Other Assets

3468	MS12	TUFF LOW LOADER	Inspect and repair: 10.08.2019_MWR_Replaced wheel bearing POS3, adjusted and greased all brake components. Replaced Hydraulic hoses, tidied up all hoses and cables using spiral wrap. Found Hole in airbag during trailer height test. Replaced airbag with one from stock. Rewired 7 pin plug on trailer. Measured landing legs for replacement. 07.08.2019_MWR_Began inspection. Greased, adjusted brakes, checked bearings, found U/S bearing, stripped down assembly, cleaned, ordered parts. Removed all damaged hoses, took to MHF for replacement. Repaired operator damage of oversize sign again. Sean found busted wheel bearing, has had to down the machine.	Repairs	10/08/2019	0	11.5			MSS Other Assets
3467	MS12	TUFF LOW LOADER	Trailer battery will not charge 06.08.2019_MWR_Inspect, made charge cable for trailer out of 12mm wire and 2 X 75 amp Anderson plugs, soldering all components together.	Repairs	6/08/2019	0	1.5		Workshop Mbh	MSS Other Assets
3408	MS12	TUFF LOW LOADER	16.07.2019_MWR_repaired revolving light wiring again; replaced POS 3 & 4 tyres & rims; repaired oversize sign brackets, straightened sign Flashing light isn't working	Damage	16/07/2019	0	3		GRV	MSS Other Assets
3375	MS12	TUFF LOW LOADER	Flashing light on trailer not working 09.07.2019_MWR_Repaired broken taillight and flashing light wiring. Checked operation - all OK. 08.07.2019_MWR_Checked over, full grease and adjust brakes. Rear flashing light not working. Traced wiring to broken wires from hydraulic hoses and wiring being dragged along road due to operators not waiting until suspension is up before driving off. Started to repair - called to breakdown.	Damage	9/07/2019	0	5			MSS Other Assets
3321	MS12	TUFF LOW LOADER	Carried out full grease and checkover. Gilly washed.	PM	18/06/2019	0	1.5		Workshop Mbh	MSS Other Assets
3237	MS12	TUFF LOW LOADER	16.05.2019_Sean rotated tyres, removed 2 x tyres and fitted. 15.05.2019_emaild Adam saying serviced on 30 March, asked how frequently should be inspected. 14.05.2019_MR_BM_emaild with photos of perished tyres on MS12.	Repairs	16/05/2019	0	0		Isaac Plains	MSS Other Assets
3127	MS12	TUFF LOW LOADER	04.04.2019_MWR_TPSC_Air leak under trailer ; Brake hose had been damaged, replace hose and fitting, test ok.	Repairs	4/04/2019	0	1		Workshop Mbh	MSS Other Assets
3130	MS12	TUFF LOW LOADER	30.03.19_MWR_"A" Service	Service	30/03/2019	0	0		Workshop Mbh	MSS Other Assets
3076	MS12	TUFF LOW LOADER	Fit Hubmeter	Capital	19/03/2019	0	1		Workshop Mbh	MSS Other Assets
3036	MS12	TUFF LOW LOADER	03.02.2019_MWR_Inspection prior to QLD transport inception for Certificate of Inspection on 6 February: replaced trailer wiring, inspected and adjusted all components, replaced 2 x lights. Greased and washed trailer, test drive.	Repairs	3/02/2019	0	5		Workshop Mbh	MSS Other Assets
2375	MS12	TUFF LOW LOADER	13.04.2018_MRF from MWR_Overhaul all brakes when time permits. Low priority, inspected and not urgent. As at 05.08.2018 Craig says will get to it but there are more pressing priorities with other machines.	Unknown	1/10/2018	0	0			MSS Other Assets
2848	MS12	TUFF LOW LOADER	NO MWR 12.08.2018_MRF_Now has 3 tyres on trailer (Quad Float) that. Have wire showing. The 2 spares also have wire showing. Need at least 6 New Tyres. (being delivered 28.08.2018) Tail lights not work.	Unknown	28/08/2018	0	0			MSS Other Assets
2874	MS12	TUFF LOW LOADER	21.08.2018_MWR_Check lights on trailer no left hand indicator and brakes/ refit stop wire on trailer. 12.08.2018_MRF_Tail lights not work.		21/08/2018	0	2			MSS Other Assets
2781	MS12	TUFF LOW LOADER	NO MWR 15.08.2018_MWR_Check plugs from truck (MS5) to trailer, jump power to trailer plug, good. check ? coil, good. Check cab fuses, good, Reconnect plugs and coil. Lift bonnet, check engine fuses, Main fuse blown, possibly because low power at ramp. (says buying fuses for ramp motor and side lights) 03.08.2018_MRF from MWR_trailer has no side lights, and has lost indicators. Side lights not working so battery for hydraulics is getting low.	Unknown	15/08/2018	0	0			MSS Other Assets
2841	MS12	TUFF LOW LOADER	Remove broken anderson connection from cable, fit new parts and cover cables.	Repairs	8/08/2018	0	0			MSS Other Assets
2782	MS12	TUFF LOW LOADER	28.07.2018_Need two new spare tyres for float (sent up in truck with Brett on 5 August)		7/08/2018	0	0			MSS Other Assets
2780	MS12	TUFF LOW LOADER	03.08.2018_MWR_Tyres down in pressure, some close to 50 PSI, pumped up to 100. 1 tyre couldn't reach.		3/08/2018	0	0			MSS Other Assets
2772	MS12	TUFF LOW LOADER	28.7.2018_Quad float tyres x 2 down to the wire. Replaced with 2 spares off the float.	Repairs	28/07/2018	0	2			MSS Other Assets

2795	MS12	TUFF LOW LOADER	COMPLETED NO MWR 25.07.2018_MRF_2 Tyres rear/Driver side pol need replaced. Have wire Ranger out.		25/07/2018	0	0			MSS Other Assets
2439	MS12	TUFF LOW LOADER	Removed both hydraulic cylinders for ramps. Stripped cylinders and found 1 x bent too I had straightened. re-sealed and re-assembled cylinders. re-fitted. replaced 1 x hydraulic hose. re-sealed electrical box. straightened oversize signs. greased trailer & adjusted brakes. washed down.	Repairs	10/05/2018	0	0			MSS Other Assets
2395	MS12	TUFF LOW LOADER	- Removed Hydraulic hose and had new ones made. - Replaced 1x Tyre with spare.	Repairs	26/04/2018	0	0			MSS Other Assets
2374	MS12	TUFF LOW LOADER	- Removed backing plates and found loose brake linings on no. 5 wheel group - Replaced brake shoes, wheel bearings and seal - Adjusted Brakes	Repairs	13/04/2018	0	0.1			MSS Other Assets
2284	MS12	TUFF LOW LOADER	ADS 02.02.18: adjusted brakes and inspected linings; full grease. Reports brake linings all very good.	PM	2/02/2018	0	2			MSS Other Assets
2275	MS12	TUFF LOW LOADER	CM: email 30.01.2018: Change two blown tyres; fit new tyres; reinstall spares to trailer		30/01/2018	0	0			MSS Other Assets