

Service Job History

Fleet No BK066		TRUCK; MACK METROLINER			S/N: 6FME06B214D710642		
Job No	Date	Staff	Completed	Days	Meter	Last Hirer	Job Description
3220	19/06/2020						Repair. Error 61 Code. Needs Cab mounts on front. 4x shocks on rear of truck are leaking. Frame of tipper cracked between duals on LH side. Passenger window winder stripped won't wind up inside door not handle. Finished fitting the last of the parts and components to the water tank.. Window winder replaced.
3191	15/06/2020	Dean	30/07/2020	34	26755		Repair. 750 HR SERVICE. REPAIR MAXI VALVE AIR LEAK, VACUUM HOSE ON TURBO, TURBO EXHAUST CLAMP, TOP UP STEER WHEEL BEARING OIL, REPLACE REFLECTORS ON TAILGATE.. Cab ride height valve. Repaired maxi valve hose leak. Repaired vacuum hose on turbo. Tightened exhaust clamp on turbo. Topped up steer wheel bearings oil. Replaced red reflectors.
2928	14/04/2020	Saul	15/04/2020	2	26619	FULTON	Repair. A/C NOT COLD. AMBER BEACON NOT WORKING.. Fix A/C and Electrical faults.
2942	14/04/2020	Gary	12/06/2020	44			Repair. EXHAUST BRAKE NOT WORKING, REFER DAVE WOOD. LH WINDOW WINDER NEEDS REPAIR.. Machinery inspection, adjust brakes, grease, repair tail gate actuator valve
2762	28/02/2020	Luke	2/04/2020	25		FULTON	Service. Trucks - 500 Service, completed 26574hrs. Rectify brake issue with maxis locking on.
2752	26/02/2020	Saul	2/04/2020	27		FULTON	Repair. Truck hard to start- refer to Luke.. park brake losing air and not releasing, park brake switch replaced, faulty park brake relay valve.
2541	8/01/2020	Trevor	28/02/2020	38		FULTON	Repair. repair hoist not working. Replaced faulty one way valve to PTO controls. Tested wiring harness. Replaced 1 x battery, removed one way valve that supplies controls
2518	7/01/2020	Luke	28/02/2020	39		FULTON	Repair. Engine will not rev (TPS switch and pedal already replaced). Has lack of power and de-rates on road. Was brought into yard on tilt tray.. Replaced faulty batteries. Checked all wiring harnesses and connections. Low voltage at TPS was the problem, should be 12v but only 8v was showing, caused by faulty battery. Fitted new one way valve on hoist air. Supply and tested. Travelled to Bowenville. Fitted Alternator. Fitted 2x new batteries. Repaired wiring issue near starter. Made new harness behind dash.
2351	2/12/2019	Will	19/12/2019	14		FULTON	Repair. Fault find truck not accelerating. check fuse and problem with dash not powering up. Replace foot pedal.
1868	14/10/2019	Luke	14/10/2019	1		FULTON	Repair. repair. attended site for starting issue.
1757	10/10/2019	Will	10/10/2019	1		FULTON	Repair. REPAIR. PARTS
1765	10/10/2019	Will	10/10/2019	1		FULTON	Repair. REPAIR. PARTS
1684	30/09/2019	DavidW	9/10/2019	8		FULTON	Repair. repair. replace new lift ram to tipper. Remove lift cylinder. Check over air leaks, needs new air dryer filter housing, hoist leaking. Fit new air dryer filter housing. Fit new hoist. Checked lights and oils.
1566	16/09/2019	DavidW	16/09/2019	1		FULTON	Service. Trucks - 1000 Service. Completed at 26,410hrs. 2000hr service.
1571	16/09/2019	DavidW	17/09/2019	2		FULTON	Repair. repair. replace back drive shaft uni on rear diff.

1229	5/08/2019	DavidW	14/08/2019	8	FULTON	Repair. repair. fit bell housing on gearbox and air fittings, fit gearbox to motor. Fit all components, remove to replace gearbox, remove starter motor.
783	25/06/2019	Will	25/06/2019	1	FULTON	Repair. Repairs. Allocatating parts from invoice.
743	12/06/2019	DavidW	24/06/2019	9	FULTON	Repair. Repairs. Repalce bushes in tork rod bars on rear diff. Fit new quick lock on maxy brake, git reflector markers on tail gate.
718	6/06/2019	PaulS	11/06/2019	4	FULTON	Repair. Check over for Machinery. Adjust clutch, repair air leak behind dash - Maxi valve air line - cut out hose, fit joiner and new 3/8 hose. Check fuel guage operation - Power at sender - pull dash out but guage part of P.C.B. Replaced L/H H/light bulb, Fit new head light sealed beam, fit new clearance light, fit new seat belt latch, inspect trans link rods.
663	28/05/2019	PaulS	28/05/2019	1	26238 FULTON	Repair. Tarp Repiars. Put leakstop in cooling system and replace failed bearing in tarp pulley handle.
623	20/05/2019	Luke	20/05/2019	1	26187 FULTON	Service. Trucks - 1000 Service Changed park brake valve in dash. Replaced bonnet cables.
633	20/05/2019	NikkiT	20/05/2019	1	FULTON	Repair. Allocate Parts. Allocate Parts
520	24/04/2019	Will	30/04/2019	5	Niland Gro	Service. Trucks - 1000 Service
485	15/04/2019	Will	24/04/2019	8	Rusca Bros	Repair. Repair. Repaired Lights.
325	13/03/2019	Luke	19/03/2019	5	25803 Niland Gro	Repair. Repairs. Fitted New steer tyres. Removed front bumper and repaired. Fitted new bonnet mounts. Removed Exhaust manifold and turbo. Removed torque rods. Place new safety stickers in cab R&R Torque rod bushes and fit intercooler hoses as required. Fitted new exhaust manifold. Refited turbo and pipe work. Fitted seals and pto shaft spool.
310	12/03/2019	Luke	12/03/2019	1	Niland Gro	Repair. Air Leak. Major air leak, seal had blown on air hose filter - Repaired.
189	5/02/2019	PaulS	5/02/2019	1	FULTON	Repair. ECM Internal Failure.. As per Cummins invoice 8069916.
111	14/01/2019	DavidW	5/02/2019	17	25089	Repair. Truck not starting. Jump start truck batterys need to be replaced. 1. RandR fuel pump as required - still had issues with starting, fuel return hose leaking and voltage low at electric primer. 2. Still having starting issues - Removed fuel lines from trans to electric priner and get new ones made. 3. Remove electric primer and inspect found thread tape in check valve. 4. Load test batteries as truck wound over slow - batteries were green in sight glass but failed load test. 5. carried out clutch adjustment. 6. cary over hard to start - swap ECM with BK068 - improved truck - call cummins, Fit new batteries as required.
34	9/11/2018	CameronB	12/11/2018	2	Nexus Deli	Repair. Replace lift pump. Replace lh front z spring hanger. Replace both transverse rods.. Replace lift pump. Replace lh front z spring hanger. Replace both transverse rods.

BK Civil - Work Order Summary

Asset:
RTT5202 (BK066) - 2004 MACK METROLINER
TIP TRUCK

Location:

Current Tracker Hours:

Current Tracker Kms:

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
29762	board lights not working	20/02/2023			21/02/2023	Ask Supervisor		David Wood
29682	A/C not cold when stopped	14/02/2023	28948	816720	14/02/2023	Repair Next Service		Murray Sampson
29645	Truck Wont Start	13/02/2023	28948	816720	13/02/2023	Do Not Operate		
29600	Truck de-rating	09/02/2023	28948	816720	09/02/2023	Do Not Operate		
29534	weld crack in exhaust, cut off beam on body and weld bracket	03/02/2023	28948	816720	03/02/2023	Ask Supervisor		Jordan Humberdross
29345	Exhaust cracked behind turbo - minor	18/01/2023	28948	816720	03/02/2023	Routine Service		Murray Sampson
29275	Broken shocky	14/01/2023	28948	816720	14/01/2023	Do Not Operate		Juston Free
29252	Blown Power Steering Hbse	12/01/2023	28948	816720	10/01/2023	Do Not Operate		Clay Baran
29205	tyres	10/01/2023	28948	816720	06/01/2023	Repair Next Service		Clay Baran
29054	regroove tires	19/12/2022	28948	816720	16/12/2022	Ask Supervisor		Corey Roseby
29018	inspect overheating issue	14/12/2022	28948	816720	15/12/2022	Ask Supervisor		Joseph Giles
28907	investigate over heating	06/12/2022	28948	816720	06/12/2022	Ask Supervisor		Scott Debney Trevor Mbrtimer
28775	service due	25/11/2022			16/12/2022	Routine Service		Trevor Mbrtimer
28689	Shutting off when in reverse	18/11/2022	28948	816720	19/11/2022	Ask Supervisor		Juston Free
28594	Multiple Prestart Defects	09/11/2022			15/11/2022	Repair Next Service		Justin Debney
28506	Passenger side rear tyres scuffing out	03/11/2022			04/11/2022	Ask Supervisor		
28500	truck derating	02/11/2022	28948	816720	29/10/2022	Ask Supervisor		David Wood
28409	Steer tyres marginal tread	24/10/2022			26/10/2022	Repair Next Service		Joseph Giles
28317	29000 hours service	12/10/2022	28947	816656	02/11/2022	Routine Service		Juston Free
28003	Flat tire	07/09/2022	28813	811676	07/09/2022	Ask Supervisor		Juston Free
27760	28750 hours service	16/08/2022	28694	807978	14/09/2022	Routine Service		Clay Baran
27589	Prestart Defect - Air Conditioner functional (where fitted) F	27/07/2022			30/07/2022	Ask Supervisor		Saul Whaley
27545	Brakes	21/07/2022	28597	803973	21/07/2022	Routine Service		Clay Baran
27536	Driveshaft bolts loose	20/07/2022	28593	803835	20/07/2022	Ask Supervisor		Juston Free
27422	Wiper blades need replacement	11/07/2022			21/07/2022	Repair Next Service		David Wood
27311	weld broken hinge and make pin	27/06/2022	28506	801190	25/06/2022	Ask Supervisor		Jordan Humberdross
27180	28500 hours service	15/06/2022	28445	799139	21/07/2022	Routine Service		Justin Debney
27147	Fuel lines replace	10/06/2022	28429	798654	10/06/2022	Ask Supervisor		
27073	Braking issue	03/06/2022	28395	797465	03/06/2022	Do Not Operate		Morgan Holcombe

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
26889	repair bonnet catcher	17/05/2022	28323	795004	17/05/2022	Ask Supervisor		Jordan Humberdross
26429	Air-conditioning not working properly	24/03/2022			28/03/2022	Repair Next Service		David Wood
26355	28250 hours service	18/03/2022	28199	791759	15/04/2022	Routine Service		David Wood
26158	A/C	24/02/2022	28123	789854	16/02/2022	Repair Next Service		
26066	weld crack in crossmember	11/02/2022	28113	789725	11/02/2022	Ask Supervisor		Jordan Humberdross
25964	broken fuel line	04/02/2022	28101	789099	02/02/2022	Repair Next Service		Clay Baran
25911	Gearbox	01/02/2022			01/02/2022	Ask Supervisor		David Wood
25912	RHR Rear drive brakes locked on	01/02/2022			18/02/2022	Ask Supervisor		
25814	Prestart Defect - Other Notes/Miscellaneous	21/01/2022			16/02/2022	Repair Next Service		Saul Whaley
25788	Prestart Defect - Power Steering Fluid Failed	17/01/2022			25/01/2022	Repair Next Service		Peter Lee
25775	puncture in lhr outer drive tyre	14/01/2022	28078	788719	18/01/2022	Ask Supervisor		Stephen Ware
25691	Check over before Nexus job	06/01/2022	28042	788310	18/01/2022	Ask Supervisor		Stephen Ware
25528	28000 hours service	08/12/2021	27949	786527	20/01/2022	Routine Service		Clay Baran
25319	Clutch issue, leaking rear main seal, leaking sump,tracker	10/11/2021	27567	786326	20/12/2021	Ask Supervisor		Morgan Holcombe
25254	Prestart Defect Damage to toolbox	01/11/2021			16/02/2022	Repair Next Service		Mark Ellwood
25155	Multiple Prestart Defects	23/10/2021			28/10/2021	Repair Next Service		Saul Whaley
25043	Left rear duals worn	11/10/2021			02/11/2021	Repair Next Service		Clay Baran
25021	Prestart Defect - Check Tyres inflated and free from damage F	08/10/2021			12/10/2021	Repair Next Service		Clay Baran
25000	Has miss, backfire, pop, crackle as your powering on	07/10/2021	27541	785689	12/10/2021	Ask Supervisor		Blair Batterham
24936	Manually generated 500 hours service	29/09/2021	27541	785689	28/10/2021	Routine Service		David Wood
24937	Clutch pedal sits very high	29/09/2021			02/11/2021	Repair Next Service		Saul Whaley
24926	Needs a service 150 hours over due	28/09/2021			28/09/2021	Ask Supervisor		Brandon Szkurda
24874	Tracker not working	21/09/2021	27541	785689	28/10/2021	Repair Next Service		Trevor Mortimer
24864	Multiple Prestart Defects	20/09/2021			13/10/2021	Repair Next Service		Morgan Holcombe
24766	crack in screen	08/09/2021			10/09/2021	Repair Next Service		David Wood
24290	Fuel pressure sensor fault	29/07/2021	27541	785689	29/07/2021	Ask Supervisor		Morgan Holcombe
24225	A/Cnot working	23/07/2021	27511	784454	22/07/2021	Repair Next Service		Toowoomba Branch WSHOP- R
24126	Engine brake not functioning	16/07/2021			29/07/2021	Repair Next Service		Clay Baran
23999	27500 hours service	09/07/2021	27447	781809	17/07/2021	Routine Service		Saul Whaley
23091	Repair drivers door hinge limiter	23/04/2021	27339	778365	23/04/2021	Ask Supervisor		Scott Wiggins
23080	Engine power issues	22/04/2021	27338	778345	25/05/2021	Repair Next Service		Toowoomba Branch WSHOP- W
22991	Prestart Defect - LHR axle broken	13/04/2021			21/04/2021	Routine Service		Toowoomba Branch WSHOP- W
22938	Low power, warning light on dash	08/04/2021	27320	778040	15/04/2021	Routine Service		Toowoomba Branch WSHOP- W
22805	Derating	23/03/2021	27308	777679	19/03/2021	Repair Next Service		Toowoomba Branch WSHOP- W
22708	Interior light not working	15/03/2021			07/04/2021	Ask Supervisor		Toowoomba Branch WSHOP- W
22102	Replace steering shaft uni's	05/03/2021	27303	777515	05/03/2021	Routine Service		Toowoomba Branch WSHOP- W
21984	Replace drive axle shockies	03/03/2021	27303	777515	04/03/2021	Routine Service		Toowoomba Branch WSHOP- W

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
20069	Engine oil leak at rear of engine near rear seal.	02/02/2021	27221	775541	29/08/2021	Repair Next Service		Toowoomba Branch WSHOP - W
20070	Front left blinker needs inspection, have to shake wires to	02/02/2021	27221	775541	03/03/2021	Repair Next Service		Toowoomba Branch WSHOP - W
20071	Right Rear rear has chunk missing	02/02/2021	27221	775541	15/02/2021	Repair Next Service		Toowoomba Branch WSHOP - W
20073	Injector pump leaking, Front left scrubbing out on inside of	02/02/2021	27221	775541	15/03/2021	Ask Supervisor		Toowoomba Branch WSHOP - W
20074	Power Steering Fluid low, Rear right front shockie needs rep	02/02/2021	27221	775541	03/03/2021	Ask Supervisor		Toowoomba Branch WSHOP - W
19684	27250 hours service	28/01/2021	27201	774910	19/02/2021	Routine Service		Toowoomba Branch WSHOP - W
19504	L.h.window doesn't wind up fully	25/01/2021			05/03/2021	Repair Next Service		Toowoomba Branch WSHOP - W
19032	Home for rear pivot pin	12/01/2021	27181	774509	08/01/2021	Do Not Operate		Toowoomba Branch WSHOP - W
19037	fit muffler	12/01/2021	27181	774509	08/01/2021	Do Not Operate		Toowoomba Branch WSHOP - W
17493	airbag repairs	02/12/2020	27138	773934	02/12/2020	Do Not Operate		Toowoomba Branch WSHOP - W
15803	Seat keeps going up and down by itself	06/11/2020			10/12/2020	Repair Next Service		Toowoomba Branch WSHOP - W
15578	Clutch needs adjusting	03/11/2020			06/11/2020	Repair Next Service		Toowoomba Branch WSHOP - W
13157	Prestart Defect - Air Conditioner functional (where fitted) F	21/09/2020			28/09/2020	Repair Next Service		Toowoomba Branch WSHOP - W
12510	27000 hours service	08/09/2020	26951	767819	15/09/2020	Routine Service		Toowoomba Branch WSHOP - W
12539	Exhaust Repairs	08/09/2020	26934		05/09/2020	Do Not Operate		Toowoomba Branch WSHOP - W
12384	Cracks in Body 26964hrs	03/09/2020			21/09/2020	Do Not Operate		Toowoomba Branch WSHOP - W
12387	tailgate not operating properly	03/09/2020	26934		05/09/2020	Routine Service		
11769	Shockies, Gearbox, Clutch.	19/08/2020	26934	767642	01/09/2020	Routine Service		Toowoomba Branch WSHOP - W
11010	fire extinguisher to be Checked	30/07/2020			24/08/2020	Routine Service		Toowoomba Branch WSHOP - W
10927	Repair Fuel Leak, Replace Shock absorber.	29/07/2020	26859		30/07/2020	Routine Service		William Walsh
10912	tailgate problem	28/07/2020	26859		29/07/2020	Routine Service		Trevor Mortimer
10816	Prestart Defect - Air Conditioner functional (where fitted) F	24/07/2020			24/08/2020	Do Not Operate		Toowoomba Branch WSHOP - W
10114	Fuel Gauge not working properly MBrooks	18/06/2020	26938		02/09/2020	Do Not Operate		Toowoomba Branch WSHOP - W
10026	Tailgate not closing Properly Mark Causer	12/06/2020	26859		29/07/2020	Ask Supervisor		