



Vehicle History Detail

Fleet #	LPM48							
Registration	XQ05IO							
Make	Volvo							
Model	FH16							
VIN / Chassis #	YV5AP80DXDD137228							
Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-31560	04/10/2024			Lights	Anmac Services	STRAIGHTENED L/H REAR LIGHT BAR AND FITTED NEW LIGHTS TO BOTH SIDES.	8433	\$0.00
R-31152	02/09/2024			Air Fittings	Anmac Services	replaced female air fitting on suzi coil	8382	\$0.00
S-18417	09/07/2024	1281639		C - Annual	Anmac Services	C service completed	8315	\$0.00
R-30145	09/07/2024	1281639		Cab Shock Absorbers	Anmac Services	Replaced both front cab shockies	8315	\$0.00
R-29894	09/05/2024			Door Check Strap	Anmac Services	Replaced RH Door Hand Strap	8216	\$0.00
R-29581	29/04/2024			Air Leak	Anmac Services	Repaired Air Leaks	8201	\$0.00
R-29354	19/03/2024			Fault, Trailer Light Detection	Anmac Services	Disabled Trailer Light Detection and rectified fault	8161	\$0.00
R-27986	17/11/2023			Battery	Anmac Services	Replaced batteries	8025	\$0.00
R-27981	15/11/2023			Battery	Anmac Services	Jump started truck	8023	\$0.00
T-13600	15/11/2023			Fit	Bridgestone	Fit 2x 385/65R22.5 160K BS R249 Pos 1,2	18083521	\$0.00

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-27484	04/10/2023			Door	Anmac Services	Repaired Door not opening from the outside	7954 7960	\$0.00
S-16775	21/06/2023	1271200		C - Annual	Anmac Services	C service completed	7806	\$0.00
S-16776	21/06/2023	1271200		B - 40,000 - 45,000	Anmac Services	B service completed	7806	\$0.00
R-26006	21/06/2023			Light Assembly	Anmac Services	LH lower light assembly	7806	\$0.00
R-25633	24/05/2023			Auto Electrical, Battery	Anmac Services	Replace LH Battery Auto Electrical Repairs	7755	\$0.00
R-25246	17/04/2023			Air Drier	Anmac Services	R&R air dryer unit	7714	\$0.00
R-23872	30/11/2022			Battery, Coolant	Anmac Services	Replaced batteries drained coolant to replace gearbox cooler front of radiator. Refilled coolant	7493	\$0.00
R-23518	22/11/2022			Mirror	Anmac Services	Replaced left hand mirror assembly	7479	\$0.00
R-23372	18/11/2022			Coolant	Anmac Services	Pressure test cooling system, found gearbox cooler front of radiator leaking. Change when I have received a new one which is on order	7470	\$0.00
R-22596	31/10/2022			Auto Electrical	Anmac Services	Inspect engine fault and aircon fault - scan & clear codes, truck will need a run to log further performance related codes Connect gauges to air con system and check - heater valves stuck on - Disconnect and bypass heater Top up coolant	7385	\$0.00
S-15155	31/08/2022	1252244		B - 40,000 - 45,000	Diesel Tech Fleet Services	B service completed	3313	\$0.00
T-11869	08/08/2022		0	Torque	Bridgestone	2 X torque Pos 1 & 2	16256542	\$0.00

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-14575	14/04/2022	1238008	0	B - 40,000 - 45,000	CMV Truck and Bus	B service completed See attached inv LE0052350	LE0052350	\$0.00
R-20884	10/03/2022	1230047		Speed Sensor	CMV Truck and Bus	R&R SPEED SENSOR	L01127158	\$0.00
R-20240	08/02/2022			Air Conditioner	AB Auto Electrics	COMPLETED WORK ON A/C	00289900	\$0.00
S-14157	09/12/2021	1216600	0	B - 15,000 - 20,000kms	Brisbane Workshop	B service completed	Joseph-TB1577	\$0.00
T-10605	24/11/2021	1211351	0	Puncture	Bridgestone		09678	\$0.00
R-19065	04/11/2021			Alternator, Battery	CMV Truck and Bus	R&R Battery and Alternator	LI00005945	
R-19063	31/08/2021	1180432		Battery	CMV Truck and Bus	R&R 1 x Battery	:P5030828	
S-13707	31/08/2021	1180710	0	C - Annual	CMV Truck and Bus	C Service Completed. General repairs conducted - Please see attached document.	L01119074	
R-18465	31/08/2021	1180710	0	General Repairs	CMV Truck and Bus	C Service Completed. General repairs conducted - please see the attached.	L01119074	
R-19064	24/08/2021			Bunk Cooler	AB Auto Electrics	degas and replace pressure switch	00286432	
R-18213	23/06/2021	1171679		Brakes , King Pins, Lights, Torsion bar, Wiring	CMV Truck and Bus	See attached Inv LO1115939	LO1115939	
S-13385	31/05/2021	1170746	0	C - Annual	CMV Truck and Bus	C service completed See attached Inv LE0039474	LE0039474	
T-10382	07/04/2021	1162190	0	Fit	Bridgestone	x1 Fit 11R22.5 146/143L POS 12 x1 Scrap POS 12	14448135	
R-17274	11/03/2021			Battery	AB Auto Electrics	Replace 2 X batteries	282763	
T-10141	12/02/2021	0	0	Pressure Check	Bridgestone		14174778	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-16965	30/01/2021	1154510		Air Conditioner	CMV Truck and Bus	Replaced defective A/C fan motor	L01109702	
T-9815	14/12/2020	1146985	0	Fit	Bridgestone	1 X fit 11R22.5 146/143L BS M766 Pos 8 1 X scrap	14020477	
T-9815	14/12/2020	1146985	0	Pressure Check	Bridgestone		13870752	
R-16223	24/11/2020	1135153		Front Grill, Sidesteps	CMV Truck and Bus	Replaced damaged grill & side step, painted	LE0030962	
S-12767	23/11/2020	1140455	0	B - 40,000 - 45,000	CMV Truck and Bus	B service completed	LE0031109	
R-16019	28/10/2020	1137279		Battery	CMV Truck and Bus	Supply & fit 1 X battery	L02031621	
S-12798	13/10/2020	1135153	0	B - 40,000 - 45,000	CMV Truck and Bus	B service completed	LE0029261	
T-9296	25/09/2020	1134683	0	Pressure Check	Bridgestone		13687560	
T-8018	21/04/2020	111927	0	Balance, Pressure Check, Rotation	Bridgestone	2 X rotate side to side Pos 1, 2 8 X rotate criss-cross Pos 3, 4, 5, 6, 7, 8, 9, 10	3410448506	
R-13902	09/04/2020	1117368		Belts and Tensioners, Clearance Light, Coolant, Cooler Hose, Foot Step Panel, Gaskets, Manifold, Oil Leak, Output Seal, Panel, Trailer Plug, Turntable, Walk Plate, Washer Bottle, Weather Shields, Windscreen	CMV Truck and Bus	Fitted 4 x new walk plate retainers. Trailer plug removed, wiring trimmed, re-stripped & terminated into new plug. Belts & tensioners removed, new tensioners installed and inspected for alignment, ok. Hose clamp removed, hose re-fitted to bard, clamp re-fitted in correct position & tightened. Coolant also found to be leaking from header tank cap, cap seal & mating surface cleaned of contamination & re-fitted. System pressure tested to confirm repairs, ok. Split in radiator header noted LHS, leaking coolant under pressure. Quoted 23/03/2020, approved, parted delivered. Fan cowl & radiator shroud removed, all lines	L01092348	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
						<p>to coolant reservoir disconnected & reservoir removed. Radiator removed from vehicle, seperated from intercooler & replaced with new unit. Lower mount nylon spacers replaced; unit fitted to intercooler & reservoir mount point aligned. Intercooler/radiator assembly re-installed. Condenser remounted; fan cowl & radiator shroud refitted. Weeping fracture in base of coolant resevoir noted, replaced with new unit upon re-installation of radiator. Damaged wiring noted on coolant reservoir level sensor, replaced with new unit. System pressure tested to confirm repairs, additional leak found RHS at silicon to plastoc hose connection in chassis rail (line to front radiator). Cable ties removed to allow access to casual area. Joint & area cleaned, hose clamp refitted and tightened. System pressure tested @ 13psi for 30 minutes, no pressure drop or leakage noted. Air intake ducting removed; turbo feed & drain lines disconnected from turbo. EPG clamp removed to move EPG assembly clear. Turbo oil lines and wastegate line disconnected. Turbo unbolted from manifold; manifold removed and seperated. Slip joints cleaned and seals replaced, joining past applied top surfaces. Port & turbo base mounting surfaces buffed clean and inspected. Headed cleaned & re-painted around ports. Manifold installed with new gaskets, turbo iunstalled with new base gasket, all bolts torqued to spec and marked. Turbo oil lines and wastegate line re-fitted. EPG re-fitted</p>		

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
						<p>8 clamp replaced, air ducting re-fitted. CCV separator unit removed from engine & inspected, excessive impeller runout noted. Unit dismantled to inspect bearings, impeller end bearing found to have excessive play, requiring unit replacement. CCV separator on back order ex Sydney 24/03/2020. 25/03/2020 unit arrived, installed with new sealing gasket to block. Replaced gearbox cooler hoses with new units. Banjo screws & copper washers replaced with new units, adapters to oil filter tightened & inspected for leakage. Replaced cab clearance light. Clearance light rail below tank removed for access to rear light retaining nuts and wiring, additional time required D/S due to multiple failed rivnuts not allowing removal. Non-operational light units, mounting & wiring holes bored/amended to suit. Wiring found to be exposed/damaged in areas, tested for cause of fault, no fault, rectified during install. Light rails, refitted both sides, cover trims fitted to new lights, all tested okay. Headlight & surrounding trim removed; panel removed. Indicator removed from light panel to transfer to new panel, found to have hazed lens & broken diffuser, replaced. Indicator fitted & new panel installed. Headlight re-fitted & tested. Removed and cleaned door, replaced weather shield. Replaced washer bottle. Tapered bore in sway bay, thoroughly cleaned and inspected. New drop line & bracket fitted; previous rivet holes fitted with 2 x</p>		

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
						additional retaining bolts. All bolts and nuts torqued to spec and marked. Replaced 1st dive output seal. Replaced windscreen. Put turntable in 5th wheel tool and adjusted latch to get rid of play. Removed and replaced damaged foot step panels.		
R-13894	08/04/2020	1117368		Fuel Bowl	CMV Truck and Bus	Removed fuel bowl and replaced with new. Primed fuel system and tested - all okay.	L02027305	
R-13903	05/03/2020	1115195		Suzi Coils	CMV Truck and Bus	Removed and replaced suzicoils taps and fittings.	L02026590	
S-11732	28/02/2020	1115195	0	C - Annual	CMV Truck and Bus	C service completed	LE0018818	
R-13526	20/01/2020			Dashcam, Phone Cradle	AB Auto Electrics	Installed 1 x dash camera. Removed & replaced 1 x phone kit.	00273868	
R-13122	06/01/2020			Circuit Breaker	AB Auto Electrics	Supplied & installed 2 x new circuit breakers as required Resolder A/C pressure switch wiring as required.	00273578	
R-13123	31/12/2019	1108050		Battery	AB Auto Electrics	Check vehicle for starting faults Diagnosed 2 x faulty batteries Supplied & installed 2 x EMFN150 batteries as required	00273557	
R-13287	19/12/2019	1108030		Airbag, Air Conditioner, Cab, Horn	CMV Truck and Bus	Repaired wiring for hand controller, checked op, all ok R&R new fan heater resisitor, checked op, all ok Repaired earth wire & tested, all ok Checked cab swaying from side to side, could not fault	L01085397	
T-6916	24/10/2019	1102234	0	Fit, Rotation	Bridgestone	2 X rotate Pos 1, 2 8 X fit 11R22.5 146/143L 16 BS M766 Pos 5, 6, 7, 8, 9, 10, 11, 12	3410442314	
T-6796	07/10/2019	1100223	0	Pressure Check	Bridgestone		97411301	
R-10834	04/10/2019			Fault Codes	JOHNSONS TRUCK & COACH	REQUIRES NOX SENSOR, TO BE FITTED IN ADELAIDE	H204364	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-12179	31/08/2019	1000000		Fire Extinguisher	Fire Equipment Maintenance	Tagged & tested - passed	91891	
T-6329	26/07/2019			Puncture	Bridgestone		032439	
R-11463	17/07/2019	1087929		Bump Stop	Brisbane Workshop	R&R CAB BUMP STOPS	CRAIG-BAB00488	
S-10853	17/07/2019	1087929		B - 30-35kms	Brisbane Workshop	B SERVICE COMPLETED	CRAIG-BAB00488	
R-11463	17/07/2019	1087929		Coolant	Brisbane Workshop	REPLACED 3 COOLANT HOSES REPLACED ALL COOLANT	CRAIG-BAB00488	
R-11430	09/07/2019	1087431		Power Steering	Brisbane Workshop	Find powersteering leak and remove hose, fit new filter. Fit new powersteering hose and fill system. Take for test drive and ok.	R02237Craig	
T-6033	04/06/2019	1073788		Strip & Fit	Bridgestone		96932606	
T-6024	03/06/2019	1072012		Strip & Fit	Bridgestone		96929078	
R-11016	27/05/2019	1069949		Lights	Brisbane Workshop	REPAIRED EARTH WIRE TO HEADLIGHT FITTED NEW GLOBE TO BOTTOM LIGHT ASSY REPAIRED BROKEN WIRE TO RH SPOTLIGHT	CHRIS-R02192	
R-11044	16/05/2019	1060006		NOX Sensor	Hi-Torque	R&R NOX SENSOR	661635	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-10723	02/05/2019	1058713		Fault Codes	Volvo Service Centre	ACTIVE CODE FOR VEB SOLENOID CHECKED WIRING FROM ECU TO SOLENOID-ALL GOOD REPLACED SOLENOID REMOVED ROCKER COVER-CLEARED CODES STILL ACTIVE CODES FOR LIGHTENING FILLED IN THE COOLANT STEAM CLEANED & CHECKED EXHAUST BRAKE FUNCTION EXHAUST ACTUATOR LEAKING FIT CLAMP & ROAD TESTED PROGRAMMED ENGINE ECU-STILL NO ENGINE BRAKE TOO MUCH CLEARANCE CARRIED OUT FULL VALVE SET TRPLACED MISSING TURBO BOLREASSEMBLED, TESTED OP - OK	8116232	
R-10722	20/04/2019	1056197		Alternator	Hockos Mechanical	REPLACED ALENTATEOR	16032	
R-10549	16/04/2019			General Repairs	Pro Truck Electrical	Diagnosed unit- found it wasn't charging 24v or 12v. Stripped the unit, pulled motor out, oulded front, ouldy and fly wheel off to get the magneto. Changed the charge ring, put motor back together. Gave it a good clean out, did bushed on unit, put all back together and replaced alternator. Found alternator was fualty so replaced again. Replaced redifier and redifier loom, made sure all worked and charged 26v, 13.0v, 14.2v.	PT1949	
R-10564	11/04/2019			Steer Slack Adjusters	Land Transport	Removed and replaced steer shocks.	R01940Brett	
R-10447	04/04/2019	1045759		Lights	Brisbane Workshop	REPLACED 1 X LED SIDE LIGHT AT FUEL TANK	CHRIS-BAB00053	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-10447	04/04/2019	1045759		Radiator and Cooling System	Brisbane Workshop	BLOW OUT RADIATOR	CHRIS-BAB00053	
S-10377	04/04/2019	1045759		B - 30-35kms	Brisbane Workshop	B SERVICE COMPLETED	CHRIS-BAB00053	
R-10447	04/04/2019	1045759		Ice Pack	Brisbane Workshop	ICE PACK SERVICE (4331HRS)	CHRIS-BAB00053	
R-10354	27/03/2019			Battery	Brisbane Workshop	REPLACE 4 BATTERIES	SAM-R01860	
R-10354	27/03/2019			Mudflaps	Brisbane Workshop	REPLACE BOTH FRONT MUDFLAPS ON BULLBAR	SAM-R01860	
R-10200	15/03/2019	1036856		Beacon	Land Transport	LH beacon light inop, checked and found when turn manually light starts to turn than stops. Sprayed motor with electrical contur cleaner and turned manually few times. Tested and now OK.	R01922brett	
R-10151	10/03/2019	1033358		Battery	Pengelly	Vehicle wont start, checked charging rate and found battery water low. Topped up and vehicle OK	Scott-214822	
S-10185	08/03/2019			C - Annual	Pengelly	C Service completed		
I-1891	06/03/2019				Pengelly			\$0.00
R-10296	04/02/2019	1033317		Engine	Pengelly	ENGINE REBUILD	214900	
R-9576	14/01/2019	1025335		Air Leak	Crank IT Mechanical	REPAIR AIR LEAK	PADDY	
R-9576	14/01/2019	1025335		Light Bar	Crank IT Mechanical	REPAIR REAR LIGHT BAR	PADDY	
R-9576	14/01/2019	1025335		Suspension	Crank IT Mechanical	CHECK ALL SUSPENSION COMPONENTS (STEER & DRIVE)	PADDY	
R-8970	04/12/2018			Ice Pack	Pro Truck Electrical	ICE PACK INOP	PRO TRUCK	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-8959	02/12/2018	1014656		Mirror	Brisbane Workshop	REPAIRED LH BOTTOM SPOTTER MIRROR HOUSING	CHRIS-BAB00338	
R-8959	02/12/2018	1014656		Bulbs	Brisbane Workshop	REPLACED 2 X GLOBES	CHRIS-BAB00338	
S-9897	02/12/2018	1014656		B - 18-22km	Brisbane Workshop	B SERVICE COMPLETED	CHRIS-BAB00338	
R-8959	02/12/2018	1014656		Signage	Brisbane Workshop	ADDED RIVET TO DG BOOK ON BULLBAR LHS	CHRIS-BAB00338	
R-8959	02/12/2018	1014656		Weight Gauge	Brisbane Workshop	FITTED NEW WEIGHT GAUGE	CHRIS-BAB00338	
R-8959	02/12/2018	1014656		Ice Pack	Brisbane Workshop	ICE PACK SERVICE 4004 HRS	CHRIS-BAB00338	
R-8415	23/10/2018	988063		Window	Brisbane Workshop	Replaced window switch	Craig BAB00272	
S-9629	23/10/2018	988063		B - 18-22km	Brisbane Workshop	B Service completed	Craig BAB00272	
R-8415	23/10/2018	988063		Sway Bar	Brisbane Workshop	Replaced front sway bar drop links	Craig BAB00272	
R-8560	23/10/2018	969531		Lights	Brisbane Workshop	Tightened RH outter spot light. Replaced both sides front drive axle swing bar link rods and brackets.	Brett	
R-8415	23/10/2018	988063		Air Filter	Brisbane Workshop	Reokaced AC cab air filter	Craig BAB00272	
R-8134	27/09/2018			Wiper Blades	Crank IT Mechanical	Replaced wiper blades	Paddy	
R-8134	27/09/2018			Checker Plate	Crank IT Mechanical	Fabricated 2 x checker plate hold downs and fit.	Paddy	
R-8134	27/09/2018			Lights	Crank IT Mechanical	Replaced RH headlight bulb	Paddy	
R-8175	21/09/2018	969023		Exhaust	Brisbane Workshop	Welded up cracked exhaust pipe & replaced leaking exhaust flex/	Brett R00699	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-8175	21/09/2018	969023		Airbag	Brisbane Workshop	Replaced both cab air bags.	Brett R00699	
R-8220	20/09/2018			Airbag	Brisbane Workshop	Replaced air bags - cab rear	Brett	
R-8220	20/09/2018			Wiper Blades	Brisbane Workshop	Replaced wiper blades	Brett	
R-8220	20/09/2018			Lights	Crank IT Mechanical	Replaced heap light bulb	Pat	
R-8220	20/09/2018			Checker Plate	Crank IT Mechanical	Bolts in checker plate	Pat	
I-1657	14/09/2018				Brisbane Workshop			\$0.00
S-9451	14/09/2018			C - Annual	Brisbane Workshop	C Service completed	Chris - BC 00160	
S-9371	28/08/2018	956149		B - 18-22km	Crank IT Mechanical	B SERCICE COMPLETED	PADDY	
R-7849	28/08/2018	956149		Door	Crank IT Mechanical	REPLACE BROKEN DOOR PANEL	PADDY	
R-7849	28/08/2018	956149		Lights	Crank IT Mechanical	REPLACE LH FOG LIGHT	PADDY	
T-4360	24/08/2018			Puncture	Wilsons Diesel & Auto Repairs		R00643	
R-7614	08/08/2018	941319		Lights	Brisbane Workshop	REPAIRED LH HEADLIGHT R&R HEADLIGHT MOUNT BRACKET FABRICATE & FIT BRACKETS FOR MIRROR EXTENSIONS & FIT 2 NEW SPOTTER MIRRORS	BRETT-R00654	
T-4296	07/08/2018			Strip & Fit	Bridgestone	1 X SCRAP	1659712	
T-4296	07/08/2018			Pressure Check	Bridgestone		1659712	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-7672	01/08/2018			Power Steering	Pirtek	REPAIR TO POWER STEERING HOSE	CAN510555	
R-7654	30/07/2018			Air Lines	Pengelly	REPLACED AIR LINES	208418	
S-9214	27/07/2018	932061		B - 18-22km	Brisbane Workshop	B SERVICE COMPLETD	CHRIS-BAB00440	
R-7412	27/07/2018	932061		Lights	Brisbane Workshop	REPLACED RH ROOF CEARANCE LIGHT REPLACED BLOWN GLOBE FOR LH FRONT INDICATOR	CHRIS-BAB00440	
T-4067	27/07/2018			Pressure Check	Bridgestone		95952852	
T-4171	18/07/2018			Pressure Check	Bridgestone		1420866	
R-7214	02/07/2018	912464		General Checkover	Brisbane Workshop	QUICK BLOW OUT RADIATOR, CHECK OIL/WATER, TOPPED UP WINDSCREEN WASHER WATER	CHRIS-R00335	
R-7214	02/07/2018	912464		Signage	Brisbane Workshop	FITTED COMPLIANCE PLATE	CHRIS-R00335	
R-7214	02/07/2018	912464		Lights	Brisbane Workshop	R&R BLOWN GLOBES ALSO R&R LH BOTTOM LIGHT ASSY (SPOTLIGHT) BROKEN	CHRIS-R00335	
R-7214	02/07/2018	912464		Turntable	Brisbane Workshop	ADDED GREASER TO T/TABLE	CHRIS-R00335	
T-3961	20/06/2018	903510		Rotation	Brisbane Workshop		ROB-R00201	
R-7064	20/06/2018	903510		DG Book	Brisbane Workshop	Replaced DG Book on bull bar	BAB00417 - Chris	
T-3961	20/06/2018	903510		Pressure Check	Brisbane Workshop		ROB-R00201	
S-9052	20/06/2018	903510		B - 18-22km	Brisbane Workshop	B Service completed	BAB00417 - Chris	
R-6729	22/05/2018	884011		Ice Pack	Brisbane Workshop	ICE PACK SERVICE -3522HRS	CHRIS-BAB00404	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-3740	22/05/2018	884011		Fit	Brisbane Workshop		ROB-R00253	
T-3740	22/05/2018	884011		Pressure Check	Brisbane Workshop		ROB-R00253	
S-8926	22/05/2018	884011		B - 18-22km	Brisbane Workshop	B SERVICE COMPLETED	CHRIS-BAB00404	
R-6691	16/05/2018			Seat	Pengelly	DRIVER SEAT-DISASSEMBLE TO CLEAN & ADJUST FOR SITTING SPACE	MATT MURPHY	
R-6691	16/05/2018			Coolant	Pengelly	TOPPED UP COOLANT	MATT MURPHY	
R-6691	16/05/2018			Power Steering	Pengelly	REPLACED LEAKING POWER STEERING HOSE	MATT MURPHY	
R-6679	14/05/2018	879555		Wiring	Brisbane Workshop	ZIP TIED UP WIRES TO TANK BRACKET LH FRONT TANK FOR SIDE LIGHTS ALONG FUEL TANK	CHRIS - R00156	
R-6679	14/05/2018	879555		Battery	Brisbane Workshop	TRUCK WOULDN'T START, STARTED ICE PACK THEN HOOKED UP JUMPER BATTERIES STARTED & RAN OK REFITTED BATTERY COVER TO BATTERIES CHECKED OUT CHARGE RATE 28VOLTS AT BATTERIES, LOAD TESTED OK	CHRIS - R00156	
R-6679	14/05/2018	879555		Fuel Lines	Brisbane Workshop	ZIP TIED UP FUEL HOSES HANGING DOWN OFF LH REAR FUEL TANK	CHRIS - R00156	
R-6560	24/04/2018	866246		Bracket	Brisbane Workshop	Made up new holding bracket for rear floor behind cab.	Chris	
R-6560	24/04/2018	866246		Radiator and Cooling System	Brisbane Workshop	Quick blow out of radiator	Chris	
R-6560	24/04/2018	866246		Shock Absorbers	Brisbane Workshop	Replaced all shock absorbers.	Chris	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-6780	20/04/2018	862738		Check Engine Light	Volvo Service Centre	ENGINE LIGHT ON DASH PLUGGED IN VOVOM & CHECKED FAULTS FOUND 2 ACTIVE CODES FOR BACK PRESSURES & OIL LEVEL OPEN CIRCUIT REPLACED SENSOR CLEAR CODE-ALL OK PLUG NEW SENSOR-CLEAR CODE-CODE CHANGED TO BELOW OPERATING LEVEL DRAINED ENGINE OIL, REMOVED SUMP& REPLACED OIL LEVEL SENSOR REFITTED SUMP WITH NEW GASKET REPLACED DIP STICK TUBE TESTED OP-OK	8100705-001000	
R-6546	18/04/2018	862738		Lights	Brisbane Workshop	Tightened up bottom head light. Refitted clip that holds into place.	Chris	
R-6546	18/04/2018	862738		Hose	Brisbane Workshop	Repaired drivers side washer water hose	Chris	
S-8806	17/04/2018	862731		B - 18-22km	Brisbane Workshop	B Service completed	Chris	
R-6503	15/04/2018	862731		Ice Pack	Brisbane Workshop	Ice pack service 3383hours	Chris	
R-6503	15/04/2018	862731		Lights	Brisbane Workshop	Replaced 2 x side clearance lights on fuel tank.	Chris	
R-6503	15/04/2018	862731		Radiator and Cooling System	Brisbane Workshop	Blow out radiator.	Chris	
R-6553	13/04/2018			Battery	Gepps Cross Auto Electrical Pty Ltd	Replaced both engine belts.	00040559	
R-6352	04/04/2018	855951		Battery	Gepps Cross Auto Electrical Pty Ltd	Removed and replaced batteries.	00040497	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-6558	26/03/2018	846552		Airbag	Volvo Service Centre	Replaced all 8 air abgs. Replaced broken bolts on walk plate.	8099659 - 004000	
R-6558	26/03/2018	846552		Exhaust	Volvo Service Centre	Loaded new program & calibrated.	8099659 - 004000	
R-6274	16/03/2018			Ice Pack	Brisbane Workshop	SERVICED IUCE PACK-3176 HOURS	CHRIS	
S-8865	15/03/2018	845308		B - 18-22km	Brisbane Workshop	B SERVICE COMPLETED	CRAIG	
R-6235	07/03/2018	841550		Air Drier	Brisbane Workshop	CHECK LIGHT COMING UP ON DASH INFO DISPLAY- COMPRESSOR RUNNING TOO OFTEN CHECK TRUCK FOR AIR LEAKS-NO LEAKS FOUND REMOVED AIR DRYER FILTER & FOUND A LOT OF FOREIGN MATTREER INSIDE DRYER BASE, REMOVED DRYER BASE, DISMANTLED, CLEANED & RE-ASSEMBLED , REFIT & FIT NEW FILTER	BRETT	
R-6235	07/03/2018	841550		Lights	Brisbane Workshop	REPLACED BLOWN RH HEADLIGHT LOW BEAM BULB & SUPPLIED SPARE BULBS REPAIRED LH TAILLIGHT WIRING- CUT OFF PLUGS WITH CORRODED TERMINALS, CRIMPED TERMINALS TO WIRING & TEST-ALL OK REPLACE BLOWN INTERIOR LIGHT BULBS	BRETT	
R-6235	07/03/2018	841550		Roof	Brisbane Workshop	SEAL UP LEAKS AT AERIAL BASES ON RHS OF ROOF	BRETT	
S-8518	12/02/2018	827264		B - 18-22km	Crank IT Mechanical		PADDY	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-6068	12/02/2018	827264		Ice Pack	Crank IT Mechanical	SERVICE ICE PACK	PADDY	
T-3195	05/02/2018	823485		Puncture	Brisbane Workshop		Rob	
T-3118	16/01/2018	811019		Fit	Brisbane Workshop		ROB	
R-5842	16/01/2018			Air Cleaner	Brisbane Workshop	Removed + replaced engine air cleaners. Removed + replaced cabin air cleaner.	Jake Moore	
R-5842	16/01/2018			Turntable	Brisbane Workshop	Removed + replaced turntable Removed + replaced turntable bushes	Jake Moore	
R-5842	16/01/2018			Lights	Brisbane Workshop	Removed + replaced XSLH fuel tank park lights + rewired all other lights.	Jake Moore	
R-5704	05/01/2018	806187		Ice Pack	Brisbane Workshop	SERVICED ICE PACK REPLACED 2 FAN BELTS	CHRIS	
R-5704	05/01/2018	806187		Lights	Brisbane Workshop	REPLACED 1 SPOT LIGHT GLOBE	CHRIS	
S-8304	05/01/2018	806187		B - 18-22km	Brisbane Workshop	GEAR BOX OIL & FILTER REPLACED	CHRIS	
T-3052	04/01/2018	806187		Pressure Check				
T-3052	04/01/2018	806187		Rotation	Brisbane Workshop		ROB	
S-8238	19/12/2017			A - 5-9km	Brisbane Workshop	CHECK OVER TOP UP ENGINE OIL	BRETT	
R-5535	04/12/2017	784660		Air Filter	Brisbane Workshop	Changed cab air filter	Chris	
S-8167	04/12/2017	784660		B - 18-22km	Brisbane Workshop	B Service completed	Chris	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-5535	04/12/2017	784660		Lights	Brisbane Workshop	Fitted 2 x indicators to bull bar Dropped out LH head light assembly had to pop back inot position main headlight	Chris	
T-3062	30/11/2017			Puncture	Ringtread SA Pty Ltd		39574	
S-7947	03/11/2017	767568		B - 18-22km	Brisbane Workshop		Craig	
S-7821	06/10/2017	748440		B - 18-22km	Brisbane Workshop	B Service completed	Chris & Craig	
R-5093	06/10/2017	748440		Ice Pack	Brisbane Workshop	Also serviced ice pack - 2332 hours.	Chris & Craig	
S-7713	11/09/2017	731556		B - 18-22km	Crank IT Mechanical	B Service completed	Paddy	
S-7582	07/08/2017	710860		B - 18-22km	Crank IT Mechanical	B Service completed	Paddy	
R-4795	07/08/2017	710860		Suzi Coils	Crank IT Mechanical	Replaced damaged electrical suzi lead.	Paddy	
R-4746	01/08/2017			Bracket	Crank IT Mechanical	Removed all four bracketts & replaced refit mudgaurd.	Paddy	
R-4746	01/08/2017			Mudguards	Crank IT Mechanical	Cut off mudguard brackets + remove LHR mudguard.	Paddy	
R-4753	01/08/2017			Exhaust Stack	Brisbane Workshop	Replaced exhaust stack, modify bracket & fit new clamp	Brett	
S-7493	24/07/2017	705700		A - 5-9km	Brisbane Workshop		SCOTT	
R-4649	24/07/2017	705700		Springs	Brisbane Workshop	SPRING BUSHES HAVE MOVEMENT ON FRONT AXLE	SCOTT	
R-4552	03/07/2017	694954		Turntable	Brisbane Workshop	Overhaul turntable - Remove, dismantle, clean, reassemble with new parts, grease, refit and adjust.	Brett	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-4508	26/06/2017	691157		Ice Pack	Brisbane Workshop	Serviced Ice Pack	Paddy	
S-7324	26/06/2017	691157		B - 18-22km	Brisbane Workshop	B Service completed	Paddy	
R-4508	26/06/2017	691157		Mudguards	Brisbane Workshop	Tighten all mudguards	Paddy	
R-4508	26/06/2017	691157		Lights	Brisbane Workshop	Repair right hand spotlight wiring.	Paddy	
R-4380	30/05/2017	673315		Walk Plate	Brisbane Workshop	Make up and fit walk plate brackets	Brett	
S-7106	22/05/2017	668633		B - 18-22km	Crank IT Mechanical	B Service completed	Paddy	
R-4344	22/05/2017	668633		Lights	Crank IT Mechanical	Repaired wiring to rear taillight	Paddy	
S-7088	22/05/2017	668633		B - 18-22km	Brisbane Workshop	B Service completed	Tom + Paddy	
R-4323	22/05/2017	668633		Ice Pack	Brisbane Workshop	Ice pack serviced	Tom + Paddy	
R-4344	22/05/2017	668633		Ice Pack	Crank IT Mechanical	Performed service on ice pack	Paddy	
R-4339	15/05/2017	663490		Windscreen Washers	Crank IT Mechanical	DIAGNOSE WINDSCREEN WASHERS NOT WORKING REPLACE BROKEN CROSSOVER LINE FILL WITH FLUID & TEST	PADDY	
R-4339	15/05/2017	663490		Mudguards	Crank IT Mechanical	TIGHTEN LOOSE MUDGUARDS	PADD	
R-4339	15/05/2017	663490		Exhaust	Crank IT Mechanical	REPAIR BROKEN EXHAUST STAY	PADDY	
R-4213	02/05/2017	654847		Starter Motor	Brisbane Workshop	Replaced starter motor	Tom	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-4213	02/05/2017	654847		O-Ring	Brisbane Workshop	Replaced O Ring in block for compressor coolant feed line	Tom	
R-4216	02/05/2017			Engine	Crank IT Mechanical	Asist in diagnosing faulty starter motor	Paddy	
R-4123	18/04/2017	646244		Mudguards	Brisbane Workshop	Replaced 4 drive mudguard bracketts	Brett	
S-6846	18/04/2017	646244		B - 18-22km	Brisbane Workshop	B Service completed Replaced diff oil - both diffs	Brett	
I-1081	28/03/2017	633505			Brisbane Workshop			\$0.00
S-6885	28/03/2017	633505		C - Annual	Brisbane Workshop	C Service completed	James	
S-6683	14/03/2017	624650		B - 18-22km	Brisbane Workshop	CHECK OVER GREASE CHANGE OIL & FILTERS CHANGE FUEL FILTERS	BRETT	
R-3973	14/03/2017	624650		Ice Pack	Brisbane Workshop	SERVICE ICE PACK	BRETT	
R-3866	27/02/2017	616854		Lights	Brisbane Workshop	REPLACED RH HEADLIGHT AND RH LOWER HEADLIGHT GLASS	BRETT	
R-3866	27/02/2017	616854		Gearbox	Brisbane Workshop	REMOVED & REPLACED GEARBOX COOLER	BRETT	
S-6515	13/02/2017	607445		B - 18-22km	Brisbane Workshop	B Service Check over Check lights Check for air leaks Tighen all intercooler hose clamps	Vince	
R-3816	13/02/2017	607445		Ice Pack	Brisbane Workshop	Service Ice Pack Adjust ice pack valve clearances Clean out Ice pack oil cooler	Vince	
R-3816	13/02/2017	607445		Gearbox	Brisbane Workshop	Gear box service Change gearbox oil filter	Vince	
S-6506	13/02/2017			B - 18-22km	Brisbane Workshop	B Service Check over	Andrew	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-3520	21/12/2016	590319		Power Steering	VCV Aust	CHECK POWER STEERING OIL LEAK-HOSE OR CONNECTION/FITTING LEAKING-TO GO TO VOLVO		
R-3520	21/12/2016	590319		Mirror	Brisbane Workshop	LH SPOTTER MIRROR LOOSE TIGHTEN SCREW & 1 BROKE. REMOVED BROKEN SCREW AND REPLACED WITH NEW SCREW-STILL LOOSE NEEDS FURTHER CHECKING	BRETT	
S-6211	21/12/2016	590319		B - 18-22km	Brisbane Workshop	CHANGE OIL & FILTERS CHANGE FUEL FILTERS CHECK OVER & GREASE CHECK FOR AIR LEAKS CHECK LIGHTS CHECK STEERING & SUSPENSION CHECK BRAKES	BRETT	
R-3520	21/12/2016	590319		Coolant	VCV Aust	CHECK COOLANT LEAK-POSSIBLE WATER PUMP SEAL-TO GO TO VOLVO		
T-2081	16/12/2016			Rotation	Tyres 4 U		56174	
S-6708	30/11/2016	575872		A - 5-9km	Toowoomba Workshop	A Service completed Replaced RH blinker bulb Replaced LH head light bulb Replaced roof lights Replaced belt on ice pack	Horse & Dan	
R-3382	24/11/2016	571019		Adblue	Brisbane Workshop	Checked for adblue leak - only found leak at cap. Dismantled cap, cleaned out crystalised adblue & reassembled	Vince	
R-3382	24/11/2016	571019		Ice Pack	Brisbane Workshop	Replaced ice pack drive belts	Vince	
S-5902	11/11/2016	562514		B - 18-22km	Toowoomba Workshop	B Service completed Tightened bolts on look down mirror Replaced air line at rear of cab	Dan & Horse	\$143.17
T-1931	10/11/2016			Balance	tyreright	2x disposal	46585	
T-1931	10/11/2016			Strip & Fit	tyreright		46558	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-5583	29/09/2016	539714		B - 18-22km	Brisbane Workshop	B Service completed Checked over Checked lights Checked for air leaks	Vin	
T-1697	01/09/2016	520779		New	Double D Tyre Right		81407	
R-2862	24/08/2016	517225		Fuel Filters	Toowoomba Workshop	CHANGE FUEL FILTERS	DAN	
S-5358	24/08/2016	517225		B - 18-22km	Toowoomba Workshop	B SERVICE COMPLETED	DAN	
R-2862	24/08/2016	517225		Air Conditioner	Toowoomba Workshop	CHANGE CAB A/C FILTER	DAN	
S-5229	21/07/2016	495387		B - 18-22km	Brisbane Workshop	B Service completed Checked over Checked lights Checked for air leaks	Vin	
T-1466	14/07/2016			Strip & Fit	TYRERIGHT BRISBANE	2 X DUMP OLE	46760	
T-1466	14/07/2016			Pressure Check	TYRERIGHT BRISBANE		46760	
T-1445	30/06/2016	481529		Rotation	Tyre Right		37480	
R-2458	17/06/2016	474438		Lights	Toowoomba Workshop	REPLACE 2 X LH & RH BLING LIGHTS REPLACE RH HEAD LIGHT BULB	HORSE DAN	
S-4895	17/06/2016	474438		B - 18-22km	Toowoomba Workshop	B SERVICE COMPLETED	HORSE DAN	
S-4676	11/05/2016	450897		A - 5-9km	Toowoomba Workshop	A SERVICE COMPLETED	HORSE DAN	
R-2266	11/05/2016	450897		Windscreen Repairs	Windscreen Professionals	WINDSCREEN REPLACED		
R-2266	11/05/2016	450897		Turntable	Toowoomba Workshop	RE-KIT TURN TABLE JAWS	HORSE DAN	
R-2211	05/05/2016	446576		Lights	Toowoomba Workshop	ADJUSTED SPOT LIGHTS	DAN HORSE KELSO	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
S-4622	05/05/2016	446576		B - 18-22km	Toowoomba Workshop	B SERVICE COMPLETED	DAB HORSE KELSO	
R-2211	05/05/2016	446576		Smoke Alarm	Toowoomba Workshop	FIT NEW BATTERY TO SMOKE ALARM	DAN HORSE KELSO	
R-2215	21/04/2016			Battery	A1 Auto Electrical	REPLACE BATTERIES		
R-2169	18/04/2016	436412		Lights	Toowoomba Workshop	REPLACE 7PIN TRAILER PLUG	DAN HORSE KELSO	
S-4554	18/04/2016	436412		A - 5-9km	Toowoomba Workshop	A SERVICE COMPLETED	DAN HORSE KELSO	
S-4304	04/04/2016	425960		B - 18-22km	Toowoomba Workshop	Be service completed change fuel filters		
S-4243	18/03/2016	403652		A - 5-9km	Toowoomba Workshop	A SERVICE COMPLETED	HORSE DAN	
T-1241	15/03/2016	411683		New	Ringtread SA Pty Ltd	Scrap tyres at depot	34949	
T-1178	15/03/2016			Wheel Alignment	Hancock and Just			
T-1178	15/03/2016			Replacement	Hancock and Just			
S-4231	11/03/2016	409417		A - 5-9km	Toowoomba Workshop	A SERVICE COMPLETED	KELSO HORSE	
S-4584	11/03/2016	409449		C - Annual	Toowoomba Workshop	C Service completed	Horse	
R-1881	11/03/2016	409417		Anti Spray	Toowoomba Workshop	REPLACE ANTI SPRAY AT RHR GUARD	KELSO HORSE	
I-753	11/03/2016	409449			Toowoomba Workshop			\$0.00

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1832	03/03/2016	404444		Lights	Hot Wired	LOCATE & REPAIR BROKEN WIRE IN PLUG, EJECT PIN & USE & UNUSED PARK LIGHT PIN FROM PLUG TO BE FOR SPOT LIGHT POWER. TEST OK	34682	
S-4178	03/03/2016	404444		A - 5-9km	Toowoomba Workshop	A SERVICE FRONT LH SPOT NOT WORKING SEE REPAIR	KELSEY & DAMIAN	
R-1820	26/02/2016	401386		Fire Extinguisher	Toowoomba Workshop	TEST & TAG FIRE EXTINGUISHER	HORSE KELSO DAN	
S-4159	26/02/2016	401386		B - 18-22km	Toowoomba Workshop	B SERVICE COMPLETED	HORSE KELSO DAN	
R-1820	26/02/2016	401386		Lights	Toowoomba Workshop	REPAIR BROKEN TAIL LIGHT	HORSE KELSO DAN	
R-1820	26/02/2016	401386		Gearbox	Toowoomba Workshop	CHANGE GEAR BOX OIL & FILTER	HORSE KELSO DAN	
R-1820	26/02/2016	401386		Diffs	Toowoomba Workshop	CHANGE DIFF OIL	HORSE KELSO DAN	
S-3775	05/01/2016	368340		B - 18-22km	Toowoomba Workshop	B Service completed Checked over Checked lights Repalced A/C cabin filter	Vin	
R-1846	30/11/2015	352616		Airbag	VCV Aust	RIDE HEIGHT NOT LEVELLING PROPERLY CHECKED FOR AIR LEAKS-NONE FOUND CALIBRATED AIR SUSPENSION-RE TESTED, NO AIR LEAKS AND TRUCK DID NOT FAULT	8067501	
S-3378	05/11/2015	334850		B - 18-22km	Brisbane Workshop	B service	Vince	
S-3412	05/11/2015	334850		B - 18-22km	Brisbane Workshop	B service	Vince	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1384	27/10/2015	324876		General Repairs	VCV Aust	replaced muffler tightened LH spot mirror replaced fridge replaced RH fog light top cab light fitted new plug, terminal and light, replaced fuse in central locking, replaced rh headlight cover , replaced two amber celarance lights	8065453	
R-1280	15/10/2015	324953		General Repairs	Toowoomba Workshop	ice pack replacement		
T-737	12/10/2015			Replacement	Toowoomba Workshop	old tyres dumped repalce steer 385 65r 22.5 pirelli fh01 pos1,2		
R-1844	17/09/2015	308730		Lights	Nashtech Auto Electrics	REPLACED ORANGE LIGHT ON TOP OF CAB		
R-1844	17/09/2015	308730		Battery	Nashtech Auto Electrics	REPLACED 2 BATTERIES	45999	
R-1256	04/09/2015	300864		Gearbox	VCV Aust	Inactive faults for gearbox out of calibration Replaced k5 relay Calibrated clutch Fitted new windscreen washer hose		
S-2585	18/08/2015	290598		A - 5-9km	Toowoomba Workshop	A Service completed Replaced relays for ice pack Replaced main fuse for ice pack Serviced ice pack motor	Vin	
S-2456	03/08/2015	281411		B - 18-22km	Toowoomba Workshop	B service		
R-1845	01/08/2015	278024		Power Outlets	VCV Aust	REPAIRED POWER KICK BACK	8063730	
R-1845	01/08/2015	278024		Central Locking	VCV Aust	REPAIRED CENTRAL LOCKING	8063730	
R-1845	01/08/2015	278024		Mirror	VCV Aust	REPAIR LOOSE LEFT MIRROR	8063730	
R-1845	01/08/2015	278024		Fridge	VCV Aust	REPAIRED FRIDGE RATTLE	8063730	
R-1845	01/08/2015	278024		Lights	VCV Aust	REPLACED R/H FOG LENS	8063730	
R-1845	01/08/2015	278024		Shock Absorbers	VCV Aust	REPAIRED CAB SHOCKIES	8063730	

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1845	01/08/2015	278024		Lights	VCV Aust	REPAIRED TOP CAB LIGHT	8063730	
R-1845	01/08/2015	278024		Bullbar	VCV Aust	REPAIRED BULL BAR I BOLTS	8063730	
R-958	22/07/2015	272375		General Repairs	Toowoomba Workshop	remove 2 ram air intake and refit std intake fitted and wired up back up lights		
S-2406	22/07/2015	272375		A - 5-9km	Toowoomba Workshop	A service		
S-2340	11/07/2015	262993		B - 18-22km	Toowoomba Workshop	B Service completed	Vin & Dan	
R-957	17/06/2015	211124		General Repairs	VCV Aust	Repaired fuel line repaired central locking repaired engine fault re: lights repaired driver seat repaired sun visor bracket left side		
S-2006	29/05/2015	236229		B - 20k	Toowoomba Workshop	B service replaced headlight bulbs		
S-1752	21/04/2015	214695		A - 10k	Toowoomba Workshop	A Service completed	Vin, Dan & Kelso	
T-260	10/04/2015	205785		Replacement	Toowoomba Workshop	Old tyres runouts		
S-1690	02/04/2015	191694		C - Annual	Toowoomba Workshop	C service		
R-630	02/04/2015	191694		General Repairs	VCV Aust	could not find a fault with sun roof refitted curtain rail secured left hand fog light		
T-251	02/04/2015	201556		Replacement	Toowoomba Workshop	replaced tyres pos 1 and 2. 385-65R 22.5		
I-420	11/03/2015	187000			VCV Aust			\$0.00
I-382	09/03/2015	180285			Toowoomba Workshop	COR		\$0.00
I-410	03/03/2015	180285			Toowoomba Workshop	C service completed		\$0.00

Number	Date	Kilometres	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-478	24/02/2015	178240		General Repairs	Toowoomba Workshop	Serviced ice pack Replaced cab A/C filter Replaced 2 DG signs on front of truck	Kelso & Dan	
S-1133	16/01/2015	159490		B - 20k	Toowoomba Workshop	B Service completed Replaced wiper blades	Dan & Horse	
S-724	28/11/2014	138384		B - 30k	Toowoomba Workshop	B Service completed Checked batteries		
S-565	07/11/2014	125600		A - 10k	Toowoomba Workshop	CHECKED OVER CARRIED OUT A SERVICE FILL WINDSCREEN WASHER BOTTLE		
S-374	20/10/2014	114796		B - 30k	Toowoomba Workshop	CARRIED OUT B SERVICE REPLACE AIR FITTINGS AT SUZI COIL		
I-248	09/03/2014				Toowoomba Workshop			\$0.00
301 Records							TOTAL:	\$143.17