

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
06 Jan 2019	CHECK TRUCK AND FIT SPLASH GUARDS
06 Jan 2019	CREATE TEMPLATES
07 Jan 2019	MAKE UP STEP AND FIT. MAKE UP FIRE EXT BRKTS & FIT. MAKE UP RAKE HOE MNTS
07 Jan 2019	RUNNING AROUND TRYING TO FIND REINFORCED VINYL RUBBER
07 Jan 2019	WASH AND REFUEL TRUCK
07 Jan 2019	TAKE FOR TEST DRIVE. FIT GPS AERIAL BRACKET
07 Jan 2019	TRIED TO SOURCE GPS ADAPTER
11 Jan 2019	Misc Parts Issue
31 Jan 2019	Misc Parts Issue
02 Feb 2019	Misc Parts Issue
17 Feb 2019	Richards - Internal - T35 Service 10,388 k
02 Mar 2019	Misc Parts Issue
19 Mar 2019	Richards - Internal - T35 Service 19,629 km 512 hrs
02 Apr 2019	Misc Parts Issue
18 Apr 2019	Richards - Internal - T35 Service 29,958 km 771 hrs
02 May 2019	Misc Parts Issue
02 May 2019	SPEAK TO HARRY. SORT OUT FAULTS AS REQUIRED. SPOKE TO PHILIP ABOUT REPAIRS. SPEAK TO GAVEN AT CMV RE
23 May 2019	Richards - Internal - T35 Service 39,975 km 1,020 hrs
02 Jun 2019	DIAG REM SATELLITE TRACKING MODULE, TO BE SENT FOR REPAIRS
02 Jun 2019	Misc Parts Issue
02 Jun 2019	REFIT SATELLITE TRACKING UNIT AND SET UP WITH EZY2SEE ON THE PHONE
22 Jun 2019	Richards - Internal - T35 Service 49,174 km 1,249 hrs
02 Jul 2019	Misc Parts Issue
02 Jul 2019	TRAVEL TO COCKS RD. INVESTIGATE SATELLITE TRACKING NOT WORKING. SPOKE WITH EZ2C. THEY ASKED FOR THE
20 Jul 2019	Richards - Internal - T35 Service 58,128 km 1,492 hrs
02 Aug 2019	Misc Parts Issue
02 Aug 2019	REFIT SATELLITE TRACKING & LOG IN WITH EZYC RETN BOMBALA
24 Aug 2019	Richards - Internal - T35 Service 69,540 km 1,789 hrs
02 Sep 2019	Misc Parts Issue
02 Sep 2019	REPAIRED ROLLER ON BACK OF A TRAILER
28 Sep 2019	Richards - Internal - T35 Service 79,393 km 2,064 hrs
02 Oct 2019	Misc Parts Issue
02 Nov 2019	AIR BAG
02 Nov 2019	Misc Parts Issue
02 Nov 2019	Richards - Internal - T35 Service 88,738 km 2,303 hrs
07 Dec 2019	Richards - Internal - T35 Service 100,164 km 2,567 hrs
13 Dec 2019	Richards - Internal - Adblue
16 Dec 2019	Phillip Mitchell Tractor Repairs Pty Ltd - carry out 100,000 km service as per check sheet. r&r air dryer filter with new. r&r both air filters with new. connect laptop to check ad blue faults - found low pressure faults. r&r all ad blue filters with new as were due. clear faults and recheck ok. tighten loose crossover b ar. carry out 250 hr service on both trailers. r&r broken fitting on 'a trailer level valve rod cvl with new.
16 Dec 2019	Phillip Mitchell Tractor Repairs Pty Ltd - gear oil, grease, diff filter, air filter, ad blue gauze filer, ad blue filter, ad blue pick up filter, air drier filter, power steering filter, engine filter kit, gearbox oil filter, gearbox oil, engine oil, quick fit elbow
30 Dec 2019	Richards - Internal - WPT26570195WGC28 265/70R19.5 Windpower WGC28
30 Dec 2019	Richards - Internal - Truck tyre disposal

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
11 Jan 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease and check over truck and trailers
21 Jan 2020	Richards - Internal - 295/80R22.5 152/149K Michelin XWZ Drive tyres
12 Feb 2020	Richards - Internal - Glass cleaner
12 Feb 2020	Richards - Internal - Gloves
13 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - R&R RHR mudguard, poles and brackets with new
13 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Fender pole, blue mudguard, mudguard brackets
15 Feb 2020	Richards - Internal - T35 Service 109,603 km 2,810 hrs
18 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out 250hr service. fit new mudflaps to rear of drive - reuse reflectors
18 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Eng oil, filter kit, grease, mudflaps, bolts, washers, coolant, windscreen additive
25 Feb 2020	Richards - Internal - 295/80R22.5 Bdy bandag
25 Feb 2020	Richards - Internal - Truck tyre disposal
28 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Connect computer to truck. fault find active code. Replace faulty sensor and connector. Clear faults. Road test - OK. Truck returns following day with fault present again. Diagnose exhaust brake air cylinder faulty. R&R exhaust brake actuator with new. Test - OK
28 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Connector
28 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Sensor back pressure
28 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Actuator
29 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and trailers
29 Feb 2020	Phillip Mitchell Tractor Repairs Pty Ltd - grease
14 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and both trailers as required. r&r cabin air filter with new
14 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
14 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Cab filter
21 Mar 2020	Richards - Internal - T35 Service 120,758 km 3,076 hrs
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out 250HR service. Replace leaking air fitting on 'A' trailer as required. Faults found during service - both drive belts slightly cracked, LH front shocker sweating
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Engine oil
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Swivel fitting
24 Mar 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
31 Mar 2020	Richards - Internal - plastic rego pockets
06 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and both trailers as required. R&R cab air filter with new. Repl air hose fitting and re route hose to prevent further damage to hose during loading
06 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Cab filter
06 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
06 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Fitting
06 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - consumables
21 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease and check over truck. Replace leaking safety valve on air compressor.
21 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Safety valve
23 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Safety valve - incorrect part charged on inv 24931
23 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Safety valve
24 Apr 2020	Richards - Internal - T35 Service 132,830 km 3,362 hrs
27 Apr 2020	Richards - Internal - tyre rotation
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Complete A and B services as per check sheets. Replaced broken LH tail light lens on truck
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Mack filter kit
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Oil 15w-40 x 40L
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Volvo engine oil 10L
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Filter cover
27 Apr 2020	Phillip Mitchell Tractor Repairs Pty Ltd - LH taillight lens
09 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease entire vehicle, check water and oil. repl 2 x broken bolts RHS A trailer Found leaking RH cab shock absorber. part ordered. customer to return for repairs
09 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
23 May 2020	Richards - Internal - T35 Service 142,576 km 3,615 hrs

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 250 hour service. R&R B brake switch valve. R&R air tank drain valve. made up new drain cable for front air tank drain valve. R&R front right cab shock. repl load binder release cable for A trailer
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - filter kit
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Volvo 50L
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Coolant
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Drain valve
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Tube
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Cab shock
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Stainless cable
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Cable crimps
25 May 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
28 May 2020	Richards - Internal - Daniel Mudge Replace hammer lock on pull up chain on A trailer Diagnose & carry out forced re set on satellite tracking with Ezy2C 2.5 hours
03 Jun 2020	Richards - Internal - Michelin Steer Tyres
06 Jun 2020	Nolan Auto Parts & Industrial Supplies - Foaming gun
10 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - grease on truck +trailer find oil leak under cab
11 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Repair brackets for chains (saturday labour rate applied)
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Oil leak L/H side transmission. Replaced both oil cooler hoses on transmission, topped up trans oil. (Saturday rate)
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 10L CAL8394882 Oil SAE50
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22429386 Hose
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22429384 Hose
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Repairs - Hyd oil leak, air leak uder turntable, reinstall bolts, etc. (Saturday Rate)
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 3.5 x CAL8394882 Gearbox Oil
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - ABI62005 Joiner
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 5/8 UNC Bolt
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 5/8 Nyloc Nut
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 5/8 Washer
22 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
25 Jun 2020	Traralgon Tyrepower - 265/70R19.5 Tyres
25 Jun 2020	Traralgon Tyrepower - Tyre Disposal
26 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Check for coolant leak, top up coolant, fit new binder cable. (1.5 hrs)
26 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 1.5m Stainless Cable
26 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Ferrule Crimp
26 Jun 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Coolant 2L
27 Jun 2020	Richards - Internal - T35 Service 27/06/20 154,429 km 3,905 hrs
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr Service. Replaced inoperative clearance light on B-Trailer. Top up coolant. Replace fan and alternator belts. Replaced failed bearing in idler pully. (Saturday labour rate applied)
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 6304 Bearing
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22950564 Belt
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22950621 Belt
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85121797 Volvo Engine Oil 50L
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 8394800 Volvo Coolant 2L
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease Cartridge
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Washer Additive
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL8394882 Volvo SAE50 Trans Oil 2L
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 2053 Bulk
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - SK074 Seal Kit
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - GK010 Mounting Gskt Kit
02 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
13 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Diagnose and fix low fan air flow in cab. (saturday labour rate)
13 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAC-24100 Cab Filter

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
25 Jul 2020	Richards - Internal - T35 Service 164,393 km 4,163 hrs
25 Jul 2020	Traralgon Tyrepower - 11R22.5 Bandag Retread Tyres (pos 3 4 5 6 7 8 9 10)
25 Jul 2020	Traralgon Tyrepower - 11R22.5 Case
29 Jul 2020	Traralgon Tyrepower - Adblue
29 Jul 2020	Traralgon Tyrepower - Adblue
29 Jul 2020	Traralgon Tyrepower - (EDEN) Loadbinder Straps
29 Jul 2020	Traralgon Tyrepower - Gloves
29 Jul 2020	Traralgon Tyrepower - Glass Cleaner
29 Jul 2020	Traralgon Tyrepower - Adblue
30 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr service. R/H bullbar indicator and parker needs replacing. B-Trailer L/H 2nd last clearance light needs replacing. (Saturday labour rate)
30 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
30 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85115988 Coolant 1.5L
30 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121797 Engine Oil 53L
30 Jul 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Drain gearbox oil, remove power take off and pump, disassemble PTO and replace seals and o-rings. Reassemble and fit back to gearbox. Fill gearbox with new oil. Change filter, test. Grease and check over truck and trailers. Check oil and water. Add 2L engine oil.
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 20779040 Gearbox Filter
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 8394882 Gearbox Oil
12 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121798 15W-40 Oil
14 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Refit fuel tank rubber on front support.
20 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Re-fasten hydraulic tank
24 Aug 2020	Traralgon Tyrepower - Adblue
24 Aug 2020	Traralgon Tyrepower - Puncture repair
24 Aug 2020	Traralgon Tyrepower - Tyre Disposal
24 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Travel to vehicle, diagnose fault - flat batteries. Jump start truck.
24 Aug 2020	Traralgon Tyrepower - Adblue
24 Aug 2020	Traralgon Tyrepower - Adblue
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out B-service as per check sheet. Repair brake light contacts on both L/H and R/H tail lights. Replace blown park light globe on both. Repair wiring to R/H bullbar lights. Connect laptop and troubleshoot faults for data link wire. Inspect harness - no faults. Clear faults. Jack drivewheels up and confirm power divider and diff locks are engaging. Check and adjust power divide. Inspect solenoids and clean connects. (saturday labour rate)
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 5007ULT-02B 12v Globe
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121798 VDS4 Engine Oil 50L
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
31 Aug 2020	Traralgon Tyrepower - Adblue
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Supply and fit 4 new batteries. Remove batteries, clean carriers and terminals, fit new batteries. Reassemble. Test - all ok.
31 Aug 2020	Phillip Mitchell Tractor Repairs Pty Ltd - MF95D31R Batteries
08 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease over truck and trailers, redrill holes in mudguard and refit mudflap. tighten loose J-bars. Deliver truck to customers yard. (saturday labour rate)
08 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
14 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Remove old dash cam and wiring harness. Install new one supplied and wire up. Tighten and adjust L/H rear drive guard.
14 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
17 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Repair air leak on fire wall by replacing air blanking plug
17 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 8077186 Plug
21 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease over truck and trailers, repair daylight running light wiring in bullbar. Adjust loading chain, inspect and test diff lock - ingauging fine. No air leaks. Tried several times to get it to leak.
21 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
21 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
23 Sep 2020	Traralgon Tyrepower - Tyre Drive Rotation
23 Sep 2020	Traralgon Tyrepower - 295/80R22.5 Michelin Steer Tyre
23 Sep 2020	Traralgon Tyrepower - 265/70R19.5 Falken Drive Tyres
23 Sep 2020	Traralgon Tyrepower - Truck Tyre Disposal

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
26 Sep 2020	Richards - Internal - T35 Service 188,348 km 4,745 hrs
26 Sep 2020	Traralgon Tyrepower - 265/70R19.5 Windpower Tyre (pos 33 34)
26 Sep 2020	Traralgon Tyrepower - Tyre Disposal
28 Sep 2020	Traralgon Tyrepower - Adblue
28 Sep 2020	Traralgon Tyrepower - Adblue
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out service on truck as per check sheet. Carry out trailer inspection. Replace cab air filter. Fit/wire in new LED tail lights on 6-pin. Fit connectors with reverse lights, reverse light holder.
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121797 Volvo Oil 48L
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAC-24100 Cab Air Filter
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - LS9081 Tail Light
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - EL1454 Reverse Light
29 Sep 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
29 Sep 2020	Traralgon Tyrepower - Adblue
29 Sep 2020	Traralgon Tyrepower - Adblue
30 Sep 2020	Traralgon Tyrepower - Adblue
07 Oct 2020	Traralgon Tyrepower - Adblue
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out A-service on truck. Grease over truck and trailers. Check over - all looks ok.
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85112988 Mack Coolant 4L
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121797 Volvo Engine Oil 1L
12 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - WSRMSM10F Flat Washer
19 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Locate air leak on truck and found air line rubbed through on chassis. Remove intake pipe for access, cut out damaged section of hose and fit new tail section with joiner, Remove crimp from hook pull cord. Remove hook and straighten. Cut off top section of hook to prevent catching. Refit and recrimp cable to hook.
19 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - ABI62005 Nylon Tube Joiner
19 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - AB7807B25 Black Nylon Tube
19 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Swage Crimp
22 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Perform valve adjustment, replace engine air filters, replaced CDI air filter housing, check circuit breakers for amperage
22 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85129688 Air Drier Gasket
22 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 20736230 Rocker Cover Gasket
22 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 57MD42M Air Filter
22 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CTI-B0200 Filter
26 Oct 2020	Traralgon Tyrepower - Nut Cover
28 Oct 2020	Richards - Internal - T35 Service 198,667 km 4,987 hrs
28 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Hook up tech tool, found high boost fault logged from today. Test wastegate stroke via actuator bypass test. Perform warm hold test - all ok. Suspect AVU is not supplying air to wastegate intermittently causing boost spike. Replace AVU valve and road test. Exhaust brake also coming on as per normal, may have also been affected by faulty AVU. Found boost reading at 6KPA at idle and 3 when engine is not running - suspect map sensor may also be faulty giving false readings. Order map sensor for future repairs.
28 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 21426909 Air Valve Diverter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out C-service as per check sheet. Carry out trailer inspection as per check sheet. Replace all oils and filters. Replace both adblue filters. Replace noisy belt tensioner. Header tank has small leak. R/H 2nd drive brake shoes contaminated with oil and signs of grease on backing plate - either s-cam grease seal or hub seal. Check and found cab air cleaner is blocked - replace filter.
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 5839-870678A Power Steering Filter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 20779040 Gearbox Oil Filter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 32052 GW 85W140 Oil 25L
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121797 Engine Oil 50L
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL8394882 SAE 50 Oil
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 32041 ATF DEXIII 2L
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22406383 Adblue Tank Filter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 23381562 Adblue Main Filter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - A3380W1687 Diff Oil Filter
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 2189687 Alternator Tensioner
29 Oct 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAC-24100 Cab Air Cleaner
30 Oct 2020	Traralgon Tyrepower - Adblue
30 Oct 2020	Traralgon Tyrepower - Adblue
02 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Diagnose coolant leak and found expansion tank leaking. Remove and renew expansion tank and refill coolant - all ok.
02 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 23059017 Tank Expansion
02 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85112988 Mack Coolant
02 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
04 Nov 2020	Traralgon Tyrepower - Adblue
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease over truck and trailers. Renew axle 3 L/H mudguard on drive. Fit 2 new mud flaps and signs. Install resistors to indicators to stop from flashing fast. Repair broken wires to lights in bull bar both sides. Replace blown roof light bulb. Replace broken work light brackets, back of drive. Adjust R/H mirror bracket.
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 9728-0624BM1MK18 Mudflap
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CA5470W Blue Guard
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 47QM4902M Mudflap
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CA7178 Sign
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 47501 12v Wedge Globe
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CA7179 Sign
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 680.076 Red Butt Connector
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Clearance Light
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 782-0757 Blue Butt Connector
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 57439 Deutsch Connector
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Work Light Bracket
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - LR12/2 Load Resistor
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - UNC Bolt 3/8 x 1 1/2
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 3/8 UNC Nut
11 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Flat Washer
16 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Investigate exhaust leak and found V-clamp after exhaust brake has come loose and fallen off. Refit clamp and tighten, test - all ok.
20 Nov 2020	Traralgon Tyrepower - Adblue
21 Nov 2020	Richards - Internal - T35 Service 206,856 km 5,189 hrs
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out A-service on truck and trailers. Grease over, adjust brakes and clutch.
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Reseal air leak on ride height valve B-trailer
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - ABM62520 8mm Joiner
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - AB6179N Olive 8mm
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAC24100 Cabin Filter
23 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
26 Nov 2020	Traralgon Tyrepower - 295/80R22.5 Bandag Tyre
26 Nov 2020	Traralgon Tyrepower - Truck Case
26 Nov 2020	Traralgon Tyrepower - Adblue
26 Nov 2020	Traralgon Tyrepower - 265/70R19.5 Falken Tyre
26 Nov 2020	Traralgon Tyrepower - Tyre Disposal
27 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Remove and renew bolts on A-trailer turntable cradle. Remove and renew air fitting on raise/lower valve.
27 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - ABM69521S Elbow Fitting
27 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Bolt
27 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Nut
27 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Washer
28 Nov 2020	Richards - Internal - T35 Service 208,803 km 5,239 hrs
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Fit new safety valve. Replace fitting on level air cylinder.
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - ABM69525S Fitting

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 22024367 Safety Valve ST4
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out service on truck and trailers
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85121797 Engine Oil 51L
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
30 Nov 2020	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85112988 Mack Coolant 2L
01 Dec 2020	Traralgon Tyrepower - Adblue
03 Dec 2020	Traralgon Tyrepower - Adblue
11 Dec 2020	Phillip Mitchell Tractor Repairs Pty Ltd - Test seat. Remove base. Inspect height control valve. Clean dust and dirt. Lube up linkages. Test - ok. Order new valve.
22 Dec 2020	Traralgon Tyrepower - Adblue
23 Dec 2020	Traralgon Tyrepower - 295/80R22.5 Michelin Tyre
04 Jan 2021	Traralgon Tyrepower - Adblue
04 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Remove seat squab to access level valve in seat. Remove and renew seat level valve. Build up air and test - all ok.
04 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1847100 Valve Kit
04 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
16 Jan 2021	Richards - Internal - T35 Service 220,429 km 5,517 hrs
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Service. Fit new hub seal axle 3 R/H side. Fit new brake shoe. Test repairs - all ok.
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 4707QP Brake Shoe Kit
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 47693 Hub Seal
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 32052 Diff Oil
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter Kit
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Engine Oil 50L
18 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
21 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Poor A/C performance. Test gas pressures - ok. Replace cabin filter. Test system - sits at 6 - ok.
31 Jan 2021	Traralgon Tyrepower - Tyre Rotation
31 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and trailers, check over. Test air supply system on truck. Find compressor running for excessive time. Remove air dryer silencer, air dryer leaking when compressor pumping. New air dryer needed. Not purging, filling tanks with moisture.
31 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
31 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
31 Jan 2021	Phillip Mitchell Tractor Repairs Pty Ltd - AB3568 Hose Clamp
03 Feb 2021	Traralgon Tyrepower - Adblue
03 Feb 2021	Traralgon Tyrepower - Adblue
04 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Remove checker plate, drain air tanks, remove and renew air dryer. Run truck, drain tanks multiple times, check for leaks - all ok. Reinstall checker plate.
04 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 22896454 Air Dryer Kit
08 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Found idler pulley seized, remove and renew idler pulley and fan belt.
08 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 21753149 Pulley Kit
08 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 22950564 Belt
08 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
08 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and trailers and check over.
18 Feb 2021	Leak behind cab, found CTI water trap leaking - ordered new on. Tightened loose bolt LH side B trailer. Top up coolant and check engine oil.
18 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
18 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
18 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85112988 Mack Coolant 4lt
19 Feb 2021	Richards - Internal - T35 Service 19/02/21 230,023 km 5,762 hrs
22 Feb 2021	Nolan Auto Parts & Industrial Supplies - MC553B Speaker Mic Heavy Duty
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr service Fitted new heater fan, fitted new cabin filter, fitted new intercooler rubbers, fitted new water trap bowl for CTI
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Filter kit
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CTI-204 Filter bowl
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CAC-24100 Cabin Filter x 2
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 85113771 Blower motor
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 85111312 Upper MTG Kit
22 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 50L CAL851217 Volvo VDS4 Eng Oil
23 Feb 2021	Richards - Internal - Brendan Collins Check over truck and trailers, inspect mudguards and mud flaps 1hr
24 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - UHF handpiece not working, remove dash and fit new handpiece.
24 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Exhaust shroud bracket broken RHS. Remove RH exhaust shroud and repair bracket. Replace missing sign on LH drive.
24 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CA7178 sign
24 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1/2 x 20 mushroom head bolts x 4
24 Feb 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
26 Feb 2021	Nolan Auto Parts & Industrial Supplies - MG650.LB Mudguard
28 Feb 2021	Traralgon Tyre Service - Truck strip and fit
28 Feb 2021	Traralgon Tyre Service - Tyre disposal
01 Mar 2021	Transall Motors Pty Ltd - DYGPLP630LBU L/P light blue guards
01 Mar 2021	CMV Truck & Bus Pty. Ltd - AM97280624BM1MK18 15/24 mack mudflaps
01 Mar 2021	CMV Truck & Bus Pty. Ltd - MK47QM49402M 6/24 mack mudflaps
01 Mar 2021	CMV Truck & Bus Pty. Ltd - MK47QM49402M7 18/24 mack mudflaps
02 Mar 2021	Traralgon Tyre Service - Adblue
02 Mar 2021	Traralgon Tyre Service - Adblue
05 Mar 2021	Traralgon Tyre Service - Adblue
17 Mar 2021	Traralgon Tyre Service - 20/20 Glass Cleaner
17 Mar 2021	Traralgon Tyre Service - Gloves
17 Mar 2021	Traralgon Tyre Service - CTI Coupling
17 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Cab mounts loose. Refasten L/H side cab mount, replace cab mount nut/washer R/H side, remount V-band clamp rear of exhaust brake actuator, tightened radiator hose clamps on top hose. Drill no2 fuel tank brace mounts R/H side, rebend mount bracket, refasten with new nuts, bolts and washers. Remount broken no plate. check EBS faults.
17 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
18 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Boost leak. Found hose and hose clamp damaged
18 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 20705900 Clamp
18 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - AB3569 Hose Clamp
18 Mar 2021	Traralgon Tyre Service - 11R22.5 Bandag Recaps
18 Mar 2021	Traralgon Tyre Service - Disposal
18 Mar 2021	Traralgon Tyre Service - 265/20R19.5 Falken Tyres
18 Mar 2021	Traralgon Tyre Service - Tyre Disposal
20 Mar 2021	Richards - Internal - T35 Service 239,265 km 6,020 hrs
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: B service due, EBS download, airleak with red button. top radiator hose. Repairs Consumables
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 x 85114535 filter kit
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 5L x Cal85112988 mack coolant
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 x AB1156S brake booster
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 x 22891920 radiator hose
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 x BPW Type 30air bag base only
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 2 x 01010-61650 bolt
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 x m16x75 airbag bolt
22 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - labour 9 hours
22 Mar 2021	Richards - Internal - BJ Collins Fit new mudguard and mud flap to RH front drive wheel 2.5 hours
26 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Engine wont start, found starter faulty, removed and replaced, tested ok
26 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
26 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 8201064 Starter

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
26 Mar 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 52-0040 Bush x 3
30 Mar 2021	Traralgon Tyre Service - Adblue
01 Apr 2021	Traralgon Tyre Service - Adblue 8/3/20
01 Apr 2021	Traralgon Tyre Service - Adblue 18/3/21
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - TRAILER EBS FAULTS. CAB LEAKING WATER. HEATER FAN LOW POWER. A/C NOT COLD ENOUGH. A-TRAILER HEIGHT LEVEL VALVE - BOTTOM HOSE RIPPED OFF/SNAPPED FITTING. L/H CAB SHOCK LEAKING. CAB SIDE DOORS LOOSE. EXHAUST CLAMP UNDER CAB. FUEL LEAK, FAN SHROUD BROKEN (FUEL TANK NEEDS WELDING, FAN SHROUD NEEDS REPLACING.
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - ABM69525S Air Fitting
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CAC-24100 Cabin Filter
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Exhaust Brakes Sticking - Replace AVU for exhaust brake.
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
12 Apr 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 22539850 Air Valve
13 Apr 2021	Richards - Internal - Brendan Collins Fit new number plates 1hr
30 Apr 2021	Traralgon Tyre Service - 295/80R22.5 Michelin TyreS
30 Apr 2021	Traralgon Tyre Service - Disposal
01 May 2021	Timeng Pty Ltd - Remove and repair bent exte winch brum refit
03 May 2021	Richards - Internal - T35 Service (No details provided)
04 May 2021	Traralgon Tyre Service - Adblue 6/4, 9/4, 15/4, 21/4, 26/4
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr Service Remove and renew radiator shroud
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Electrical terminals
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Oil
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Fan Shroud
05 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Fan Ring
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease truck and trailers Crimp new crimp to remove release, reconnect earth wire on cab locker box light. Made up new earth wire for bullbar lights, then connected up. Drilled and fitted RH side mudflap safety sign, secured numberplate lights back onto truck.
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Safety sign
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CW2301 wire
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Connector
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Ring Terminal
19 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Connector
20 May 2021	Traralgon Tyre Service - Wheel rotation Phillip Mitchell Tractor Repairs Pty Ltd - : WIPER BLADES U/S. AIRLEAK FROM DIFF LOCK. COOLANT LOW. R/H REAR DRIVE MUDGUARD LOOSE.
31 May 2021	ENGINE OIL LOW. NUMBER PLATE FALLEN OFF. LEAKING AIR UNDER BONNET WHEN USING EXHAUST BRAKE. BONNET RUBBING ON CAB R/H SIDE UNDER WINDSCREEN. CABLE BROKEN ON R/H TOOLBOX DOOR
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 47336 Cabin Light
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 82710488 Wiper blade
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1/4x20 Mushroom head
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Mushroom head nut
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 22889891 Actuator kit
31 May 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 84192243 Spacer
02 Jun 2021	Traralgon Tyre Service - Adblue
19 Jun 2021	Traralgon Tyre Service - Screw on Caps
19 Jun 2021	Traralgon Tyre Service - Gloves1
19 Jun 2021	Traralgon Tyre Service - 20/20 glass cleaner

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
19 Jun 2021	Traralgon Tyre Service - CRC
19 Jun 2021	Traralgon Tyre Service - Loadbinder strap
22 Jun 2021	Richards - Internal - T35 Service 263,380 km 6,568 hrs
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Carry out service on truck and trailers. Installed new spade connector on RH bullbar circuit. Install bonnet spacers to lift bonnet. move mounts forward until cab mounts can be installed.
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Volvo VDS4 engine oil
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Spacer kit
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Male plug
23 Jun 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Female plug
29 Jun 2021	Traralgon Tyre Service - Puncture repair
06 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Replace air pressure valve
06 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Fitting
12 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Reposition tank straps
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - replace left and right hand exhaust elbows. Replace cab bump stop and bushings. Top up oil and coolant
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - VDS4 engine oil
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Coolant
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Elbow
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Support
13 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Rubber spring
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - L/H REAR DIFF BEAM EYE BOLT MISSING. Fit new aligning plates bolt washer and nut, adjust axle
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Quick align washer
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Hex screw
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Repair leaking L/h fuel tank. mudguard r/h axle 3 truck damaged. l/h cab mount u/s.
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Welding of tank
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Mudflap
19 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease over and weekly check
20 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Repair AIRLEAK FROM B-TRAILER Travel to site for job
20 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Travel
20 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Air drain
22 Jul 2021	Traralgon Tyre Service - 295/80 R22.5
22 Jul 2021	Traralgon Tyre Service - Disposal
22 Jul 2021	Traralgon Tyre Service - CTI coupling
22 Jul 2021	Traralgon Tyre Service - CTI hose straight
22 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - L/H REAR DIFF BEAM EYE BOLT MISSING. Parts missing from invoice 29188 Washer
22 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Washer
22 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Hex nut
24 Jul 2021	Richards - Internal - T35 Service 275,771 km 6,833 hrs
28 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr service as per attached invoice
28 Jul 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Parts and consumables
03 Aug 2021	Traralgon Tyre Service - Adblue for July
17 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Coolant leaking from overflow. Fit overflow bottle to header tank to confirm if pressurising. Top up coolant.
17 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CAL85112988 Coolant 20L
20 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Low coolant, topped up. Air leak on trailer - ordered replacement valve.
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Brake solenoid valve leaking. using coolant. clearance light pole broken.
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Side light assembly

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Wash, top up coolant. Supply coolant drum. add stopleak.
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Stop leak
30 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Mack coolant
31 Aug 2021	Traralgon Tyre Service - Adblue 2/8, 12/8, 24/8
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 250hr service. a&b trailer service. Seized fan clutch. cti rotator replace
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - VDS4 Engine oil
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Wassher additive
31 Aug 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Rotator
03 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Repair - Hammer lock on trailer load chain snapped.
03 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Connecting link
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: exhaust leak - leak on turbo outlet flange, missing 4 out of 6 bolts. Grease over truck and trailers. Air leak in truck. air leak in a-trailer - found split hose in chassis rail on truck.
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Fitting
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Joiner
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Turbo drain gasket
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Oil feed gasket
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - O ring
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Turbo gasket
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Bolt
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Clamp
13 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
14 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CAB AIR LEVEL VALVE LEAKING. COOLANT LOW - fit new cab air level valve
14 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Cab level valve
14 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Mack coolant
15 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: coolant leak - transmission oil cooler radiator leaking - replace.
15 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Radiator
15 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Coolant
15 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
27 Sep 2021	Sapphire Coast Fire & Safety - Fire extinguisher servicing
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: 250hr service due. mudflaps need replacing. running lights on bullbar in/op
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Engine oil
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Ring terminal
27 Sep 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Air filter
30 Sep 2021	Traralgon Tyre Service - Adblue 3/9, 17/9, 28/9
06 Oct 2021	Traralgon Tyre Service - 295/80 R22.5 Michelin
06 Oct 2021	Traralgon Tyre Service - Rotation
08 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: broken hammer lock - load chain adjuster
08 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 101810 Connecting link
13 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: <ul style="list-style-type: none"> •strap release cable broken •grease truck and trailers. •mudguard axle 1 r/h side b-trailer broken •check air leaks on trailer
13 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
13 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Cable pull
13 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
13 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Mudguard
23 Oct 2021	Richards - Internal - BJ Collins Refit air tanks and plumb up 2 hrs
29 Oct 2021	Richards - Internal - BJ Collins Remove broken drain cork from air tank and fit block off plug 2.5 hrs

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
30 Oct 2021	Traralgon Tyre Service - Aluminum cleaner
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: L/H rear drive shock u/s. seat goes up and down while sitting in it. air leak on a-trailer level valve rod. Emergency brake on b-trailer not working. service brake valve on b-trailer damaged. axle 1 L/H side b-trailer airbag u/s.
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Shocker
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Valve
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - SR3 valve
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Elbow fitting
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Airbag w base
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Barb fitting
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Clamp
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Elbow fitting
30 Oct 2021	Phillip Mitchell Tractor Repairs Pty Ltd - R12P valve
03 Nov 2021	Traralgon Tyre Service - 265/70 R19.5 Windpower
03 Nov 2021	Traralgon Tyre Service - Disposal
03 Nov 2021	Traralgon Tyre Service - Adblue - Oct
17 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - engine brake not working, found dirty contacts on back pressure sensor
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CARRY OUT 100,000KM SERVICE AS PER CHECK SHEET, CARRY OUT VALVE ADJUSTMENT. REMOVE AND RENEW ADBLUE FILTER.
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - CONSUMABLES
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X 57MD42M AIR FILTER
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 8235A3380W1687 DIFF FILTER
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 36L X 32052 GW GEAR OIL
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 5839-870678A FILTER
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 5L X 32041 GW DEXIII TRANS FLUID
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 20779040 FILTER
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 20L X CAL8394882 TRANS OIL
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 85114535 FILTER KIT
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 50L X CAL85121798 VDS4 ENGINE OIL
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - GREASE
22 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 23381558 ADBLUE FILTER
24 Nov 2021	Traralgon Tyre Service - 295/80R 22.5 Tyre
24 Nov 2021	Traralgon Tyre Service - Disposal
24 Nov 2021	Traralgon Tyre Service - 295/80R 22.5 Case Pentarch Logistics - Repairs to Truck Rego XV77BN damaged at Pentarch on 21/10/21
30 Nov 2021	Repair Summary: Ext Labour/Parts 23/10 - \$465 Int Labour 23/10/21 - 2 hours @ \$80ph Int Labour 29/10/21 - 2.5 hours @ \$80ph (supporting documentation provided)
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 21469181 BOLT
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 21469181 NUT
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X 21469187 WASHER
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 20755337 ALIGNMENT WASHER
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 20755339 ALIGNMENT WASHER
30 Nov 2021	Phillip Mitchell Tractor Repairs Pty Ltd - REPAIRS: DRIVE TRUCK INTO WORKSHOP. RE-ALIGN AXLE. INSTALL NEW WASHERS, BOLTS AND NUTS. REALIGN. RETURN TRUCK TO CUSTOMERS YARD.
02 Dec 2021	Traralgon Tyre Service - 10 NOVEMBER 2021 ADBLUE
02 Dec 2021	Traralgon Tyre Service - 23 NOVEMBER 2021 ADBLUE
09 Dec 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Tank strap
09 Dec 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Wire crimp
09 Dec 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Hose
09 Dec 2021	Phillip Mitchell Tractor Repairs Pty Ltd - P Clamp
09 Dec 2021	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: R/H fuel tank turned - hard to get fuel cap. Strap release cable broken front of A-Trailer.
23 Dec 2021	Traralgon Tyre Service - Adblue

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
06 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Truck not starting, tested batteries - unserviceable Replaced 4 x batteries
06 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 4 x Batteries
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REPAIRS: CARRY OUT 250HR SERVICE ON TRUCK AND TRAILERS AS PER CHECK SHEET.
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 50L X CAL85121797 VDS4 ENGINE OIL
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 85114535 FILTER KIT
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X CAC-24100 CAB FILTER
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
13 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 22024367 Safety Valve
13 Jan 2022	Richards - Internal - Adam Vary Air compressor valve and hose. 2.5 hrs
13 Jan 2022	Richards - Internal - BJ Collins Replace safety valve in outlet pipe from, compressor 2.5 hrs
18 Jan 2022	Richards - Internal - Adam Vary Attempt to repair GPS, replace compressor hose and engine belts 5 hrs
20 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 22950564 Belt
20 Jan 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 22950621 Belt
26 Jan 2022	Richards - Internal - Adam Vary Fit new GPS unit 3 hrs
26 Jan 2022	Richards - Internal - BJ Collins Remove old GPS tracking unit, fit new GPS tracking unit, check over truck and trailers 1.5 hrs
31 Jan 2022	Traralgon Tyre Service - Adblue
02 Feb 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
02 Feb 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
02 Feb 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 22114869 Discharge Pipe
02 Feb 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Truck not building up air pressure. Remove and renew discharge lower line - upper still to replace. Grease over truck.
02 Feb 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease over trailers.
07 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - PICK UP TRUCK FROM CUSTOMERS YARD. REMOVE SEAT CUSHION. REMOVE AND RENEW SEAT VALVE. TEST - ALL OK. REINSTALL CUSHION. DROP TRUCK BACK TO YARD.
07 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 1847100 SEAT LEVEL VALVE
09 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - B Service on truck
09 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
09 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Filter kit
09 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
09 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - VDS4 oil
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REMOVE BRACKET FROM DOOR AND WELD REPAIRS. REFIT AND TEST OPERATION - OK. TIGHTEN UP BRACKET TO L/H SIDE EXHAUST. REPLACE MISSING RELEASE CABLE. TIGHTEN LOADING CHAIN. RENEW LEAKING AVU VALVE.
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2.5M X STAINLESS CABLE
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X CRIMP CABLE CRIMP
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 22539850 AIR VALVE
10 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REMOVE HUB FROM AXLE, CLEAN UP THREADS AND AXLE. ASSEMBLE NEW HUB TO SPEC WITH ALL NEW HARDWARE AND BEARINGS. PREPACK BEARINGS. FIX EBS SENSOR BRACE, INSTALL NEW WHEEL SPEED SENSOR. CABLE TIE AND ROUTE. REMOVE S-CAM EXTRACT OLD BUSH, REMOVE ALL OLD HARDWARE, INSTALL NEW BUSH, INSTALL S-CAM WITH ALL NEW HARDWARE TO SPEC.
17 Mar 2022	INSTALL BRAKE SHOES, INSTALL HUB, ADJUST BEARING TO SPEC. CHECKOVER ALL. INSTALL AND TENSION WHEELS. TENSION HUBCAPS. ADJUST BRAKES. TROUBLESHOOT LEVEL VALVE, FOUND BROKEN FITTINGS. REMOVE AND RENEW FITTINGS. CABLETIE AIRLINES OUT OF WAY. CONNECT LAPTOP TO TRUCK AND CHECK FAULT CODES. FOUND EXHAUST BACK PRESSURE SENSOR FAULT. REMOVE AND RENEW SENSOR AND CONNECTOR. TEST AND CLEAR FAULTS
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - consumables
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0256065890 CIRCLIP INNER

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0980107050TSSC BEARING KIT
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0580700440 NUT KIT
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0509700KIT S-CAM KIT
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0256062290 CIRCLIP OUTER
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0327246390 HUB
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0531008441 TONE RING
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X AB8690 SENSOR
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0203165900 SENSOR BUSH
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 0509119220BH95 BRAKE SHOE KIT
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 85139619 EGP SENSOR
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 21582423 PIGTAIL CONNECTOR
17 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 3 X QFM5-8MMX1/8 FITTING
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X 23235129 AIRBAG
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X 85109229 BUSH
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 4000-60383000 D BUSH
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Freight
24 Mar 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REPAIRS: REMOVE REAR DRIVE SUSPENSION BEAMS, PRESS OUT OLD WORN BUSHES, PRESS NEW BUSH IN X4, 2 LOWER D BUSHES AND 2 PIVOT BUSHES. FIT BEAM AND ALIGN AXLE. R/H SIDE AIRBAG REAR HAS CRACKS, REPLACE AIRBAG. L/H SIDE AIRBAG REAR IS WORN WHERE BROKEN SHOCK MOUNT HAS BEEN RUBBING, REPLACE AIRBAG. REPLACE MISSING L/H REAR SHOCK MOUNT BOLTS, NUTS AND WASHERS. GREASE OVER TRUCK AND TRAILERS. CHECK OVER. TIGHTEN ADJUST R/H REAR GUARD J-BAR. CHECK ALL, BOTH DRIVES HAS WORN TORQUE ROD BUSHES - WORN PARTS TO BE ORDERED.
29 Mar 2022	Transall Motors Pty Ltd - 5295 Bush threaded
04 Apr 2022	Traralgon Tyre Service - Adblue for March
20 Apr 2022	Traralgon Tyre Service - Adblue
21 Apr 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 85114535 FILTER KIT
21 Apr 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 50L X 5022 FULL PROTECTION OIL
21 Apr 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
21 Apr 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2 X AS0025/7340 SHOCK STRAPS
21 Apr 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables Phillip Mitchell Tractor Repairs Pty Ltd - PERFORM COMPRESSION TEST, CYLINDER #2 HAS NO COMPRESSION PERFORM TEST MULTIPLE TIMES TO CONFIRM, HAS BROKEN VALVE OR WORN VALVE SEAT/VALVE RECESSON, NEEDS HEAD REMOVED PERFORM CLUTCH SYSTEM TESTS, CLUTCH WEAR IS OK, HAS OVER 50 PER CENT REMAINING. PERFORM PWM TESTS AND FAILED 1 OUT OF 4 TESTS. SUSPECT PWM VALVE AT FAULT. CHECK 2ND DRIVE LH WHEEL BEARING AND FOUND TO HAVE EXCESSIVE PLAY, THIS WILL BE CAUSING AIR GAP FAULTS. 2ND AXLE RH WHEEL ON A-TRAILER, LOOSE WHEEL BEARING. COMPLETE SERVICE DEFECTS: LOW COMPRESSION ON CYL #2 VALVE RECESSON. NEEDS HEAD EXHAUST MANIFOLD GASKETS LEAKING MULTIPLE TORQUE ROD BUSHES SHOWING WEAR AND CRACKS WINDSCREEN HAS MULTIPLE CRACKS LH 2ND DRIVE WHEEL BEARING LOOSE, NEEDS ADJUSTING/REPAIR ROOF CLEARANCE LIGHT BLOWN - RH INNER ABS LIGHT INTERMITENTLY ON OIL LEAK RH REAR OF ENGINE, POSSIBLE HEAD, OR TIMING COVER ENGINE LIGHT IS FROM MECH INJECTOR FAULT CAUSED BY LOW COMPRESSION ON CYL #2 ABS LIGHT DUE TO LOOSE WHEEL HUB 2ND DRIVE LH SIDE ATC LIGHT SUSPECT PWM FAULTY, FAILED ENGAGEMENT TESTS CANNOT FAULT DIFF AIR LEAK, ALL TESTED AND WORKING NORMALLY SUSPECT SQUEAK IS LH BONNET RUBBER BUT COULD NOT REPLACE
28 Apr 2022	Sapphire Coast Windscreen - Windscreen MK1801
28 Apr 2022	Sapphire Coast Windscreen - Windscreen MK1802

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REPLACE WORN RUBBER FUEL LINE FROM HEAD TO FILTER. REMOVED REAR 3RD AXLE OUTER TORQUE RODS AND REPLACE TYHEM (STILL FIT (2ND AXLE) RODS TO BE ORDERED AND REPLACED) FIT NEW ENGINE BRAKE SWITCH IN DASH. LOCATE DIFF LOCK SOLINOID REMOVE FROM CHASSIS RAIL, EXHAUST HOLE FULL OF MUD, DISASSEMBLE AND CLEAN REASSEMBLE TEST, ADD FITTING AND HOLE FOR THE EXHAUST TO PREVENT MUD ENTRY. CONNECT LAPTOP TROUBLESHOOT ABS FAULT OLH REAR DRIVE WHEEL, REMOVE WHEELS, BEARINGS HAS MOVMENT AND WHEEL SEAL LEAKING, DISASSEMBLE, CLEAN DRUM, REPLACE BRAKE SHOES AND WHEEL SEAL REASSEMBLE. REMOVE TINT OFF PASSANGER SIDE GLASS. CHECK OVER FOR NOISE FIND BONNET MOUNTS BOLTS ARE WORN AND NEEDED REPLACING, REPLACED BOLTS. CONNECT LAPTOP - CARRY OUT SOFTWARE UPDATE ON TRANSMISSION, CARRY OUT CALIBRATION OF TRANSMISSION. ADJUST DUMMY BOLSTER TO SEAT PROPERLY ON BOLSTER. CHECK REVERSE LIGHT POWER - OK - FAULTY TAILLIGHT LH TRUCK.
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 21316269 FUEL LINE
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X 85112668 TORQUE ROD
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 22222498 SWITCH
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB1990405 90 DEGREE 1/8 X 3/8
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 4707QP BRAKE SHOE KIT
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 47693 HUB SEAL
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 5-103X STEERING UNIVERSAL
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Freight
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
03 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
18 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - ALL BRAKE LIGHTS IN OP 3 FOUND 10 AMP FUSE IN TOP OF DASH FISHED PARTEL BLOWN REPLACED FUES, TESTED-OK LOOKED FOR SHORT, NOT FOUND
18 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 10 AMP MINI FUSE
19 May 2022	Traralgon Tyre Service - 295/80R22.5 Tyre
19 May 2022	Traralgon Tyre Service - 295/80R22.5 Bandag
19 May 2022	Traralgon Tyre Service - Disposal
24 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
24 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - GREASE TRUCK + TRAILER FIT DASH CAM A-TRAILER LH AXLE 3 SPRING EYE BUSH
25 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Mudflap strap
25 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Washers
25 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - AXLE 3 LH MUDFLAP FELL OFF AXLE 2 LH MUDFLAP ABOUT TO FALL OFF, VERY LOOSE
25 May 2022	Nolan Auto Parts & Industrial Supplies - CTI772 Tyre hose
25 May 2022	Nolan Auto Parts & Industrial Supplies - 52710BL fuse
25 May 2022	Nolan Auto Parts & Industrial Supplies - 54490BL Fuse
26 May 2022	Traralgon Tyre Service - 295/R22.5 Bandag
26 May 2022	Traralgon Tyre Service - Strip and fit
27 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - CLEAN OFF OLD DOUBLE SIDED TAPE, RE-APPLY NEW TAPE AND RESTICK TO WINDSCREEN CHECK SOLINODE, TEST POWER SUPPLY-OK, REMOVE SOLINODE DISASSEMBLE CLEAN OUT RUBBER STOPPING FROM SEALING REASSEMBLE, TEST-OK TRUCK RETURNED NEXT DAY WITH SAME FAULT, DISASSEMBLED SOLINODE CLEAN, BLOW OUT CTI HOSE'S ON TIRES, SUGGEST TIRES NEED CLEANING OUT OTHERWISE FAULT IS GOING TO CONTINUE
31 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - COMPLETED SERVICES ON THE TRUCK + TRAILERS ADJUSTED DUMMY BOLESTER RECLINED RHS MIDDLE AXLE ON A-TRAILER RE-STUCK ON THE DASH CAM REPLACED X1 PARKER GLOBE REPLACED BRAKE LIGHT FUSE

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
31 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 85114536 FILTER KIT
31 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
31 May 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 0509119220BH95 BRAKE
31 May 2022	Traralgon Tyre Service - Adblue
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Female socket
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - LED tail light
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Glass
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Sealing
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Lock
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Spacer
15 Jun 2022	Phillip Mitchell Tractor Repairs Pty Ltd - STRIP DOWN RH DOOR, REMOVE GLASS & INSTALL NEW GLASS, REASSEMBLE DOOR
15 Jun 2022	RENEW RH TAIL LAMP ASSEMBLY
01 Jul 2022	Traralgon Tyre Service - Adblue June
06 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 22539850 AVU VALVE
06 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 3LTRS VOLVE COLANT
06 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
06 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - CONNECT LAPTOP & CHECK FAULT CODES, FOUND BACK PRESSURE FAULTS, TEST EXHAUST BRAKE & FOUND AIR TO CYLINDER IS LOW TEST AVU VALVE & FOUND IT TO BE FAULTY REMOVE & RENEW AVU VALVE, TEST ALL OK TOP UP COOLANT & TIGHTEN LEAKING HOSE CLAMP
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - DRAIN COOLANT, REMOVE BELTS & REMOVE OLD WATER PUMP, INSTALL NEW WATER PUMP, CHECK PULLEYS WHILE BELTS ARE OFF, IDLER BEARING U/S REMOVE & RENEW BEARING REFIT BELTS, FILL COOLING SYSTEM & TEST ALL -OK REMOVE CHASSIS CATWALK TEST AIR DRYER, FOUND IT DOES NOT BLOW OFF REMOVE & RENEW GOVERNOR VALVE RETEST ALL -OK ALSO RENEW LEAKING SAFETY VALVE AT COMPRESSOR REMOVE & RENEW AXLES 3 LH MUDGUARD, INSTALL LUPE KITS BETWEEN MUDGUARDS, FIT NEW MUDFLAPS TO BACK OF DRIVE, 1X NEW SIGN & REFLECTOR IN END OF J-BARS
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 5L VCS COOLANT
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 6304-2RS BEARING
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 85122309 ST4 SAFETY VALVE
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB0939 1/8 FEMALE NPT X 1/8 MALE NPT
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 57A4323 WATER PUMP
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Freight
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 12X BOLT1/4X50MHB BOLT
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 12X NUT1/4 NUT
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X MFMMS24A MUDFLAP TOP STRAP
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X 22946424 MUDFLAP MACK
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X CA5499 LOOP KIT
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X MGP650LB MUDGUARD
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X CA7179 SIGN
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X CA5495 REFLECTOR
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 8X NC38112 BOLT 3/8 X 1-1/2
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 8X NNC38 NUT 3/8
13 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X CA5593BK MUDGUARD
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB0943 REDUCING BUSH 1/2" NPT> 3/8 NPT
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - GREASE & CHECK OVER VEHICLE CONNECT LAPTOP & CHECK FAULTS, FOUND FAULT FOR CLUTCH CARRIED OUT TEST USING TECH TOOL, TEST WERE INCONCLUSIVE SUGGEST REPLACING PWM VALVE, IF THAT DOES NOT FIT IT, GEARBOX WILL NEED TO COME OUT
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - replace air tank drain valve
19 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Drain valve

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - CARRY OUT B-SERVICE ON TRUCK & TRAILER
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 50LTRS DELVAC FULL PRO OIL
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X VO85114535 FILTER KIT
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 3LT COOLANT
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB1156S BRAKE BOOSTER
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Mudflap ribbed
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Mudflap black
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - BROKEN MUDGUARD ON TRAILER MUDGUARD LOW (RUBBING ON TYRE) ON AXLE 3 OF TRUCK REPAIR: REPLACED MUDGUARD. PUT MUDFLAPS ON TRAILER
22 Jul 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REMOVE BROCKEN TOP BRACKET - REWELD BRACKET - REFIT TO TRUCK BOTTOM FITTING ON LEVEL VALVE AIR CYLINDER BROCKEN REPLACE FITTING
02 Aug 2022	Traralgon Tyre Service - Adblue for July
08 Aug 2022	Richards - Internal - Chris Gordon Wash down truck 2.5hr
12 Aug 2022	Richards - Internal - Zane Bright Fit drum to hub 1hr
16 Aug 2022	Richards - Internal - Rory Shields Replace red/yellow button, steer mudflaps, air fitting in LHS air tank, look at fault in air leaks under bonnet, order parts 3.83hr
16 Aug 2022	Richards - Internal - Zane Bright Remove cradle for phone and old microphone 1.5hr
17 Aug 2022	Transall Motors Pty Ltd - LK600 Look kit
17 Aug 2022	Transall Motors Pty Ltd - MB01B Mudguard
17 Aug 2022	Transall Motors Pty Ltd - 0509705264 C/Shaft
17 Aug 2022	Richards - Internal - Bill Patching Fit wifi unit .75hr
17 Aug 2022	Richards - Internal - Rory Shields Replace RHF exhaust shield mount, a/c filter, steering dampner, oil filter o ring, front shockers, tighten loose bolts on b trailer above elphinestone plate, tighten loose LHS under cab door mount. Repair wiring to combination light LHR, replace RHR front mudguard brackets, fit loop to RHS drive guards, replace outer mudguard mounting bracket, top up coolant 8.5hr
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT23701845 Hose oil cooler
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT23701846 Hose oil cooler
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT20593022 Mount air intake cabin
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT8071883 Clamp
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT85151124 Filter
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT21780376 Seal ring
18 Aug 2022	CMV Truck & Bus Pty. Ltd - MK5435SC2920 Stab Cylinder
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT23359394 Front shocket
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT21144812 Tractor valve
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT21895024 Exhaust pipe flex
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT2137065 Exhaust flex mack
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT994195 Bolt
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT1629499 Clamp
18 Aug 2022	CMV Truck & Bus Pty. Ltd - VT990951 Nut
18 Aug 2022	Transall Motors Pty Ltd - 62D0T12 Union
18 Aug 2022	Richards - Internal - James lavell removed hoses from under cab on side of gearbox .75hr
18 Aug 2022	Richards - Internal - Jon Wawrzkow refit interior trims, fit air dryer, repair scales wiring 2hr
18 Aug 2022	Richards - Internal - Rory Shields Replace trans cooler hoses, tighten hyd fitting on trailer drive motor, look at scales fault 8hr
19 Aug 2022	Richards - Internal - Chris Gordon Safety check 1hr

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
19 Aug 2022	Richards - Internal - James Lavell Changed lead for scales and brake hose 7hr
22 Aug 2022	Richards - Internal - James Lavell B service, tensioned all wheel nuts and hub caps 2.25
22 Aug 2022	Richards - Internal - Rory Shields B service, replace fuel tank cross over bolts 3.5hr
23 Aug 2022	Richards - Internal - Tony Murphy Test drive, take to CMV for repairs 1.5hr
23 Aug 2022	Transall Motors Pty Ltd - 26260CAK-V amber light
25 Aug 2022	Transall Motors Pty Ltd - 109001 Valve relay
25 Aug 2022	Richards - Internal - Adam Vary Repair tail lights and scales 5.5hr
25 Aug 2022	Richards - Internal - James Lavell Picked up from CMV, changed tie rod ends, fit cover back on chassis, repaired wiring issues with reverse lights and work lights, changed valve on air tank, helped with scales, swept up 10hr
25 Aug 2022	Richards - Internal - Zane Bright Parts run, clean cab 2.25hr
26 Aug 2022	Richards - Internal - Adam Vary Scales reset and refit 2hr
27 Aug 2022	CMV Truck & Bus Pty. Ltd - VT20965167 drag link steering box
27 Aug 2022	CMV Truck & Bus Pty. Ltd - VT85112009 Tie rod end
27 Aug 2022	CMV Truck & Bus Pty. Ltd - VT85112008 Tie rod end
30 Aug 2022	CMV Truck & Bus Pty. Ltd - Check and advise transmission faults
30 Aug 2022	CMV Truck & Bus Pty. Ltd - Check and advise cruise control faults
30 Aug 2022	CMV Truck & Bus Pty. Ltd - Check and advise Power steer pump leaking
31 Aug 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 22024367 200PSI PREASURE PROTECTION
31 Aug 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 85129688 AIR DRYER FILTER
31 Aug 2022	Phillip Mitchell Tractor Repairs Pty Ltd - TROUBLESHOOT AIRLEAK, DIAGOSED AS COMPRESSOR PREASE PROTECTION VALVE REMOVE & REPLACE VALVE, REMVE CHECKER PLATE REMOVE & REPLACE AIR DRYER FILTER RE-INSTALL CHECKER PLATE, TEST - ALL OK
01 Sep 2022	CMV Truck & Bus Pty. Ltd - 49402M7 mudflap
01 Sep 2022	CMV Truck & Bus Pty. Ltd - 49402M mudflap
01 Sep 2022	CMV Truck & Bus Pty. Ltd - 74801693 valve
01 Sep 2022	CMV Truck & Bus Pty. Ltd - VT24122024 filter kit
01 Sep 2022	CMV Truck & Bus Pty. Ltd - VT85129688 filter air dryer
01 Sep 2022	Traralgon Tyre Service - Agust adblue
02 Sep 2022	Richards - Internal - Zane Bright repair RHR drive airbag 6.5hr
08 Sep 2022	Boltweld - 282015 5/8 2 GR flange bolt
08 Sep 2022	Boltweld - 28210 5/8 1.5 UNF flange bolt
08 Sep 2022	Boltweld - 282015 5/8 2 GR flange bolt
08 Sep 2022	Boltweld - 283010 5/8UNF flange conelock
09 Sep 2022	Richards - Internal - Mick Lovell Repair fault in instruments on truck and trailers 1hr
13 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Air dryer
13 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Safety valve
13 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Air leak - remove and replace air dryer and safety valve pressure relief Richards - Internal - Brendan Collins No air pressure
16 Sep 2022	Check air compressor discharge hoses and pipe, found blocked hoses and pipe, clean out, remove air dryer assy and clean out, reassemble and test, found leaking compressor discharge hose, make up new hose and fit, tested ok 5hr
17 Sep 2022	Richards - Internal - Brendan Collins Fit new compressor discharge hose and reconnect pipework, replace leaking coolant pipe from header tank to radiator 3hr

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
19 Sep 2022	D & M Automotive - Hyd hose repair
19 Sep 2022	D & M Automotive - 3/4 hyd hose
19 Sep 2022	D & M Automotive - Straight JIC fitting
19 Sep 2022	D & M Automotive - 90o JIC fitting
20 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 20489118 SWITCH
20 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 25165995 SWITCH
20 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 22327069 SOLENOID
20 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REMOVE & REPLACE 3X SHOCK STRAPS B-TRAILER, AXLE 1, AXLE 2, AXLE 3 LHS CHECK LIGHTS, WIRING BOTH SIDES RUBBED, REPAIR WIRES INSULATE WIRES REPLACE CLUTCH ACCUATOR MODULE ON SIDE IF TRANSMISSION REPLACE BOTH BRAKE LIGHT SWITCHES - FIREWALL + UNDER DAHS REPLACE LEAKING FITTING ON FIREWALL CARRY OUT CLUTCH CALIBRATION
23 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - VOL-22043157 COMPRESSOR HOSE
23 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - V404P-10-6 HEATER TAP
23 Sep 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 21053033 COOLANT HOSE CONNECT TO BOTH TRAILERS - NO ACTIVE CODES DISCONNECT PLUGS AND CLEAN TERMINALS CLEAR ALL FAULTS AND TEST DRIVE VEHICLE NO FAULT BECAME ACTIVE REMOVE FOTTWELL PANEL, DISCONNECT BRAKE LIGHT SWITCH JOIN WIRES TO MAKE LIGHTS COME ON, WIRING OK LEAVE SWITCH UNPLUGGED TO CHECK IF THE PROBLEM SWITCH OR ANOTHER ISSUE BRINGING LIGHTS ON LIGHTS DIDN'T COME ON SUSPECT RAILER HAND PIECE SUPPLYING AIR TO SWITCH THROUGH INTERNAL LEAKAGE PROBLEM NOT RESOLVED REPLACE BROKEN WORK LIGHT RHS LOAD RACK
01 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X LV0111 LIGHT Phillip Mitchell Tractor Repairs Pty Ltd - CLUTCH WEAR 0.3MM LEAK TEST - PASSED PERFORMANCE TEST - FAILED NO ENGINE FAULTS ACTIVE OR INACTIVE COULD NOT FAULT PRESSURE VALVE ON COMPRESSOR PIPE COULD NOT FAULT AIR PRESSURE VALVE ON COMPRESSOR PIPE, DID NOT LEAK DURING TEST HOOK UP TECH TOOL NO ENGINE FAULTS IN SYSTEM ACTIVE OR IN ACTIVE, CANNOT CONTINUE DIAGNOSIS WITH NO FAULT ATS LIGHT CAUSED BY CLUTCH FAULT, TEST CLUTCH CYLINDER + CLUTCH WEAR - BOTH OK HEAPS OF LIFE LEFT TO CLUTH, PASSED LEAKING TEST - NO LEAKS WERE FOUND PWM VALVE FAILS PERFORMANCE TESTS, IS TO SLOW + LEAKING AIR FROM EXHAUST, NEEDS REPLACING NO ABS FAULTS IN SYSTEM ACTIVE OR INACTIVE FOUND 3 COUNTS FROM BRAKE LIGHT WITCH DATA ERROR. CHECKED
04 Oct 2022	Traralgon Tyre Service - Adblue Phillip Mitchell Tractor Repairs Pty Ltd - PRESSURE COOLING SYSTEM FOUND SPLIT IN HEADER TANK DRAIN COOLANT REMOVE TANK FIT NEW TANK FILL WITH COOLANT RE-PRESSURE TEST, OK REMOVE CENTRE DASH PANELS LOCATE LEAK TO HAND PIECE DISCONNECT AIR LINE SHORTEN LINE TO MACK NEW SEALING SURFACE BUILD UP AIR TEST OK
20 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1 X 23911823 HEAD TANK
20 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 5L X VCS COOLANT
20 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 3X 22024367 SAFTEY VALVE

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 22539850 VALVE
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 21053055 COOLANT VENT HOSE
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 10L AMP22567335 VOLVO COOLANT
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 4L CAL8394800 MACK/VOLVO COOLANT
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 85114535 MACK FILTER KIT
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 50L 5022-208 15W-40 FULL PROTECTION OIL
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 56485 P CLAMP
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X 47501 12V 5WATT GLOBE
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X 4000-67274530 TORQUE ROD
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 25111676 VALVE DASH
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB8475 R12P VALVE
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X GREASE
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - REMOVE STEEL PIPES UNDER CAB, COMPRESSOR PIPES BLOCKED WITH CARBON, CLEAN/DE-SCALE CARBON FROM PIPES, RE-ASSEMBLE PIPES
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - TILT BONNET/BULLBAR, PRESSURE TEST COOLING SYSTEM, FIND LEAK/VENT HOSE LOWER BONNET, MEET TRUCK AT COCKS YARD LOWER BONNET, REMOVE & REPLACE VENT HOSE - HAD TO EXTRACT BROKEN PEICE CABLETIE VENT HOSE, REFILL COOLING SYSTEM TOP UP 10L, WASH ENGINE DOWN TEST - ALL OK
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - COMPLETE 250 HR SERVICE AS PER SERVICE SHEET PULL DASH APART TO GAIN ACESS TO BRAKE HAND PIECE, AIR BYPASSING VALVE, REPLACE VALVE, WHEN REPLACINGVALVE NOTICED AIR COMING UP THE SIGNAL LINE WHICH WHEN RESTRICTED THE SERVICE BRAKES START TO APPLY BRING ON BRAKE LIGHTS, ISOLATE TRUCK AND B-TRAILER PROBLEM WITH A-TRAILER, FOLLOW BLUE LINE/SERVICE LINE TO RELAY VALVE, VALVE BY PASSING/LEAKING, REPLACE VALVE TEST - OK REASSEMBLE DASH AND OTHER COMPONENTS ISOLATE BAR LIGHTS COMING ON WITH BRAKE LIGHTS TO A-TRAILER REAR LIGHT BAR, STRIP HARNESS APART FIND SHORT BETWEEN WORK LIGHTS AND BRAKES BEHIND LH LIGH ASSEMBLE, REPAIR WIRING TEST PROBLEM - FIXED REPLACE 2ND AND LH TOPGUE BODS
21 Oct 2022	Phillip Mitchell Tractor Repairs Pty Ltd - PLUGGED IN THE COMPUTE TO CHECK FOR ANY FAULTS - ALL OK REMOVED AND REPLACED EXHAUST BRAKE CONTROL VALVE ADJUST TRAILER BRAKES
25 Oct 2022	Traralgon Tyre Service - Strip and fit
25 Oct 2022	Traralgon Tyre Service - Disposal
31 Oct 2022	Traralgon Tyre Service - Adblue
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - DRAIN COOLANT REPLACE HEATER HOSE BEHIND STEERING BOX TOP UP COOLANT CONNECT COMPUTER FOR TROUBLE SHOOTING REPAIR SPEED SENSOR ON GEARBOX TO ENGINE DE-RATING
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X AB7621 DRIAN VALVE
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 21637042 MACK HEATER HOSE
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X ABM69525S 8MM - 1/8 TUBE JOINER
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 10L AMP22567335 MACK/VOLVE COOLANT
01 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
21 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 959.640-301 LED PLATE LIGHT
21 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 100k Service Kit
21 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - CARRY OUT 100,000KM SERVICE AS PER SERVICE SHEET REPLACE TRUCK NUMBER PLATE LIGHT
23 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 2X 30AMP FUSES
23 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 1X 20874147 CAB SHOCK
23 Nov 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
23 Nov 2022	START TO UNDERTAKE TUNE UP/VAVE SET FOUND TIGHT VALVE WEXHAUST NO2 INSPECTION FOUND ENGINE BRAKE PISTON PROTRUDING MORE THEN OTHERS LOOSEN ROCKER COVER SHAFT + LIFRT ROCKER GEAR FROM ENGINE REMOVE NO 2 PISTON FROM ROCKER LEVEL PISTON END CAP FOUND LOSE CAUSING PROBLEM, TIGHTEN CAP + REASSEMBLE LEVER REINSTALL ROCKER GEAR ONTO ENGINE + TENSION DOWN SHAFT CARRY OUT COMPLETE VALVE + INJECTOR ADJUSTMENTS, REINSTALL ROCKER COVER & INTAKE PIPING REPLACE LH CAB SHOCK REPLACE BLOWN WORK LIGHT FUSES + TURN ON, FUSE NOT BLOWING, INSPECT ALL CONNECTORS + JOINERS IN WIRING - OK INSPECT ENTIRE HARNESS FOR ANY VISUAL DAMAGES - OK PULL WIRING IN VARIOUS WAYS - NO ISSUE FAULT TO BE MONITORED/INSPECTED FURTHER TRAILER RIDE HEIGHT VALVE OVERRIDE CYLINDER AIR LEAKING, REPLACE TORN OFF AIR FITTING FOUND CRACK IN A TRAILER, REMOVE CRACKED ANGLE MOUNT AND REPAIR CRACK THEN PAINT REFIT TO TRAILER
25 Nov 2022	Traralgon Tyre Service - 295/80R22.5 Bandag
25 Nov 2022	Traralgon Tyre Service - 295/80R22.5 Case
25 Nov 2022	Traralgon Tyre Service - Disposal
25 Nov 2022	Traralgon Tyre Service - Disposal
02 Dec 2022	Traralgon Tyre Service - Adblue
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Faults: LH tail and park lights not working. Greased truck and trailers, replaced LH park light, fitted 4 mudflaps - 2 rear of truck, 2 rear of B-Trailer.
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Grease
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - LS9081 Tail Light
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 15/62M2 Mudflap
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 20734156 Sump Gasket
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 85114535 Oil Filter Kit
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 5022-208 55L 15W-40 Oil
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - CA5470W Blue Mudguard
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - Consumables
23 Dec 2022	Phillip Mitchell Tractor Repairs Pty Ltd - 250HR Service (407,084 km / 10,032 hrs) Remove sump, clean and block. Replace gasket, refit and tension sump. Weld up 2 cracks in exhaust pipe below muffler. Wash engine and drive back to Cocks Yard. Removed and replaced RHS front mudguard.
16 Jan 2023	Boltco Pty Ltd - 7/8x6" UNF bolt
16 Jan 2023	Boltco Pty Ltd - 7/8x7" UNF bolt
17 Jan 2023	Traralgon Tyre Service - Adblue December
03 Feb 2023	Richards - Internal - Andrew Stewart Make up drums and brackets for winch chains 6.5hr
03 Feb 2023	Richards - Internal - Chris Gordon Check over and grease 2.75hr
03 Feb 2023	Richards - Internal - Rory Shields Work out how to set up winches 3hr
04 Feb 2023	Richards - Internal - Andrew Stewart Change the winch from straps to chains 5hr
04 Feb 2023	Richards - Internal - James Lavell Helped fit chains and brackets to binders 2.5hr
06 Feb 2023	Richards - Internal - Andrew Stewart Cut and fold sheets for chain boxes Weld up boxes and fit to truck 7hr
06 Feb 2023	Richards - Internal - Isaac Stewart Fit chain boxes 1.33hr

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
06 Feb 2023	Richards - Internal - Rory Shields Make chains and assist fitting toolboxes 1.75hr
07 Feb 2023	CMV Truck & Bus Pty. Ltd - VT20399824 Strap mounting air tank
07 Feb 2023	CMV Truck & Bus Pty. Ltd - VT8150742 Pin tank strap
07 Feb 2023	CMV Truck & Bus Pty. Ltd - VT60112468 Bolt heat sheild muffler
07 Feb 2023	LV CNC - 8mm small chain
07 Feb 2023	Richards - Internal - James Lavell Parts run 1hr
09 Feb 2023	CMV Truck & Bus Pty. Ltd - VT8150740 Pin air tank
09 Feb 2023	CMV Truck & Bus Pty. Ltd - VT60112470 Screw air tank bracket
10 Feb 2023	Traralgon Tyre Service - Truck strip and fit
10 Feb 2023	Traralgon Tyre Service - Disposal
13 Feb 2023	Richards - Internal - Chris Gordon Safety inspection, top up hyd oil, fit airtank strap 2.25hr
13 Feb 2023	Richards - Internal - James Lavell Safety check 2.25hr
13 Feb 2023	Phillip Mitchell Tractor Repairs Pty Ltd - DRIVE UP, CONNECT TO BATTERIES LET CHARGE UP FOR 20 MINS CHECK OIL AND WATER START ENGINE, MAKE SURE EVERYTHING IS OK RETURN TO WORKSHOP
22 Feb 2023	Richards - Internal - James Lavell Safety check, found and repaired wiring fault, changed mudflaps and swept up 4hr
22 Feb 2023	Richards - Internal - Zane Bright safety check and repairs 5.5hr
24 Feb 2023	Richards - Internal - James Lavell Repaired indicator wiring fault, picked up parts 3.25hr
27 Feb 2023	Truck Hydraulic Solutions - 10500300200 Gear pump
27 Feb 2023	CMV Truck & Bus Pty. Ltd - VT85114535 Filter kit
03 Mar 2023	Richards - Internal - Zane Bright Repair indicator and window switch .5hr
06 Mar 2023	CMV Truck & Bus Pty. Ltd - VT82278971 switch window
09 Mar 2023	Richards - Internal - James Lavell 1000hr service, wired up tablet holder and mounted 10.25hr
09 Mar 2023	Richards - Internal - Rory Shields 1000hr service and repairs Wire in new camera and charger, replace air dryer blow off valve 10.5hr
09 Mar 2023	Richards - Internal - Zane Bright Help finish repairs 1.25hr
10 Mar 2023	Richards - Internal - Chris Gordon repair wiring on driving lights, get working again off ignition 1.5hr
10 Mar 2023	Richards - Internal - James Lavell Changed alternator, fitted new fan belt 1.25hr
10 Mar 2023	Richards - Internal - Rory Shields Inspect alternator fault, order parts 2hr
10 Mar 2023	CMV Truck & Bus Pty. Ltd - VT23961744 Belt alternator
14 Mar 2023	Richards - Internal - Isaac Stewart Repair wiring .5hr
14 Mar 2023	Richards - Internal - Rory Shields Check indicator fault, change fuse, check wiring to indicators, run new wire from A to B trailer 1.5hr
14 Mar 2023	Richards - Internal - Zane Bright Assist with indicator fault 1hr
16 Mar 2023	Traralgon Tyre Service - 295/R22.5 Yokohama
16 Mar 2023	Traralgon Tyre Service - Disposal

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
20 Mar 2023	Pirtek LV - 5/8 SAE Airbrake tube
20 Mar 2023	Transall Motors Pty Ltd - 509119220BH95 B/shoe
20 Mar 2023	Transall Motors Pty Ltd - 310990030 B/drum
20 Mar 2023	Transall Motors Pty Ltd - T03-1701 Valve
20 Mar 2023	Richards - Internal - Zane Bright Replace 7 core wire 6.75hr
27 Mar 2023	Richards - Internal - Chris Gordon Replace steer shaft unis, check tie rods/ dragliner ends. find ok 2hr
01 Apr 2023	Gippsland Truck Wrecking - ALTERNATOR
11 Apr 2023	CMV Truck & Bus Pty. Ltd - VT85114535 Kit Filter basic MP8-MP10 Engine Mack
12 Apr 2023	Surdex Steel Pty Ltd - 301 10mm round g4140 - 6.0m
13 Apr 2023	CMV Truck & Bus Pty. Ltd - Check advice lighting bolt on dash. AVU diverter valves failed internally. Customer reported of loss of power and lighting bolt on dash. Dounf AVU to be bypassing air internally and diverter valve to be sticking, tilt bonnet, brained air, removed and replaced AVU valve. Remove and replaced diverter valve, built up air and no leaks. carries out test drive and lighting bolt gone off dash and full. Boost when driving
13 Apr 2023	CMV Truck & Bus Pty. Ltd - VT23992701 - VALVE AVU ENGINE BRAKE AIR MP8-10
13 Apr 2023	CMV Truck & Bus Pty. Ltd - VT236260442 - AIR SHUTTLE VALVE ENGINE BRAKE MP8-10
13 Apr 2023	Richards - Internal - Isaac Stewart Repair air fitting .5hr
16 Apr 2023	Richards - Internal - Chris Gordon Safety check, diagnose adblue pump fault 3hr
20 Apr 2023	Richards - Internal - James Lavell repaired CTI fault 1hr
22 Apr 2023	Richards - Internal - Rory Shields Wouldnt build air, cleaned out air line 1hr
29 Apr 2023	Richards - Internal - James Lavell Safety check 1.5hr
29 Apr 2023	Richards - Internal - Zane Bright Safety check 1.5hr
05 May 2023	Repc Vic - GVESPK11 Elastic strap
08 May 2023	Richards - Internal - Rory Sheilds Look at scale fault 1.5hr
17 May 2023	CMV Truck & Bus Pty. Ltd - VT85129688 Filter Air dryer
17 May 2023	Richards - Internal - Rory Sheilds Look at fault with air blowing off, needs new air dryer 1hr
22 May 2023	Richards - Internal - Zane Bright Repair air leaks 2hr
23 May 2023	Richards - Internal - Zane Bright 300hr service 5hr
31 May 2023	Pirtek LV - 01NS Elbow
31 May 2023	Pirtek LV - J26-17 Nipple
31 May 2023	Pirtek LV - JF1-1712P 3/4 hose
31 May 2023	Richards - Internal - Andrew Stewart Repair chain winch 1hr
31 May 2023	Richards - Internal - James Lavell Inspect and repair breakdown 6hr
31 May 2023	Richards - Internal - Rory Shields Dianosed over phone, ordered parts, parts run, replaced head on air compressor, topped up coolant, replaced air dryer, unblocked lines 6hr
01 Jun 2023	Richards - Internal - Andrew Stewart Unblock hotline for compressor 1hr
02 Jun 2023	Richards - Internal - Chris Gordon Replace air fitting on air dryer govener, remove hotline and burn all carbon out, refit hotline, assist with safety check 6hr

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
02 Jun 2023	Richards - Internal - Isaac Stewart' Safety check 1.5hr
02 Jun 2023	Richards - Internal - Zane Bright Safety check, repair air leak at air dryer, repair air cti issue 5hr
05 Jun 2023	CMV Truck & Bus Pty. Ltd - VT22896454 Air dryer
05 Jun 2023	CMV Truck & Bus Pty. Ltd - VT22203109 Kit air compressor
05 Jun 2023	CMV Truck & Bus Pty. Ltd - VT24078864 Coolant
05 Jun 2023	CMV Truck & Bus Pty. Ltd - VT85155724 Air compressor
06 Jun 2023	Richards - Internal - James Lavell Removed parts to get to gearbox 3.5hr
06 Jun 2023	Richards - Internal - Zane Bright Load up and travel to APM, do induction, remove tailshaft, assist tow company 2hr
07 Jun 2023	Richards - Internal - Andrew Stewart Assist with gearbox 2hr
07 Jun 2023	Richards - Internal - Zane Bright remove gearbox and clutch, clean bell housing, remove spigot bearing 5.5hr
08 Jun 2023	Gippsland Bearing Supplies Pty Ltd - 7316570950885 Bearing
08 Jun 2023	Richards - Internal - Brendan Collins Fit new clutch 1.5hr
08 Jun 2023	Richards - Internal - Zane Bright Fit clutch 2.5hr
09 Jun 2023	Richards - Internal - Andrew Stewart Assist refitting gearbox 1.5hr
09 Jun 2023	Richards - Internal - Brendan Collins Adjust alignment of new clutch, refit gearbox 3hr
09 Jun 2023	Richards - Internal - Rory Shields Book into CMV for clutch program .5hr
09 Jun 2023	Richards - Internal - Zane Bright Parts run, align clutch, fit gearbox, refit all parts, change front drive airbags 8.75hr
09 Jun 2023	Richards - Internal - Zane Bright Assist CMV with computers 2hr
10 Jun 2023	CMV Truck & Bus Pty. Ltd - VT9996049 Tool radiator drain
12 Jun 2023	Richards - Internal - Zane Bright Move truck 0.5 hr
13 Jun 2023	Richards - Internal - Rory Shields Check over after gearbox was fitted. Tighten loose tail shaft bolts, centre bearing, bell housing, fill gearbox with oil, tighten front diff, air bags, repair air leak to RHS air bag. 4 hrs
13 Jun 2023	Transall Motors Pty Ltd - 60271-002 Air spring assembly
13 Jun 2023	CMV Truck & Bus Pty. Ltd - VT22327069 VALVE PWM CLUTCH M-DRIVE AT03112D CMV Truck & Bus Pty. Ltd - STARTED TRUCK, ATTEMPTED TO ENGAGE FORWARD GEAR, DASH REPORTING TRUCK IN GEAR BUT NO FORWARD TRAVEL. CONNECTED VCADs, ACTIVE DTC FOR PWM/ACTIVATION CYLINDER UNABLE TO MEASURE CLUTCH POSITION. INSPECTED PWM, PWM MAKING LOUD BUZZING SOUND. UNABLE TO RUN ANY TESTS ON PWM, PWM UNRESPONSIVE. TRAVELLED TO WORKSHOP AND BACK TO RETRIEVE NEW PWM, FITTED NEW PWM, FOUND ALOT OF METAL SHAVINGS BEHIND PWM. STARTED TRUCK WITH NEW PWM FITTED, STILL NO DRIVE. ATTEMPTED COMMUNICATION WITH PWM AGAIN, STILL UNRESPONSIVE. GEARBOX NEEDS TO BE REMOVED FOR FURTHER DIAGNOSIS OF ACTIVATION CYLINDER AND CLUTCH POSITION SENSOR.

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
13 Jun 2023	CMV Truck & Bus Pty. Ltd - KLM Travel
13 Jun 2023	CMV Truck & Bus Pty. Ltd - Travel
13 Jun 2023	CMV Truck & Bus Pty. Ltd - VT85022454 Activation cylinder clutch
13 Jun 2023	CMV Truck & Bus Pty. Ltd - VT24159627 Clutch plate
13 Jun 2023	CMV Truck & Bus Pty. Ltd - VT22317110 Pressure plate
13 Jun 2023	CMV Truck & Bus Pty. Ltd - TRANSMISSION AIR PRESSURE. INSPECTED GEARBOX CONNECTORS, FOUND GEARBOX HARNESS CHASSIS CONNECTOR LOCK TO BE BROKEN AND CONNECTOR NOT LOCKED IN, LOCKED IN CONNECTOR, GEAR POSITION READING ON DASH NOW. WENT TO CALIBRATE GEABOX FOUND TO REQUIRE AIR, FILLED TRUCK WITH AIR, REQUIRED AIR TANK TO BE REMOVED AND MOVED BACK TO GET AIR
15 Jun 2023	FITTING ON, FILLED GEARBOX AIR TANK WITH AIR. CARRIED OUT CALIBRATION, WENT TO START TRUCK, BATTERIES FLAT, HOOKED UP CUSTOMER JUMPER PACK, JUMPER PACK FLAT, MOVED BREAKDOWN UTE INTO WORKSHOP, CONNECTED JUMPER CABLES, WAITED FOR TRUCK BATTERIES TO CHARGE ENOUGH TO START, FINISHED CALIBRATION, PACKED UP, REPOSITIONED AIR TANK, ADVISED CUSTOMER OF FINDINGS AND TRUCK GOOD TO GO, TRAVELLED BACK TO
15 Jun 2023	CMV Truck & Bus Pty. Ltd - Travel
16 Jun 2023	Repc Vic - RH72470BL-2 Globe H7
20 Jun 2023	Burson Automotive Pty. Ltd - 81878 Permatex 85gr ul;tra copper silicone
21 Jun 2023	Richards - Internal - Isaac Stewart Fixed air winch, looked over gearbox. 1.5 hrs
21 Jun 2023	Richards - Internal - Rory Shields Look at 2nd winch, replace with spare winch. 1.5 hrs
29 Jun 2023	Richards - Internal - James Lavell Fixed lights 0.5 hr
29 Jun 2023	Richards - Internal - Rory Shields Repair tail lights 0.5 hr
03 Jul 2023	Richards - Internal - Rory Shields Replace broken CTI fitting, make air fitting kit. 1 hr
04 Jul 2023	Richards - Internal - Chris Gordon Wash up hub for Rory 0.5 hr
04 Jul 2023	Richards - Internal - James Lavell Washed brake drum and helped Rory with brakes 1.5 hrs
04 Jul 2023	Richards - Internal - Rory Shields Replace LHF drive wheel bearing 1.5 hrs
05 Jul 2023	Richards - Internal - James Lavell Changed headlight globe. 0.5 hr
05 Jul 2023	Richards - Internal - Rory Shields Clean up from last job 1 hr
06 Jul 2023	Transall Motors Pty Ltd - 3216V48A Pipe
06 Jul 2023	Transall Motors Pty Ltd - 2206C3A Diff Oil Return Pipe
12 Jul 2023	Richards - Internal - Chris Gordon Start service, wash engine. 1.5 hrs
12 Jul 2023	Richards - Internal - James Lavell Started service and cleaned area. 1.25 hrs
12 Jul 2023	Richards - Internal - Rory Shields Get parts ready for next day. 0.75 hrs

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
13 Jul 2023	Richards - Internal - Chris Gordon Assist with service, replace front axle slack adjusters on A-trailer, start removing air compressor. 7.5 hrs
13 Jul 2023	Richards - Internal - James Lavell 300-hour service (454,359 km / 11,174 hrs) 3.25 hrs
13 Jul 2023	Richards - Internal - Rory Shields Service and repairs, order parts 6.5 hrs
14 Jul 2023	CMV Truck & Bus Pty. Ltd - VT992065 O RING COMPRESSOR MOUNTING V3-3-MP8
14 Jul 2023	Richards - Internal - Andrew Stewart Repairing the exhaust 3.5 hrs
14 Jul 2023	Richards - Internal - Chris Gordon Remove air compressor, clean mounting area. Refit stud, spec up new compressor. Fit sprocket. Fit compressor. Remove exhaust, refit exhaust. Fill coolant and start up. Check over. 10 hrs
14 Jul 2023	Richards - Internal - Rory Shields Look up tensions for air compressor, assist Chris with changing air compressor. 1.5 hrs
15 Jul 2023	Richards - Internal - Andrew Stewart Weld chain links and set up the bolster(?) 3.5 hrs
15 Jul 2023	Richards - Internal - Rory Shields Adjust bolster settings 3.25 hrs
17 Jul 2023	Von Pace Group - VP94162BL NARAVA TAIL LAMP ASSY
27 Jul 2023	Von Pace Group - AS PER ATTACHED
31 Jul 2023	Richards - Internal - James Lavell Swept floor, changed rear torque rod. 1.25 hrs
31 Jul 2023	Richards - Internal - Rory Shields Assist Jamie with changing torque rod, repair air leak on trailer. 0.5 hr
01 Aug 2023	Richards - Internal - Chris Gordon Assist with fitting wheels and park brake valve replacement 1 hr
15 Aug 2023	Richards - Internal - Chris Gordon Remove RH rear engine mount and place into position. Start to remove LHR engine mount. 5.5 hrs
15 Aug 2023	Richards - Internal - James Lavell Swept floor, changed torque rod, helped Chris change engine mounts. 5.25 hrs
15 Aug 2023	Transall Motors Pty Ltd - SK2905/20 Foot pin bush set
16 Aug 2023	Richards - Internal - Chris Gordon Drain coolant, remove LH engine mount, Fit new mount. Tighten al mount bolts, refit all parts removed. Refill coolant, replace reflectors on trailers. 8 hrs
16 Aug 2023	Richards - Internal - James Lavell Helped Chris finish changing engine mounts, refitted exhaust pipe. 4.75 hs
28 Aug 2023	Richards - Internal - Rory Shields Show driver how to use trailer 1 hr
30 Aug 2023	Richards - Internal - Chris Gordon Assist Rory with sensor replacement, run and check over. 1 hr
30 Aug 2023	Richards - Internal - Rory Shields Look up fault code, order parts, fit new exhaust back pressure sensor and intake manifold sensor. 3.5 hrs
31 Aug 2023	Richards - Internal - James Lavell Took truck to CMV 1 hr
31 Aug 2023	Richards - Internal - James Lavell Picked up truck from CMV 1 hr
31 Aug 2023	Richards - Internal - Rory Shields Look at fault with (?), book into CMV 3 hr
01 Sep 2023	Richards - Internal - James Lavell Changed air fittings on winches and went to Pirtek and hyd & pneumatic to get more fittings. 1 hr

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
05 Sep 2023	Richards - Internal - Rory Shields Repair damaged LHs light on truck, repair bent bar and number plate mount. Replace combination light and number plate light. 2 hrs
06 Sep 2023	Richards - Internal - Rory Shields Fix air CTI fault with dumping air 1.5 hrs
07 Sep 2023	Richards - Internal - Rory Shields Safety check and repairs 6 hrs
07 Sep 2023	Richards - Internal - Chris Gordon Assist Rory with safety check, replace LHS DTRL(?). 2.5 hrs
12 Sep 2023	Richards - Internal - Rory Shields Replace drag link inch bolt 1.25 hrs
27 Sep 2023	CMV Truck & Bus Pty. Ltd - VT20874147 Rear shocker cabin
27 Sep 2023	Richards - Internal - Matt Kearns Service (463,355 km / 11,461 hrs) and repairs
03 Oct 2023	Richards - Internal - Look at faults with exhaust brake and traction control, contact tech support for assistance on new scan tool. RS
03 Oct 2023	Richards - Internal - Clean valve out and check codes with scanner MK
04 Oct 2023	Richards - Internal - Hook up scan tool and check for faults. RS
05 Oct 2023	Richards - Internal - Repair CTI control valve air leak RS
06 Oct 2023	Richards - Internal - Hook up scan tool, clear faults, complete safety check. MK
06 Oct 2023	Richards - Internal - Hook up scan tool and clear faults, reset ATC in truck, complete safety check. RS
09 Oct 2023	Richards - Internal - Go through faults list and check off faults done RS
10 Oct 2023	Richards - Internal - Breakdown, patch up to get back to yard RS
11 Oct 2023	Transall Motors Pty Ltd - 940MBASSY Contitech 30K Assembly
11 Oct 2023	Transall Motors Pty Ltd - 0508214432 Spring
11 Oct 2023	Transall Motors Pty Ltd - 053480360 Retaining Strip
12 Oct 2023	Richards - Internal - Replace mud guard, check if part come MK
13 Oct 2023	Transall Motors Pty Ltd - 0328136140AL2 Plate Alignment Dowel 70mm
13 Oct 2023	Transall Motors Pty Ltd - 031139410 Bush
13 Oct 2023	Transall Motors Pty Ltd - 0331030490 Ring
13 Oct 2023	Transall Motors Pty Ltd - 0235060700 Bump Stop
13 Oct 2023	Transall Motors Pty Ltd - 0250255611 Bolt
13 Oct 2023	Transall Motors Pty Ltd - Freight
13 Oct 2023	Richards - Internal - Set matt up with parts and jobs RS
16 Oct 2023	Richards - Internal - Chase up lift axle parts. RS
17 Oct 2023	Elphinstone Weighing Systems - 11/0235060700 Bump Stop Axle Lift Airlight 2
17 Oct 2023	Elphinstone Weighing Systems - 11/0311394100 Nylon Bush ALU/Hanger Axle Lift
17 Oct 2023	Elphinstone Weighing Systems - 11/0250255611 Bolt Hex M10x50 Axle Lift
17 Oct 2023	Elphinstone Weighing Systems - 11/0332034550 Washer Spring Eye M24
17 Oct 2023	Elphinstone Weighing Systems - 11/AS0024-2 Spring Tension Axle Lift
17 Oct 2023	Elphinstone Weighing Systems - 11/0311300540 Bush Stepped Steel ALU/Hanger Axle Lift
17 Oct 2023	Elphinstone Weighing Systems - 11/0518915150 Bracket Lift Arm AL2
17 Oct 2023	Elphinstone Weighing Systems - Freigh
17 Oct 2023	Richards - Internal - Fit alternator and belt. Run tests on computer. CG
17 Oct 2023	Richards - Internal - Hook up computer and test exhaust/engine brake fault, move bolster positions, make new bolster stoppers. RS
17 Oct 2023	Richards - Internal - Fit bolster stops. CG
18 Oct 2023	CMV Truck & Bus Pty. Ltd - Pulley
24 Oct 2023	Von Pace Group - VP300914 Belt Tensioner

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
24 Oct 2023	Von Pace Group - VP8PK1390TM Drive Belt
24 Oct 2023	Von Pace Group - VP300971 Belt Tensioner
24 Oct 2023	Von Pace Group - VP10PK1470TM Drive Belt
24 Oct 2023	Von Pace Group - VP8442P TP5 Brake Valve
24 Oct 2023	Richards - Internal - Safety check CG
26 Oct 2023	Richards - Internal - Safety check, order parts, do repairs. RS
26 Oct 2023	Gippsland Steel Centre - Steel 75 x 50 x 6mm Painted RHS
27 Oct 2023	Transall Motors Pty Ltd - LK600 KIT-LOOP .600MM x 330MM L
27 Oct 2023	Transall Motors Pty Ltd - SSBK-1 Spraysafe Fender Support Kit
27 Oct 2023	Richards - Internal - Replace drive guards RS
27 Oct 2023	Richards - Internal - Replaced mudguards IS
31 Oct 2023	Transall Motors Pty Ltd - 0328136140AL2 Plate Alignment Dowel 70mm
31 Oct 2023	Transall Motors Pty Ltd - 031139410 Bush
31 Oct 2023	Transall Motors Pty Ltd - 0331030490 Ring
31 Oct 2023	Transall Motors Pty Ltd - 0235060700 Bump Stop
31 Oct 2023	Transall Motors Pty Ltd - 0250255611 Bolt
01 Nov 2023	Von Pace Group - MG P650S 650 Mudguard Wide - Silver
01 Nov 2023	Von Pace Group - VPTAS85124A Reman Exchange Kenworth Steering Box
01 Nov 2023	Von Pace Group - Core Deposit (For Steering Box)
03 Nov 2023	Von Pace Group - VP21097682 Bonnet Guide
03 Nov 2023	Von Pace Group - VP24340518 Park Brake Valve Assy
03 Nov 2023	Von Pace Group - VP480102800 Wabco EBS Unit
03 Nov 2023	Von Pace Group - VPCRS6548P 5"-6"x1200MM Curved Chromed Stack with Adblue Ceramic Coating
03 Nov 2023	Von Pace Group - RS 615L 600MM x 150MM Left HS Strip Aluminium
03 Nov 2023	Von Pace Group - RS 615R 600MM x 150MM Right HS Strip Aluminium
03 Nov 2023	Richards - Internal - Chase up CMV about fault with exhaust brakes. RS
04 Nov 2023	TNT Express Australia - Freight - Von Pace Parts for T35
06 Nov 2023	Richards - Internal - Replace stacks, talk to CV regarding fault. RS
09 Nov 2023	Richards - Internal - Replaced mudguards, replaced belts and tensioners IS
09 Nov 2023	Richards - Internal - Pick up truck from CMV ML
09 Nov 2023	Richards - Internal - Replace all trailer guards, replace belt tensioners and fan belts. RS
10 Nov 2023	Von Pace Group - VPACR285SR Chrome Push on Hub Cap
14 Nov 2023	CMV Truck & Bus Pty. Ltd - Carry out valve adjustment, air intake removed, rocket cover removed, carried out full valve set, rocket cover re-fit, air intake piping re-fit, test and driver - all ok.
14 Nov 2023	CMV Truck & Bus Pty. Ltd - Consumables and cleaning
14 Nov 2023	CMV Truck & Bus Pty. Ltd - Check and repair exhaust ram. Found exhaust ram seal to be blown out. Replaced exhaust ram. Road tested and rechecked - all ok.
14 Nov 2023	CMV Truck & Bus Pty. Ltd - VT22889891 Air Cylinder Kit
14 Nov 2023	CMV Truck & Bus Pty. Ltd - VT276948 O-Ring Kit Injector
14 Nov 2023	CMV Truck & Bus Pty. Ltd - VT21261987 Washer Injector Nozzle
16 Nov 2023	Richards - Internal - Straighten guard bracket. CG
21 Nov 2023	Richards - Internal - Safety check IS
21 Nov 2023	Richards - Internal - Safety check and repairs RS
22 Nov 2023	Transall Motors Pty Ltd - AF1969M Fleetguard Air Filter
23 Nov 2023	Traralgon Tyre Service - Strip and Fit
23 Nov 2023	Traralgon Tyre Service - Tyre Disposal Fee
27 Nov 2023	Richards - Internal - Look at fault with transmission not working, check for air leaks. Check actuators for air leak. check solenoids for operation. Book in truck for wheel alignment. RS
29 Nov 2023	Richards - Internal - Trailer fold motor fault AV
29 Nov 2023	Richards - Internal - Check out why trucks not coming on and hydraulics Arnt getting hot. Found motor in front of trailer is LI/S. Found ?? head motor not fit. Set pressure and test ok. ML

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
30 Nov 2023	Richards - Internal - Take truck over to CMV to get transmission fault checked out. Pick up truck from CMV later in the morning from CMV ML
30 Nov 2023	Big Wheels Truck Alignment - Inspect vehicle inline with customer advice. Carry out inspection of all steering, Suspension and underbody components.
30 Nov 2023	Big Wheels Truck Alignment - Front wheel alignment
30 Nov 2023	Big Wheels Truck Alignment - Drive alignment
30 Nov 2023	Big Wheels Truck Alignment - Consumables
01 Dec 2023	Von Pace Group - VP8942339641 Steering Arm Assembly
01 Dec 2023	Von Pace Group - VO894755521 Steering Arm Bolt
01 Dec 2023	Von Pace Group - VP0911165140 Nut
01 Dec 2023	Von Pace Group - VP091614140 Washer
01 Dec 2023	Von Pace Group - VP890496890 Washer
01 Dec 2023	Von Pace Group - Freight
06 Dec 2023	Richards - Internal - Exhaust stacks and cleaning up workshop AS
11 Dec 2023	Richards - Internal - Taking truck over to traralgon tyers and pick up AS
11 Dec 2023	Richards - Internal - Assist Chris with drive motor for trailer. Fold replacement, reset pressures. Book in for tyres. RS
13 Dec 2023	Traralgon Tyre Service - 295/80 R22.5 Bandag Tyre
13 Dec 2023	Traralgon Tyre Service - Truck Case
13 Dec 2023	Traralgon Tyre Service - Tyre Disposal Fee
14 Dec 2023	CMV Truck & Bus Pty. Ltd - VT82710488 Wiper Blade Assembly
15 Dec 2023	Valley Tyrepower Morwell - Golden Crown 265/70R19.5 Tyre
15 Dec 2023	Valley Tyrepower Morwell - Tyre disposal fee
15 Dec 2023	Valley Tyrepower Morwell - Golden Crown 265/70R19.5 Tyre
15 Dec 2023	Valley Tyrepower Morwell - Tyre disposal fee
18 Dec 2023	Richards - Internal - Look at fault with transmission. Plug in scan tool. found fault with speed sensor/54 counts. Removed and inspected wiring harness and order parts. RS
18 Dec 2023	Richards - Internal - Hook up computer and start test to check for faults. CG
18 Dec 2023	Richards - Internal - Help remove loom CG
19 Dec 2023	Richards - Internal - Replace speed sensor wiring. 1000hr service. RS
19 Dec 2023	Richards - Internal - Fit new gearbox loom. Straighten bracket on A trailer. Fix winch on B trailer. Carry out 1000hr service. CG
20 Dec 2023	Richards - Internal - Remove radiator & trans cools. replace alt. replace both belts and tensioners. Fit radiator & trans cooler. CG
28 Dec 2023	Richards - Internal - Program gearbox RS
09 Jan 2024	Richards - Internal - Repair, clean out AC system. Replace AC compressor. Clean up work area. RS
16 Jan 2024	Richards - Internal - Light repairs HP
19 Jan 2024	Richards - Internal - Start wiring for new rear bar HP
20 Jan 2024	Richards - Internal - Pack up both saw ?? and get 8 drive tyres back on rims. Repair fault in exhaust valve on CTI controls. ML
23 Jan 2024	Richards - Internal - Start service. HP
24 Jan 2024	Richards - Internal - Refit gear box/hook back up to trailers. Start refitting old gear box back together. ML
24 Jan 2024	Richards - Internal - Carry out service. Replacce RH tie rod end, refit wheels. Removed and tension. Assist with spring replacement. Assist with turntable bush replacement CG
24 Jan 2024	Richards - Internal - Replace rear bar and cab guard lights HP
24 Jan 2024	Richards - Internal - Assist carrying out service MK
24 Jan 2024	Richards - Internal - Finish helping installing wheels, the pull foward and replace rear right spring on B trailer. MK
25 Jan 2024	Richards - Internal - Look at fault with speed sensor jumping, check sensor, check wiring, found loose connection. RS
30 Jan 2024	CMV Truck & Bus Pty. Ltd - VT22038908 Transmission Filter

Richards Harvesting & Haulage

Service History

XW68KC - 2018 Mack Superliner



Date	Description
30 Jan 2024	CMV Truck & Bus Pty. Ltd - VTCAL8394882 Gearbox Oil 20L
05 Feb 2024	CMV Truck & Bus Pty. Ltd - VT22387296 Sensor speedo FH-M V2-4 D12-D16 M-DRIV CD02
09 Feb 2024	LV CNC - 40mm rail stiffeners
12 Feb 2024	Richards - Internal - Turbo, organise new one AV
12 Feb 2024	Richards - Internal - Go to workshop. get parts. travel to stockbale & assist Jon to get LHR drive back onto bead. return to workshop. CG
12 Feb 2024	Richards - Internal - Go out to truck, find turbo failed, R&R turbo. return to w/shop CG
12 Feb 2024	Richards - Internal - Went to Nar Nar Goon to pick up new turbo for t34, Drove back to the yart to get Air cti hose then drove to Yarrum to deliver turbo + air cti hose to Chris JH
13 Feb 2024	Transall Motors Pty Ltd - 1246V116 Dowel
13 Feb 2024	Transall Motors Pty Ltd - LK600 Kit Loop 600mm x 330 mm I
13 Feb 2024	Transall Motors Pty Ltd - SSCT-1 Support-Fender Chassis Tube
13 Feb 2024	Richards - Internal - Replace LHR drive guard, RHF drive hats seal, check over AV
13 Feb 2024	Richards - Internal - Replace LHR guard & guard pole, assist with hub seal replacement CG
13 Feb 2024	Richards - Internal - Assist Andy with chain/bolster stopper CG
13 Feb 2024	Richards - Internal - RH front drive hub seal to and a lead bearing MK
13 Feb 2024	Von Pace Group - VP21638569 Mack Turbocharger assy
13 Feb 2024	Von Pace Group - VP305421 Stud
13 Feb 2024	Von Pace Group - VP305480 Lock Nut
13 Feb 2024	Von Pace Group - Delivery
15 Feb 2024	Richards - Internal - Repairing the centre chain set up and making buckets for winches AS
15 Feb 2024	Richards - Internal - go to fit winches. find winch booster leaks. other booster to big CG
16 Feb 2024	Richards - Internal - Making brackets for chain winches AS
16 Feb 2024	Richards - Internal - Fit winches & latch fit cable carry out safety check CG
20 Feb 2024	CMV Truck & Bus Pty. Ltd - VT85147411 Compressor Air Conditioner New Breed
20 Feb 2024	CMV Truck & Bus Pty. Ltd - VT82781567 Receiver Dryer R13A CMH New Breed
20 Feb 2024	CMV Truck & Bus Pty. Ltd - VT85113770 TX Valve New Breed