

# Edit Fleet Information

Fleet No

Unit Description

RL012

CAT CS663E Vibratory Roller

Year Model

Engine No

2008

CPT30891

Chassis No

Rego No

CATCS663HDAG00685

Enter rego no

Location

Ophir Rd



Vehicle Category

Plant Equipment

Vehicle type

Roller

Vehicle Status

Active

All Fuel

Maintenance

Report

2025



≡ July

Job number	Description	Job type	OD
<a href="#">M_00292</a>	sterring HMU seals leaking	Defect	(3366-Hrs)
<a href="#">M_00293</a>	Fleet - RL012, Prestart - 2290, Jobcard By - Daniel Bock	Prestart Defect	(500-Hrs)
<a href="#">M_00295</a>	500hr service	500 HR Service	(3368-Hrs)
<a href="#">H_00226</a>	replace blown roller tyre	Breakdown	(3368-Hrs)

2023



≡ November

Job number	Description	Job type	OD
<a href="#">L_00048</a>	Hard to start. Replaced neural start sensor	Prestart Defect	(3145-Hrs)

≡ October

Job number	Description	Job type	OD
<a href="#">H_00168</a>	Service	250 HR Service	(3115-Hrs)

≡ March

Job number	Description	Job type	OD
------------	-------------	----------	----

≡ March

Job number	Description	Job type	OD
<u>M 00116</u>	replace l/h drum mount pad	Defect	(2786-Hrs)

2022

≡ November

Job number	Description	Job type	OD
<u>H 00080</u>	Hyd. Oil leak	Breakdown	(2786-Hrs)

≡ April

Job number	Description	Job type	OD
<u>1673</u>	Drum pads- replace Service *Adjust belts	750 HR Service	(0-Hrs)

2021

≡ December

Job number	Description	Job type	OD
<u>1616</u>	Replaced failed roller	Defect	(0-Hrs)

≡ August

Job number	Description	Job type	OD
<u>1554</u>	Door gets stuck and can't open-ordered new door seal Needs new fire ext. bracket	Defect	(0-Hrs)

≡ July

Job number	Description	Job type	OD
<u>1515</u>	Column strut- Replaced	Defect	(0-Hrs)

≡ June

Job number	Description	Job type	OD
<u>1483</u>	Remove and replace both batteries	Defect	(0-Hrs)
<u>1493</u>	Test and replace batteries	Defect	(0-Hrs)

2020



≡ November

Job number	Description	Job type	OD
<u>1357</u>	Replace coolant bottle	Defect	(0-Hrs)

≡ September

Job number	Description	Job type	OD
<u>1295</u>	Fuel guage broken Missing clip on UHF Sunvisor broken off Regas AC?	Defect	(0-Hrs)

≡ July

Job number	Description	Job type	OD
<u>1233</u>	Replace horn switch	Defect	(0-Hrs)
<u>1246</u>	Service due URGENT Broken E stop - Replaced Oil cooler hose leaking Crankcase breather hose missing AC & alternator belts squealing Needs cleaning brush	500 HR Service	(0-Hrs)

2019



≡ November

Job number	Description	Job type	OD
<u>1080</u>	Jump start and test alternator. Test ok.	Defect	(0-Hrs)

2018



≡ December

Job number	Description	Job type	OD
<u>856</u>	Seat Cover Coolant Leak - resealed No radio - fitted No UHF - fitted Service	250 HR Service	(0-Hrs)

Fleet Gallery

+ Add Images

Serviced Hrs

Machine Hrs

3368

3368

Next Service

Rego Date

3618

01/01/2100

Rego Due Date

