

Workshop Transaction Report
Printed on 12/07/2024 Date range From: 01/01/2017 To: 30/06/2024
Unit:TP10002 Job Cards All service types From opened Jobs To Any Status

Document	Type	Description	Date	Status	
102236	Job Card	TIPPER BODY NOT OPERATING CORRECTLY	20/01/17	Completed	
					Total Cost: 0.00
106111	Job Card	TILT TRAY MINOR SERVICE	29/03/17	Completed	
					Total Cost: 0.00
108074	Job Card	MODIFY COVER OVER BARTLET BALL	05/05/17	Completed	
					Total Cost: 0.00
108828	Job Card	TILT TRAY MAJOR SERVICE	17/05/17	Cancelled	
					Total Cost: 0.00
108878	Job Card	REPLACE MAC VALVE	17/05/17	Completed	
					Total Cost: 0.00
109256	Job Card	TILT TRAY MAJOR SERVICE	23/05/17	Completed	
					Total Cost: 0.00
116204	Job Card	TILT TRAY MINOR SERVICE	27/09/17	Completed	
					Total Cost: 0.00
123881	Job Card		24/02/18	Completed	
					Total Cost: 0.00
128027	Job Card		15/05/18	Completed	
					Total Cost: 0.00
130708	Job Card		28/06/18	Completed	
					Total Cost: 0.00
133710	Job Card	MINOR CHEDULED SERVICE	21/08/18	Completed	
					Total Cost: 0.00
136829	Job Card	TILT TRAY MINOR SERVICE	18/10/18	Completed	
					Total Cost: 0.00
139655	Job Card	CHECK TAILGATE LOCKS, FIT SAFETY	30/11/18	Completed	
					Total Cost: 0.00
139691	Job Card	CHECK TAILGATE OPERATION/LOCKING	03/12/18	Completed	
					Total Cost: 0.00
141631	Job Card	TILT TRAY MAJOR SERVICE	10/01/19	Completed	
					Total Cost: 0.00
148244	Job Card	TWO NEW TYRES, DOUBLE COIN.	29/04/19	Completed	
					Total Cost: 0.00
152182	Job Card	TILT TRAY MINOR SERVICE	27/06/19	Completed	
					Total Cost: 0.00

Workshop Transaction Report
Printed on 12/07/2024 Date range From: 01/01/2017 To: 30/06/2024
Unit:TP10002 Job Cards All service types From opened Jobs To Any Status

Document	Type	Description	Date	Status	
162683	Job Card	TILT TRAY MINOR SERVICE	09/12/19	Completed	
					Total Cost: 0.00
164349	Job Card	NEEDS TWO STEER TYRES	14/01/20	Completed	
					Total Cost: 0.00
164668	Job Card	TILT TRAY MAJOR SERVICE	21/01/20	Completed	
					Total Cost: 0.00
165633	Job Card	REPLACE TWO MUDFLAPS AS REQD.	05/02/20	Completed	
					Total Cost: 0.00
172050	Job Card	TILT TRAY MINOR SERVICE	15/05/20	Completed	
					Total Cost: 0.00
173811	Job Card	REPLACE FOUR REAR TYRES	12/06/20	Completed	
					Total Cost: 0.00
179034	Job Card	TILT TRAY MINOR SERVICE	31/08/20	Completed	
					Total Cost: 0.00
184223	Job Card	TILT TRAY MINOR SERVICE	16/11/20	Completed	
					Total Cost: 0.00
187901	Job Card	REMOVE AND CLEAN RADIATOR.	06/01/21	Completed	
					Total Cost: 0.00
187912	Job Card	TILT TRAY MAJOR SERVICE	06/01/21	Completed	
					Total Cost: 0.00
192392	Job Card	CHECK GPS BATTERY	12/03/21	Completed	
					Total Cost: 0.00
193276	Job Card	TILT TRAY MINOR SERVICE	25/03/21	Completed	
					Total Cost: 0.00
196548	Job Card	REVERSE LIGHT U/S, FLH PARKER LIGHT	11/05/21	Completed	
					Total Cost: 0.00
199503	Job Card	TILT TRAY MINOR SERVICE	18/06/21	Completed	
					Total Cost: 0.00
205764	Job Card	TILT TRAY MINOR SERVICE	07/09/21	Completed	
					Total Cost: 0.00
209080	Job Card	ADJUST TARP CABLES.	21/10/21	Completed	
					Total Cost: 0.00
211674	Job Card	TILT TRAY MINOR SERVICE	24/11/21	Completed	
					Total Cost: 0.00

Workshop Transaction Report
Printed on 12/07/2024 Date range From: 01/01/2017 To: 30/06/2024
Unit:TP10002 Job Cards All service types From opened Jobs To Any Status

Document	Type	Description	Date	Status	
212900	Job Card	TILT TRAY MAJOR SERVICE	10/12/21	Completed	
					Total Cost: 0.00
215000	Job Card	MIRROR FALLEN OUT OF HOLDER.	17/01/22	Completed	
					Total Cost: 0.00
218960	Job Card	TILT TRAY MINOR SERVICE	11/03/22	Completed	
					Total Cost: 0.00
219762	Job Card	REPLACE TYRE AS REQD, INNER LEFT.	22/03/22	Completed	
					Total Cost: 0.00
220551	Job Card		31/03/22	Completed	
					Total Cost: 0.00
224819	Job Card	TAIL LIGHTS NOT WORKING	26/05/22	Completed	
					Total Cost: 0.00
225046	Job Card	TILT TRAY MINOR SERVICE	30/05/22	Completed	
					Total Cost: 0.00
227467	Job Card	ANDERSON PLUG NOT CHARGING TRAILER	29/06/22	Completed	
					Total Cost: 0.00
228914	Job Card	NUMBER PLATE	19/07/22	Completed	
					Total Cost: 0.00
231196	Job Card	TILT TRAY MINOR SERVICE	17/08/22	Completed	
					Total Cost: 0.00
234257	Job Card	COOLANT TEMP SENS FAULT	28/09/22	Completed	
					Total Cost: 0.00
237581	Job Card	TILT TRAY MINOR SERVICE	10/11/22	Completed	
					Total Cost: 0.00
238413	Job Card	TILT TRAY MAJOR SERVICE	21/11/22	Completed	
					Total Cost: 0.00
239582	Job Card	RH LOW BEAM OUT	05/12/22	Completed	
					Total Cost: 0.00
243683	Job Card	TILT TRAY MINOR SERVICE	06/02/23	Completed	
					Total Cost: 0.00
244054	Job Card	OIL LEAKING FROM SUMP	10/02/23	Completed	
					Total Cost: 0.00
245749	Job Card	FIT 4 NEW TYRES	02/03/23	Completed	
					Total Cost: 0.00

Workshop Transaction Report
Printed on 12/07/2024 Date range From: 01/01/2017 To: 30/06/2024
Unit:TP10002 Job Cards All service types From opened Jobs To Any Status

Document	Type	Description	Date	Status	
248611	Job Card	TARP ROLLER REPAIRS	17/03/23	Completed	
					Total Cost: 0.00
252074	Job Card	TILT TRAY MINOR SERVICE	03/05/23	Completed	
					Total Cost: 0.00
258239	Job Card	TILT TRAY MINOR SERVICE	17/07/23	Completed	
					Total Cost: 0.00
264928	Job Card	TILT TRAY MAJOR SERVICE	02/10/23	Completed	
					Total Cost: 0.00
272690	Job Card	TILT TRAY MINOR SERVICE	08/01/24	Completed	
					Total Cost: 0.00
279987	Job Card	WASH BAY CLEANING PROCEDURE	28/03/24	Completed	
					Total Cost: 0.00
279988	Job Card	TILT TRAY MINOR SERVICE	28/03/24	Completed	
					Total Cost: 0.00
280652	Job Card	OFF HIRE REPAIRS	09/04/24	Completed	
					Total Cost: 0.00
285288	Job Card	CARRY OUT REPAIRS	30/05/24	Completed	
					Total Cost: 0.00