



Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

Safety Recalls

Campaign Code
[BGG55]

Recall Description
Power window master switch (driver's side) may insufficiently be lubricated & cause a short circuit which may be a fire hazard

Recall Number
2015/14999

Recall Status
● Complete

Completion Date
26/03/2018

Vehicle Details

VIN	6T153BK400X105751
Model	Camry L4
Colour	Arctic Frost
Trim	Javelin Dark Grey
Series	Sedan 5A 2.4 Altise
Production year/month	2010-08
Time/Date	11:26:58 20/03/2023

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best information currently available to Toyota.

*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit
<https://www.vehiclecalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.