

From: **Hawkdiesel via MechanDesk** nreply@mg.mechanidesk.com.au  
Subject: Hawkdiesel Invoice #9484 - Replace R12H valve and other jobs.  
Date: 28 August 2023 4:53 pm  
To: tera.mc.mufflers@bigpond.com



Hi O&L Hiab Service,

Please find attached invoice #9484 which is due on 28/08/2023

Job/invoice details:

- For: White Western Star 1BXF327.
- Description: Replace R12H valve and other jobs.

If you have any further questions, please let us know.

Best regards,

**Hawkdiesel**  
589 Bickley Rd  
Maddington WA 6109  
A.B.N: 33775677584  
Phone: 0419192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)

[Unsubscribe](#)



## TAX INVOICE

Tax Invoice Number: 9484  
Date: 28/08/2023  
Due Date: 28/08/2023  
Payment Term: COD

**BILL TO:**  
**O&L Hiab Service**

Email:  
tera.mc.mufflers@bigpond.com

589 Bickley Rd  
Maddington WA 6109  
ABN: 33775677584  
Licence: MRB 5967  
Tel: 0419192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)

**FOR:**  
Replace R12H valve and  
other jobs.  
Odometer: 365,345 Kms

Thank you for your business. Please make prompt payment to Hawklease BSB 016464 Account # 191086344.

<b>Subtotal</b>	\$2,533.68	<b>GST</b>	\$253.37	<b>Total</b>	\$2,787.05	<b>Paid</b>	\$0.00	<b>Balance Due</b>	\$2,787.05
-----------------	------------	------------	----------	--------------	------------	-------------	--------	--------------------	------------

13/7/23.  
 Checked brake adjustment. Adjusted clutch. Repaired air leaks. Replaced leaking rhd height valve and Horton solenoid. Overhauled diff lock. Overhauled leaking steering pump and replaced suction hose. Replaced leaking park brake valves in dash.  
 Further work: Flywheel housing. LHF/D air bag. Uni on jack shaft.

Description	Qty.	Unit Price	GST	Amount
LABOUR HOURS	10.0	\$140.00	\$140.00	\$1,400.00
Valve height control suits Airtiner	1.0	\$257.78	\$25.78	\$283.56
Switch low air bandix 1/4"NPT	2.0	\$63.04	\$12.61	\$126.07
Solenoid Kit Honda	1.0	\$256.14	\$25.61	\$281.75
Hose 1" Petrol and Oil Suction/Delivery	0.5	\$38.82	\$1.94	\$19.41
Clamp T Bolt 34-37mm	2.0	\$5.78	\$1.16	\$11.56
Seal Kit Vickers V20F (incl bng and shaft).	1.0	\$244.58	\$24.46	\$269.04
Diff lock Kit Meritor	1.0	\$102.04	\$10.20	\$112.24
Joiner 1/4 Straight Pl.	2.0	\$13.74	\$2.75	\$27.48
Mount Gasket Power Steering S60	1.0	\$15.00	\$1.50	\$16.50
Valve R12 Standard vertical 1/2" ports	1.0	\$73.62	\$7.36	\$80.98

Make	Western Star	Reg No.	1BXF327	Fleet No.	036623	VIN	
------	--------------	---------	---------	-----------	--------	-----	--



# TAX INVOICE

Tax Invoice Number: 10840

Date: 14/10/2024

Due Date: 14/10/2024

Payment Term: COD

**BILL TO:**

**O&L Hiab Service**

Email:

tera.mc.mufflers@bigpond.com

Tel: 08 62855406

Licence: MRB 11947

ABN: 33775677584

Maddington WA 6109

589 Bickley Rd

Email: ruben@hawkdiesel.com.au

**FOR:**

Steering pump sucking eng oil

into reservoir & engine cover

bolts (left off from last job)

Odometer: 390,322 Kms

Make	Model/Year	Body Type	Reg No.	Fleet No.	VIN
Western Star			1BXF327		936623

Description	Qty.	Unit Price	GST	Amount
Power Steering Pump	1.0	\$1,844.70	\$184.47	\$1,844.70
Gasket Power Steering Pump	1.0	\$15.60	\$1.56	\$15.60
Gasket-Cover 4 QT Reservoir	1.0	\$2.46	\$0.25	\$2.46
Power Steering Filter	1.0	\$37.75	\$3.78	\$37.75
7/8" JIC Fixed male x 1-1/16" Uno 90 Deg	1.0	\$39.61	\$3.96	\$39.61
1-5/16" JIC Fixed male x 1-5/16" Uno 45 Deg	1.0	\$87.67	\$8.77	\$87.67
1-5/16" JIC F/S x 1" Hose Tail Straight	1.0	\$26.23	\$2.62	\$26.23
Labour	3.0	\$140.00	\$42.00	\$420.00

Steering pump sucking engine oil into reservoir  
 Removed steering pump, cleaned steering pump outg surface, drained the  
 power steering reservoir and flushed out all the power steering lines.  
 Cleaned inside the reservoir and fit new filter and seal, get new fittings for new  
 power steering pump and fit pump to truck and connect up all the lines, fill power  
 steering res and bleed the system, topped fluid back up after system was bled.  
 Engine cover bolts (left off from last job)  
 Fitted bolts to engine cover

Subtotal	\$2474.02
GST	\$247.40
Total	\$2,721.42
Paid	\$0.00
Balance Due	\$2,721.42

Thank you for your business. Please make prompt payment to Hawkdiesel BSB 016464 Account # 191086344.  
 All work carries a 12 month warranty from date of invoice.  
 Title to the Goods shall remain vested in Hawkdiesel Pty Ltd and shall not pass to the Buyer until the purchase price for  
 the Goods has been paid in full and received by Hawkdiesel Pty Ltd.

From: **Hawkdiesel via MechanicDesk** noreply@mg.mechanicdesk.com.au  
Subject: Hawkdiesel Invoice #8988 - Air leak  
Date: 31 January 2023 4:57 pm  
To: tera.mcmufflers@bigpond.com



Hi O & L Hiab Service,

Please find attached invoice #8988 which is due on 31/01/2023

Job/invoice details:

- For: White Western Star 1BXF327.
- Description: Air leak

If you have any further questions, please let us know.

Best regards,

**Hawkdiesel**  
589 Bickley Rd  
Maddington WA 6109  
A.B.N: 33775677584  
Phone: 04 19192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)



## TAX INVOICE

Tax Invoice Number: 8988  
Date: 31/01/2023  
Due Date: 31/01/2023  
Payment Term: COD

**BILL TO:**  
O & L Hiab Service  
Email:

[tera.mcmufflers@bigpond.com](mailto:tera.mcmufflers@bigpond.com)

589 Bickley Rd  
Maddington WA 6109  
A.B.N: 33775677584  
Licence: MRB 5967  
Tel: 04 19192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)

**FOR:**  
Air leak

Make	Model/Year	Body Type	Reg No.	Fleet No.	VIN
Western Star			1 BXF327		936623

Qty	Unit Price	GST	Amount
1.0	\$55.58	\$5.56	\$55.58

RDPB3030 - Brake Booster 30/30

24/1/23

Replaced leaking LHF brake booster.

Subtotal	\$55.58
GST	\$5.56
Total	\$61.14
Paid	\$0.00
Balance Due	\$61.14

Thank you for your business. Please make prompt payment to Hawkdiesel BSB 016464 Account # 191086344.

From: Hawkdiesel via MechanicDesk noreply@mg.mechanicdesk.com.au  
Subject: Hawkdiesel Invoice #8816 - Steer brake booster.  
Date: 16 November 2022 2:11 pm  
To: tera.mc.mufflers@bigpond.com



Hi O & L Hiab Service,

Please find attached Invoice #8816 which is due on 16/11/2022

Job/Invoice details:

- For: White Western Star 1BXF327.
- Description: Steer brake booster.

If you have any further questions, please let us know.

Best regards,

**Hawkdiesel**  
589 Bickley Rd  
Maddington WA 6109  
A.B.N: 33775677584  
Phone: 0419192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)



## TAX INVOICE

Tax Invoice Number: 8816  
Date: 16/11/2022  
Due Date: 16/11/2022  
Payment Term: COD

**BILL TO:**  
O & L Hiab Service  
Email:

[tera.mc.mufflers@bigpond.com](mailto:tera.mc.mufflers@bigpond.com)

589 Bickley Rd  
Maddington WA 6109  
A.B.N: 33775677584  
Licence: MRB 5967  
Tel: 0419192579  
Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)

**FOR:**  
Steer brake booster.  
Odometer: 339,584 Kms

Make	Model/Year	Body Type	Reg No.	Fleet No.	VIN
Western Star			1BXF327		906628

Thank you for your business. Please make prompt payment to Hawkdiesel BSB 015464 Account # 191086344.

8/11/22	Replaced RHF drive brake booster. (not steer).	
	Further work: Front cam seal leak. Head gasketweep. Leak from filling below power steering pump. Bung below water pump leaking. Gearbox output leak. Rear main seal leak.	
Subtotal	\$387.15	
GST	\$38.72	
Total	\$425.87	
Paid	\$0.00	
Balance Due	\$425.87	

Description	Qty.	Unit Price	GST	Amount
LABOUR - LABOUR HOURS	25	\$130.00	\$32.50	\$325.00
30.30K - Brake Booster 3030	1.0	\$62.15	\$6.22	\$62.15

Description	Qty.	Unit Price	GST	Amount
LABOUR HOURS	50.0	\$140.00	\$700.00	\$7,000.00
Detroit Powercool	60.0	\$5.90	\$354.00	\$354.00
Oil Mobil 15W40 Modern Full Protection	40.0	\$7.05	\$282.00	\$282.00
Oil & Filter Disposal	1.0	\$20.00	\$20.00	\$20.00
Hose S60 coolant bypass hose	2.0	\$54.52	\$109.00	\$109.03
Hose S60 oil cooler	2.0	\$58.50	\$117.00	\$117.00
Clamp lap 5" stainless	2.0	\$15.39	\$30.80	\$30.78
Flex Exh 5" SS	1.0	\$183.79	\$183.80	\$183.79
Overhaul Kit 12.7 S60 Early elliptical dome IM	1.0	\$5,936.61	\$5,936.61	\$5,936.61
Filter kit Series 60 non-egr	1.0	\$92.90	\$92.90	\$92.90
Air Filter Tapered	1.0	\$115.54	\$115.55	\$115.54
Nut 10mm S60 Turbo	4.0	\$1.72	\$6.88	\$6.88
Washer 10mm hardened	4.0	\$10.36	\$41.44	\$41.44
Stud 10mm S60 turbo	4.0	\$14.79	\$59.16	\$59.16
Hose Sillicon 2 1/2"	0.5	\$153.26	\$76.63	\$76.63
Hose Hosesorce	1.0	\$248.81	\$24.88	\$248.81
Shim counterbore 0.030"	6.0	\$55.24	\$331.44	\$331.44
Counterbore repair	6.0	\$200.00	\$1,200.00	\$1,200.00
Cylinder head Series 60 12.7	1.0	\$5,089.00	\$5,089.90	\$5,089.00
Valve S60 oil regulator	2.0	\$76.89	\$153.80	\$153.78
Hose boost KW 4"	4.0	\$72.60	\$290.40	\$290.40

**VEHICLE:**  
 Inframe overhaul estimate  
 Vehicle Owner: O&L Hiab Service  
 Reg No: 1BXF327  
 VIN: 936623  
 Model: Western Star

**PREPARED FOR:**  
 O&L Hiab Service  
 Email: [tera.mc.mufflers@bigpond.com](mailto:tera.mc.mufflers@bigpond.com)

**QUOTE #532**  
 Issue Date: 23/05/2024  
 Expiry Date: 22/06/2024

589 Bickley Rd  
 Maddington WA 6109  
 ABN: 33775677584  
 ACN: 165091547  
 Licence: MRB 5967  
 Tel: 08 62855406  
 Email: [ruben@hawkdiesel.com.au](mailto:ruben@hawkdiesel.com.au)



*Handwritten:* Total \$5000  
 9,997.81  
 currency

*Handwritten:* kept as 83-5-24

*Handwritten:* 25,000.00  
 9,928.70  
 \$34,928.70  
 Private Acc  
 Payment

This is a quote to carry out an "in-chassis overhaul"  
 Injector, turbo and oil pump replacement is recommended but not  
 essential at this stage.  
 I will require a deposit of \$25k to start assembly of engine the the  
 balance on pickup.  
 Bank details  
 Hawk diesel  
 BSB 016464  
 Account 191086344

Subtotal	\$31,816.28
GST	\$3,181.63
Total	\$34,997.91

Isolator for sump bolt	10.0	\$10.23	\$10.23	\$102.30
Isolator, Intermediate cover, Early.	10.0	\$15.72	\$15.72	\$157.20
Clamp boost 4'	8.0	\$24.30	\$19.44	\$194.40
Clamp CT350	4.0	\$17.82	\$7.13	\$71.28
CLAMP 1 3/4 IN - 2 5/8 IN	4.0	\$17.88	\$7.15	\$71.52
Clamp CT300	8.0	\$16.75	\$13.40	\$134.00
Clamp V Band 4"	1.0	\$60.97	\$6.10	\$60.97
Hose Silicon 1"	1.5	\$41.99	\$6.30	\$62.99
Nut big-end S60	12.0	\$12.94	\$15.53	\$155.28
Spray Paint Can Hawk diesel Green	1.0	\$31.68	\$3.17	\$31.68
ANCHOR PRIMER GREY 300G	1.0	\$38.19	\$3.82	\$38.19
V Clamp 5" exhaust.	1.0	\$69.41	\$6.94	\$69.41
O-ring turbo outlet	1.0	\$33.40	\$3.34	\$33.40
Clamp Hose 25-40mm	2.0	\$5.11	\$1.02	\$10.22
Injector reliabil 5695	6.0	\$846.00	\$507.60	\$5,076.00
Turbo Borg Warner S60	1.0	\$2,450.00	\$245.00	\$2,450.00
Oil pump S60	1.0	\$1,358.24	\$135.82	\$1,358.24

Description	Qty.	Unit Price	GST	Amount
LABOUR HOURS	52.0	\$140.00	\$728.00	\$7,280.00
Detroit Powercool	60.0	\$5.90	\$35.40	\$354.00
Oil Mobil 15W40 Modern Full Protection	40.0	\$7.05	\$28.20	\$282.00
Oil & Filter Disposal	1.0	\$20.00	\$2.00	\$20.00
Hose S60 coolant bypass hose	2.0	\$25.56	\$5.11	\$51.12
Hose S60 oil cooler	2.0	\$25.81	\$5.16	\$51.61
Overhaul Kit 12.7 S60 Early elliptical dome IM	1.0	\$5,936.61	\$593.66	\$5,936.61
Filter Kit Series 60 non-egr	1.0	\$92.90	\$9.29	\$92.90
Nut 10mm S60 Turbo	4.0	\$1.72	\$0.69	\$6.88
Washer 10mm hardened	4.0	\$10.36	\$4.14	\$41.44
Stud 10mm S60 turbo	4.0	\$14.79	\$5.92	\$59.16
Hose Sillicon 2 1/2"	1.0	\$153.26	\$15.33	\$153.26
Shim counterbore 0.030"	6.0	\$55.24	\$33.14	\$331.44
Counterbore repair	6.0	\$200.00	\$120.00	\$1,200.00
8922740 - Valve S60 oil regulator	2.0	\$102.09	\$20.42	\$204.18
Isolator, Intermediate cover, Early.	10.0	\$19.31	\$19.31	\$193.05
Clamp boost 4"	8.0	\$24.30	\$19.44	\$194.40
Clamp CT350	4.0	\$17.82	\$7.13	\$71.28
CLAMP 1 3/4 IN - 2 5/8 IN	4.0	\$17.88	\$7.15	\$71.52
Clamp CT300	8.0	\$16.75	\$13.40	\$134.00
Clamp V Band 4"	1.0	\$60.97	\$6.10	\$60.97
Hose Sillicon 1"	1.5	\$41.99	\$6.30	\$62.99
Nut big-end S60	12.0	\$12.94	\$15.53	\$155.28

Make	Western Star
Model/Year	
Body Type	
Reg No.	1BXF327
Fleet No.	
VIN	936623

FOR: Inframe overhaul estimate

389955  
 2185421027  
 Paid - 15/6/24  
 9,928.07

Tax Invoice Number: 10409  
 Date: 14/06/2024  
 Due Date: 14/06/2024  
 Payment Term: COD  
 BILL TO:  
 O&L Hiab Service  
 Email: terra.mc.mufflers@bigpond.com

589 Bickley Rd  
 Maddington WA 6109  
 ABN: 33775677584  
 Licence: MRB 5967  
 Tel: 08 62855406  
 Email: ruben@hawkdiesel.com.au



TAX INVOICE

Private Acc

Intrame rebuild  
 Removed hump inside truck to gain better access to engine.  
 Found 2 stripped bolts holding hump down so had to cut them out and fit riv-nuts.  
 Drained engine coolant and oil.  
 Removed all necessary parts to be able to remove cylinder head.  
 Removed cylinder and inspected - found N4 piston to have failed and valves on same cylinder.  
 Removed sump, oil pump and pickup.  
 Removed cylinder kits and cleaned all parts.  
 Cut counter bores to suit 30thou shims as counterbores were pitted.  
 Replaced main bearings and fitted new cylinder kits.  
 Replaced N4 conrod with a good condition second hand one due to being damaged.  
 Replaced coolant hoses on engine.  
 Replaced starter motor.  
 Painted new cylinder head and assembled all removed parts to it.  
 Fitted cylinder head to truck along with all removed parts using new seals and gaskets.  
 Fitted new injectors to engine and cam bearings.  
 Assembled cam and measured gear train back lash.  
 Refitted all removed parts.  
 Filled radiator with new coolant.  
 Filled engine oil and got truck running.  
 Ran truck up to temp and topped up engine levels.  
 Degreased engine and road tested truck, found everything to be ok.

Subtotal	\$31,753.36
GST	\$3,175.34
Total	\$34,928.70
Paid B. Transfer	\$25,000.00
Balance Due	\$9,928.70

Spray Paint Can Hawkdiessel Green	1.0	\$31.68	\$31.68	\$31.68
ANCHOR PRIMER GREY 300G	1.0	\$38.19	\$38.19	\$38.19
V Clamp 5" exhaust	1.0	\$69.41	\$69.41	\$69.41
O-ring turbo outlet	1.0	\$16.09	\$16.09	\$16.09
Clamp Hose 25-40mm	2.0	\$5.11	\$10.22	\$10.22
Injector reliabil 5695	6.0	\$846.00	\$507.60	\$5,076.00
Turbo Borg Warner S60	1.0	\$2,145.00	\$214.50	\$2,145.00
Head S60 inconnel valves	1.0	\$5,089.50	\$508.95	\$5,089.50
Plug. 3/8" square socket head	2.0	\$3.90	\$0.78	\$7.80
Kit Turbo Mount S60.	1.0	\$72.51	\$7.25	\$72.51
Freight Charges	1.0	\$49.80	\$4.98	\$49.80
Starter Motor 12V 39MT 11 Tooth.	1.0	\$531.70	\$53.17	\$531.70
Belt 13A1270	2.0	\$26.07	\$5.21	\$52.13
Belt fan/ac	1.0	\$31.41	\$3.14	\$31.41
Clamp 4" Boost Spring T bolt	8.0	\$22.69	\$18.15	\$181.48
Filter air W/star reverse type	2.0	\$120.87	\$24.17	\$241.75
Valve adjuster screw	24.0	\$23.89	\$57.35	\$573.46
Gasket S60 sump black	1.0	\$143.00	\$14.30	\$143.00
Header tank repair	1.0	\$286.00	\$28.60	\$286.00
Belt vee 13A1590 W/star 4800	3.0	\$30.58	\$9.17	\$91.73
Clamp WD 79-152mm SS	1.0	\$6.42	\$0.64	\$6.42