



Komatsu Forklift Australia Pty Ltd
 ABN 71 080 792 730

Call No. 950352

Unit No. FLB50

Van No. 4113

Work Order

Name		HIRE MAINTENANCE		BRANCH NUMBER	
		FIXED PRICE MAINTENANCE		PLANNED REPAIR	
		WARRANTY		BREAKDOWN	
Authorised By		Post Code		CUSTOMER	
CUSTOMER DAMAGE		INTERNAL			
Make Baoli	Order No	Date Serviced 22.12.21	SMR 2906	Location onsite	
Model KB25	Serial No B16006G02798	Engine/Controller No			

FAULTS	Brakes	RESOLUTION CODE

CAUSE	

A-10711

CORRECTION	Inspect machine adjust Brakes. No better remove drum find oil on shoes. LMS. disassemble brake and order parts.

unit has extensive ROPS damage.

QUOTE	NEXT CALL	Customer Name	Technician's Name
LEAVE IT	BOOK TIME	Customer Signature	Technician's Signature

VAN PARTS USED			OIL USAGE	
Part No.	Description	Qty		Lt.
			Transmission	
			Engine	
			Hydraulic	
			Gear	
			Brake Fluid	
			Degreaser	

CALL TYPE	FUEL	TERRITORY	CONS	CALL FEE \$	COMPLETED	DETAILED INVOICE
-----------	------	-----------	------	-------------	-----------	------------------

Please execute at my cost, as soon as you conveniently can, the service and repairs listed above together with any work considered essential. I have read and accept the Terms and Conditions, set out on the reverse side hereof, as the basis on which the work will be undertaken.

Customer Signature

QUOTED PRICE	\$
--------------	----



Komatsu Forklift Australia Pty Ltd
ABN 71 080 792 730

Call No. 956 352

Unit No. FBK 50

Van No. 1110

Work Order

514 /		HIRE MAINTENANCE	BRANCH NUMBER	41
		FIXED PRICE MAINTENANCE	PLANNED REPAIR	
		WARRANTY	BREAKDOWN	/
Authorised By		Post Code	CUSTOMER	/
Make BAOKI	Order No	Date Serviced 13/1/22	INTERNAL	
Model VB 25	Serial No B16206602792	Engine/Controller No	SMP 2905	Location AS ABOVE

FAULTS	RESOLUTION CODE
L/A FRONT BRACKETS LEAKING DIFF OIL.	

CAUSE

CORRECTION
<p>Check if shoes & drum front track lined & brake & lead to frame transport to assemble L/H brackets - change w/ outer beam & seal for drum. - ASSEMBLE DRUM ONTO MACHINE. - FIT L/H FRONT WHEEL - ADJUST & TEST BRACKETS TOP UP DIFF OIL.</p>

R-19815

QUOTE	NEXT CALL	Customer Name	Technician's Name
LEAVE IT	BOOK TIME	Customer Signature	Technician's Signature

VAN PARTS USED			OIL USAGE	
Part No.	Description	Qty		Lt.
	AXLE OIL	95-110 DIFF OIL	4.	
				Transmission Lt.
				Engine Lt.
				Hydraulic Lt.
				Gear Lt.
				Brake Fluid Lt.
				Degreaser Lt.

CALL TYPE	FUEL	TERRITORY	CONS	CALL FEE \$	COMPLETED /	DETAILED INVOICE /
-----------	------	-----------	------	-------------	-------------	--------------------

Please execute at my cost, as soon as you conveniently can, the service and repairs listed above together with any work considered essential. I have read and accept the Terms and Conditions, set out on the reverse side hereof, as the basis on which the work will be undertaken.

Customer Signature

QUOTED PRICE	\$
--------------	----

R# 21085

Repair Job Sheet

R 5364

REPAIR JOB SHEET

Registration: _____ Fleet No: FUB 50 ODO/Hubo No: 2915 hrs Date: 10/2/22

Registration Due Date: _____ E-Tag No: _____ NHVAS Label No: _____

Phone: Fuel Cards: REPAIR REQUEST:

forklift

JOB DESCRIPTION / NOTES / PARTS USE

Problems, Check, Blow out RADIATOR
+ ENGINE BAY.

20

ENTERED

09 MAY 2022

BY:

Repair carried out by: CITUS Date: 10/2/22