



## Vehicle History Detail



|                 |                   |
|-----------------|-------------------|
| Fleet #         | XN01AM            |
| Registration    | XN01AM            |
| Make            | KENWORTH          |
| Model           | T408              |
| VIN / Chassis # | 6F50000009A440684 |

| Number | Date       | Kms     | Hours | Type              | Repairer    | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|-------------------|-------------|---|---------|------------|
| R-1807 | 13/12/2022 | 2000000 | 0     | Clutch Adjustment |             |   |         | \$0.00     |
| S-2656 | 02/11/2022 | 2843516 | 0     | A - Fortnightly   |             |   |         | \$594.00   |
| R-1781 | 18/10/2022 | 2000000 | 0     | Wiper Blades      |             |   |         | \$114.60   |
| S-2615 | 20/09/2022 | 2000000 | 0     | A - Fortnightly   | Jack        | A service Replace Inner Hub Seal on L/H rear drive axle<br>Replace brakes and clean hub assembly clean diff breather, change diff oil |         | \$1,378.72 |
| S-2618 | 17/09/2022 | 2000000 | 0     | B - 50k           | Tony Madden | Replaced Fuel Primer B Service Repair Grease Lines  |         | \$1,689.89 |
| T-561  | 25/08/2022 | 9940893 | 66687 | New, Strip & Fit  |             | 4x haulmax 4x truck tyre disposal 2x strip and fit  | 108038  | \$2,910.00 |
| R-1701 | 09/08/2022 | 2000000 |       | Brakes            |             | refit slack adjuster  |         | \$198.00   |
| O-191  | 18/07/2022 | 0       | 0     | Registration      |             |   |         | \$4,685.00 |
| R-1597 | 14/06/2022 | 2000000 |       | ABS               | Dylan       | refit abs plug  |         | \$71.50    |
| R-1634 | 14/06/2022 | 2791912 | 0     | Mirrors           | Dylan       | replace broken mirror   |         | \$318.88   |

| Number | Date        | Kms     | Hours | Type                  | Repairer | Repairer Notes   | Invoice | Cost        |
|--------|-------------|---------|-------|-----------------------|----------|--|---------|-------------|
| R-1596 | 10/06/2022  | 2000000 |       | Brakes, Suspension    |          | remove and fit new steer axle Springs, Shackles & Pins, King Pins, Wheel Bearings, Hub Seals, Brake Drums, Brake Shoes, S-cams remove leaking air block on firewall and refit new air block and fittings replace leaking gearbox pressure switch sent truck to get wheel alignment at pro axle in sydney on 10/6/2022  |         | \$11,239.24 |
| R-1167 | 17/05/2022  | 2000000 | 0     | Differential Oil Leak | Kobi     | call out inspected driveline one uni joint slightest movement whole drive line with a lot of back lash vehicle to come back and have diff oil checked for metal (23/06/2021) diffs checked for metal on 25/6/21 no metal present replaced welsh plug in water pump housing replace oil spinner hose replace rear brakes replace rhrd hub seal replace front brakes replace lhf hub seal replace jack shaft seal replace rear uni joint |         | \$0.00      |
| T-519  | .06/05/2022 | 2000000 | 0     | New                   |          | 2x hankook 2x truck tyre disposal  | 106954  | \$1,446.00  |
| R-1545 | 03/05/2022  | 2000000 |       | Electronic Diary      | Jack     | Removal of Electronic Diary NAVMAN Unit  |         | \$35.75     |
| R-1522 | 27/04/2022  | 2000000 | 0     | Wheels                | Dylan    |  |         | \$987.60    |
| R-1441 | 19/04/2022  | 2000000 | 0     | Engine Brake          |          |  |         | \$0.00      |
| R-1397 | 19/04/2022  | 2000000 | 0     | Defect                |          |  |         | \$0.00      |
| R-1427 | 19/04/2022  | 2000000 | 0     | Bunk Air Con          |          |  |         | \$0.00      |
| R-1439 | 19/04/2022  | 2000000 | 0     | Auto Greaser          |          |  |         | \$0.00      |

| Number | Date       | Kms     | Hours | Type                 | Repairer | Repairer Notes   | Invoice     | Cost       |
|--------|------------|---------|-------|----------------------|----------|--|-------------|------------|
| R-1428 | 13/04/2022 | 2000000 | 0     | Brakes               |          | general inspection of truck<br>replace first axel right hand side<br>air bag adjust rear brakes<br>refit/replace grease line fittings  |             | \$539.00   |
| S-2525 | 08/04/2022 | 2771003 | 0     | B - 50k              | Dylan    |  |             | \$666.69   |
| S-2531 | 07/04/2022 | 2731000 | 0     | C - 150k + RTA Insp. | Dylan    |  |             | \$713.79   |
| S-2517 | 06/04/2022 | 2766535 | 0     | A - Fortnightly      | Jack     |  |             | \$594.00   |
| T-477  | 16/03/2022 | 2761698 | 0     | Good year tyre       |          | Goodyear Tyre @ \$710.00 plus<br>fitting \$110.00 1x disposal<br>\$20.50 53 km's each way Total<br>106km's \$110 1 hour @ \$140.00   | NBS10054075 | \$980.50   |
| R-1464 | 20/02/2022 | 2000000 | 0     | ABS                  | Jack     | rewire abs plug  |             | \$572.00   |
| R-1564 | 17/02/2022 | 2000000 |       | Air Leak             |          | fix air leak   |             | \$154.00   |
| R-1462 | 16/02/2022 | 2000000 | 0     | Hub Leak             | Dylan    | Replaced hub seal  |             | \$0.00     |
| R-1459 | 14/02/2022 | 2000000 | 0     | Gearbox              | Jack     | put new gear box oil in box and<br>greased all driveline parts if fault<br>returns truck will need to go to<br>canberra truck repairs for<br>gearbox rebuild   |             | \$295.53   |
| R-1456 | 06/02/2022 | 2000000 | 0     | Body Repairs         | Jack     | JR 1052 INLAND TRUCKS<br>replace bonnet straps   |             | \$806.12   |
| R-1473 | 25/01/2022 | 2000000 |       | over heating         |          | SUBLET ADAMS AUTO<br>ELECTRICS TO REPAIR.<br>CHECK A/C SYSTEM, LOCATE<br>FAULTY COMPRESSOR AND<br>REPLACE. FLUSH A/C HOSE,<br>REPLACE T.X VALVE AND<br>RECIEVER DRYER. REMOVE<br>EVAPORATOR AND CLEAN.<br>REPAIR HEATER BOX. PRICE<br>INCLUDES ALL PARTS.<br>\$2497.00 | 1187722     | \$4,953.69 |

| Number | Date       | Kms     | Hours | Type                            | Repairer    | Repairer Notes  | Invoice   | Cost       |
|--------|------------|---------|-------|---------------------------------|-------------|---|-----------|------------|
| R-1438 | 27/12/2021 |         | 0     | Air Conditioner                 |             | CANBERRA TRUCKS   |           | \$0.00     |
| R-1402 | 22/12/2021 | 2000000 |       | Alternator                      |             | UNIT BOOKED TO WORKSHOP FOR NOT STARTING. CHECK UNIT OVER & CARRY OUT DIAGNOSIS. FOUND ALTERNATOR & TERMINAL LOOSE & BURNT OFF. R&R ALTERNATOR. REPAIRED WIRING. REPLACED WORN BELT & TESTRUN UNIT. | SI-225299 | \$1,086.87 |
| S-2516 | 11/12/2021 | 2731000 | 0     | B - 50k                         | Jack        |   |           | \$666.69   |
| R-1419 | 11/11/2021 | 2000000 | 0     | Add Oil                         | Jack        |   |           | \$33.79    |
| R-1418 | 02/11/2021 | 2000000 | 0     | grease line                     | Dylan       | repair grease lines   |           | \$175.17   |
| R-1414 | 19/10/2021 | 2000000 | 0     | Electrical                      | Jack        | replace clearance light   |           | \$71.50    |
| R-1413 | 05/10/2021 | 2000000 | 0     | Add Oil                         | Jack        | top up oil  |           | \$44.20    |
| T-414  | 02/10/2021 | 2000000 | 0     | Cap and case, Recamic, Regroove |             | 4x recamic cap and case 2x regroove   | 104588    | \$2,036.00 |
| R-1361 | 24/09/2021 | 2000000 | 0     | engine oil                      | Driver      | driver added engine oil himself then got workshop to top back up his oil container as he carries spare oil for this fridge motor as it burns oil  |           |            |
| S-2339 | 20/09/2021 | 2689891 | 41443 | A - Fortnightly                 | Dylan       |   |           |            |
| S-2341 | 20/09/2021 | 2649402 | 0     | B - 50k                         | Dylan, Jack |   |           |            |
| T-403  | 08/09/2021 | 2000000 | 0     | Puncture                        |             | 1x puncture repair 1x truck valve repair  | 104357    | \$114.00   |
| R-1342 | 24/08/2021 | 2000000 | 0     | Suzi Coils                      |             | replaced with pole spring off xn02am  |           |            |
| S-2335 | 16/08/2021 | 2000001 | 0     | B - 50k                         |             |   |           | \$0.00     |

| Number | Date       | Kms     | Hours | Type               | Repairer    | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|--------------------|-------------|---|---------|------------|
| R-1336 | 16/08/2021 | 2000000 | 0     | Bunk Air Con       |             | replaced fuse working fine  |         |            |
| T-391  | 13/08/2021 | 2000000 | 0     | Strip & Fit        |             | 2x strip and fit and balance steers plus pressure   | 104124  | \$220.00   |
| S-2320 | 09/08/2021 |         | 0     | A - Fortnightly    |             |   |         |            |
| R-1323 | 02/08/2021 | 2000000 | 0     | body               |             | new part fitted to xn30am   |         |            |
| R-1307 | 16/07/2021 | 0       | 0     | Wiper Blades       | Jack        | remove air intake and air filter to give enough room in engine bay to adjust wiper linkages   |         |            |
| R-1271 | 28/06/2021 | 606254  | 0     | Battery            |             | replaced 4 x n70zz hilltops diesel  |         | \$848.72   |
| S-2287 | 26/06/2021 | 2601385 | 0     | A - Fortnightly    | Kobi        |   |         | \$332.97   |
| R-1269 | 23/06/2021 | 2000000 | 0     | Exhaust Brake      | Jack        | replaced exhaust brake stalk  |         | \$405.94   |
| R-1263 | 22/06/2021 | 0       | 0     | Dash - Gauges      | Jack        |   |         | \$151.25   |
| R-1246 | 14/06/2021 | 2591398 | 0     | Windscreen Cracked |             |   |         | \$365.20   |
| S-2248 | 11/06/2021 | 2590728 | 0     | A - Fortnightly    | Dylan       |   |         | \$308.00   |
| S-2192 | 28/05/2021 | 2581214 | 0     | D - 300k           | Dylan, Jack |   |         | \$1,987.90 |
| R-1164 | 18/05/2021 |         |       | Wiper Blades       | Jack        | This problem happened around two months ago in sydney and was sent to gilbert and roach, they hit it with a hammer and unjammed it and told us it needs to be replaced soon. Now it jams every few minutes tony was informed of issue on 10/05/21 |         | \$639.12   |
| S-2173 | 07/05/2021 | 2566079 | 0     | A - Fortnightly    |             |   |         | \$308.00   |
| R-1166 | 07/05/2021 | 2566079 | 0     | Clearance Lights   | Jack        | replace broken clearance light  |         | \$98.45    |
| R-1114 | 30/04/2021 | 2563379 | 0     | Windscreen Cracked |             | Replaced Friday 30/4/21   | 127237  | \$322.00   |

| Number | Date       | Kms     | Hours | Type               | Repairer       | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|--------------------|----------------|---|---------|------------|
| T-307  | 23/04/2021 | 0       | 0     |                    |                |   |         |            |
| T-349  | 23/04/2021 | 2000000 | 0     | Puncture           |                | 1x puncture repair  | 103026  | \$85.00    |
| T-348  | 22/04/2021 | 2000000 | 0     | New                |                | 2x michelin   | 103006  | \$1,540.00 |
| R-1124 | 16/04/2021 | 2551199 | 0     | Suspension         | Zane           | replace front shocks, check wheel bearings and go over other steering and suspension components |         | \$1,158.21 |
| R-1101 | 07/04/2021 | 0       | 0     | Clutch Adjustment  |                |   |         |            |
| R-1083 | 23/03/2021 | 2000000 | 0     | Wiper Blades       |                | replace wiper motor. job is getting done at in sydney, order number kb407                       |         |            |
| R-1052 | 18/03/2021 | 2515193 |       | Gearbox            |                | adjusted clutch   |         | \$75.90    |
| R-1065 | 18/03/2021 | 2535191 |       | Brakes             | Dylan          | Greasing line replaced  |         | \$115.50   |
| S-2051 | 18/03/2021 | 2535191 | 0     | A - Fortnightly    |                |   |         | \$308.00   |
| R-1079 | 18/03/2021 | 2535191 | 0     | Dash - Gauges      | Jack           | replaced water temp gauge replaced volt gauge part no 72507                                     |         | \$246.21   |
| R-1053 | 05/03/2021 | 2529990 |       | Windscreen Cracked | Steve T        | Monitoring Booked in to Wagga windscreen Dr, Friday 5/3/21 10:00. Order number ST390.           |         |            |
| S-2012 | 04/03/2021 | 2530152 | 0     | B - 50k            | Dylan, Steve T |   |         | \$664.24   |
| R-1017 | 01/03/2021 | 2527087 | 0     | Clutch Adjustment  | Kobi           |   |         | \$57.75    |
| R-1043 | 01/03/2021 | 2527680 | 0     | ABS, Trailer Plug  |                | Fixed ABS plug again  |         | \$35.75    |
| S-2007 | 01/03/2021 | 2527680 | 0     | A - Fortnightly    | Dylan          | Adjust clutch   |         | \$165.00   |
| R-1018 | 17/02/2021 | 2519234 | 0     | Coolant Leak       | Steve T        | Heater hose replaced  |         | \$230.58   |

| Number | Date       | Kms     | Hours | Type                  | Repairer   | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|-----------------------|------------|---|---------|------------|
| R-1034 | 17/02/2021 | 2518907 |       | Exhaust               |            | Found broken mount bracket and damaged band clamp. Remove and replace broken mount bracket & repair. Remove & replace exhaust band clamp  | 11986   | \$207.35   |
| R-1020 | 17/02/2021 | 2521026 | 0     | ABS, Trailer Plug     | Jack       |   |         | \$57.75    |
| R-962  | 12/02/2021 | 2515151 | 0     | Air Conditioner       | Jack, Zane | Repair delayed due to new carpet manufacture. (Inland)  |         | \$2,011.32 |
| R-732  | 28/01/2021 | 2000000 | 0     | Differential Oil Leak |            |   |         | \$188.66   |
| R-955  | 27/01/2021 | 2000000 | 0     | Gearbox               | Kobi       | New X/Y module fitted   |         | \$1,659.99 |
| S-956  | 15/01/2021 | 2512571 | 0     | A - Fortnightly       | Zane       | Icepak service overdue - Jeff Gunning reported this 18/12 Tripac overdue oil change/filter 11/1/21  |         | \$343.41   |
| R-830  | 15/01/2021 | 0       | 0     | Dash - Gauges         | Driver     | Driver fixed rattle himself by tightening a bolt under the clutch pedal   |         |            |
| R-916  | 15/01/2021 | 0       | 0     | Trailer Plug          | Steve T    |   |         | \$55.95    |
| R-1001 | 08/01/2021 | 2000000 |       | Fridge Motor          |            | Unit has alternator alarm and is cutting out. Found alternator not charging, repaired wiring harness to alternator & replaced belts. Start unit and found fuel leaking from injector pipes & engine mounts broken. Remove all panels & brackets, replace engine mounts. Remove intake manifold, free up seized fuel return pipe. Weld split in pipe & replace fuel injector seals & return hoses, reassemble & test run. Fit supplied air filter & top up oil |         | \$1,189.22 |
| R-875  | 04/01/2021 | 2250509 | 0     | Wiper Blades          | Steve T    |   |         | \$83.97    |

| Number | Date       | Kms     | Hours | Type                   | Repairer    | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|------------------------|-------------|---|---------|------------|
| T-248  | 31/12/2020 | 2000000 | 0     | Strip & Fit            |             | 2x strip and fit  | 101662  | \$220.00   |
| R-988  | 18/12/2020 | 2000000 |       | Air Conditioner        |             | #1 Found unit with discharge hose blown off between compressor & evaporator. Remove & replace blown discharge line & fittings, pressure test for leaks, now evidence of further leaks. Evacuate system & charge with refrigerant #2 Unit returned wit seized compressor. Remove compressor & clean oil from system, replace oil & replace with new compressor. Pressure tst system for leaks, test run - all okay |         | \$1,825.78 |
| R-730  | 05/12/2020 | 2485904 | 0     | Air Conditioner        |             | Truck a/c re gassed ,bunk hose repaired and re gassed, Waiting on Blue Tongue invoice   |         | \$0.00     |
| R-731  | 01/12/2020 | 2482968 | 0     | Body Repairs, Steering | Zane        | Inspect and shim. Only shims from Kaiser Kit used. ( not full cost)   |         | \$376.66   |
| S-896  | 30/11/2020 | 2482968 | 0     | C - 150k               | Dylan, Zane | Oil & fuel filter dates show overdue for service  |         | \$1,066.19 |
| T-188  | 18/11/2020 | 2000000 | 0     | Cap                    |             | 6x cap and case 2x caps 3x truck tyre disposal  | 101098  | \$3,689.50 |
| S-780  | 08/10/2020 | 2496517 | 0     | A - Fortnightly        | Yard        |   |         | \$308.00   |
| S-774  | 03/10/2020 | 2443673 | 0     | B - 50k                | Dylan, Zane |   |         | \$690.14   |
| S-619  | 16/09/2020 | 2432236 | 0     | A - Fortnightly        | Dylan, Yard |   |         | \$165.00   |
| T-143  | 15/09/2020 | 2000000 | 0     | New, Strip & Fit       |             | 2x goodyear 1x truck tyre disposal 2x strip and fit   | 100410  | \$1,428.50 |
| R-581  | 15/09/2020 | 0       | 0     | Air Conditioner        |             |   | 2319    | \$315.70   |



| Number | Date       | Kms     | Hours | Type              | Repairer          | Repairer Notes  | Invoice | Cost       |
|--------|------------|---------|-------|-------------------|-------------------|---|---------|------------|
| T-137  | 03/09/2020 | 2000000 | 0     | Strip & Fit       |                   | 1x strip and fit 1x truck tyre disposal   | 100283  | \$82.50    |
| R-584  | 27/08/2020 | 0       | 0     | Electrical        | Jack              | Replaced trailer plug   |         | \$49.45    |
| R-442  | 24/08/2020 | 2000000 |       | Defect            | Mick, Yard        | DEFECT CLEARED  |         | \$229.90   |
| R-433  | 07/08/2020 | 2406209 |       | Trailer Plug      |                   | Replace 7 pin. Had to strip back wiring as wires were damaged. Resolder wires. Test operation, found okay |         | \$130.35   |
| R-423  | 30/07/2020 | 2000000 | 0     | Lights            |                   |   |         | \$268.40   |
| S-537  | 24/07/2020 |         | 0     | A - Fortnightly   | Yard              | Steering box drop arm   |         | \$308.00   |
| R-419  | 20/07/2020 | 0       | 0     | Steering          |                   |   |         | \$3,552.25 |
| S-363  | 11/07/2020 | 2393422 | 0     | A - Fortnightly   | Yard              |   |         | \$154.00   |
| O-57   | 01/07/2020 | 0       | 0     | CTP               |                   |   |         | \$1,212.06 |
| O-56   | 01/07/2020 | 0       | 0     | Registration      |                   |   |         | \$4,599.15 |
| S-273  | 28/06/2020 | 2382230 | 0     | B - 50k           |                   |   |         | \$601.18   |
| R-349  | 11/06/2020 | 2000000 |       | Electrical        | Jack              |   |         | \$442.59   |
| R-236  | 24/05/2020 | 0       | 0     | Cab               |                   | Removed guard and repaired crack with aluminum plate and rivets. 1x sundries.                             |         | \$129.25   |
| S-667  | 22/05/2020 | 2356960 | 0     | A - Fortnightly   | Yard              | Replace wiper blades  |         | \$165.00   |
| S-199  | 18/05/2020 | 2351000 | 0     | D - 300k          |                   | duplicated job created  |         |            |
| R-182  | 26/04/2020 | 2340088 | 0     | Wiper Blades      | Yard              |   |         | \$64.13    |
| S-141  | 17/04/2020 | 2335471 | 0     | B - 50k           | Dylan, Jack, Mick | 1 x LF1400nn oil filter 1 x FS1007 fuel filter 41 litres engine oil Done by Michael, Dylan, Jack          |         | \$598.14   |
| R-129  | 14/04/2020 |         |       | Clutch Adjustment | Yard              |   |         |            |
| R-148  | 03/04/2020 | 2000000 | 0     | ABS, Battery      | Jack              |   |         | \$41.39    |

| Number | Date       | Kms     | Hours | Type              | Repairer   | Repairer Notes   | Invoice | Cost       |
|--------|------------|---------|-------|-------------------|------------|--|---------|------------|
| R-31   | 27/03/2020 | 322171  |       | Clutch Kit        |            | Clutch kit replaced -  |         | \$5,887.81 |
| R-88   | 18/03/2020 | 0       | 0     | Clutch Adjustment |            | Refer R -31  |         |            |
| R-22   | 11/03/2020 | 0       | 0     | Air Conditioner   | Gus        | repaired   |         |            |
| R-394  | 24/02/2020 | 2000000 |       | ABS               | Kobi, Yard | Adjust RHR drive ABS sensor  |         | \$71.50    |
| T-12   | 21/02/2020 | 316000  | 0     | New               |            |  | 140034  |            |
| S-13   | 20/02/2020 | 2305313 | 0     | B - 50k           |            | PARTS USED : 45 LTR ENG OIL 1 X CS41011 1 X REDROO SHOCK DRIVE 2X M401 ENGINE PIPE RUBBERS B2 SERVICES CARRIED OUT , REPAIR ENGINE PIPE BRACKETRY, REPLACE EX PIPE RUBBERS, REPLACE LHF DRIVE, SHOCK, CHECK TOP RAD HOSE REPLACED BY ALLAN 16.2.20 |         |            |
| R-40   | 16/02/2020 | 0       | 0     | Engine            | Yard       | repaired   |         |            |
| T-28   | 10/02/2020 |         |       | New - Trailer     |            |  |         |            |
| S-430  | 07/02/2020 | 2296322 | 0     | A - Fortnightly   | Yard       |  |         | \$165.00   |
| R-20   | 03/02/2020 | 0       | 0     | Body Repairs      |            |  |         |            |
| S-334  | 10/01/2020 | 2278481 | 0     | C - 150k          | Yard       |  |         | \$714.14   |
| S-44   | 06/01/2020 | 2271987 | 0     | B - 50k           | Yard       | completed  |         | \$689.91   |
| S-997  | 06/12/2019 | 2253062 | 0     | A - Fortnightly   |            |  |         | \$308.00   |
| S-47   | 18/11/2019 | 2242454 | 0     | C - 150k          | Yard       | Adjust clutch. Replace steering column, service Tripac   |         | \$714.14   |
| S-996  | 15/10/2019 | 2000000 | 0     | A - Fortnightly   |            | Replace brake foot valve   |         | \$396.00   |
| R-787  | 11/10/2019 | 2000000 |       | Radiator          |            | Radiator recore (barclays)<br>Replace heater tap L & R front charge cooler hoses   |         | \$4,857.15 |

| Number             | Date       | Kms     | Hours | Type               | Repairer | Repairer Notes  | Invoice       | Cost               |
|--------------------|------------|---------|-------|--------------------|----------|---|---------------|--------------------|
| R-786              | 02/10/2019 | 2000000 |       | Mud Guard          |          | Replace spinner supply hose.<br>Replace L/H mud guard                             |               | \$887.71           |
| S-57               | 17/09/2019 | 2210612 | 0     | B - 50k            | Yard     | completed   |               | \$564.81           |
| S-1233             | 23/08/2019 | 2201279 | 0     | A - Fortnightly    |          | Replaced LHR eng mount bolt &<br>lower pad/washer Replace LH<br>brake light globe |               | \$167.20           |
| S-1234             | 02/08/2019 | 2191190 | 0     | A - Fortnightly    |          | Tighten s/box drop arm  |               | \$165.00           |
| S-1235             | 26/07/2019 | 2186514 | 0     | A - Fortnightly    |          |   |               | \$165.00           |
| S-1483             | 16/07/2019 | 2178589 | 0     | B - 50k            |          | 45ltr oil   |               | \$699.04           |
| S-1484             | 28/06/2019 | 2168014 | 0     | A - Fortnightly    |          | top up grease pot Repair air leak<br>- Seat/Blower fitting in floor               |               | \$393.49           |
| S-1637             | 30/03/2019 | 2105919 | 0     | A - Fortnightly    |          | Repair grease line on FR slack<br>adjuster. No plate light 91530 RH               |               | \$308.00           |
| S-1638             | 11/03/2019 | 2098125 | 0     | C - 150k           |          |   |               | \$1,067.84         |
| T-8                |            |         |       |                    |          |   |               |                    |
| R-1645             |            |         | 66643 | Windscreen Cracked |          |   |               | \$0.00             |
| <b>143 Records</b> |            |         |       |                    |          |   | <b>TOTAL:</b> | <b>\$97,574.98</b> |