

Job: 1C ASSESS FOR REPAIRS - OIL LEAK

Labour
LABOUR

Tech#

Price
\$1,916.91

WASHED OIL FROM GENERATOR TO DETERMINE ORIGIN OF LEAK
 - FOUND OIL LEAK COMING FROM DIP STICK
 FOUND LEAK FROM CRANKSHAFT SEAL
 REMOVED ROCKER COVER AND RESEALED
 REMOVED TOP COVER OF GENERATOR
 REMOVED GENERATOR MOTOR ASSEMBLY & ELECTRICAL CONNECTIONS
 TO MOTOR
 REMOVED AIR CLEANER HOUSING & BATTERY PLATE
 REMOVED FLYWHEEL & CRANKSHAFT OIL SEAL & CLEANED
 REPLACED CRANKSHAFT SEAL & REFITTED FLYWHEEL
 REFITTED TO MOTOR & ELECTRICAL CONNECTIONS
 REFITTED AIR CLEANER HOUSING & TOP COVER
 STARTED THE MACHINE & RAN FOR 2 HOURS TO CHECK FOR LEAKS = NO LEAKS

Replacement Part Description	Part Number	Qty	Price
BENDIX BRAKE CLEAN 400G BBC4	BUBRAKLEEN	1.00	17.00
	Total - Parts		\$17.00
	Job#		Price
	1		220.00
SEAL OIL SEAL		1	80.19
	Total		\$300.19
Workshop Consumables	Job#		Price
SHOP SUPPLIES	1		15.00
	Total		\$15.00

Account terms are 30 days EOM

Total Invoice Amount:	\$2,249.10
Plus GST:	\$224.91
Your Invoice Amount:	\$2,474.01

Job: 1C TRACKER NOT WORKING

Labour
LABOUR

Tech#

Price
\$313.76

TRAVELLED TO JOB SITE
LOCATED TRACKER
CHECKED FUSE = OK
CHECKED BATTERY EYELETS = IN POOR CONDITION
- REPLACED EYELETS WITH NEW
OPENED TRACKER BOX TO CONFIRM POWER INSIDE BOX = OK
REFITTED COVER & SECURED INTO UNIT
ON INSPECTION FOUND THAT BATTERY NEGATIVE CLAMP WAS BROKEN
- CUT OFF CLAMP & REPLACED WITH NEW
ATTEMPTED TO TURN GENERATOR ON HOWEVER CIRCUIT BREAKER WOULDN'T STAY ON
ON FURTHER INVESTIGATION FOUND THE POSITIVE STUD ON STARTER SOLENOID
WAS LOOSE (INTERNALLY)
ADDED A NUT TO THE STUD TO LOCK IT UP AGAINST SOLENOID HOUSING
REATTACHED CABLES
RESET CIRCUIT BREAKER = GENERATOR STARTED WITH NO ISSUES
PACKED UP WORK AREA & TOOLS & UTE
TRAVELLED BACK TO WORKSHOP

NB: NEED TO REPLACE STARTER MOTOR AND BATTERY ISOLATOR

Workshop Consumables
SHOP SUPPLIES

Job#

1

Price

15.00

Total

\$15.00

Account terms are 30 days EOM

Total Invoice Amount: \$328.75
Plus GST: \$32.88

Your Invoice Amount: \$361.63

Labour	Operation	Description	Units	Amount
Job# 1	01ZZBREAKDOWN	FIELD SERVICE BREAKDOWN	Tech(s): 306	337.50
CONTACT ON SITE IS STEFAN 0447 000 043 CARRY OUT SERVICE ON GENERATOR AS REQUIRED DUE TRAVELLED TO SITE, CARRIED OUT GENERATOR SERVICE AS REQUIRED USING CUSTOMER SUPPLIED PARTS AND OILS				
<<< Total For Job 1 >>>				337.50

	Total Labour	337.50
	Total Parts	0.00
	Total POL	0.00
	Total Sublet	0.00
	Total Misc	0.00
	Total Tax	33.75
Total Including GST	Total Invoice	<u>371.25</u>

WE ARE PLEASED TO OFFER FIXED PRICE SERVICING FOR ALL OF YOUR EQUIPMENT. PLEASE CALL US IF YOU WOULD LIKE ANY FURTHER INFORMATION