Uneck your DIVIVI Recall Status

Step 1	Step 2	Step 3	Step 4		
VIN		Model	Year	Colour	Chassis
WBAFF420X0LZ11638		E70 X5_3.0d	2007	SPACE GREY METALLIC	LZ11638

BMW TECHNICAL ACTIONS AND RECALL INFORMATION

Your vehicle was affected by following recall(s) however this has now been rectified.

Defect Code	PRA (ACCC code)	Description	Status	Defect Comment
0012390300	N/A	E7X M57 REPLACE THE THREADED BOLT OF THE DEFLECTING ELEMENT	0	COMPLETED
0032510200	2017/16230	BMW E7x Replace Driver Airbag Generator. (Takata)	0	COMPLETED
0061890500	N/A	Checking and reworking blower controller plug connection	0	COMPLETED
0072710100	2017/16298	BMW E7x Replace Passenger Airbag. (Takata)	0	COMPLETED

= Recall has been rectified/fixed.

Return to search

Generate PDF Report

