

Ezyquip Hire Pty Ltd

Service History Listing Active Units

Date: 02/12/2022
Time: 2:00:03PM

For Equipment Code From: EX08012 To: EX08012
For Date Posted From: All To: All
Don't Show Cost

For Customer Code From: All To: All
For Branch Code From: All To: All

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
196170	COLLECT BUCKETS	MAM08MRM	24/10/2022	Internal	3885.0	\$0.00	
193527	DECOMMISSION	OBK01	02/09/2022	Internal	3885.0	\$0.00	
193071	PREP MACHINE TO TRAVEL FROM MRM TO DARWIN	DINK01SAWAY	24/08/2022	Internal	3885.0	\$0.00	
192788	REPLACE WORN TRACKS	XXXX	18/08/2022	Internal	3885.0	\$0.00	
192754	BOOM & STICK REPAIRS	XXXX	16/08/2022	Internal	3885.0	\$0.00	
192009	Scheduled Service Job. PM Service 4,000 HR	XXXX	15/08/2022	Internal	3885.0	\$0.00	
191081	Scheduled Service Job. PM Service 750 HR	MUJ08AWAY	11/08/2022	Internal	3885.0	\$0.00	
189677	REPLACE QUICK HITCH	XXXX	11/08/2022	Internal	3885.0	\$0.00	
191922	REPAIR OIL LEAK	MAM08MRM	30/07/2022	Internal	3885.0	\$0.00	
191753	REPLACE WORK LIGHTS	MUJ08AWAY	27/07/2022	Internal	3776.0	\$0.00	
190992	REPAIR HYDRAULIC LEAK	MAM08MRM	09/07/2022	Internal	3504.0	\$0.00	
190280	REPLACE DRYER	DINK01SAWAY	28/06/2022	Internal	3504.0	\$0.00	
190124	REPLACE ENGINE MOUNTS	HAST06MRM	23/06/2022	Internal	3504.0	\$0.00	
185547	REPLACE A/C HOSES	XXXX	16/06/2022	Internal	3504.0	\$0.00	
191627	LABOUR ADJUSTMENT - REFER JOB # 187287	XXXX	14/06/2022	Internal	3660.0	\$0.00	
187287	Scheduled Service Job. PM Service 500 HR	SUB	14/06/2022	Internal	3660.0	\$0.00	
188572	FIX BOOM OIL LEAK - HITCH HOSE HYD LEAK	MUJ08AWAY	10/06/2022	Internal	3504.0	\$0.00	
188198	ENGINE CODE	DINK01SAWAY	13/05/2022	Internal	3418.0	\$0.00	
187467	DIAGNOSE ENG FAULT	MAM01MRMBASE	28/04/2022	Internal	3418.0	\$0.00	
187063	QUICK HITCH REPAIRS	XXXX	13/04/2022	Internal	3385.0	\$0.00	
186617	REPLACE DOOR HINGES / CHECK OVER	BAK03AWAY	04/04/2022	Internal	3385.0	\$0.00	
185548	SEAT REPAIRS	DINK01SAWAY	04/04/2022	Internal	3339.0	\$0.00	
186149	REPLACE DIFFERENTIAL PRESSURE SENSOR	SAB03TRADEAWAY	23/03/2022	Internal	3329.0	\$0.00	
185821	#REPLACE DAMAGED MONITOR	SAB03TRADEAWAY	23/03/2022	External	3329.0	\$1,670.76	
184049	#REPLACE DAMAGE DOOR PANEL	BAK03AWAY	21/03/2022	External	3329.0	\$3,489.63	
185052	A/C REPAIRS	DINK01SAWAY	08/03/2022	Internal	3298.0	\$0.00	
185261	#BUCKET CYLINDER REPAIRS	SAB03TRADEAWAY	03/03/2022	External	3298.0	\$1,511.72	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
183997	STICK REPAIRS	BAK03AWAY	24/02/2022	Internal	3298.0	\$0.00	
184656	#REPLACE BROKEN CAB DOOR GLASS	DINK01SAWAY	23/02/2022	External	3298.0	\$650.86	
184598	#REPAIR DAMAGE TO BOOM CYLINDER PIPING	SAB03TRADEAWAY	14/02/2022	External	3298.0	\$1,043.58	
183998	BOOM REPAIRS - PARTS ONLY	XXXX	01/02/2022	Internal	3298.0	\$0.00	
179062	Scheduled Service Job. PM Service 250 HR	BAK03AWAY	31/01/2022	Internal	3298.0	\$0.00	
182673	#REPAIR DAMAGE TO BOOM PIPES & MOUNTING BRACKETS	BAK03AWAY	25/12/2021	External	3236.0	\$1,803.34	
180756	A/C FAULT	DINK01SAWAY	03/12/2021	Internal	3173.0	\$0.00	
180713	RESEAL SPARE BUCKET CYL - PARTS	XXXX	03/12/2021	Internal	3173.0	\$0.00	
180489	RESEAL STICK CYL	BAK07	29/11/2021	Internal	3173.0	\$0.00	
176540	Scheduled Service Job. PM Service 1,000 HR	BAK03AWAY	24/10/2021	Internal	3089.0	\$0.00	
176619	#REPLACE DAMAGED BUCKET CYLINDER	DINK01SAWAY	01/10/2021	External	2898.0	\$4,601.80	
174907	RESEAL BOOM CYLINDER	XXXX	01/10/2021	Internal	2898.0	\$0.00	
176312	REPLACE COMPRESSOR AND IDLER PULLEY	DINK01SAWAY	29/09/2021	Internal	2894.0	\$0.00	
176294	#REPLACE DAMAGED BOOM PIPE	BAK03AWAY	27/09/2021	External	2880.0	\$706.18	
175830	REPLACE FAULTY ALTERNATOR	SAB03TRADEAWAY	21/09/2021	Internal	2841.0	\$0.00	
174148	Scheduled Service Job. PM Service 750 HR	DRC01AWAY	28/08/2021	Internal	2788.0	\$0.00	
174003	OIL LEAK	BAK03AWAY	12/08/2021	Internal	2580.0	\$0.00	
173996	ELECTRICAL FAULT	DINK01SAWAY	12/08/2021	Internal	2560.0	\$0.00	
173772	#DAMAGE TO BOOM CYLINDER	DRC01AWAY	08/08/2021	External	2540.0	\$3,412.27	
172194	REPLACE ENGINE MOUNTS	MAM01MRMBASE	17/07/2021	Internal	2534.0	\$0.00	
172758	#DAMAGED BOOM CYLINDER PIPES	BAK03AWAY	16/07/2021	External	2534.0	\$3,308.56	
172650	HYD LEAK	DINK01SAWAY	09/07/2021	Internal	2501.0	\$0.00	
171238	CAB REPAIRS - DOOR & A/C	DINK01SAWAY	09/07/2021	Internal	2534.0	\$0.00	
169001	Scheduled Service Job. PM Service 500 HR	BAK03AWAY	25/06/2021	Internal	2500.0	\$0.00	
171418	HYD OIL LEAK	XXXX	15/06/2021	Internal	2449.0	\$0.00	
169738	AC REPAIRS	DINK01SAWAY	07/06/2021	Internal	2449.0	\$0.00	
170565	BOOM CYLINDER LEAK	SAB03TRADEAWAY	21/05/2021	Internal	2446.0	\$0.00	
169873	STICK CYLINDER REPAIR	ROJ08AWAY	15/05/2021	Internal	2435.0	\$0.00	
169733	HYD WIRING FAULT	DINK01SAWAY	01/05/2021	Internal	2415.0	\$0.00	
168722	#REPLACE DAMAGED PANELS	ROE03MRM	17/04/2021	External	2400.0	\$5,905.20	
168419	# REPLACE DAMAGED BOOM CYLINDER PIPES	ROE03MRM	17/04/2021	External	2400.0	\$2,289.29	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
168404	BUCKET FAILURE	DINK01SUPERVISOR	26/03/2021	Internal	2381.0	\$0.00	
168395	REPAIR OIL LEAK IN BOOM CYLINDER	DINK01SAWAY	26/03/2021	Internal	2381.0	\$0.00	
167101	#REPLACE DAMAGED PANELS	PRL01TRADEAWAY	24/03/2021	External	2381.0	\$5,993.70	
168228	OVER HEATING FAULT	BOUC01AWAY	23/03/2021	Internal	2381.0	\$0.00	
167547	REHOSE TILT BUCKET	ROJ08AWAY	06/03/2021	Internal	2270.0	\$0.00	
167104	ENGINE LIGHT FAULT	MAB06AWAYMRM	23/02/2021	Internal	2250.0	\$0.00	
165595	Scheduled Service Job. PM Service 250 HR	XXXX	21/02/2021	Internal	2250.0	\$0.00	
166672	#REPLACE DAMAGED BRACKET & PIPES ON BOOM CYLINDER	DINK01SAWAY	14/02/2021	External	2232.0	\$1,399.88	
166341	HYD LEAK	DINK01SAWAY	04/02/2021	Internal	2196.0	\$0.00	
165837	A/C REPAIRS - REPLACE EVAPORATOR	ROJ08AWAY	28/01/2021	Internal	2130.0	\$0.00	
165608	# REPLACE DAMAGED BOOM CYLINDER VALVE & PIPES	DINK01SAWAY	27/01/2021	External	2130.0	\$3,528.63	
164699	#REPLACE DAMAGED PUMP ROOM DOOR	PRL01TRADEAWAY	22/01/2021	External	2104.0	\$5,004.37	
165532	HYD FITTING REPAIRS	BOUC01AWAY	15/01/2021	Internal	2013.0	\$0.00	
164836	#REPLACE DAMAGED BOOM SENSOR, HOSE & BRACKET	BOUC01AWAY	08/01/2021	External	2013.0	\$1,944.44	
164224	REPLACE TILT BUCKET HOSES	MAB06AWAYMRM	09/12/2020	Internal	1977.0	\$0.00	
159044	Scheduled Service Job. PM Service 2,000 HR	XXXX	07/12/2020	Internal	2013.0	\$0.00	
163744	MRM SITE COMPLIANCE REPAIRS	MAB06AWAYMRM	29/11/2020	Internal	1946.0	\$0.00	
162216	REPLACE TILT BUCKET PIN	DINK01SAWAY	17/11/2020	Internal	1807.0	\$0.00	
160340	REPLACE HOSE ON BOOM	DINK01SAWAY	26/10/2020	Internal	1807.0	\$0.00	
158981	MRM MINE SITE SPEC REPAIRS	XXXX	16/10/2020	Internal	1784.0	\$0.00	
158705	REPAIR HYDRAULIC LEAK ON BOOM	BAJ15AWAY	11/10/2020	Internal	1784.0	\$0.00	
153791	Scheduled Service Job. PM Service - 750 HR	BOUC01AWAY	30/09/2020	Internal	1775.0	\$0.00	
155478	REPAIR HYDRAULIC LEAK	DINK01SAWAY	25/09/2020	Internal	1754.0	\$0.00	
154926	ACCIDENT DAMAGE - BOOM TO STICK HOSING & PIPEWORK	SAB03TRADEAWAY	08/08/2020	Internal	1662.0	\$0.00	10/08/2020 - JOB CHARGED OUT ON JOB # 154374 - JW
154374	#ACCIDENT DAMAGE - BOOM TO STICK HOSING & PIPEWORK	SAB03TRADEAWAY	08/08/2020	External	1662.0	\$5,569.38	
153777	READY FOR HIRE	DINK01SAWAY	11/07/2020	Internal	1652.0	\$0.00	
153665	JOYSTICK REPLACEMENT	MON01NORMAL	09/07/2020	Internal	1600.0	\$0.00	
153041	BUCKET REPAIRS - GET	MON01NORMAL	29/06/2020	Internal	1599.0	\$0.00	
152468	REPLACE BELTS	BAJ15	16/06/2020	Internal	1660.0	\$0.00	
152460	OFFHIRE INSPECTION	BAJ15	16/06/2020	Internal	1599.0	\$0.00	
150607	REPAIR BUCKET CYLINDER AND HOSES	NAP01	08/05/2020	Internal	1599.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
149157	REPLACE JOYSTICKS	NAP01	08/05/2020	Internal	1599.0	\$0.00	
149693	HYD LEAK	NAP01	23/04/2020	Internal	1599.0	\$0.00	
148622	VISION LINK FAULTS	NAP01	27/03/2020	Internal	1582.0	\$0.00	
148051	PREP FOR HIRE	NAP01	17/03/2020	Internal	1580.0	\$0.00	
145858	OFF HIRE / PRE DELIVERY / REPLACE BATTERY	MON01NORMAL	24/01/2020	Internal	1580.0	\$0.00	
143187	REPLACE TRACK LINKS AND PADS	NAP01	23/01/2020	Internal	1580.0	\$0.00	09/12/2019 - TRACKS REMOVED TO PUT ON EX08004. - REFER J.W & P.N.
141193	WASH AND DETAIL	EWC01	29/10/2019	Internal	1580.0	\$0.00	
138207	REPAIRS TO BOOM/STICK	SUB	10/10/2019	Internal	1580.0	\$0.00	
137348	REMOVE STICK & BOOM FOR EX08004	NAP01	24/09/2019	Internal	1580.0	\$0.00	
134220	OFF HIRE / PRE DELIVERY INSPECTION	EWC01	20/08/2019	Internal	1578.0	\$0.00	WORKS CARRIED OUT BY MICHAEL STUART - FKG
133701	WASH AND DETAIL	EWC01	06/08/2019	Internal	1548.0	\$0.00	
132980	OFFHIRE/PREDELIVERY INSPECTIONS	DENS01	30/07/2019	Internal	1548.0	\$0.00	
132397	HYDRAULIC REPAIRS	DENS01	17/07/2019	Internal	1525.0	\$0.00	
131498	GET CHANGE OUT	NAP01	08/07/2019	Internal	1525.0	\$0.00	
130948	Scheduled Service Job. PM Service 500 HR	XXXX	08/07/2019	Internal	1525.0	\$0.00	
130934	HYDRAULIC REPAIRS	MAB06	11/06/2019	Internal	1394.0	\$0.00	
129622	ROTATE EDGE	MAB06	17/05/2019	Internal	1300.0	\$0.00	
129442	REPAIRS TO CYLINDER	MAB06	17/05/2019	Internal	1300.0	\$0.00	
128015	Scheduled Service Job. PM Service 250 HR	XXXX	17/05/2019	Internal	1300.0	\$0.00	
123711	STRAIGHTEN AUGER	DENS01	07/02/2019	Internal	1107.5	\$0.00	
123384	WASH AND DETAIL	ALLA01 NORMAL	01/02/2019	Internal	1107.5	\$0.00	
122865	QUICK HITCH INSPECTION	DALE01	23/01/2019	Internal	1105.0	\$0.00	
119795	REMOVE STICK CYLINDER FOR EX08004	RES02	21/11/2018	Internal	1105.0	\$0.00	
119209	OFF HIRE / PRE DELIVERY INSPECTION	TOML01	08/11/2018	Internal	1103.0	\$0.00	
118570	REPLACE BUCKET TEETH WITH TIGER TEETH (PARTS ONLY)	XXXX	30/10/2018	Internal	1014.0	\$0.00	
116713	OFFHIRE INSPECTION/PREDELIVERY INSPECTION	COP01	11/10/2018	Internal	1014.0	\$0.00	
116559	WASH AND DETAIL	ALLA01 NORMAL	09/10/2018	Internal	1014.0	\$0.00	
116473	CHECK BEFORE HIRE	COP01	09/10/2018	Internal	1014.0	\$0.00	
110571	REPLACE RIPPER (PARTS ONLY)	COP01	02/08/2018	Internal	1003.0	\$0.00	20/06 - Customer damage - recovered on rental contract 38738
111292	OFF HIRE - PRE DELIVERY	RES02	04/07/2018	Internal	1003.0	\$0.00	Parts only

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
111078	RETURN - WASH AND DETAL	WIJ03	03/07/2018	Internal	975.0	\$0.00	
110597	Scheduled Service Job. PM Service	XXXX	03/07/2018	Internal	1003.0	\$0.00	
110449	RETURN - OFF HIRE - PRE DELIVERY	COP01	20/06/2018	Internal	975.0	\$0.00	
109958	QUICK HITCH REPAIRS	RES02	08/06/2018	Internal	975.0	\$0.00	
109542	OFF HIRE INSPECTION	RES02	08/06/2018	Internal	962.0	\$0.00	
108928	REPLACE GET ON BUCKET	EDB01	22/05/2018	Internal	937.0	\$0.00	
108961	REPAINT COUNTER WEIGHT	EDB01	21/05/2018	Internal	937.0	\$0.00	
108364	OFF HIRE INSPECTION	LOS01AWAY	21/05/2018	Internal	937.0	\$0.00	
107648	REPLACE HYDRAULIC FITTING ON BOOM	LOS01AWAY	26/04/2018	Internal	905.0	\$0.00	
107367	WASH AND DETAIL	HAP01	19/04/2018	Internal	905.0	\$0.00	
107274	ROTATE CUTTING EDGE ON TILT BUCKET	EDB01	18/04/2018	Internal	905.0	\$0.00	
107267	REPAIR JUMP START PLUG	HAP01	17/04/2018	Internal	905.0	\$0.00	
107230	REPAIR HYDRAULIC LEAKS	HAP01	17/04/2018	Internal	905.0	\$0.00	
107212	OFF HIRE INSPECTION	EDB01	17/04/2018	Internal	905.0	\$0.00	
104742	Scheduled Service Job. PM Service 750 HR	XXXX	17/04/2018	Internal	905.0	\$0.00	
104454	REPLACE HYRAULIC HOSE AND COUPLER	SUB	15/02/2018	Internal	582.0	\$0.00	
100436	REPAIR REAR DOOR	HAP01	10/01/2018	Internal	582.0	\$0.00	
100115	WASH AND DETAIL	SWB03	22/12/2017	Internal	540.4	\$0.00	
100012	OFF HIRE INSPECTION	MAJ01	20/12/2017	Internal	540.4	\$0.00	
97353	WASH AND DETAIL	SWB03	24/11/2017	Internal	540.4	\$0.00	
97152	OFF HIRE INSPECTION	MAJ01	22/11/2017	Internal	540.4	\$0.00	
96048	WASH AND DETAIL	SWB03	03/11/2017	Internal	500.5	\$0.00	
95560	OFF HIRE INSPECTION	LOS01	30/10/2017	Internal	500.5	\$0.00	
94584	Scheduled Service Job. PM Service 500HR	XXXX	30/10/2017	Internal	500.5	\$0.00	
95529	WASH AND DETAIL	SWB03	26/10/2017	Internal	467.0	\$0.00	
90152	REPLACE LATCH COVER AND ASSEMBLY	LOS01	10/08/2017	Internal	415.0	\$0.00	
86233	Scheduled Service Job. PM Service 250HR	XXXX	30/05/2017	Internal	240.0	\$0.00	226HRS MACHINE IS STILL CURRENTLY 30HRS OFF A SERVICE - KLK
86387	DIAGNOSE AND REPAIR HYD OIL LEAK	MAJ01	24/05/2017	Internal	196.0	\$0.00	
82619	DIAGNOSE COMPACTION WHEEL FAULT	LOS01AWAY	23/03/2017	Internal	114.0	\$0.00	
81910	WASH & DETAIL	SAB03	09/03/2017	Internal	98.0	\$0.00	
81449	REPLACE HOSE	SAB03	28/02/2017	Internal	93.0	\$0.00	
81448	OFF HIRE INSPECTION	SAB03	28/02/2017	Internal	98.0	\$0.00	
81200	FIT AUGER TO MACHINE	LOS01	23/02/2017	Internal	93.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: EX08012		Description: Excavator 8t					
Make: Caterpillar		Model: 308E2 SB L		Serial No.: FJX06458			
80715	OFF HIRE INSPECTION	LOS01	16/02/2017	Internal	93.0	\$0.00	
80738	WASH AND DETAIL	HEP01	15/02/2017	Internal	93.0	\$0.00	
79180	WASH AND DETAIL	ROAD01	16/01/2017	Internal	87.3	\$0.00	
78714	OFF HIRE INSPECTION	WAT01	13/01/2017	Internal	87.0	\$0.00	
78718	WASH AND DETAIL	WAT01	06/01/2017	Internal	87.0	\$0.00	
							10.01.2017 TROY JEFFERY (OPERATOR) IS CURRENTLY WORKING IN THE ROMA YARD WASHING ALL MACHINES, NO TIME WILL BE BOOKED OUT TO WASH AND DETAIL JOBS - KLK
77014	WASH AND DETAIL	HEP01	24/11/2016	Internal	17.0	\$0.00	
76942	OFF HIRE INSPECTION	ROAD01	23/11/2016	Internal	17.0	\$0.00	
76106	INSPECT AUGER DRIVE FUNCTION	HAP01	07/11/2016	Internal	7.0	\$0.00	
72272	EX08012 CAPITAL ACQUISITION/PREPARATION	XXXX	16/08/2016	Cap Prep	0.0	\$0.00	
Equipment Total:						\$53,833.59	
Customer Total:						\$53,833.59	