

Ezyquip Hire Pty Ltd

Service History Listing Active Units

Date: 25/02/2021

Time: 11:06:21AM

For Equipment Code From: AT40012 To: AT40012

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
166204	EQUIPMENT CLEANING	JAC01	02/02/2021	Internal	12946.0	\$0.00	
162388	ELECTRICAL INSPECTION & REPAIRS	DAK02AWAY	19/11/2020	Internal	12946.0	\$0.00	
160630	Scheduled Service Job. PM Service 1,000 HR	XXXX	19/11/2020	Internal	12946.0	\$0.00	
161823	DECOMMISSION FOR SALE	AVT01	09/11/2020	Internal	12946.0	\$0.00	
161750	REPAIR HYDRAULIC OIL LEAKS	AVT01	05/11/2020	Internal	12946.0	\$0.00	
161749	REPAIR OIL LEAKS ON TRANSMISSION	AVT01	05/11/2020	Internal	12946.0	\$0.00	
161748	REPAIR LEAKING BRAKE HOSES	AVT01	05/11/2020	Internal	12946.0	\$0.00	
161747	REPLACE FENDERS, GUARD COVERS	AVT01	05/11/2020	Internal	12946.0	\$0.00	
160411	REPAIRS TO SUSPENSION STRUT	AVT01	28/10/2020	Internal	12944.0	\$0.00	
158426	OFF HIRE & DEMOBE	MAB06AWAYMRM	06/10/2020	Internal	12944.0	\$0.00	
156666	SPRAY REPAIRS	PRL01TRADEAWAY	18/09/2020	Internal	12935.0	\$0.00	
156474	HYD REPAIRS	MAB06AWAYMRM	14/09/2020	Internal	12935.0	\$0.00	
156453	TRACTION CONTROL FAULT	MAB06AWAYMRM	14/09/2020	Internal	12935.0	\$0.00	
156389	ELECTRICAL FAULT	PRL01TRADEAWAY	14/09/2020	Internal	12935.0	\$0.00	
155025	REPLACE PARK BRAKE ACTUATOR	PRL01TRADEAWAY	14/09/2020	Internal	12935.0	\$0.00	
156416	REPAIR RUST HOLE	PRL01TRADEAWAY	13/09/2020	Internal	12935.0	\$0.00	
154112	Scheduled Service Job. PM Service 750 HR	SAB03TRADEAWAY	10/08/2020	Internal	12743.0	\$0.00	
153801	STEERING & SUSPENSION REPAIRS	SAB03TRADEAWAY	07/08/2020	Internal	12733.0	\$0.00	
154664	12MONTH FIRE SUPPRESSION SERVICE	MAB06	02/08/2020	Internal	12608.0	\$0.00	
151792	REPLACE CAB MOUNTS	MAB06	01/08/2020	Internal	12608.0	\$0.00	
154620	REPLACE ENGINE MOUNTS	NAP01	31/07/2020	Internal	12608.0	\$0.00	
153755	REPLACE HYDRAULIC HOSES	DALE01BRAD	21/07/2020	Internal	12608.0	\$0.00	
151753	Scheduled Service Job. PM Service 500 HR	MAB06AWAYMRM	09/07/2020	Internal	12514.0	\$0.00	
151723	REAR TANK WATER PUMP REPAIRS	DALE01	10/06/2020	Internal	12325.0	\$0.00	
153094	RESEAL CYL	SUB	09/06/2020	Internal	12320.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
149517	Scheduled Service Job. PM Service 250 HR	XXXX	06/06/2020	Internal	12325.0	\$0.00	
152032	REPLACE BROKEN STUDS	MAB06AWAYMRM	05/06/2020	Internal	12325.0	\$0.00	
151769	REPLACE RUSTED COOLANT TANK	MAB06AWAYMRM	05/06/2020	Internal	12325.0	\$0.00	
152008	RESEAL THERMOSTAT HOUSING / REPLACE THERMOSTATS	MAB06AWAYMRM	04/06/2020	Internal	12325.0	\$0.00	
150762	RESEAL CYLINDER HEAD	DINK01SAWAY	04/06/2020	Internal	12325.0	\$0.00	
149245	REPLACE LOWER STEERING STOPS	DINK01SAWAY	04/06/2020	Internal	12325.0	\$0.00	
149244	RESEAL LEAKING TRANSFER CASE	DINK01SAWAY	04/06/2020	Internal	12325.0	\$0.00	
150799	REPLACE HYDRAULIC HOSES	DENS01AWAY	31/05/2020	Internal	12325.0	\$0.00	
151705	REPLACE FIRE SUPPRESSION BOTTLE	XXXX	29/05/2020	Internal	12265.0	\$0.00	
151199	REPLACE TRACTION CONTROL ACCUMULATOR	DALE01	18/05/2020	Internal	12265.0	\$0.00	
150966	RESEAL TRANSMISSION PUMP	DINK01SAWAY	15/05/2020	Internal	12180.0	\$0.00	
150870	REPLACE STEER CYLINDER PINS & BEARINGS	DINK01SAWAY	13/05/2020	Internal	12180.0	\$0.00	
150652	COMPLETE VALVE SET	DINK01SAWAY	10/05/2020	Internal	12180.0	\$0.00	
148887	REPLACE ENGINE BRAKE VALVES	XXXX	09/05/2020	Internal	12180.0	\$0.00	
150143	FIRE SUPPRESSION SERVICE	SUB	01/05/2020	Internal	12127.0	\$0.00	
149553	SPRAY REPAIRS	MAB06AWAY	20/04/2020	Internal	12026.0	\$0.00	
149213	REPAIR COOLANT LEAKS	MAB06AWAY	16/04/2020	Internal	11997.0	\$0.00	
149034	REPLACE TANK MOUNT BOLTS	DALE01	15/04/2020	Internal	11997.0	\$0.00	
149248	RESEAL SUMP FLYWHEEL HOUSING	XXXX	14/04/2020	Internal	11992.0	\$0.00	
149246	REPLACE FRONT DIFF DRAIN BUNG	DALE01	14/04/2020	Internal	11992.0	\$0.00	
149214	REPLACE TURBO HOSE CLAMPS	XXXX	13/04/2020	Internal	11992.0	\$0.00	
145358	Scheduled Service Job. PM Service 2000HR	DALE01	13/04/2020	Internal	11997.0	\$0.00	
148890	REPLACE CENTRE DIFF A FRAME BEARING - ONGOING (SEE NOTES)	XXXX	03/04/2020	Internal	11875.0	\$0.00	ORDERED AHEAD OF TIME. WORK TO BE COMPLETED AT A LATER DATE.. CREW/SWING DEPENDENT.
148889	REPLACE FRONT STRUTS, LOWER PINS AND BEARINGS	XXXX	03/04/2020	Internal	11875.0	\$0.00	PARTS ONLY - ORDERED AHEAD OF TIME. WORK TO BE COMPLETED AT A LATER DATE.. CREW/SWING DEPENDENT.
148573	INSPECT ENGINE NOISE	DINK01SAWAY	27/03/2020	Internal	11875.0	\$0.00	
148344	REPAIR A FRAME -BY LINE BORING FOR SERVICE JOB 146260	SUB	23/03/2020	Internal	11849.0	\$0.00	
148275	TRACTION CONTROL FAULT	DALE01	21/03/2020	Internal	11849.0	\$0.00	
147074	REHOSE CENTRE HITCH	ROJ08AWAY	21/02/2020	Internal	11849.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
146825	REHOSE TANK	ROJ08AWAY	17/02/2020	Internal	11849.0	\$0.00	
145996	CANNON REPAIRS	BAK03AWAY	17/02/2020	Internal	11849.0	\$0.00	
128376	# REPLACE DAMAGED HOSE REEL & CONTROL BOX	BAJ15	17/02/2020	External	11849.0	\$8,091.00	
146260	A FRAME REPAIRS	DALE01	15/02/2020	Internal	11849.0	\$0.00	
145182	AT40012 - REPLACE MIRROR	BAK03	09/01/2020	Internal	11776.0	\$0.00	
145004	A/C REPAIRS	DINK01SAWAY	08/01/2020	Internal	11776.0	\$0.00	
143170	Scheduled Service Job. PM Service 750 HR	ROJ08AWAY	07/01/2020	Internal	11776.0	\$0.00	
144911	TRACTION CONTROL FAULT	DALE01	30/12/2019	Internal	11534.0	\$0.00	
143089	REPLACE STEER & HYDRAULIC HOSE	DALE01	21/12/2019	Internal	11650.0	\$0.00	
142030	Scheduled Service Job. PM Service 500 HR	PRL01	07/12/2019	Internal	11515.0	\$0.00	
142758	REPLACE HYDRAULIC FITTINGS	DALE01	30/11/2019	Internal	11441.0	\$0.00	19/02/20 - THIS JOB SHOULD HAVE BEEN PART OF JOB # 137679 - JW
142656	OIL LEAK	TODD01	29/11/2019	Internal	11441.0	\$0.00	
142563	REPLACE AM/FM RADIO	DINK01SAWAY	26/11/2019	Internal	11425.0	\$0.00	
137679	#SPRAY REPAIRS	DALE01	24/11/2019	External	11408.0	\$2,398.50	
142334	REPLACE BLOWN HYDRAULIC HOSE	DALE01	21/11/2019	Internal	11353.0	\$0.00	120220 HOSE NOT LISTED IN STOCKED WAREHOUSES - JH
141916	GEAR LEVER	DALE01	13/11/2019	Internal	11261.0	\$0.00	
142525	CYLINDER RESEAL	XXXX	11/11/2019	Internal	11261.0	\$0.00	
141729	FIRE SUPPRESSION REPAIRS	ROJ08AWAY	11/11/2019	Internal	11261.0	\$0.00	
138412	Scheduled Service Job. PM Service 250 HR	XXXX	08/11/2019	Internal	11261.0	\$0.00	
137603	ADJUST SPRAYS	DINK01SAWAY	04/11/2019	Internal	11231.0	\$0.00	
139934	BLOWN HOSE	CHAD01AWAY	23/10/2019	Internal	11104.0	\$0.00	
139925	REPLACE ALL 6 TYRE WITH NEW XTRA DEFEND E4	DALE01	23/10/2019	Internal	11125.0	\$0.00	
139720	REPLACE STARTER MOTOR	DALE01	21/10/2019	Internal	11104.0	\$0.00	
137276	STEERING FAULT - REPLACE HMU PUMP	DINK01SAWAY	16/10/2019	Internal	11070.0	\$0.00	
137310	Scheduled Service Job. PM Service 1,000 HR	XXXX	15/10/2019	Internal	11070.0	\$0.00	
138284	SANDBLAST, CRACK TEST AND PAINT RIMS - TITAN	SUB	11/10/2019	Internal	10911.0	\$0.00	
136184	Scheduled Service Job. PM Service 750HR	MCPH01	20/09/2019	Internal	10770.0	\$0.00	
136199	OIL COOLER REPLACEMENT	BAK03	06/09/2019	Internal	10609.0	\$0.00	
134647	#DAMAGED SPRAYER REPAIRS	KIB02TRADEAWAY	02/09/2019	External	10594.0	\$6,498.71	
136132	COMPLETE RIM CHANGE OUT - KALTIRE	XXXX	29/08/2019	Internal	10583.0	\$0.00	
134547	POS 5 INFLATION	BAK03	20/08/2019	Internal	10512.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
134149	REPLACE LH ARMREST - REPLACED AT SERVICE REFER 133268	PRL01	19/08/2019	Internal	10511.0	\$0.00	
133268	Scheduled Service Job. PM Service 500 HR	XXXX	19/08/2019	Internal	10511.0	\$0.00	
133367	HOIST PUMP RESEAL	BAK03	30/07/2019	Internal	10352.0	\$0.00	
133222	FIRE SUPPRESSION FAULT	BAK03	27/07/2019	Internal	10308.0	\$0.00	
134143	Scheduled Service Job. FIRE SUPPRESSION	SUB	22/07/2019	Internal	10244.0	\$0.00	
131884	Scheduled Service Job. PM Service 250 hr	XXXX	22/07/2019	Internal	10258.0	\$0.00	
132460	REPLACE POS 1 STRUT BEARINGS	CHAD01AWAY	11/07/2019	Internal	10157.0	\$0.00	
131787	TRACTION CONTROL FAULT	SAB03	11/07/2019	Internal	10157.0	\$0.00	
132200	REPLACE HYDRAULIC HOSES	KNJ01	08/07/2019	Internal	10130.0	\$0.00	
130080	REPLACE WASHER BOTTLE - PART ONLY	CHAD01AWAY	23/06/2019	Internal	10010.0	\$0.00	
130816	Scheduled Service Job. PM Service 2,000 HR	BAK03	22/06/2019	Internal	10009.0	\$0.00	
131253	A.C REPAIRS	CHAD01AWAY	19/06/2019	Internal	9964.0	\$0.00	
129975	WATER PUMP & SPRAY REPAIRS	PRL01	14/06/2019	Internal	9838.0	\$0.00	
130922	RESEAL STEERING CYLINDER	XXXX	12/06/2019	Internal	9838.0	\$0.00	
130548	OIL FROM SERVICE - REF 129657	BAK03	03/06/2019	Internal	9749.0	\$0.00	
129657	Scheduled Service Job. PM Service 750 HR	BAK03	03/06/2019	Internal	9749.0	\$0.00	
130442	INSPECT & REPAIR ALL LIGHTS	CHAD01AWAY	02/06/2019	Internal	9721.0	\$0.00	
130386	SUSPENSION ADJUSTMENT	CHAD01AWAY	31/05/2019	Internal	9717.0	\$0.00	
130342	REPLACE L/H STEERING CYLINDER	CHAD01AWAY	30/05/2019	Internal	9705.0	\$0.00	
128930	REPLACE POS 2 STRUT	KNJ01	13/05/2019	Internal	9543.0	\$0.00	
128375	#REPLACE DAMAGED PANEL & GRILL	DINK01SAWAY	13/05/2019	External	9543.0	\$1,965.55	
128770	FRONT STRUT - SERVICE AND ADJUST	CHAD01AWAY	07/05/2019	Internal	9507.0	\$0.00	
128761	SPRAY REPAIRS	KNJ01	03/05/2019	Internal	9507.0	\$0.00	
127809	Scheduled Service Job. PM Service 500 HR	DINK01SAWAY	28/04/2019	Internal	9446.0	\$0.00	
128252	REPLACE BLOWN BRAKE HOSE	DINK01SAWAY	26/04/2019	Internal	9426.0	\$0.00	
128156	SPRAY ADJUSTMENTS	CHAD01AWAY	22/04/2019	Internal	9426.0	\$0.00	
126077	STEER CYLINDER REPAIRS	SAB03	15/04/2019	Internal	9426.0	\$0.00	
127173	TYRE REPAIRS - POS 6	CHAD01AWAY	01/04/2019	Internal	9275.0	\$0.00	
123066	Scheduled Service Job. PM Service 750 HR	CHAD01AWAY	31/03/2019	Internal	9272.0	\$0.00	
125792	DROP BOX REPAIRS	DINK01SAWAY	19/03/2019	Internal	9207.0	\$0.00	
126371	REPLACE HYDRAULIC HOSE	CHAD01AWAY	12/03/2019	Internal	9223.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
126341	RESEAL OTG PUMP	DINK01SAWAY	12/03/2019	Internal	9213.0	\$0.00	
126199	REPLACE DOGBONE BUSHES	DINK01SAWAY	11/03/2019	Internal	9213.0	\$0.00	11/05/19 - JOB DIDNT NEED TO BE DONE - PUT PARTS BACK IN STOCK - JW
127009	FIRE SUPPRESSION REPAIRS - HOSES - PARTS ONLY	XXXX	02/03/2019	Internal	9207.0	\$0.00	
123772	REPLACE TRANSFER GEAR CASE	DINK01SAWAY	02/03/2019	Internal	9207.0	\$0.00	
125804	SPRAY REPAIRS	DALE01	01/03/2019	Internal	9207.0	\$0.00	
123757	A FRAME REPAIRS	CHAD01AWAY	17/02/2019	Internal	9207.0	\$0.00	STARTING LAB ON JOB 123772
124798	START REPAIRS	KNJ01	08/02/2019	Internal	9207.0	\$0.00	
122592	WATER PUMP REPAIRS	DINK01SAWAY	28/01/2019	Internal	9105.0	\$0.00	
123063	CHANGE POS 2 TYRE O RING	DINK01SAWAY	27/01/2019	Internal	9102.0	\$0.00	
122288	LIGHT REPAIRS	DINK01SAWAY	22/01/2019	Internal	9060.0	\$0.00	
122198	REPLACE BONNET SEAL	DINK01SAWAY	22/01/2019	Internal	9060.0	\$0.00	
121105	Scheduled Service Job. PM Service 1,000 HR	XXXX	18/01/2019	Internal	9049.0	\$0.00	
122238	REPLACE BRAKE COOLER HOSE	DINK01SAWAY	17/01/2019	Internal	9049.0	\$0.00	
122360	REPLACE HEATER HOSE / TAPS	DINK01SAWAY	16/01/2019	Internal	9049.0	\$0.00	
122197	WINGBOLT REPLACEMENT - A.C FILTER - PARTS ONLY	DINK01SAWAY	15/01/2019	Internal	9042.0	\$0.00	
122194	EXHAUST REPAIRS	DINK01SAWAY	15/01/2019	Internal	9042.0	\$0.00	
122192	REPLACE TURBO GAURD	DINK01SAWAY	15/01/2019	Internal	9042.0	\$0.00	
121666	CHARGE POS 1 STRUT	SAB03	01/01/2019	Internal	8942.0	\$0.00	
121103	REBUILD WATER PUMP	DINK01SAWAY	12/12/2018	Internal	8900.0	\$0.00	
119384	Scheduled Service Job. PM Service 750 HR	XXXX	10/12/2018	Internal	8900.0	\$0.00	
120914	INSPECT TIMING COVER	SAB03	09/12/2018	Internal	8897.0	\$0.00	
122540	Scheduled Service Job. FIRE SUPPRESSION	SUB	08/12/2018	Internal	8897.0	\$0.00	
118365	FIRE SUPPRESSION REPAIRS	DINK01SAWAY	06/12/2018	Internal	8897.0	\$0.00	
116066	REPLACE OIL FILTER HOSE	DINK01SAWAY	02/12/2018	Internal	8777.0	\$0.00	
119431	SPRAY REPAIRS - REPLACE CYLINDERS	DINK01SAWAY	27/11/2018	Internal	8692.0	\$0.00	
119488	POS 5 TYRE - INFLATION	DINK01SAWAY	15/11/2018	Internal	8631.0	\$0.00	
119039	POS 5 TYRE INFLATION	SAB03	13/11/2018	Internal	8631.0	\$0.00	
118577	A.C REPAIRS	DINK01SAWAY	30/10/2018	Internal	8528.0	\$0.00	
115663	SPRAY REPAIRS	BENC02AWAY	17/10/2018	Internal	8512.0	\$0.00	
116060	BRAKE AND SUSPENSION REPAIRS	DINK01SAWAY	15/10/2018	Internal	8512.0	\$0.00	
115793	Scheduled Service Job. PM Service 500 HR	XXXX	12/10/2018	Internal	8485.0	\$0.00	
115558	HYDRAULIC HOSE REPIRS	BENC02AWAY	27/09/2018	Internal	8380.0	\$0.00	
115266	STRUT REPAIRS [STEERING COLUMN]	DINK01SAWAY	26/09/2018	Internal	8380.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
115907	SECURE FIRE SUPPRESSION	PRL01	25/09/2018	Internal	8352.0	\$0.00	
115805	SECURE TANK - MOUNT BOLTS	PRL01	25/09/2018	Internal	8352.0	\$0.00	
115012	REPLACE FRON WINDSCREEN	DINK01SAWAY	25/09/2018	Internal	8352.0	\$0.00	
114380	A.C REPAIRS	DINK01SAWAY	25/09/2018	Internal	8352.0	\$0.00	
115755	ADDITIONAL LAB - REF - 114476 - ELECTRICAL REPAIRS - LIGHTS	DINK01SAWAY	21/09/2018	Internal	8352.0	\$0.00	
115754	REPLACE VISION LINK UNIT	DINK01SAWAY	21/09/2018	Internal	8352.0	\$0.00	
114565	FRAME REPAIRS - DOG BONE	XXXX	17/09/2018	Internal	8352.0	\$0.00	
114200	Scheduled Service Job. PM Service 250 HR	PRL01	14/09/2018	Internal	8250.0	\$0.00	
114476	LIGHT REPAIRS	DINK01SAWAY	11/09/2018	Internal	8255.0	\$0.00	
115010	FIRE SUPPRESSION REPAIRS	DINK01SAWAY	10/09/2018	Internal	8255.0	\$0.00	
114939	RETORQUE WHEEL NUTS	DINK01SAWAY	07/09/2018	Internal	8203.0	\$0.00	
114602	ELECTRICAL REPAIRS	XXXX	06/09/2018	Internal	8203.0	\$0.00	
114463	FIT VHF RADIO - MRM PARTS	DINK01SAWAY	02/09/2018	Internal	8152.0	\$0.00	
112245	Scheduled Service Job. PM Service 2,000 HR	PRL01	30/08/2018	Internal	8000.0	\$0.00	
113504	REPLACE U.S RADIATOR CAP	BENC02AWAY	19/08/2018	Internal	8075.0	\$0.00	
113538	FIRE SUPPRESSION PRESSURES	BENC02AWAY	14/08/2018	Internal	8060.0	\$0.00	
112938	REPLACE BLOWN OUT MUFFLER	BENC02AWAY	10/08/2018	Internal	8041.0	\$0.00	
111694	REPAIR R/H STEER CYLINDER - PARTS FOR JOB ON - 111553	POD03	29/07/2018	Internal	7891.0	\$0.00	CONFUSION BETWEEN SUSPENSION AND STEER CYLINDER - PARTS WERE ORDERED ON JOB 111553 - JOB HAS SINCE BEEN POSTED - LABOR ONLY - JOB COMPLETED - MADDISEN
112559	REPAIRS TO DOOR LATCH HANDLE	DINK01SAWAY	25/07/2018	Internal	7874.0	\$0.00	
110803	Scheduled Service Job. PM Service 750 HR	XXXX	14/07/2018	Internal	7762.0	\$0.00	
112888	RESEAL R/H FRONT SUSPENSION STRUT - REF 111553	POD03	10/07/2018	Internal	7695.0	\$0.00	
111553	REPLACE R/H FRONT SUSPENSION STRUT	POD03	10/07/2018	Internal	7695.0	\$0.00	
111314	WATER GAUGE REPAIRS	DINK01SAWAY	06/07/2018	Internal	7699.0	\$0.00	
111088	VISION LINK INSPECTION	DINK01SAWAY	02/07/2018	Internal	7690.0	\$0.00	
111021	WATER LEVER SENSOR - WIRING INSPECTION	BENC02AWAY	02/07/2018	Internal	7690.0	\$0.00	
110749	HEADLIGHT REPAIRS	POD03	23/06/2018	Internal	7645.0	\$0.00	
110113	A.C INSPECT AND REPAIR	DINK01SAWAY	13/06/2018	Internal	7548.0	\$0.00	
109298	Scheduled Service Job. PM Service 500 HR	XXXX	06/06/2018	Internal	7545.0	\$0.00	
109263	REPAIRS TO BLOWN HYD LINES	POD03	28/05/2018	Internal	7434.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
108731	[ADDITIONAL LAB] Scheduled Service Job. PM Service 250 HR - 107157 PM Service	POD03	16/05/2018	Internal	7266.0	\$0.00	
107157	Scheduled Service Job. PM Service 250 HR	XXXX	14/05/2018	Internal	7266.0	\$0.00	
106434	ELECTRICAL REPAIRS - BATTERY & ESTOP	DINK01SAWAY	16/04/2018	Internal	7155.0	\$0.00	
107112	LIGHT REPAIRS	DINK01SAWAY	14/04/2018	Internal	7147.0	\$0.00	
107661	[ADDITIONAL LAB] REPAIRS TO VISION LINK - 102819	DINK01SAWAY	10/04/2018	Internal	7023.0	\$0.00	
102819	REPAIRS TO VISION LINK	DINK01SAWAY	10/04/2018	Internal	7023.0	\$0.00	12/02/18 - JOB ON GOING - VISION LINK CONTROLLER NOT TALKING TO ET - AH 28/03/18 - JOB ON GOING - MC
106284	INSPECT AND REPAIR COOLANT LEAK	DINK01SAWAY	03/04/2018	Internal	7023.0	\$0.00	
106481	HYD HOSE LEAK - REPAIRS	POD03	29/03/2018	Internal	7031.0	\$0.00	
106208	INSPECT AND REPAIR FIRE SUPPRESSION	DINK01SAWAY	24/03/2018	Internal	7020.0	\$0.00	HOURS AS PER SERVICE SHEET PROVIDED BY FITTER
105546	CALL SIGNS - FAB	RES02	13/03/2018	Internal	7023.0	\$0.00	
105165	REPLACE MISSING HITCH LINE SUPPORT BRACKET	HUD05	05/03/2018	Internal	7023.0	\$0.00	HOURS AS PER SEVICE SHEET PROVIDED BY FITTER - MADDISEN 21/03
104954	A/C REPAIRS	DINK01SAWAY	27/02/2018	Internal	6969.0	\$0.00	
104520	TOP UP COOLANT	POD03	15/02/2018	Internal	6969.0	\$0.00	
97097	Scheduled Service Job. PM Service 1,000 HR	XXXX	12/02/2018	Internal	6969.0	\$0.00	
103065	INPSECT AND REPAIR OIL LEAK AT HYD TANK	DINK01SAWAY	07/02/2018	Internal	6960.0	\$0.00	
102817	REPAIRS TO AUTO REWIND	DINK01SAWAY	03/02/2018	Internal	6962.0	\$0.00	
101135	FIT MIRRORS	POD03	22/01/2018	Internal	6952.0	\$0.00	
101057	ORDER PARTS FOR WINDSCREEN REPLACMENT	POD03	18/01/2018	Internal	6952.0	\$0.00	21/08 - PARTS MOVED INTO STOCK - TO BE ALLOCATED WHEN JOB CAN BE COMPLETED - MADDISEN
100826	HOSEREEL REPAIRS	DINK01	16/01/2018	Internal	6952.0	\$0.00	25/01 - MADDISEN - PO - 10080436 NOT COMPLETE - SENT TO EAP TODAY
101025	SERVICE FIRE SUPPRESSION	SUB	15/01/2018	Internal	6952.0	\$0.00	
100806	WASH AND DETAIL	ALLA01 NORMAL	15/01/2018	Internal	6906.0	\$0.00	
100799	REMOVE TAILGATE	BENC02	15/01/2018	Internal	6952.0	\$0.00	
99965	FIT WATER TANK TO MOXY	COP01	15/01/2018	Internal	6952.0	\$0.00	5/03 - REQUESTED COPY OF OUTSTANDING INVOICE- AH
100711	REPLACE DECALS	RES02	13/01/2018	Internal	6952.0	\$0.00	
99866	TUB TO TANK SWAP	XXXX	19/12/2017	Internal	6906.0	\$0.00	
99844	FIT TWO NEW TYRES	HUD05	19/12/2017	Internal	6906.0	\$0.00	
97991	UNLOAD AND RETURN MACHINE	RES02	05/12/2017	Internal	6906.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
94856	Scheduled Service Job. PM Service 750 HR	XXXX	08/11/2017	Internal	6815.0	\$0.00	
93347	Scheduled Service Job. PM Service 500 HR	XXXX	30/09/2017	Internal	6497.0	\$0.00	19/10 - SERVICE COMPLETE - WAITING ON PO - 10072424 - HAVE EMAILED HASTINGS TO GET COPY OF INVOICE - WILL SEND TO EAP AND POST - MADDISEN
93356	REPLACE & UPGRADE HOIST PUMP - STOCK RETURN	XXXX	22/09/2017	Internal	6426.0	\$0.00	
93147	CHANGE OUT POS 3 TYRE	PACI02AWAY	19/09/2017	Internal	6359.0	\$0.00	
92541	INSPECT FOR MINE SITE	BENC02AWAY	10/09/2017	Internal	6359.0	\$0.00	
92303	REPLACE UHF	JLKE01	07/09/2017	Internal	6359.0	\$0.00	
93181	REPLACE ARTICULATION HOSE	SUB	06/09/2017	Internal	6359.0	\$0.00	
92049	REPLACE & UPGRADE HOIST PUMP	JLKE01	06/09/2017	Internal	6359.0	\$0.00	
91731	REPAIRS TO VARIOUS OIL LEAKS	JLKE01	06/09/2017	Internal	6359.0	\$0.00	290817 VARIOUS OIL LEAKS INCLUDE TRANSMISSION ENGINE HOIST PUMP STEERING STARTER MOTOR - JH
91472	DEHIRE & PREP FOR HIRE	JLKE01	06/09/2017	Internal	6359.0	\$0.00	
91739	REPLACE ROD BUSHES & UNI JOINTS	JLKE01	05/09/2017	Internal	6348.0	\$0.00	
92091	INSPECT & REPAIRS TO VISION LINK	SUB	04/09/2017	Internal	6348.0	\$0.00	
91905	REPLACE BRAKE COOLING RETURN HOSE	JLKE01	01/09/2017	Internal	6348.0	\$0.00	050917 LABOUR POSTED TO JOB 91734 - JH
91734	RESEAL HEAD GASKET	JLKE01	01/09/2017	Internal	6348.0	\$0.00	
91730	REPLACE L/H & R/H GUARDS	SUB	31/08/2017	External	6348.0	\$1,900.51	AT40012 - CATERPILLAR - 740 REPLACE LEFT & RIGHT HAND WHEEL ARCH GAURDS DAMAGED DURING HIRE.
91796	SERVICE FIRE SUPPRESSION SYSTEM/ PRESSURE TEST BOTTLE	SUB	27/08/2017	Internal	6348.0	\$0.00	
90292	Scheduled Service Job. PM Service { BK HIRE }	SUB	22/08/2017	Internal	6348.0	\$0.00	
87109	Scheduled Service Job. PM Service BK HIRE	SUB	13/06/2017	Internal	6061.0	\$0.00	
87960	REPAIRS TO ELECTRICAL SYSTEM	SUB	05/06/2017	Internal	5686.0	\$0.00	
86693	REPLACE POS 1 & 2 TYRES	SUB	31/05/2017	Internal	5740.0	\$0.00	
81945	Scheduled Service Job. PM Service 750 HR { BK HIRE }	SUB	08/04/2017	Internal	5740.0	\$0.00	
82241	CARRY OUT TYRE INSPECTION	SUB	07/04/2017	Internal	5740.0	\$0.00	150317 CREATED AS PER MATT HANRAHAN - JH

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
81444	REPLACE CRACKED ENGINE TIMING COVER { WESTRAC }	SUB	01/03/2017	Internal	5686.0	\$0.00	ENGINE TIMING COVER REPLACED DUE TO CRACK RUNNING FROM ALTERNATOR MOUNTING STUD .CHECKED FOR PIP BUT IT WAS OUT OF DATE .TRUCK TRANSPORTED TO WESTRAC WAGGA TO COMPLETE REPAIRS.MH1703
81066	PART ONLY - DUAL AXIS INCLINOMETER & COVER	SUB	21/02/2017	Internal	5582.0	\$0.00	
79563	Scheduled Service Job. PM Service 500 HR	SUB	06/02/2017	Internal	5585.0	\$0.00	
79849	TEST & TAG FIRE SUPPRESSION	SUB	30/01/2017	Internal	5582.0	\$0.00	
75341	REPLACE POS1 AND 2 TYRE	SUB	19/10/2016	Internal	5004.0	\$0.00	WORK COMPLETED BY TYRE DOCTOR AT THE LAKE COWAL MINESITE AS PER NICK DARCY'S REQUEST
73834	SUPPLY UHF RADIOS FOR SITE PURPOSES	SUB	15/09/2016	Internal	5073.0	\$0.00	
70568	CARRY OUT SITE INSPECTION - MT CARLTON	GIJ01	08/07/2016	Internal	4947.0	\$0.00	
68877	HOIST CYLINDER REPAIRS - STOCK RETURN	SUB	27/05/2016	Internal	4947.0	\$0.00	
68475	1000HR PM SERVICE - LABOUR ONLY	JAC01	19/05/2016	Internal	4947.0	\$0.00	190516 ADDITIONAL LABOUR REQUIRED AFTER SERVICE SHEET HANDED IN AND ORIGINAL JOB POSTED (67756) - JH
68103	WASH & DETAIL	HEM01	10/05/2016	Internal	4939.0	\$0.00	
68044	REPALCE BIN STICKERS	AVS01	09/05/2016	Internal	4939.0	\$0.00	
67999	REPAIR L/H FENDER	AVS01	09/05/2016	Internal	4939.0	\$0.00	
67998	DEHIRE & CHECK OVER	AVS01	09/05/2016	Internal	4947.0	\$0.00	
67987	SUPPLY OWNERS MANUAL - PARTS ONLY	SUB	06/05/2016	Internal	4939.0	\$0.00	
67766	HITCH REPAIRS - PARTS RETURN	SUB	03/05/2016	Internal	4931.0	\$0.00	030516 JOB CREATED TO RETURN PARTS ON ORIGINAL P/O 10047523 - JH
67764	REPAIRS TO BODY PINS - PARTS RETURN	SUB	03/05/2016	Internal	4931.0	\$0.00	030516 JOB CREATED TO RETURN PARTS ON ORIGINAL P/O 10047520 - JH
67756	1000 HR PM SERVICE	VAA01	03/05/2016	Internal	4931.0	\$0.00	
67449	TRACTION CONTROL LIGHT STAYING ON	PACI02	22/04/2016	Internal	4885.0	\$0.00	
64865	A FRAME REPAIRS - PARTS ONLY	MTG01	11/04/2016	Internal	4659.0	\$0.00	170516 ALL LABOUR AND JOB CARDS ON JOB 64874 - JH
66185	750 HR PM SERVICE	VAA01	01/04/2016	Internal	4777.0	\$0.00	
66124	REPLACE WORK TAILGATE BUSHES	MAC03	22/03/2016	Internal	4680.0	\$0.00	
66123	PAINTED TAILGATES	MAC03	22/03/2016	Internal	4680.0	\$0.00	
65657	WASH DOWN & DETAIL	MAC03	11/03/2016	Internal	4660.0	\$0.00	
65656	PREP, SAND & PAINT MACHINE	MAC03	11/03/2016	Internal	4660.0	\$0.00	
65490	REPLACE STICKERS - PARTS ONLY	AVT01	08/03/2016	Internal	4660.0	\$0.00	
64878	HITCH REPAIRS	MTG01	07/03/2016	Internal	4659.0	\$0.00	
64877	HOIST CYLINDER REPAIRS	MTG01	07/03/2016	Internal	4659.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
64874	REPAIRS TO BODY PINS	MTG01	07/03/2016	Internal	4659.0	\$0.00	
65363	REPLACE MIRROR - PARTS ONLY	AVT01	04/03/2016	Internal	4660.0	\$0.00	
65279	SERVICE FIRE SUPPRESSION SYSTEM	SUB	02/03/2016	Internal	4660.0	\$0.00	
64917	REMOVE AND REFIT EXTERNAL ESTOPS	MTG01	23/02/2016	Internal	4659.0	\$0.00	
64649	DEHIRE / CHECKOVER	MAC03	17/02/2016	Internal	4659.0	\$0.00	
63001	500 HR PM SERVICE	SUB	13/01/2016	Internal	4598.0	\$0.00	
60379	FIT TAIL GATE	AVT01	04/11/2015	Internal	4252.0	\$0.00	
59161	DEHIRE & CHECK OVER	MTG01	07/10/2015	Internal	4244.0	\$0.00	
59162	DEHIRE / CHECKOVER	MTG01	06/10/2015	Internal	4251.0	\$0.00	
58204	DEHIRE / CHECKOVER	MTG01	14/09/2015	Internal	4224.0	\$0.00	
57190	SERVICE FIRE SUPPRESSION FOR MDG15	SUB	20/08/2015	Internal	4224.0	\$0.00	
57059	PREP FOR MDG15 COMPLIANCE	DAK02	18/08/2015	Internal	4215.0	\$0.00	
56978	DEHIRE CHECK PREP FOR HIRE	AVT01	17/08/2015	Internal	4223.0	\$0.00	
56874	250 HR PM SERVICE	AVS01	13/08/2015	Internal	4215.0	\$0.00	
56402	DEHIRE / CHECKOVER	SUB	31/07/2015	Internal	4195.0	\$0.00	
56378	PUMP UP POS 1 TYRE	JAC01	31/07/2015	Internal	4183.0	\$0.00	
55727	WASH AND DETAIL	COK01	15/07/2015	Internal	4105.0	\$0.00	
55713	SERVICE FIRE SUPPRESSION SYSTEM	SUB	14/07/2015	Internal	4105.0	\$0.00	
55689	DEHIRE/ CHECK PREP FOR HIRE	AVT01	14/07/2015	Internal	4105.0	\$0.00	
55688	REPLACE REAR SUSPENSION BUSHES	AVT01	14/07/2015	Internal	4093.0	\$0.00	
55392	REPLACE BATTERIES	DAK02	06/07/2015	Internal	4066.0	\$0.00	
54898	REMOVE STEEL FROM TYRE	GES01	26/06/2015	Internal	4056.0	\$0.00	
54074	2000 HR PM SERVICE	AVS01	05/06/2015	Internal	3956.0	\$0.00	
53676	REPLACE MIRROR AND LATCH ASEMBLY	AVS01	28/05/2015	Internal	4926.0	\$0.00	
52538	DEHIRE/ CHECK PREP FOR HIRE	JOR01	29/04/2015	Internal	3757.0	\$0.00	
52265	750 HR PM SERVICE	AVS01	25/04/2015	Internal	3756.0	\$0.00	
51720	REPLACE ALL ENGINE AIR FILTERS	JAC01	09/04/2015	External	3636.0	\$373.72	
51276	WASH, CLEAN AND DETAIL	AVT01	26/03/2015	Internal	3583.0	\$0.00	
51082	DEHIRE CHECK / PREP FOR HIRE	AVS01	23/03/2015	Internal	3582.0	\$0.00	
51079	ROTATE TYRES ON UNIT	AVT01	23/03/2015	Internal	3582.0	\$0.00	
51051	REPLACE A FRAME BEARING	AVS01	20/03/2015	Internal	3583.0	\$0.00	
49921	REMOVE TAIL GATE FROM MACHINE	EDB01	18/02/2015	Internal	3487.0	\$0.00	18/02/2015 - REMVOED TAIL GATE FOR TRANSPORT. REPAIR FIRE SUPPRESSION
49859	REPLACE RH ARM REST	LOS01	18/02/2015	Internal	3485.0	\$0.00	
47499	WASH AND DETAIL	DIA01	15/12/2014	Internal	3485.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
47498	OFF HIRE INSPECTION	LOS01	15/12/2014	Internal	3485.0	\$0.00	
45332	WASH AND DETAIL	DIA01	30/10/2014	Internal	3463.0	\$0.00	
45157	500 HR PM SERVICE	LOS01	29/10/2014	Internal	3464.0	\$0.00	
45331	OFF HIRE INSPECTION	EDB01	28/10/2014	Internal	3463.0	\$0.00	
43229	REPLACE/REPAIR DAMAGED MIRROR	LOS01	25/09/2014	Internal	3313.0	\$0.00	17/09/2014 - CHRIS MEDCRAFT NOTIFIED US THAT MACHINE HAS A BROKEN MIRROR AND MISSING NUT & WASHER. 1. ORGANISE REQUIRED PARTS. 2. REPAIR/REPLACE DAMAGED MIRROR.
42414	WASH MACHINE	HEM01	29/08/2014	Internal	3230.0	\$0.00	
42216	WASH AND DETAIL	MAJ01	26/08/2014	Internal	3230.0	\$0.00	
42113	ATTACH TAILGATE TO MACHINE	MTG01	25/08/2014	Internal	3230.0	\$0.00	25/08/2014 - RE-ATTACH TAILGATE TO MACHINE POST BEING TRANSPORTED TO ROMA. 1. REATTACH TAILGATE.
42071	DEHIRE AND CLEAN	JAC01	25/08/2014	Internal	3230.0	\$0.00	
41748	WASH AND DETAIL	LOS01	17/08/2014	Internal	3230.0	\$0.00	
41515	COMPLETE ELECTRICAL INSPECTION	SUB	11/08/2014	Internal	3230.0	\$0.00	
41070	REPAIR DEFECTS FROM OFF HIRE	JOY01	10/08/2014	Internal	3229.0	\$0.00	03/08/2014 - SHANE MARTIN NOTED ON OFF HIRE THAT MACHINE REQUIRES NEW LEFT SIDE TOP MIRROR, FIRE SUPPRESSION SWITCH ON BOTTLE, & E STOP IN CAB. 1. REPLACE LEFT TOP MIRROR. 2. REPLACE FIRE SUPPRESSION SWITCH. 3. REPLACE E-STOP IN CAB
41136	WASH AND DETAIL MACHINE	MAJ01	06/08/2014	Internal	3228.0	\$0.00	
41008	OFF HIRE INSPECTION	JOY01	03/08/2014	Internal	3230.1	\$0.00	
39341	250 HR PM SERVICE	MOP01	02/07/2014	Internal	3213.0	\$0.00	
39009	ADJUST TYRE PRESSURES	MOP01	24/06/2014	Internal	3128.0	\$0.00	
37934	PUMP UP POS 2 TYRE & CHECK FOR LEAKS	JAC01	19/05/2014	Internal	3060.0	\$0.00	
35504	INSPECT NOISE AT POS 1	JAC01	06/04/2014	Internal	2849.0	\$0.00	
35387	1000 HR PM SERVICE	JAC01	03/04/2014	Internal	3008.0	\$0.00	
33230	750 HR PM SERVICE	JAC01	12/02/2014	Internal	2721.0	\$0.00	
31463	500 HR PM SERVICE	NAT01	13/12/2013	Internal	2346.0	\$0.00	
31257	SERVICE & INSPECT FIRE SUPPRESSION	SUB	09/12/2013	Internal	2306.0	\$0.00	
31051	DIAGNOSE AND REPAIR ALARM	NAT01	05/12/2013	Internal	2306.0	\$0.00	
30272	PREP DOOR TO INSTALL NEW WINDOW	NAT01	14/11/2013	Internal	2286.0	\$0.00	
28932	250 HR PM SERVICE	NAT01	25/10/2013	Internal	2268.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: EZYQUIP							
Equip. Code: AT40012		Description: Articulated Dump Truck 40t					
Make: Caterpillar		Model: 740		Serial No.: L4E01308			
28467	REPLACE BLOWN TRANSMISSION HOSE	JOR01	29/09/2013	Internal	2046.0	\$0.00	FIT NEW TRANS HOSE - WASH MACHINE DOWN.
27312	1000 HR PM SERVICE	NAT01	16/08/2013	Internal	2015.0	\$0.00	
25900	750 HR PM SERVICE	NAT01	06/08/2013	Internal	1720.0	\$0.00	
25544	CONDUCT PRESTART ON SITE	NAT01	08/07/2013	Internal	1555.0	\$0.00	
25183	ALARM IN CAB-DIAGNOSE AND REPAIR	NAT01	26/06/2013	Internal	1450.0	\$0.00	
25019	Fabricate Mine Call Signs 'A12'	IMM01	24/06/2013	Internal	1450.0	\$0.00	
24832	500 HR PM SERVICE	ROW03	21/06/2013	Internal	1550.0	\$0.00	
24358	SUPPLY FIRST AID KIT FOR MINE COMPLIANCE	XXXX	07/06/2013	Internal	1339.0	\$0.00	
23749	FIT WHEEL CHOCKS	MAD01	20/05/2013	Internal	1329.0	\$0.00	
23696	REPLACE SPOT MIRRORS	MAD01	17/05/2013	Internal	1329.0	\$0.00	
23662	SERVICE FIRE SUPPRESSION	SUB	16/05/2013	Internal	1329.0	\$0.00	
23441	REMOVE TAILGATE/SIDE ARMS FOR T/PORT	ENJ01	13/05/2013	Internal	1328.0	\$0.00	
23203	DEHIRE / CHECKOVER	MOP01	01/05/2013	Internal	1324.0	\$0.00	
22916	CARRY OUT DEHIRE.	HAP01	19/04/2013	Internal	1285.0	\$0.00	
21968	250 HR PM SERVICE	ROW03	01/04/2013	Internal	1240.0	\$0.00	
20486	JUMP START MACHINE	ROW03	01/02/2013	External	963.0	\$158.13	
20252	1,000 HR PM SERVICE	WED02	21/01/2013	Internal	952.0	\$0.00	CARRY OUT 100 HR PM SERVICE
18705	750 HR PM SERVICE	WED02	23/11/2012	Internal	725.0	\$0.00	
17836	500 HR PM SERVICE	WED02	28/10/2012	Internal	549.0	\$0.00	
17699	INSPECT REAR SUSPENSION FAULT	JOR01	17/10/2012	Internal	439.0	\$0.00	
17450	INSPECT BODY RAISE PROBLEM	SCL05	05/10/2012	Internal	349.0	\$0.00	TUB WOULD RAISE SLOWLY OR NOT AT ALL. INSPECT PRESSURE AND FOUND RAISE PRESSURE AT 1800PSI (SPEC 3265PSI). TESTED CYLINDERS FOR BY-PASS. CONTACTED HASTINGS FOR INSPECTION. HASTINGS TECHNICIAN FOUND PRESSURES AT 2800PSI & TUB WAS LIFTING SATISFACTORILY. HASTINGS REPLACING RELIEF VALVE AS PRECAUTION.
16944	250 HR PM SERVICE	SCL05	16/09/2012	Internal	258.0	\$0.00	
16308	INSPECT OTG FILTER BLOCKAGE	ROW03	13/08/2012	Internal	12.0	\$0.00	
16034	STICKERS AND CHECK OVER	SUB	30/07/2012	Internal	0.0	\$0.00	
16029	Commision unit	SUB	30/07/2012	Internal	0.0	\$0.00	
Equipment Total:						\$21,386.12	
Customer Total:						\$21,386.12	