



## Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

### Safety Recalls

---

Campaign Code

[2611H]

Recall Description

Power window master switch operation defect may cause switch to become inoperative and/or switch assembly to over-heat & melt

Recall Number

2012/13327

Recall Status

● Complete

Completion Date

05/04/2013

---

Campaign Code

[AGG33]

Recall Description

Front seat track potential spring mechanism defect may cause seat to move in an accident, increasing the risk of injury

Recall Number

2014/14057

Recall Status

● Complete

Completion Date

05/02/2016

---

Campaign Code

[BGG23]

Recall Description

CRITICAL - AFFECTED TAKATA AIRBAG INFLATOR PASSENGER SIDE  
[STOP DRIVING IMMEDIATELY]

Recall Number

2015/14794

Recall Status

● Complete

Completion Date

05/02/2016

## Vehicle Details

---

<b>VIN</b>	JTDKW923X02026872
<b>Model</b>	Yaris
<b>Colour</b>	Black Mica Metallic
<b>Trim</b>	Dark Grey
<b>Series</b>	5DR Hatch 5M 1.3L
<b>Production year/month</b>	2008-01
<b>Time/Date</b>	11:30:37 02/06/2023

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best

information currently available to Toyota.

\*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit  
<https://www.vehiclecalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.