

# Coates Hire Pre Divestment Inspection Checklist

## Air Compressors

Description 130 CFM Compressor Asset # 1065934 Service Job # \_\_\_\_\_

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at [www.coateshire.com.au](http://www.coateshire.com.au).

General Information: \*\*\* Copy Data Plate information in this section \*\*\*

Make/ Model ATLAS COPCO XAS130 Engine / Motor - Make / Model Deutz D 2011 L03  
 Year 2011 Engine Serial Number ~~2811111111~~ 10993052  
 Serial Number APP136872 Meter Reading 2737

Comments: \_\_\_\_\_

Features: List features or options for the machine:

Air Pressure Range 1 bar (102psi) 10.3 bar (150psi) Frame Mount ☐  
 Air C.F.M. Rating ~~130 CFM~~ 130 CFM Trailer Mount ☒

Comments: \_\_\_\_\_

Overall Appearance:

	Good	Fair	Poor
Control Station/Operator Station	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Sheet metal/Fiberglass Condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Paint	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: Broken bonnet hinge & bonnet melted in LHF corner

Control Station

	Operates		N/A
	Yes	No	
Operator Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gauges Operational?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: unknown unable to start or power up

Engine or Electric Motor:

Power: Diesel ☒ Gas ☐ Electric ☐  
 Does it start? Yes ☒ No ☐  
 Did it need to be jumped? ☐ ☐  
 Acceptable Power ☐ ☐  
 Unusual Noises ☐ ☐

Comments: Exhaust broken (irreparable) unable to start or power up

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A
Landing Gear / Outriggers	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Frame Condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trailer Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trailer Electrical Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Trailer Brakes	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Switches	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Separator	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Pressure Release Valve	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hoses	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: Pressure vessel and safety valve inspection required  
unable to test trailer lights  
Handbrake not working

Tyre Condition:

Left - Front		Left - Rear		Right	
Brand- <u>Headway</u>		Brand- <u>Centara</u>			
Size- <u>165R 13C</u>		Size- <u>165R 13C</u>			
Condition- <u>Poor</u>		Condition- <u>Fair</u>			

Comments: RHS rim damaged  
Possible bent axle

Any other known issues, faults:

known problem with engine