Coates Inspection Checklist

Generators (Diesel or Petrol)

See Generator Photo Log for required pictures **Asset #** _____ 1066233

Photos

General Information: *** Copy Data Plate information in this section ***

Make/ Model	KUBOTA Generator - 15kVA (Diesel)	Engine / Motor - Make / Model	V2203
Year	2011	Engine Serial Number	G20973L0220FCC
Serial Number	L05031	Meter Reading	19778

Comments:

☐ Data Plate

Features:

List features or options for the machine:

Generator Type: Single Phase ☒ 3 Phase ☐; Frame mount ☒ Trailer mount ☐

Generator KVA Rating: 15

Power Outlets: Qty Single Phase 3 — Amps per outlet 15; Qty 3 Phase ____ — Amps per outlet ____

4-Corner Photos

☐ Left-Front Corner
☐ Left-Rear Corner
☐ Right-Front Corner
☐ Right-Rear Corner

☐ *Damage*
☐ *Damage*

Overall Appearance:

	Good	Fair	Poor	Comments:
Control Station\Operator Station	☒	☐	☐	Out lets and circuit brakers old need replacing
Sheet metal\Fiberglass Condition	☒	☐	☐	
Paint	☒	☐	☐	
Lights	☒	☐	☐	

Control Station

	Operates Yes	Operates No	N/A	Comments:
Operator Controls	☒	☐		
Gauges Operational?	☒	☐	☐	

☐ Hour Meter
☐ Guages
☐ *Damage*
☐ *Damage*

Engine:

Power: Diesel ☒ Petrol ☐

	Yes	No	Comments:
Does it start?	☐	☐	
Did it need to be jumped?	☐	☒	
Acceptable Power	☐	☒	
Unusual Noises	☐	☒	

☐ Right Side hood open
☐ Left Side hood open

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Landing Gear / Outriggers	☐	☐	☐	☐	☐	☒	
Frame Condition	☒	☐	☐	☐	☐	☐	
Trailer Lights	☐	☐	☐	☐	☐	☐	
Trailer Electrical Connections	☐	☐	☐	☐	☐	☐	
Trailer Brakes	☐	☐	☐	☐	☐	☒	
Switches	☐	☐	☒	☐	☐	☐	
Power Cables	☐	☐	☐	☐	☐	☐	

☐ Hitch
☐ Lights on
☐ Light Tower (Extended)

Tire Condition:

Left	Right
Brand-	Brand-
Size-	Size-
Condition-	Condition-

Tire pictures at a 45 degree angle showing the tread and side walls

☐ Left
☐ Right