

Coates Inspection Checklist

Light Towers

Photos

See Light Tower Photo Log for required pictures

Asset # 1099920

General Information: *** Copy Data Plate information in this section ***

Make/ Model	<u>Allight MS6L-9</u>	Engine / Motor - Make / Model	<u>PERKINS 403D11</u>
Year	<u>2012</u>	Engine Serial Number	<u>GJ65701R/011928U</u>
Serial Number	<u>GJETRAMLIBLUC0025</u>	Meter Reading	<u>10134 HRS.</u>

Data Plate

Comments: Beyond Years - 12 Years Old

Features:

List features or options for the machine:

Number of Lights	<u>4</u>	Wattage per light	<u>1500 W</u>
Height of Mast	<u>9m</u>	Generator KVA	<u>12 KVA</u>
Power Outlets	Qty Single Phase <u>N/A</u>	Amps per outlet	<u> </u>
	Qty 3 Phase <u>N/A</u>	Amps per outlet	<u> </u>

4-Corner Photos

Left-Front Corner
 Left-Rear Corner
 Right-Front Corner
 Right-Rear Corner
 Damage
 Damage

Overall Appearance:

	Good	Fair	Poor	Comments: <u>X1 GLOBE NOT WORKING</u>
Control Station/Operator Station	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Sheet metal/Fiberglass Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Paint	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Control Station

	Operates			Comments:
	Yes	No	N/A	
Operator Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Gauges Operational?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Hour Meter
 Gauges
 Damage
 Damage

Engine or Electric Motor:

Power:	Diesel <input checked="" type="checkbox"/>	Gas <input type="checkbox"/>	Electric <input type="checkbox"/>	
	Yes	No		
Does it start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>		Comments: <u>- JUST JUMP STARTED TO TEST STARTER</u>
Did it need to be jumped?	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>MOTOR & LIGHTS.</u>
Acceptable Power	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>- NO BATTERY INSTALLED</u>
Unusual Noises	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<u>- LEAK AT THE ENGINE VALVE COVER</u>

Right Side hood open
 Left Side hood open

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Landing Gear / Outriggers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>- SOME LIMIT SWITCHES</u>
Frame Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>AT THE MAST NEED</u>
Trailer Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>NEW.</u>
Trailer Electrical Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trailer Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Switches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>- X1 LIGHT/GLOBE</u>
Light Tower (Take picture with tower up)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>NOT WORKING</u>
Lights (Take picture with lights on)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>- DAMAGED JOCKEY</u>
Power Cables	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>WHEEL - BENT WHEEL</u>

Hitch
 Lights on
 Light Tower (Extended)

Tire Condition:

Left	Right
Brand- <u>GOODYEAR</u>	Brand- <u>EVENT</u>
Size- <u>205R16LT</u>	Size- <u>205/80R16</u>
Condition- <u>GOOD</u>	Condition- <u>GOOD</u>

Tire pictures at a 45 degree angle showing the tread and side walls

Left
 Right