

Coates Inspection Checklists

DINGO AND TRAILER

Photos

Asset # 100196

General Information:

*** Copy Data Plate information in this section ***

Type of Tool: TRAILER
 Make/ Model: Z93
 Year: 2012
 Serial Number: 679T20AEBSBOATC
101

Engine / Motor - Make / Model: _____
 Engine Serial Number: _____
 Meter Reading: _____

Data Plate

Comments:

Features:

List features or options for the machine:

Machine Type:

Frame Mount

Trailer Mount

AC / DC Range

Engine Horsepower

Auxiliary Power

Leads

Leads Length

Yes

No

4-Corner Photos

- Left-Front Corner
- Left-Rear Corner
- Right-Front Corner
- Right-Rear Corner
- Damage
- Damage
- Damage

Overall Appearance:

Good
 Fair
 Poor

Switches/cords
 Sheet metal/Fiberglass Condition
 Paint
 Fit for Designed Purpose

Control Station

Operates
 Yes
 No
 N/A

Comments:

Engine or Electric Motor:

Power: Diesel Petrol Hydraulic Electric Air
 Does it start? Yes No
 Did it need to be jumped?
 Acceptable Power
 Unusual Noises

Comments:

- Hour Meter
- Operator Controls
- Safety devices
- Guages
- Damage
- Damage

Hydraulics

Operates
 Yes
 No
 N/A

Leaks

Yes
 No
 N/A

Comments:

Wiring & Lights

Damaged
 Yes
 No

Comments:

Chassis:

Good
 Fair
 Poor
 Inoper
 Missing
 N/A

Comments: TOW HITCH REMOVED, CAN NOT BE TOWED

- Frame condition
- Handles/Lifting points
- Guards condition

Tyre Condition:

Left - Front

Brand-
Size-
Condition-

Left - Rear

Brand-
Size-
Condition-

Right - Front

Brand-
Size-
Condition-

Right - Rear

Brand-
Size-
Condition-

Tire pictures at a 45 degree angle showing the tread and side walls

- Left-Front
- Left-Rear
- Right-Front
- Right-Rear

R/H RIM IS BENT.

*R/H STUB AXLE BENT
 BROKEN WHEEL STUDS*

** CAN NOT BE
 TOWED*