

Coates Hire Pre Divestment Inspection Checklist

Trucks / Motor Vehicles

Description Mitsubishi 6+ tray Asset # 1100946 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate Information in this section ***

Make/Model Mitsubishi Fuso 4x4 FG84DF Engine/Motor - Make/Model _____
 Year 2010 Engine Serial Number 4M50D49913
 Serial Number 2031287 Meter Reading 260096 kms.
 Comments: VIN JLFFG84DEOKJ10024

Features:
 Pickup Flat Bed Dump Boom Other Comments: _____
 Drive System 2WD 4WD Power Take Off Yes No
 Axle Weights Rating: Front _____
 Axle Weights Rating: Rear _____
 Registration Information Number 1H04PM Year 2010

Overall Appearance:

	Good	Fair	Poor	Comments:
Control Station/Operator Station	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Sheet metal/Fiberglass Condition	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Paint	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Operator Station	Good	Fair	Poor	N/A	Comments:		
Seat Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>Small crane Maxlift n130</u> <u>not in use - out of service &</u> <u>servicable year</u>		
Steering Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
Powertrain Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
Hydraulic Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>			
	Operates			Operates			
Safety Belt	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	Yes	No	N/A
Gauges	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioner	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heater	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					Horn	<input type="checkbox"/>	<input type="checkbox"/>
					Warning Alarms	<input type="checkbox"/>	<input type="checkbox"/>
					Odometer	<input type="checkbox"/>	<input type="checkbox"/>
					Wipers	<input type="checkbox"/>	<input type="checkbox"/>

Engine or Electric Motor:
 Power: Diesel Gas Comments: _____
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No
Overheats quick. Suspected blown head gasket or cracked head.

Transmission
 Transmission Auto Manual Hydrostatic No. Speeds 5 Comments: _____
 Operates Yes No N/A _____
 Forward Reverse Shifting
 Clutch Parking Brake Brakes
Clutch & Brakes average.

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Bumpers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Windshield Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trailer Electrical Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Work Body Function	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- _____	Brand- <u>N/A</u>	Brand- _____	Brand- <u>N/A</u>
Size- _____	Size- _____	Size- _____	Size- _____
Condition- <u>New</u>	Condition- <u>Need replacing</u>	Condition- <u>New</u>	Condition- <u>Need replacing</u>

Full Name of Employee completing inspection: Thys Stryker Branch where inspection completed: _____

Any other known issues, faults:

