

Coates Hire Pre Divestment Inspection Checklist

Boom Lift (Electric or Internal Combustion)

Name Luke Branch Whyalla
 Description 45' knuckle Asset # 1152787 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/ Model Genie Z-45/25JRT Engine/Motor - Make/Model Deutz
 Year 2015 Engine Serial Number _____
 Serial Number 24525140-515 Meter Reading 963

Comments: _____

Features: Max Lift Height 13.7m Comments: _____
 Drive System 2WD 4WD Platform size 1.8 x 0.75
 AC Chord to Basket Yes No Battery Charger Yes No
 Air to Basket Yes No Generator Yes No
 Does Basket Rotate Yes No Outriggers Yes No
 Knuckle Boom Yes No Extendable axles Yes No
 Straight Boom Yes No Articulating Jib Yes No

Overall Appearance: Good Fair Poor Comments: _____
 Control Station/Operator Station Good Fair Poor
 Sheet metal/Fiberglass Condition Good Fair Poor
 Paint Good Fair Poor
 Lights Good Fair Poor

Control Station Operates Yes No N/A Comments: _____
 Operator Controls: Platform Yes No N/A
 Operator Controls: Ground Yes No N/A
 Gauges Operational? Yes No N/A

Engine or Electric Motor: Power: Diesel Gas Dual Fuel Electric
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No

Hydraulics Operates Yes No Leaks Yes No Comments: _____
 Pump Yes No Yes No
 Hoses Yes No Yes No
 Cylinders Yes No Yes No
 Drive Motors Yes No Yes No
 Brakes Yes No Yes No
 Parking Brakes Yes No Yes No

Chassis: Good Fair Poor Inoper Missing N/A Comments: _____
 Frame Condition Good Fair Poor Inoper Missing N/A
 Mast/ Boom Sections Good Fair Poor Inoper Missing N/A
 Boom Extension Wear Guides Good Fair Poor Inoper Missing N/A
 Basket Condition Good Fair Poor Inoper Missing N/A
 Outriggers and Pads Condition Good Fair Poor Inoper Missing N/A
 Rotational Gear Condition Good Fair Poor Inoper Missing N/A
 Extendable Axle Good Fair Poor Inoper Missing N/A
 TurnTable Bearing Play Good Fair Poor Inoper Missing N/A

Tyre Condition: Left - Front Left - Rear Right - Front Right - Rear
 Brand- Outrigger Brand- Brand- Brand-
 Size- 315/45R220 Size- Size- Size-
 Condition- Fair Condition- Condition- Condition-

Definium Device fitted? Yes No Definium device returned to BU ASM

