Description Ligh	1+ 10	ver	Cu	be	Asset	t# <u>\</u>	207	182	7_	Servic	e Job#	4130	1886
This checklist is a record of a inspection and assessment of from defects in materials and Competition and Consumer A Coates which conditions, war Conditions of Sale apply to thwww.coateshire.com.au.	of the equipment workmanship Act 2010, nor cranties and one sale of all u	ent. The eq p, or compl statutes, ru bligations of used equip	uipment is lies with all ules or regu cannot, or o ment and th	used and so relevant law ulations from cannot to a l his checklist	old as is. C ys, Australi time to tin mited exte should be	oates doe an Standa ne in force ent be exc	es not war ards, licer e in Austra luded, res	rrant that th nce or perm alia which ir stricted or m	ne equiproit require mply cer nodified.	ment is new, ements. Noth tain condition The Coates	fit for purpo ing herein is or warrai Hire Used	ose, of mero shall limit th nties or imp Equipment	chantable quality, for those provisions of those obligations on Terms and
General Information:	*** Copy Dat	a Plate info	ormation in	this section	***								
Make/ Model 🔥	ATILAS CA	DECO/H	HAIGHT	185†	/ Motor - M	lake / Mod	HA HA	ITZ 1	1B50	T-3		¥ 2	
	2018			Linguis / Motor Make / Moder				1618 014918					
_	ES#204179						8102 HRS.			110			
Serial Number	Serial Number EST2041T9				Meter Reading 81				٥,				
Comments:	11												
i i just ja i													
Features: List featur	es or options	for the ma	chine:	·		-							
Number of Lights Height of Mast	28 4 8m			age per light rator KVA	350 u	-/1110	TED	Commen	ts:				<u> </u>
Power Outlets Qty Single Qty 3 Pha	Phase W/	A A		s per outlet s per outlet		-						3	3
Overall Appearance:				C- 1			,						
Control Station\Operator Stat Sheet metal\Fiberglass Cond Paint Lights	tion .	ood Fa		or -NA	Comme	nts:						Al	
Control Station												44	
Operator Controls Gauges Operational?		No N	/A	ments:						7		,	
Engine or Electric Motor:													
Power: Diesel Does it start? Did it need to be jumped? Acceptable Power Unusual Noises	Yes I	No -	Electi	ric 🗌	Comme	nts:	* &			,			
Chassis													
Landing Gear / Outriggers Frame Condition Trailer Lights Trailer Efectrical Connections Trailer Brakes Switches Light Tower (Take picture wit Lights (Take picture with ligh Power Cables	th tower up)		Fa P P P P P P P P P P P P P P P P P P P	ir Poor	Inoper	Missing		Commen	F	PHOTÁS E-MAIL.		SEVI	THROUGH
Tyre Condition: WA Left - Front	Lef	t - Rear			1	Comme	nts:						
Brand-	Bra	nd-		/	4								
Size-	Size	9-			4								
Condition-	Cor	ndition-					-						
Any other known issues, fa	ults: p	AST	CYLINT	PER LE	AKING	, 12∨	OLTS	ALTERN	ATOR,	/CHARG	ER MOT	WORK	LING
								20			.9	Ga :	
* 8													
Issue 1.1				1/1/201	3				AST-C	L-011A Asse	t Inspectio	n Checklist	- Light Tower

Coates Hire Pre Divestment Inspection Checklist Light Towers