



## **DISCLAIMER: Second-Hand Plant Condition and Safety**

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

### **Important Information**

#### **Safety & Compliance of the Plant**

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed Condition Report** sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

#### **Operational Safety Notice**

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

#### **Operating condition of the plant**

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



## Used Sale Safety & Compliance Check

MHE-000265 / GS3016D-5577 / Timothy Hodson / 27/03/2026 / Other / GS1932

Complete

Flagged items	0
Report ID	MHE-000265
Technician Name	Timothy Hodson
Conducted on	27/03/2026 2:30 PM AEST
Branch	Brisbane
Unit Details	
Equipment No.	GS3016D-5577
Brand	Other
Genie	
Model	GS1932
Mast ID	NA

### Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8

### Observations Summary

#### Truck Category

Category 8 - Access Equipment

Enter date of commission and ensure photo of compliance plate uploaded

16/02/2017



Photo 9

Is regulatory servicing up to date

No

Are emergency controls and retrieval system functioning correctly

Yes

Are visual and audible alarms (inc. flashing light/strobe and beeper/squawker) functioning correctly

Yes

Are harness anchor points in good condition

Yes

Are all cables, wiring harness etc. in good condition and secure

Yes

<b>Are wheels and tyres in serviceable condition</b>	Yes
<b>Do brakes function</b>	Yes
<b>Are all placards, labels, warnings and control markings legible</b>	No
Very worn and not legible	
<b>Are operator's manual in machine and legible</b>	Yes
<b>Are outriggers/stabilisers in serviceable condition</b>	N/A
<b>Is guardrail system including gates with self-closing action in serviceable condition</b>	No
<b>For boomlifts, is slew lock pin with machine and in serviceable condition</b>	Yes
<b>For boomlifts, is slew brake system in serviceable condition</b>	Yes
<b>Are there any visual structural defects or damage</b>	No
A lot of corrosion	
<b>Do all drive, speed and lift functions work correctly including any speed limiting devices</b>	Yes
<b>If a secondary guarding system is fitted is it functioning correctly</b>	N/A

**Additional Observations & Actions**

**List any other notable defects or faults e.g. ROPS/FOPS damage etc.**

Machine requires a thorough clean.

**Technician Sign off**



Timothy Hodson  
27/03/2026 2:43 PM AEST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9