Coates Hire Pre Divestment Inspection Checklist		
Generators (Diesel or Petrol)		
Description 40KUA Asset # 123 8287 Service Job #	` !	
Note that this internal checklist is merely a physical and not structural inspection of the machine with disclosure of any known issues at the time to assist in making a condecision on the viability of that item. At the discretion of Coates Hire, this report may be available to potential buyers. It is the buyer's or bidder's sole responsibility to furth and repair the item and ensure its compliance with all relevant legislation before being used and to ensure that it is maintained in a fully operational, safe and serviceable condition.	er assess	
General Information: *** Copy Data Plate information in this section ***		
Make/ Model JCB C30RS Engine / Motor - Make / Model JCB		
Year 2019 Engine Serial Number 49 08501940		
Serial Number PARMD 3 IF J 216 4425 Meter Reading 9986		
Comments:	-	
	- :	
Features: List features or options for the machine:		
Comments:  Generator Type Single Phase ☐ 3 Phase ☑ ☐ 3 Phase ☑ ☐ 3 Phase ☑ ☐ 3 Phase ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		
Frame mount Trailer mount	-	
Generator KVA Rating 40	-	
Power Outlets Qty Single Phase Amps per outlet 15_A		
Qty 3 Phase 2 Amps per outlet & A X SOA X		
Overali Appearance:		
Good Fair Poor Comments:  Control Station\Operator Station		
Control Station\Operator Station	- '	
Lights	-	
Control Station Comments:		
Operates Yes No N/A	<b>-</b>	
Operator Controls	-	
Engine: Comments:		
Power: Diesel 🗍 Petrol 📋		
Yes No Does it start?		
Did it need to be jumped?		
Unusual Noises		
Chassis Good Fair Poor Inoper Missing N/A Comments:		
Landing Gear / Outriggers		
Trailer Lights		
Trailer Brakes	-	
Power Cables		
Tyre Condition: Left - Front Left - Rear Right≠ Front Right - Rear		
Brand- Brand- Brand-		
Size- Size- Size- Size-	<u> </u>	
Condition- Condition- Condition		
Any other known issues, faults:		
2 x DOOR MANDLET BROKEN		