



VCV Brisbane South

In Progress

Date 23/06/2015

Quote No. MFLa2015000084

Version 0

Alternative 1

Your ref.

Technical Specification

FH13 HA 6x4 Tractor Air Ride Chassis 201185

Truck Use

B-Double
Well maintained surfaced roads >95% driving distance
Long distance transport cycle
Predominantly flat topography
Without dust shields on drive axle brakes
Gross combination weight 70.0 tonnes
Van body/box body/curtain sider

Core Components

Globetrotter XL cab
3200mm wheel base
Eu5 SCR Selective Catalytic Reduction
Eu5 SCR engine, 13C litre, 540hp, 2600nm
Engine brake, VEB+
Volvo Eu5 I-shift 12 speed automatic transmission (2600nm)
Australian road friendly certification
Single reduction tandem 23t GCW70t
Rear axle ratio 3.40:1

Packages

Sound system-advanced
Safety package plus

**VOLVO TRUCKS.
DRIVING PROGRESS**





VCV Brisbane South

In Progress

Date 23/06/2015
Quote No. MHA2015000084
Version 0
Alternative 1

Chassis

2 leaf parabolic front springs (normal stiffness)
Front axle load 7.5 tonnes
Front stabiliser bar-medium stiffness
Rear axle load 21 tonnes
Rear stabiliser bar-normal stiffness
Front disc brake-standard 430mm diameter-solid
Electronic brake system package
24v/12v trailer lighting voltage converter
24v/12v trailer ABS voltage converter
Frame section thickness 8mm
Across frame battery box
Two batteries 225 Ah
Battery charge indicator (in the DID)
Isolation toggle switch LHS of chassis
RHS 650 litre alloy fuel tank with steps
LHS 650 litre alloy fuel tank with steps
AdBlue tank 150 litres (underbelly)
Fuel tank cap with lock
Raised horizontal muff with vertical RHS outlet
Chromed steel exhaust stack
Exhaust heat shield
7 pin electrical trailer connection
Trailer brake connections (suzi coils)
Hand controlled trailer brake
Spray suppression on drive axles
LED tail lights

Rims and Tyres

10 stud dura-bright alloy disc rims
Steer tyre 295/80 R22.5
BRIDGESTONE, R150-II
Drive tyre 11R 22.5
BRIDGESTONE, M722
Jack, 15 tonnes
Toolkit extended
Tyre inflation hose (18 metres)

Sport tyre + wheel

Powertrain Equipment

Fuel optimized gear changing software
Manual gear shift in auto mode
Driving conditions - good
Standard I-shift PTO functions
Transmission Oil Cooler (air+water)
Air cleaner with second filter element

VOLVO TRUCKS.
DRIVING PROGRESS





VCV Brisbane South

In Progress

Date 23/06/2015

Quote No. MHA2015000084

Version 0

Alternative 1

Alternator, 150 Ampere

Cab Interior - Driving

Steering wheel material - standard
Mechanical instrument cluster with colour DID.
Dashboard trim, skylark/raven
Standard cruise control
ESP package (trailer combinations with ABS)
Electronically controlled air conditioning
Electric windows
Interior side sunvisor - driver's door
Interior sunvisor-front (manual)
Lower centre section of dash - pull out drawer
Upper-cup holders & lower-pull out drawer
CENTER SECTION DASH PANEL TOP, TRAY
Reversing alarm
Fire extinguisher 2.5 kg
Writing pad

Cab Interior - Living

Textile interior trim, matching grey & beige colours
Drivers seat, heated & air suspended.
Drivers seatbelt pretensioner
Passenger relax seat with swivel and tilt
Armrests both sides - driver's & passenger's seat
Seat armrest upholstery - leather
Instep grab handle - standard
Floor mats-textile & rubber
Lower bunk 955mm wide, extendable (non reclinable)
Mattress lower bunk - semi firm
Without mattress overlay
Bunk restraint
Luxury sleeper control panel
Under bunk storage
Rear upper cab storage-245 litres, 440mm
33 litre refrigerator under lower bunk
Bottle holder in driving & resting areas
12v outlet in resting area
Interior white and red (night) light
Flexible reading lamp (snake light)
Roof hatch-manual - tinted glass - rear opening
Vanity mirror
Auxiliary shelf, front upper storage

→ Air Ride

VOLVO TRUCKS.
DRIVING PROGRESS





VCV Brisbane South

In Progress

Date 23/06/2015

Quote No. MHA201500004

Version 0

Alternative 1

Cab Exterior

Standard exterior trim level. (refer Fact Sheet.. disregard "FH16 Standard". not offered)

Winter white cab (other cab colours via RTO)

Central door locking-Key

Bumper-plastic

Wildbar

Insect net in front of radiator

Electrical cab tilt pump

Front cab suspension-mechanical spring

Rear cab suspension-mechanical spring

Electrically heated & operated flat glass mirrors

Exterior sunvisor

Aero dynamic roof kit

Aero dynamic cab side kit

Windscreen stoneguard

Standard head lamps

Without headlamp protection

Head lamp adjustment

Integrated driving lights

Integrated fog lights

Identification lamps-amber

Beacon light wire preparation

Yellow chassis grab handles

Aux. spot light wiring preparation (front of cab)

Globetrotter illuminated cab sign prep kit

Globetrotter XL decal

Single electric Jericho air horn (behind grill)

Antenna for CB radio, single antenna

Storage compartments under cab-both sides

→ Bullbar + crossbar ??

Weather Shields

Protectors

Straight exhaust
Rain hat.

Superstructure Preparations

5th wheel L-profiles

Fifth wheel light

2 x H3/70W work lamps with white lens.

Body builder module

Body builder chassis electrical interface, 1 x 7 pin connector

2 flexible switches (AUX 1 & AUX 2) + additional 4 flexible switches

4 extra bi-stable switches wired to BBM

**VOLVO TRUCKS.
DRIVING PROGRESS**





VCV Brisbane South

In Progress

Date 23/05/2015
Quote No. MHa2015000084
Version 0
Alternative 1

Telematic Services

Assistance switch & microphone-VAS (Volvo Action Service)
Telematics gateway with 3G & WLAN
TESP (Dynafleet) with transport info
Dynafleet-fuel & environment service-monthly
Dynafleet-positioning service-monthly

Options

Internal Workshop

Turntable Jost Jsk37
Walk Plate
UHF Radio TX4500
Chrome Hub & Nut Covers
Tint Windows
Seat Covers

External Workshop

Polish Tanks
Electric Cooling System Koolkat

Ecowind

2 x Roo Shoo

2 x Lightforce

**VOLVO TRUCKS.
DRIVING PROGRESS**





VCV Brisbane South

In Progress

Date 23/09/2015
Quote No. MHa2015000084
Version 0
Alternative 1

Vehicle Sales Price \$ 255,000.00

Total Price \$ 255,000.00

GST Amount

Model 10.00 % \$ 25,500.00

Total Price (Incl. GST) \$ 280,500.00

The above pricing does not include Registration, Stamp Duty, CTP Insurance or any other Government charges associated with On Road Costs.

Yours sincerely

Michael Hamilton
VCV Brisbane South

**VOLVO TRUCKS.
DRIVING PROGRESS**




MODEL RANGE



Volvo Trucks. Driving Progress

FH13 HA 6x4 Tractor Air Ride FH 64 T3HA



Chassis Dimensions [mm]

WB Wheelbase	3000	3200	3600
A Overall Chassis Length	6540	6740	7140
D Centre of rear axle to back of cab	2006	2206	2606
T Theoretical Wheelbase	3685	3885	4285

Chassis Weights [kg]

Front Axle	5185	5105	5215
Rear Bogle	3495	3505	3525
Kerb Weight	8680	8700	8740

Turning Diameter [mm]

Turning Circle Diameter Kerb to Kerb	13300	13900	15100
Turning Circle Diameter Wall to Wall	14700	15300	16500

Plated Weights [kg]

	Plated	Design
Gross Vehicle Weight	23000	28100
Gross Combination Weight	42500	44000
Front Axle	6500	7100
Rear Bogle	16500	21000

Important Notes

Chassis Dimensions

Cab Height: +305 mm for CAB-HSLP, -203 mm for CAB-LSLP, +450 mm for CAB-XHSL.

D-measure includes a front clearance of 50 mm and for rigid trucks also a subframe of 100 mm.

Height can vary ± 20 mm for leaf and ± 15 mm for air suspension.

All dimensions are for unladen chassis and any tag axles down. Chassis height used: CHH-HIGH.

Height change when chassis height CHH-MED, FRAME300: -60 mm.

Weight and dimensions are based upon the following tyres:

Front Axle Tyres: 295/80R22.5

Drive Axle Tyres: 295/80R22.5

Chassis weight includes oil, water, AdBlue, 70 litres fuel and without driver. Kerb weight can vary $\pm 3\%$.

Turning diameters are theoretically calculated.

Legal weights can differ from country to country.

For more detailed weight information, including optional equipment weights, ask your Volvo sales contact to enter your specification into the Volvo Weight Information system (WIS).

Do NOT use this drawing for bodybuilding. Refer to Volvo Bodybuilder Instructions and chassis assembly drawing FH64T3HA.

MODEL RANGE

FH13 HA 6x4 Tractor Air Ride FH 64 T3HA

Truck use

- **RC-ROUGH** Operating class on/off road
- **RC-SMOOTH** Well maintained surfaced roads >95% driving distance

Core components

- **FH-SLP** Sleeper cab
- **FH-XHSL** Globetrotter XL cab
- **EU6SCR-M** Eu5 SCR Selective Catalytic Reduction (mandatory)
- **D13C460** Engine, 13C litre, 460hp, 2300mm
- **D13C500** Engine, 13C litre, 500hp, 2500mm
- **D13C640** Engine, 13C litre, 640hp, 2600mm
- **EBR-VEB+** Volvo Engine Brake + (VEB+)
- **AT2612D** Volvo I-shift 12 speed automatic transmission (2600mm)
- **RVC1** Australian road friendly certification
- **RTH2610B** Volvo RTH2610B hub reduction rear axles
4 planet gears per hub
Ade rating: 26,000 kg
115 tonne train weight
(Application approved)
- **RTS2370B** Single reduction tandem 23t GCW70t

Packages

- **OC1BED** Resting package 1 person
- **OC1BED+** Resting package plus- 1 person
- **OC2BED** Resting package 2 persons
- **OC2BED+** Resting package plus- 2 persons
- **AUDHIG** Sound system-advanced
- **AUDHIGP** Sound system-advanced power
- **OCVSGTR** Visibility package Globetrotter
- **OCVSI** Visibility package
- **OCVSI+** Visibility package - plus
- **OCASAFE** Safety package
- **OCASAFE+** Safety package plus

Chassis

- **FST-PAR** Parabolic leaf spring front suspension
- **FST-PAR3** 3 leaf parabolic front springs (stiffer than normal)
- **FAL6.5** Front axle load 6.5 tonnes
- **FAL7.1** Front axle load 7.1 tonnes
- **FAL7.5** Front axle load 7.5 tonnes
- **FSTAB** Front stabilizer, normal stiffness
- **FSTAB2** Front stabiliser bar increased stiffness
- **FSTAB3** Heavy duty front stabiliser bar
- **RAL17** Rear axle load 17 tonnes
- **RAL21** Rear suspension load rating: 21,000 kg
- **RSTAB1** Rear stabiliser bar
- **RSTAB3** Heavy duty rear stabiliser bar
- **ACTST-TO** Volvo Dynamic Steering
- **EBS-MED** Electronic Brake System (EBS) contains
ABS, Traction control, Hill start aid
Off lock control, Brake assist
Wheel brake monitoring, EBS status
- **TRCO-12V** 24v/12v trailer lighting voltage converter
- **TABS-12** 24v/12v trailer ABS voltage converter
- **FST7070** Frame section thickness 7mm
- **FST8080** Frame section thickness 8mm
- **FIL-TXEB** Liner (inner) - trans x-mm to end of bogie
- **BBOX-AC** Across frame battery box
- **2BATT225** 2x225 Ah batteries
- **BATTAMP** Battery amperage indicator (in the DID)
- **MSWI-C** Isolation toggle switch LHS of chassis

- **MSWI-R** Isolation switch on key fob (press door lock twice to isolate)
- **R385A71S** RHS 385 litre alloy fuel tank with steps
Min volume 385l
Max volume 690l
- **L415A71S** LHS 415 litre alloy fuel tank with steps
Min volume 415l
Max volume 690l
- **ADB064** AdBlue tank 64 litres (LHS)
- **ADB090** AdBlue tank 90 litres (LHS)
- **ADB150** AdBlue tank 150 litres (underbelly)
- **ADB190** AdBlue tank 190 litres (underbelly)
- **ADTC-BF** AdBlue tank cover-bright finish
- **FCAP-L** Fuel tank cap with lock
- **ESH-HGH** Muffler horizontal, right exhaust outlet
- **ESH-VERT** Muffler horizontal, vertical exhaust outlet on right hand side
- **ESHQVERT** Raised Horizontal MultiVertical outlet
- **EXST-SSP** Polished stainless steel exhaust stack
- **EXST-STC** Chromed steel exhaust stack
- **TBC-AUS** Trailer brake connections (suzi coils)
- **TRBR-HCR** Hand controlled trailer brake, reduced pressure
- **TL-LED** LED tail lights

Rims and Tyres

- **RT-ALDPD** 10 stud dura-bright alloy disc rims
- **RT-ALDU** 10 stud alloy disc rims
- **RT-ALPDU** 10 stud polished alloy disc rims
- **RT-STEEL** 10 stud steel disc rims
- **SPWT-D** Spare rim & tyre equal to drive
- **SPWT-F** Spare rim & tyre equal to steer
- **SWCP-T2** Transport mounted spare wheel
- **JACK-16T** 16 tonne capacity jack and brace
- **TOOLKIT** Tool kit complete
- **INFLAHOS** Tyre inflation hose (20 metres)

Powertrain equipment

- **TP-DIGON** Distribution and Construction optimized gear changing software
- **TP-FUEC** Fuel optimized gear changing software
- **TP-HD** Heavy duty (OCM) control software
- **AMSO-AUT** Manual gear shift in automatic mode.
- **AVC-ENH** AMT Vocational option - enhanced
- **APF-ENH** Enhanced I-shift PTO functions
- **TC-MACH2** High performance transmission cooler
- **ACL1ST-S** Air cleaner with two stage filter element
- **24AL120B** High capacity alternator, 120 Ampere.
- **24AL150B** Alternator, 150 Ampere
- **PTER-DIN** Power Take Off / splined shaft groove (female) DIN5162.
- **PTER1490** Rear engine mounted power-take-off with flange SAE 1410
- **HPE-F101** F1-101 Hydraulic pump rear engine mounted
- **HPE-F41** F1-41 Hydraulic pump rear engine mounted
- **HPE-F61** F1-61 Hydraulic pump rear engine mounted
- **HPE-F81** F1-81 Hydraulic pump rear engine mounted
- **HPE-F81** F1-81 Hydraulic pump rear engine mounted
- **HPE-T63** F2-63/63 twin flow hyd pump rear engine mounted
- **HPE-T70** F2-70/53 twin flow hyd pump rear engine mounted
- **HPE-V120** V1-120 variable pump rear engine mounted
- **HPE-V46** V1-46 variable pump rear engine mounted
- **HPE-V76** V1-76 variable pump rear engine mounted
- **PTR-D** Low speed PTO with DIN connection
- **PTR-DH** High speed PTO with DIN connection
- **PTR-DM** Medium speed PTO with DIN connection

■ Standard Equipment

□ Optional Equipment

For more detailed information about cab and powertrain equipment, please refer to separate specification sheets.

For all possible options and combinations of options please consult your Volvo sales contact who can create a specification to match your requirements using the Volvo Sales Support system (VSS).

The factory reserves the right to modify design and change equipment without previous notification.
The specification can vary from country to country.

MODEL RANGE

FH13 HA 6x4 Tractor Air Ride FH 64 T3HA

☐ PTR-F	Rear PTO trans. flange 100% speed	☐ GRABHI-B	Instep grab handle - standard
☐ PTR-FH	High speed PTO with flange connection	☐ GRABHI-L	Instep grab handle - leather bound
☐ PTR-FL	Low speed PTO with flange connection	☐ FMAT-RUB	Floor mats-rubber
☐ PTRD-D	PTO with 2 DIN connections rear + 1 DIN connection front	☐ FMAT-TX2	Floor mats-tertile & rubber
☐ PTRD-D1	PTO with 1 DIN + 1 flange connection rear + 1 DIN connection front	☐ LBK30F	Lower bunk 815mm wide
☐ PTRD-D2	PTO with 2 flange connection rears + 1 DIN connection front	☐ LBK30FRE	Lower bunk 815mm wide, electrically reclining
☐ PTRD-F	PTO with 1 DIN + 1 flange connection rear	☐ LBK30FRM	Lower bunk 815mm wide, manually reclining
☐ HPG-P101	F1-101 hydraulic pump gearbox mounted	☐ MATL-SF	Mattress lower bunk - semi firm
☐ HPG-F41	F1-41 hydraulic pump gearbox mounted	☐ OLMAT-SA	Mattress overlay - basic
☐ HPG-F61	F1-61 hydraulic pump gearbox mounted	☐ TBK70AD	Top bunk 700mm wide, foldable & height adjustable
☐ HPG-F81	F1-81 hydraulic pump gearbox mounted	☐ TBK70F	Top bunk 700mm wide, foldable
☐ HPG-V120	VP1-120 hydraulic pump gearbox mounted	☐ SLCP-BAS	Standard sleeper control panel
☐ EIDLES	Engine idle shutdown (2.5 minutes)	☐ SLCP-LUX	Sleeper control panel
☐ STWM-LE	Steering wheel material - leather	☐ SAFE	Safe box at bed-end
☐ INST-MED	Mechanical instrument cluster with (H)	☐ RUS-BAS	Rear upper cab storage-154 litres, 300mm
☐ DTRI-SRA	Dashboard trim, skyjack/aven	☐ RUS-HIG	Rear upper cab storage-245 litres, 440mm
☐ CRUIS-E	Cruise control (can be used only with TP-FUEC)	☐ TABLE	Table
☐ CRUISEC	Cruise control	☐ REFR-RUS	26 litre refrigerator in upper rear storage
☐ ESP-BAS1	ESP package (trailer combinations with ABS)	☐ REFRIG	33 litre refrigerator under lower bunk
☐ ESP-BAS2	ESP package (trailer combinations without ABS)	☐ MICRO-PK	Prep kit for microwave
☐ HWS-AC	Adaptive cruise control & forward collision warning	☐ BOTH-D	Bottle holder in driving area
☐ LSS-DW	With lane departure system	☐ BOTH-DL	Bottle holder in driving & resting areas
☐ LCS	Lane change support	☐ BOTH-L	Bottle holder in resting area
☐ DAS-W	Driver alert support warning	☐ SOL12S	12v outlet in resting area
☐ RSENS-W	Rain sensor to activate wipers	☐ INLI-BAS	Interior night lights
☐ CU-ECC	Climate controlled air conditioning	☐ INLI-NL	Interior white and red (night) light
☐ IMMOBIL	Engine immobiliser	☐ INLI-NLD	Interior light including night light and dimmer function
☐ ALARM-B	Anti-theft alarm (cab)	☐ ARL-FLEX	Flexible reading lamp (snake light)
☐ WLIFT-AD	Electric windows	☐ RH-ETR	Roof hatch-electric - tinted glass - rear opening
☐ ISUNS-D5	Interior side sunvisor - driver's door	☐ RH-MTR	Roof hatch-manual - tinted glass - rear opening
☐ ISUNF-RE	Interior sunvisor-front (electric)	☐ VANMIR	Vanity mirror
☐ ISUNF-RM	Interior sunvisor-front (manual)	☐ AS-FUS	Auxiliary shelf, front upper storage
☐ CSPL-BXD	Centre section dash panel pull out drawer	☐ INFOT-PK	LCD screen mount - 6lgs max
☐ CSPL-SDR	Upper-cup holders & lower-pull out drawer	Cab exterior	
☐ CSPL-SDS	Dash panel-upper storage & lower in-slot	☐ EXTL-BAS	Standard exterior trim level
☐ CSPL-SS	Upper-cup holders & lower-storage area	☐ EXTL-ENH	Enhanced exterior trim level
☐ ADFS	2 din slots in front shelf	☐ LOCK-CTL	Central door locking-Key
☐ BUPALARM	Reverse alarm	☐ LOCK-REM	Central door locking with remote control
☐ LOADIND	Load indicator, electronic controlled suspension (SUSPL-EC)	☐ BUMP-B	Bumper-plastic
☐ REMC-MF	Multifunction wireless remote control	☐ BUMP-B2	Bumper-steel
☐ FIREX25A	Fire extinguisher 2.5 kg	☐ WILDBAR	Wildbar
☐ WRITPAD	Storable steering wheel fit clip board	☐ BUMP-SP	Bumper spoiler
☐ UPHTRI03	Teddie interior trim, matching grey & beige colours	☐ BUGNET	Insect net in front of radiator
☐ DST-CF5	Fully adjustable driver's comfort seat	☐ CTILT-P-E	Electrical cab tilt pump
☐ SBPRE-D5	Drivers seat belt pretensioner	☐ FCABS-A	Front cab suspension-air bellows
☐ PST-BAS1	Basic passenger's seat	☐ FCABS-M	Front cab suspension-mechanical spring
☐ PST-CF5	Fully adjustable passenger comfort seat	☐ RCABS-A	Rear cab suspension-air bellows
☐ PST-RX1	Passenger relax seat with swivel and tilt	☐ RCABS-M	Rear cab suspension-mechanical spring
☐ SBPRE-P5	Passenger seatbelt pretensioner	☐ MIRFLA3	Electrically operated flat mirrors
☐ ARMRE-BB	Armrests both sides - driver's & passenger's seat	☐ SUNV-H	Exterior sunvisor
☐ ARMRE-DB	Armrests both sides - driver's seat	☐ AD-ROOF	Aero-dynamic roof mounted deflector
☐ ARU-LEA	Seat armrest upholstery - leather	☐ AD-SIDEL	Aero-dynamic cab side deflectors
		☐ GUARD-W	Windscreen winguard
		☐ HL-BASIC	Standard head lamps

☐ Standard Equipment

☐ Optional Equipment

For more detailed information about cab and powertrain equipment, please refer to separate specification sheets.

For all possible options and combinations of options please consult your Volvo sales contact who can create a specification to match your requirements using the Volvo Sales Support system (VSS).

The factory reserves the right to modify design and change equipment without previous notification. The specification can vary from country to country.

MODEL RANGE

FH13 HA 6x4 Tractor Air Ride FH 64 T3HA

- HL-BHID Xenon head lamps high intensity discharge
- HL-CBL Bi-Xenon headlamps with Dynamic Bending Light
- HL-CLEAN Head lamp cleaning system
- HL-ADJ Head lamp adjustment
- DRL-LED V-shaped LED daytime running light
- DRVL2 Integrated driving lamps
- UDRNL Without driving lights
- FOGL-WC Integrated fog lamps
- CL-STAT Corner light static
- ASL-RF2 Auxiliary spotlights inside Globetrotter sign box
- IDLAMP-A Identification lamps amber
- BEACON-P Beacon light wire preparation
- SPOTP-F Aux spotlight preparation, 280W maximum
- ROS-ILP Globetrotter illuminated cab sign prep kit
- CSGN-GTR Globetrotter decal
- HORN-F15 Single electric Jericho air horns (behind grill)
- HORN-R25 Chromed air horns, two roof mounted
- ANT-CBR Antenna for CB radio, single antenna
- STUC-B Storage compartments under cab both sides

Superstructure

- 5WM-OBLP 5th wheel L-profiles
- SRWL-PK Wiring prep for chassis mounted reverse/working lamps-3 position switch
- SWL-PK Wiring prep for chassis-mounted working lamps-2 position switch
- WL-TA1W Fifth wheel light
- WLC-H2W 2 x H3/70W high mounted work lamps with white lens
- WLC-PKH Prep kit for high mounted work lamps
- WLC-PKL Prep kit for low mounted work lamps
- WLC-PKLH Prep kit for low and high mounted work lamps
- ECBB-HIG Body builder module
- BBCHA31 Body builder chassis electrical interface, 1 x 7 pin connector
- AESW2PK 2 flexible switches (AUX 1 & AUX 2) + additional 4 flexible switches
- AUXSW-4 4 extra bi-stable switches wired to BSM

Delivery services

- TGW-3GWL Telematics gateway with 3G & WLAN
- TESP-T TESP (Dynafleet) with transport info
- FMS-PK Fleet management system gateway

VOLVO

Volvo Truck Corporation
www.volvotrucks.com

VOLVO FH (4)

NEW VEHICLE WARRANTY

INTERNAL SALES GUIDE



FH (4)

VOLVO FH (4) - NEW VEHICLE WARRANTY COVERAGE

0-12mths / Unlimited kms (standard coverage)

- Applicable to VOLVO FH (4) vehicles New Series – delivered to Customer after 1st July 2014
- Applies up to 170t GCM; GCM applications over 170t will require prior approval from VGA

VOLVO DRIVELINE WARRANTY (ENGINE)

48 MONTHS / 800,000KMS / 12,500 HRS²

Coverage on the Volvo driveline including the following components on the engine:

- Cylinder block casting
- Cylinder liner and piston (2)
- Timing mechanism (2)
- Con rods
- Oil Cooler (2)
- Internal pipes (2)
- Internal seals (2)
- Engine brake (2)
- Intercooler (2)
- Coolant pump (1)
- Thermostat and housing (1)
- Turbocharger (1)
- Injectors (1)
- Cylinder head casting
- Valve mechanism (2)
- Crank shaft
- Oil pump and pickup pipe (2)
- Oil filter housing (2)
- Internal gaskets (2)
- Flywheel housing
- Flywheel (2)
- Exhaust/intake manifold (2)
- Fan (2)
- Radiator (2)
- Fuel pump (1)
- Injector harness (1)

VOLVO DRIVELINE WARRANTY (GEARBOX)

HWY¹

48 MONTHS / 800,000KMS / 12,500 HRS²

Coverage of the Volvo Driveline including the following components on the gearbox:

- Clutch housing
- Shafts and gears
- Synchro cones* (2)
- Sleeves* (2)
- Internal seals (2)
- Oil cooler (2)
- Transmission ECU (1)
- Gearbox casing
- Bearings
- Hubs* (2)
- Internal pipes (2)
- Splitter unit (2)
- Internal gear selector (2)
- Automated gear box (2)

VOLVO (ENGINE ONLY) - SPECIAL COVERAGE

49-60 MONTHS / 1,000,000 KMS / 12,500 HRS / 800,000 LITRES FUEL (3)

VOLVO DRIVELINE WARRANTY (DIFFERENTIAL)

HWY¹

48 MONTHS / 800,000KMS / 12,500 HRS²

Coverage on the Volvo driveline including the following components on the differential:

- Propeller shafts (1)
- Rear axle housing
- Differential gears
- Differential lock (2)
- Hub & hub reduction gears (2)
- Centre bearing (1)
- Differential casing
- Differential bearings
- Half shafts-axle (2)
- Universal joints (1)

CAB EXTENDED PROTECTION COVERAGE

36 MONTHS³

Cab Structure / Cab Corrosion

Disclaimer

These periods of coverage only apply to driveline components and are designed to protect you against the unlikely event of a major defect occurring within the driveline componentry. Driveline components are defined in the warranty booklet.

APPLICATIONS

HWY¹ - Highway / HD - Heavy Duty / EHD - Extra Heavy Duty / SHD - Severe Heavy Duty

FH (4)	Operating GCM	Months	Kilometres / Hours	Fuel Burn
Highway (HWY) Standard Coverage	Up to 90 tonne	0 - 12	Unlimited / 12,500	450,000 ltrs
Highway (HWY) Extended Coverage	Up to 90 tonne	13 - 48	800,000 / 12,500	450,000 ltrs
Heavy Duty (HD) Standard Coverage	91 - 131 tonne	0 - 12	Unlimited / 6,250	450,000 ltrs
Heavy Duty (HD) Extended Coverage	91 - 131 tonne	13 - 48	600,000 / 9,250	450,000 ltrs
Extra Heavy Duty (EHD) Standard Coverage	132 - 145 tonne	0 - 12	500,000 / 6,250	500,000 ltrs
Extra Heavy Duty (EHD) Extended Coverage	132 - 145 tonne	13 - 24	500,000 / 6,250	500,000 ltrs
Severe Heavy Duty (SHD) Standard Coverage	146 - 170 tonne	0 - 12	250,000 / 4,000	250,000 ltrs

Note: This is based on months, hours, kilometres or fuel consumed, whichever occurs first.

* = Not covered for wear.

- (1) = Items covered for 2yrs / 500,000kms / 6,250hrs / 500,000ltrs
 (2) = Items covered for 3yrs / 800,000kms / 12,500hrs / 450,000ltrs
 (3) = On Application - additional customer charges apply - refer to Warranty conditions

Applicable to VOLVO FH (4) vehicles - delivered to Customer after 1st July 2014

Release 1.3 01/12/2014

² Refer to Warranty booklet or Warranty Policy for more details on HD / EHD / SHD application warranty for driveline components

Special Coverage – Engine Only

- 49-60 months / 1,000,000 kms / 12,500 hrs / 800,000 litres fuel

Terms and Conditions

- On Application only - includes VGA 13L and 16L engines only.
- Must be purchased prior to delivery of vehicle.
(The extended engine warranty is customer charge – Please contact your Volvo dealer for details).
- Mid-Life maintenance requires mandatory components to be replaced at customer charge. At each scheduled maintenance interval (based on months / kms / hours / fuel, whichever occurs first), perform all maintenance repairs which are due for scheduled maintenance.
- If Mid-life scheduled maintenance is not completed, and any subsequent failure is caused by a mandatory replacement component, warranty is void.
- Recommended scheduled maintenance service intervals listed in table below should not impede any normal scheduled maintenance intervals as defined in any VOSP (Volvo Optimized Service Plan)

RECOMMENDED SCHEDULED MAINTENANCE

INCLUDES 500,000KMS "MID-LIFE" SUPPORT (CUSTOMER CHARGE)

Every 6 months / 50,000kms / 750hrs (1st)	Every 12 months / 100,000kms / 1,500hrs (2nd)	2.5 years / 500,000kms / 7,500hrs (3rd)
Basic Service - Inspect / Repair / Replace	Annual Service - Inspect / Repair / Replace	Annual Service - Inspect
• Replace lubricating filter • Replace lubricating oil • Replace engine fuel filter • Replace air filter • Replace coolant filter • Check air intake system • Visually inspect / replace oil seals & hoses • Inspect cooling system for leaks • Test coolant glycol & coolant additive • Inspect battery electrolyte levels, cables, connections for corrosion, chaffing & security etc. • Visually inspect engine wiring harnesses for chaffing & security • Inspect / replace belt tensioners, idler pulleys & fan hub	• Drain clean-oilpan • Operational check of exhaust system • Clean radiator / change air condenser coils • Pressure test charge air & cooling system • Inspect / service air compressor • Test/check starting electric system • Visually inspect engine mounting bolts • Clean crankcase breather • Adjust valves & engine brakes • Inspect/check turbocharger decelerates & waste gate actuator inert • Replace Adblue filter • Inspect / Service / Replace - Air compressor • Inspect / Service / Replace - Alternator • Inspect / Service / Replace - Adblue Dosing pump	Mandatory Replacement Components • Turbocharger • Fuel injectors • Engine sensors • Water pump • Fuel pump
(1) Perform maintenance checks which are due at scheduled period - whichever level occurs first (2) Note: These intervals should not impede any normal scheduled maintenance as defined in any VOSP (Volvo Optimized Service Plan) Mid-life component replacement costs: 13L - \$7,810.00 (parts only) 16L - \$8,250.00 (parts only) Prices shown are:- 1. GST inclusive 2. Subject to review based on CPI and other Market factors 3. Indicative only and may vary between participating dealers		

GET ADDED PROTECTION

WITH BOTH STANDARD WARRANTY AND EXTENDED WARRANTY COVERAGE (ENGINE ONLY)

Warranty Coverage		Warranty Period				Inclusions
		Years	Kms	Hrs	Fuel burn / litres	
Base Engine Warranty	Standard Warranty	2	400,000	6,250		
Base engine warranty - major components coverage for 13L and 16L engines	Standard Warranty	4	800,000	12,500		Includes following major components • Camshaft & following assemblies • Cylinder block • Cylinder head casting & bolts • Crankshaft & Main bearing bolts • Gear train gears • Connecting rods & bolts • Intake Manifold Casting
Extended Warranty - Engine Only	Extended Warranty - Engine Only	5	1,000,000	12,500	800,000	Refer to Warranty Policy

PC	Type	Code	Description (Original)	#
⑥	■	VO-9130476	SPLICE BLUE	10
⑥	■	VO-6781769	SPLICE RED	10
⑥	■	VO-984725	BOLT M6*16 FL	4
⑥	■	VO-990949	NUT M6 FL LOCKING	4
⑥	■	VO-994847	WASHER M6*18	8
	□		(TO INCLUDE WIRING BULLBAR INDICATORS)	
⑥	*	80	SUBLET - TYRERIGHT	
	□		STRIP & FIT 10X WHEELS. SUPPLY & FIT	
⑥	■	AU2-20572280	WHEEL 22.5 X 8.25	11
	□		1X BRIDGESTONE 295/80R22.5	
	□		INVOICE NO: 62576126	
	□		FORWARD & BACK	
⑥	*	91	WORKSHOP CONSUMABLES	
⑧ ⑥ <u>2015-07-15 - Mileage: 100 - Order nr: 8062335</u>				
⑥	⑥	LO-170	REGISTRATION	2.5
⑥	⑥	LO-170	TRAVEL TO NORTH SIDE	2
⑧ ⑥ <u>2015-07-15 - Mileage: 0 - Order nr: 8237230</u>				
⑥	*	000P43ALL	4300 Driversbag, Rsakit, Giveaways	
⑥	■	OTH-VTDRIVERSBAG	VOLVO DRIVERS BAG	1
⑧ ⑥ <u>2015-05-18 - Mileage: 125 - Order nr: 8236000</u>				
⑥	⑥	LO-812	FIT UP AERO KITS WHERE APPLICABLE	2.7
⑥	⑥	LO-850	REMOVE PLASTIC COVERING FROM	0.3
	□		INSIDE CAB	
⑥	⑥	LO-234	REMOVE PROTECTION STRIPS FROM	0.4
	□		TANK STRAPS	

PC	Type	Code	Description (Original)	#
⊖	⊞	OTH-NPNC/PCOVER	90-3 COVER KEYLOCK	2
⊖	⊞	OTH-NPNC/PLATCH	E3-15-25 LATCH KEYLO	2
⊖	⊞	OTH-NPNC/PKEY	E3-5-15 KEY KEYLOCK	2
⊖	⊞	MK-12AX128P150	TANK STRAP RUBBER	1
⊖	⊞	MK-1553-30540	BLK CONTACT ADHESI	1
⊖	⊞	MK-9711-9208086ARS	IMEX HUB CAP KIT	1
⊖	⊞	VO-1075226	WHEEL TRIM CHROME ALU-DISC	2
⊖	⊞	OTH-VSHEEPV4PAIRSB	VOLVO SHEEP PAIR V4 S/BELTS	1
⊖	⊖	LO-890	S&F WEATHER SHIELDS TO BOTH RH & LH SIDE DOORS	1.2
⊖	⊖	LO-773	S&F DURABRITE WHEELS	2
⊖	⊞	VO-84165756	WIND DEFLECTOR KIT	1
⊖	⊞	OTH-PXR1088C	ROUND BLACK 8.8" XPLOER D/L	2
⊖	⊞	VO-20552688	WHEEL NUT M22 FOR ALLOY RIMS	60
⊖	⊞	VO-993360	HOUSING	1
⊖	⊞	VO-983014	CABLE TERMINAL	2
⊖	⊞	VO-25617877	CABLE SEAL	2
⊖	⊞	VO-994847	WASHER M6*18	6
⊖	⊞	VO-994847	WASHER M6*18	6
⊖	⊞	VO-949746	CLAMP M12	12
⊖	⊞	MK-NARV56602	HEATSHRINK 1=1 150	1
⊖	⊞	VO-9130476	SPLICE BLUE	12
⊖	⊞	MK-NARV56306	CABLE TIE 1=10PK	1
⊖	⊞	UNK-NTH612269TB	SHUROO KIT	1
	⊞		INVOICE NO: 27023	
	⊞		INVOICE NO: 17878	
⊖	⊞	VO-6781769	SPLICE RED	3
⊖	⊞	VO-9130476	SPLICE BLUE	3

PC	Type	Code	Description (Original)	#
2015-07-24 - Mileage: 283 - Order nr: 8237211				
		LO-171	PRE-DELIVERY WITH PLATES	6.5
	*	10	TARE WEIGHT	
	*	80	SUBLET - DETAIL VEHICLE	
	E		P/O NO: 4104695	
2015-07-22 - Mileage: 283 - Order nr: 8237203				
	E		S3425 EMS, noise level, SW update. FH/FM (4) HDE13	4
		LO-922	S&F JOST JSK37CZ	
	E		185MM FEET, 16MM PLATE. 100MM FOC W/HOLES 50MM	2
		LO-840	S&F CHECKER PLATE WALK PLATE	
	*	80	SUBLET - S&F UHF	2
	E		P/O NO: 4104698	
		LO-771	S&F CHROME HUB & NUT COVERS	1.2
		LO-851	S&F L&R SHEEP SKIN SEAT COVERS	
	*	80	SUBLET - TINT WINDOWS	
	E		P/O NO: 4104696	
	*	80	SUBLET - SUPPLY CERT. FOR TURNTABLE	
	*	80	SUBLET - POLISH FUEL TANKS	
	E		P/O NO: 4104699	6
		LO-840	S&F SHUROO BEHIND BULLBAR	
		LO-352	S&F 2X LIGHTFORCE DRIVING LIGHTS	6
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2800500	EMS, SW, update. Only campaign	0.2
	E		P/O NO: 4104697	1
		AU2-9703- JSK37CZ201TO	.JSK 37 CZ/185 C/W	
		OTH-B6124	ANTI LUCE FASTENER 19MM	2
		OTH-FMCPLATE	5MM FLPLCOVERS	1

PC	Type	Code	Description (Original)	#
	☑		maximum 10 000 km.	
☞		<u>2015-10-12 - Mileage: 14138 - Order nr: 411900</u>		
☞	☞	VO-1721000	Warranty service. After 4 weeks or maxim	2
	☑		maximum 10 000 km.	
☞		<u>2015-10-09 - Mileage: 0 - Order nr: 8238528</u>		
☞	*	834	LHS CENTRAL LOCKING NOT WORKING	
	☑		COULD NOT FAULT	
☞	☑	<u>2015-08-20 - Mileage: 14138 - Order nr: 8237931</u>		
☞	☞	VO-1721000	Warranty service. After 4 weeks or maxim	2
	☑		maximum 10 000 km.	
☞	☞	VO-2592200	Filler cap, AdBlue, replace	0.1
☞	☞	VO-2596700	Combined tank unit, replace	0.6
☞	☑	VO-20926021	ADBLUE FILLER CAP	1
☞	☑	VO-22203918	COMBINED TANK UNIT	1
☞	☑	VO-21480006	FILLER NECK	1
☞	☞	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.2
	☑		(DEF) tank, filler neck insert, replace	
☞		<u>2015-08-20 - Mileage: 0 - Order nr: 8237953</u>		
☞	*	170	First service----- parts	
☞	☑	VO-20779040	AT G/BOX FILTER	1
☞	☑	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
☞	☑	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	16
☞		<u>2015-07-29 - Mileage: 0 - Order nr: 2168059</u>		
☞	*	CARD	CANCELLED	

PC	Type	Code	Description (Original)	#
⊗	⊗	OTH-8901087	BRAKE CLEANER	1
⊗	⊗	VO-21834205	FILTER	1
⊗	⊗	OTH-893140	INDUSTRY CLEANER 500ML	2
⊗	⊗	VO-1674223	T-BOLT CLAMP	1
⊗	⊗	VO-3944785	COMP.AIR FILTER	1
⊗	⊗	MK-9728-SSA100	ARCH SPRAY SUPPRES	1
	⊗		SET SERVICE INTERVAL FOR 45000km	
	⊗		(DEF) tank, filler neck insert, replace	
⊗	*	91	WORKSHOP CONSUMABLES	

⊗ 2015-10-15 - Mileage: 42371 - Order nr: 8239114

⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊗	⊗	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	⊗		area	
⊗	⊗	VO-2331100	Filter, water separator, replace	0.3
⊗	⊗	VO-2330600	Fuel filter, replace (one)	0.3
⊗	⊗	VO-1707300	Service alert system, configuration and	0.4
	⊗		reports	
	⊗		SET SERVICE INTERVAL FOR 40000KM	
⊗	⊗	VO-8559000	Smoke detector, new install	0.2
⊗	⊗	LO-393	MOVE UHF MIC TO	0.2
	⊗		OVER HEAD CONSOL	
⊗	⊗	VO-FK18B	FILTER KIT	1
⊗	⊗	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊗	⊗	VO-20919810	SMOKE DETECTOR	1
	⊗		REFER CRAIG COSTELLO	
⊗	*	91	WORKSHOP CONSUMABLES	

⊗ 2015-10-12 - Mileage: 14138 - Order nr: 8239069

⊗	⊗	VO-1721000	Warranty service. After 4 weeks or maxim	2
---	---	------------	--	---

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.33
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.33
Ⓢ	Ⓢ	VO-1707300	Service alert system, configuration and reports	0.44
Ⓢ	Ⓢ	LO-352	REPLACED HEADLIGHT BULB	0.1
Ⓢ	Ⓢ	VO-3632400	Windscreen washer pump, replace	0.4
Ⓢ	Ⓢ	VO-2341300	Filler cap, replace	0.1
Ⓢ	Ⓢ	VO-8394887	OIL TEST KIT	4
Ⓢ	Ⓢ	VO-FK18B	FILTER KIT	1
Ⓢ	Ⓢ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Ⓢ	Ⓢ	LO-561	REPLACED AIR DRIER FILTER	0.4
Ⓢ	Ⓢ	VO-2583200	Aftertreatment diesel exhaust fluid (DEF	0.2
Ⓢ	Ⓢ	VO-990037	H/LIGHT BULB H7	1
Ⓢ	Ⓢ	VO-22335630	FILLER CAP	2
Ⓢ	Ⓢ	VO-22223804	AIR DRYER FILTER "FH4"	1
Ⓢ	Ⓢ	VO-21480006	FILLER NECK	1
Ⓢ	Ⓢ	VO-84081002	PUMP	1
Ⓢ	Ⓢ	LO-2324	REPLACED BLOCKED AIR CLEANER ELEMENT	0.1
Ⓢ	Ⓢ	LO-820	REPLACED R/H/S 1ST DRIVE SPRAY	0.3
Ⓢ	Ⓢ		SUSPRESSION TORN OFF	
Ⓢ	Ⓢ	VO-2510400	Gaskets, exhaust manifold, replace	2
Ⓢ	Ⓢ	VO-20855371	GASKET	6
Ⓢ	Ⓢ	VO-20784537	GASKET	1
Ⓢ	Ⓢ	VO-1543499	FLANGE NUT	4
Ⓢ	Ⓢ	VO-21940615	SEALING RING	2
Ⓢ	Ⓢ	VO-20828303	SEALING RING	1
Ⓢ	Ⓢ	VO-8192189	SEALING RING	1
Ⓢ	Ⓢ	VO-976929	DOWDY WASHER	1
Ⓢ	Ⓢ	VO-420641	TURBO FEED GKT	1
Ⓢ	Ⓢ	VO-420643	TURBO DRAIN GKT	1
Ⓢ	Ⓢ	VO-469601	TURBO O-RING	1

PC	Type	Code	Description (Original)	#
⊗	⊗	VO-FK18B	FILTER KIT	1
⊗	⊗	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊗	⊗	VO-990037	H/LIGHT BULB H7	1
⊗	⊗	VO-992516	BULB HI 24V 70watt	1
⊗	⊗	LO-561	AIR COMPRESSOR INLET HOSE SPLIT	0.3
⊗	⊗	VO-20554213	BELLOWS	1
⊗	⊗	VO-992085	HOSE CLAMP 40mm	2
⊗	⊗	UNK-NTH614231SS	4381-2109 led indicator	1
⊗	⊗	VO-1701000	Connect-disconnect of diagnostic tool	0.2
⊗	⊗	VO-5602100	APM, status	0.3
⊗	⊗	VO-5602300	Pneumatics system, status	0.2
⊗	*	91	WORKSHOP CONSUMABLES	

🔍 2016-04-08 - Mileage: 125521 - Order nr: 8614231

⊗	⊗	VO-4320800	Gear selector, replace	0.5
⊗	⊗	LO-1940000	Travel Time To Breakdown	3
⊗	⊗	VO-22647976	GEAR SELECTOR	1
	⊗		COMPLAINT: TRUCK WILL NOT SELECT GEARS	
⊗	⊗	VO-1701000	Connect-disconnect of diagnostic tool	0.2
⊗	⊗	VO-1701200	Fault codes, reading	0.2
⊗	*	92	VAN MILEAGE 274 km's Ö Å0.98/km.	

🔍 2016-01-21 - Mileage: 83752 - Order nr: 8241382

	⊗		S3485 Instrument cluster, SW update, FH/FM (4)	
⊗	⊗	VO-1701000	Connect-disconnect of diagnostic tool	0.2
⊗	⊗	VO-3815800	IC, SW update, Campaign only	0.3
⊗	⊗	VO-1706300	6 Months ECU download and oil sample. On	0.9
	⊗		Only valid for Australian market	
⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	2.97
⊗	⊗	VO-1751300	Engine, oil and filter, replace. Lube ar	0.77

PC	Type	Code	Description (Original)	#
⊗	■	VO-4803748	HOSE	3
⊗	■	VO-984727	BOLT M6*25 FL	2
⊗	■	VO-990939	NUT M6 FLANGED NON LOCKING	2
⊗	■	MK-NARV56306	CABLE TIE 1=10PK	1
⊗	■	VO-975269	HOSE CLAMP	2
⊗	⊙	VO-1701000	Connect-disconnect of diagnostic tool	0.2
⊗	⊙	VO-2840700	Sensor values, check	0.2
⊗	⊙	VO-3710200	Electric wires and connections, check	0.4
⊗	⊙	VO-1702600	Program control unit	0.1
⊗	*	91	WORKSHOP CONSUMABLES	

⊗ 2016-06-13 - Mileage: 154731 - Order nr: 8244697

⊗	⊙		C3538 Cab tilt pump, filler plug, replace. FH (4)	
⊗	⊙	LO-8600100	Cab tilt pump, check	0.5
⊗	⊙	LO-8600200	Cab tilt cylinder check. Campaign only	0.7
⊗	⊙	LO-8600300	Cab tilt cylinder replace. Campaign only	0.6
⊗	*	1701200	FAULT LIGHT COMING UP ON DASH	
⊗	*	810	FRIDGE WORKS HALF THE DAY	
⊗	■	VO-22861085	REPAIR KIT	1
⊗	■	VO-22074730	FLANGE SCREW	1
⊗	■	VO-992520	BULB	1
⊗	■	VO-84222218	CONTROL UNIT	

⊗ 2016-04-18 - Mileage: 128132 - Order nr: 8243380

⊗	⊙	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊗	⊙	VO-2331100	Filter, water separator, replace	0.3
⊗	⊙	VO-2330600	Fuel filter, replace (one)	0.3
⊗	⊙	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	⊙		area	
⊗	⊙	LO-350	R/H HEAD LIGHT NOT WORKING	0.5

PC	Type	Code	Description (Original)	#
⊗	⊗	VO-1706400	12 Months ECU download and oil sample. O	0.9
⊗	*	1774600	Annual service. Chassis lubrication and.	
⊗	⊗	VO-2330600	Fuel filter, replace (one)	0.3
⊗	⊗	VO-2331100	Filter, water separator, replace	0.3
⊗	⊗	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.7
⊗	*	97	ENVIRONMENTAL CHARGE	
⊗	⊗	VO-1752700	Final drive oil, change. Lube area	0.5
⊗	⊗	VO-2141300	Valves and unit injectors, adjust	3
⊗	⊗	LO-353	CHECK ALL LIGHTS	0.2
⊗	⊗	VO-4651400	Pinion sealing ring, replace	2
⊗	⊗	VO-990037	H/LIGHT BULB H7	1
⊗	⊗	VO-8394887	OIL TEST KIT	4
⊗	⊗	VO-FK18B	FILTER KIT	1
⊗	⊗	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊗	⊗	VO-82354791	VENTILATION FILTER	1
⊗	⊗	VO-82348995	VENTILATION FILTER	1
⊗	⊗	VO-20779040	AT G/BOX FILTER	1
⊗	⊗	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	16
⊗	⊗	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
⊗	⊗	VO-3192615	PINION SEAL	1
⊗	⊗	LO-258	AD-BLUE LEAK AT BREATHER PIPE INTO TANK	1.5
⊗	*	881	CLOCK RESETS EVERYTIME THE VEHICLE IS	
⊗	⊗	VO-995906	HEXAGON SCREW	4
⊗	⊗	VO-25339078	HEXAGON NUT TS	4
⊗	⊗	VO-8171338	LOCK NUT	1
⊗	⊗	VO-3944785	COMP.AIR FILTER	1
⊗	⊗	VO-22679934	T-PIPE	1
⊗	⊗	VO-22681764	MANIFOLD	1
⊗	⊗	VO-20915849	HOSE CLAMP 27MM	2
⊗	⊗	VO-21032572	CLAMP	2
⊗	⊗	VO-21429181	HOSE	3

PC	Type	Code	Description (Original)	#
<u>2016-11-30 - Mileage: 221972 - Order nr: 8249219</u>				
	*	M	PLEASE FILL IN	
			Mileage:	
		VO-1706500	18 Months ECU download and oil sample. O	0.9
		VO-1774400	Basic service. Chassis lubrication and o	2.7
		VO-2331100	Filter, water separator, replace	0.3
		VO-2330600	Fuel filter, replace (one)	0.3
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
		VO-8394887	OIL TEST KIT	4
		VO-FK18B	FILTER KIT	1
		AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
		LO-252	EXHAUST FLEX LEAKING	0.8
		VO-22321908	EXHAUST PIPE	1
		VO-1629499	EXH CLAMP FH	2
		VO-990951	NUT M10 FLANGE LOCK	2
		VO-994195	BOLT M10*50 FL	2
	*	91	WORKSHOP CONSUMABLES	
<u>2016-08-30 - Mileage: 0 - Order nr: 8246764</u>				
	*	M	PLEASE FILL IN	
			Mileage:	
	*	210	RECTIFY ENGINE LIGHT KEEPS COMING	
<u>2016-06-13 - Mileage: 168268 - Order nr: 8244816</u>				
		VO-8736600	Control unit, replace	0.6
		VO-84222218	CONTROL UNIT	1
		VO-1774600	Annual service. Chassis lubrication and	2.4
			oil changes included only in some models	
		VO-8100300	12 Months cab inspection	0.4

PC	Type	Code	Description (Original)	#
W	Q	LO-3540800	Interior Lights, Cable Harness, Install	0.5
W	Q	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Q	VO-2549400	ACM, SW, update, only campaign	0.2
Q	Q	LO-430	GEARBOX - GENERAL	0.5
W	R	VO-22935545	WIRES	8
Q	Q	VO-1774400	Basic service, Chassis lubrication and o	1.3
Q	Q	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
R	Q	VO-2330600	Fuel filter, replace (one)	0.2
Q	Q	VO-2331100	Filter, water separator, replace	0.3
R	Q	VO-1707300	Service alert system, configuration and	0.4
Q	*	97	ENVIRONMENTAL CHARGE	
Q	R	VO-FK18B	FILTER KIT	1
Q	R	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Q	R	VO-8394887	OIL TEST KIT	1
R	*	91	WORKSHOP CONSUMABLES	
R	*	91	WORKSHOP CONSUMABLES	

2017-01-23 - Mileage: 250668 - Order nr: 8250498

W	Q	VO-8850300	Refrigerator, replace	0.2
W	R	VO-82174077	REFRIGERATOR	1
W	Q	VO-3116800	Battery system, test, Battery tester	0.4

2016-12-30 - Mileage: 0 - Order nr: 2181314

Q	*	CARD	NOT REQUIRED	
---	---	------	--------------	--

2016-12-29 - Mileage: 0 - Order nr: 8249943

Q	Q	LO-311	BATTERY SLOW TO CRANK	1.4
	Q		CARRY OUT BATTERY TEST, FOUND	
R	R	AU2-20935640	Volvo MAINT N200	2
Q	*	91	WORKSHOP CONSUMABLES	

PC	Type	Code	Description (Original)	#
⊕	■	VO-8394887	OIL TEST KIT	4
⊕	■	VO-FK18B	FILTER KIT	1
⊕	■	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊕	■	VO-82354791	VENTILATION FILTER	1
⊕	■	VO-82348995	VENTILATION FILTER	1
⊕	■	VO-20779040	AT G/BOX FILTER	1
⊕	■	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	16
⊕	■	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
⊕	■	VO-21516229	FILTER	1
⊕	■	VO-22223804	AIR DRYER FILTER "FH4"	1
⊕	*	91	WORKSHOP CONSUMABLES	

⊕ 2017-03-24 - Mileage: 279340 - Order nr: 8252060

⊕	⊕	LO-510	TRAILER BRAKES WON'T APPLY	3.47
⊕	■	VO-21114977	MODULATOR	1
⊕	■	VO-82485683	WIPER BLADE KIT	1
	⊞		Connected laptop	
⊕	*	91	WORKSHOP CONSUMABLES	

⊕ 2017-03-16 - Mileage: 278119 - Order nr: 8251820

⊕	*	M	PLEASE FILL IN	
	⊞		Customer Order Number:	
⊕	⊕	LO-870	A/C INTERMITTANT OPERATION	2.5
⊕	■	OTH-84191414	VALVE	1
⊕	■	VO-82693739	ACCUMULATOR	1
⊕	■	VO-82348995	VENTILATION FILTER	1
⊕	*	91	WORKSHOP CONSUMABLES	

⊕ 2017-01-31 - Mileage: 264473 - Order nr: 8251129

	⊞		C3628 Cab, interior lights, cable harness, install. FH (4)	
--	---	--	--	--

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	LO-258	EMISSION FAULT LIGHT FLASHING ON DASH	3
	Ⓢ		VEHICLE DERATE 30 HRS	
Ⓢ	*	91	WORKSHOP CONSUMABLES	
Ⓢ 2017-05-17 - Mileage: 0 - Order nr: 8253296				
Ⓢ	Ⓢ	LO-810	FIT NEW HEADLIGHT SURROUND PANELS	2.5
	Ⓢ		BOTH SIDES	
Ⓢ	Ⓢ	VO-21874450	PANEL	1
Ⓢ	Ⓢ	VO-21874457	PANEL	1
Ⓢ	*	810	RECTIFY SUN VISOR NOT LOCKING IN PLACE	
Ⓢ	*	91	WORKSHOP CONSUMABLES	
Ⓢ 2017-05-16 - Mileage: 308134 - Order nr: 8253212				
Ⓢ	Ⓢ	VO-1774600	Annual service. Chassis lubrication and	2.4
	Ⓢ		oil changes included only in some models	
Ⓢ	Ⓢ	VO-1706600	24 Months ECU download and oil sample. O	0.9
Ⓢ	Ⓢ	VO-8100500	24 Months cab inspection	0.4
Ⓢ	*	177	ANNUAL SERVICE PARTS TO THIS LINE	
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.3
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.3
Ⓢ	*	97	ENVIRONMENTAL CHARGE	
Ⓢ	Ⓢ	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
Ⓢ	Ⓢ	VO-1752700	Final drive oil, change. Lube area	0.6
Ⓢ	Ⓢ	VO-2141300	Valves and unit injectors, adjust	3
Ⓢ	Ⓢ	VO-2582200	Filter, AdBlue, replace	0.4
Ⓢ	Ⓢ	VO-5616600	Air drier cassette, replace	0.4
Ⓢ	Ⓢ	VO-5240800	Brake pedal, split pin, check/adjust. Ca	0.5
Ⓢ	Ⓢ	VO-1701000	Connect-disconnect of diagnostic tool	0.2
Ⓢ	Ⓢ	VO-2800800	EMS and ACM, sw, update. Only campaign	0.4

PC	Type	Code	Description (Original)	#
⊕	⊕	VO-8394887	OIL TEST KIT	4
⊕	⊕	VO-22223804	KIT	1
⊕	*	91	CONSUMABLES	
⊕	⊕	<u>2018-01-09 - Mileage: 0 - Order nr: 2190798</u>		
⊕	*	CARD	NOT REQUIRED	
⊕	⊕	<u>2017-10-24 - Mileage: 374941 - Order nr: 8257473</u>		
⊕	⊕	VO-2580700	Pump unit, replace	0.48
⊕	⊕	VO-22851845	PUMP UNIT	0.6
⊕	⊕	VO-1701000	Connect-disconnect of diagnostic tool	0.12
⊕	⊕	VO-2584600	SCR system, test	0.3
⊕	⊕	<u>2017-10-05 - Mileage: 0 - Order nr: 8256909</u>		
⊕	⊕	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊕	⊕	VO-2331100	Filter, water separator, replace	0.3
⊕	⊕	VO-2330600	Fuel filter, replace (one)	0.3
⊕	⊕	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	⊕		area	
⊕	⊕	VO-FK18B	FILTER KIT	1
⊕	⊕	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊕	*	97	ENVIRONMENTAL CHARGE	
⊕	*	91	WORKSHOP CONSUMABLES	
⊕	⊕	<u>2017-06-19 - Mileage: 323217 - Order nr: R15548</u>		
⊕	⊕	VO-2583700		
⊕	⊕	VO-22827995	SENSOR	1
⊕	⊕	<u>2017-06-16 - Mileage: 320715 - Order nr: 8254066</u>		

PC	Type	Code	Description (Original)	#
③	✱	VO-85122800	ATF DEX 3	2
③	✱	91	WORKSHOP CONSUMABLES	

🔍 2018-03-27 - Mileage: 440206 - Order nr: 8261479

	📅		AIRBAG MODULE, REPLACE. FH/FM (4)	
③	③	VO-8842000	Airbag module, replace	0.3
③	③	VO-1774400	Basic service, Chassis lubrication and o	2.7
③	③	VO-2331100	Filter, water separator, replace	0.3
③	③	VO-2330600	Fuel filter, replace (one)	0.3
③	③	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
③	✱	VO-FK18B	FILTER KIT	1
③	✱	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
③	✱	VO-84433698	AIRBAG MODULE	1
③	③	LO-363	REPLACE WIPERS	0.3
③	③	LO-350	L/H TAIL LIGHT BRACKET LOOSE	0.4
③	✱	VO-82485683	WIPER BLADE KIT	2
③	✱	VO-984859	BOLT M14*70 FL	2
③	✱	VO-994522	NUT M14 FLANGED crimped	2
③	✱	97	ENVIRONMENTAL CHARGE	
③	✱	91	WORKSHOP CONSUMABLES	

🔍 2018-01-10 - Mileage: 402513 - Order nr: 2190767

③	③	LO-560	AIR DRIER FILTER - REPLACE	1
③	③	VO-1706700	30 Months ECU download and oil sample. O	0.9
	📅		JULY TO DEC 2017 OFFER	
③	③	VO-1774400	Basic service, Chassis lubrication and o	3.5
③	✱	93	ENGINE OIL & GREASE	
③	✱	94	WASTE DISPOSAL	
③	✱	91	CONSUMABLES	
③	✱	VO-FK18B	FILTER KIT	1

PC	Type	Code	Description (Original)	#
①	*	91	WORKSHOP CONSUMABLES	
①	①	<u>2018-06-20 - Mileage: 482209 - Order nr: 8263641</u>		
①	①	VO-1774600	Annual service	6
①	①	VO-2331100	Filter, water separator, replace	0.3
①	①	VO-2330600	Fuel filter, replace (one)	0.3
①	①	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	①		area	
①	①	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
①	①	VO-1752700	Final drive oil, change. Lube area	0.5
①	①	VO-2141300	Valves and unit injectors, adjust	3
①	①	VO-2341400	Filter for fuel tank ventilation, replac	0.2
①	①	VO-2582200	Filter, AdBlue, replace	0.2
①	①	VO-5616600	Air drier cassette, replace	0.1
①	①	VO-21516229	FILTER	1
①	①	VO-21743197	AIR CLEANER	2
①	①	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
①	①	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	16
①	①	VO-20779040	AT G/BOX FILTER	1
①	①	VO-FK18B	FILTER KIT	1
①	①	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
①	①	LO-640	RECTIFY POWER STEERING LEAK NEAR	3
①	①	LO-352	CHECK AND RECTIFY LARGE TOP CORNER	1.5
①	①	LO-250	AD-BLUE LEAKING FROM WELD ON MUFFLER	1
①	①	VO-85111407	BULB	1
①	①	VO-3091446	CAP	1
①	①	VO-3091445	GASKET	1
①	①	AU2- WUR089010810	BRAKE CLEAN	1
①	①	VO-990945	FLANGE NUT	2
①	①	VO-994219	LOCK NUT	1

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	LO-510	CHECK AND RECTIFY AIR LEAK FROM	1
	Ⓢ		VALVE INSIDE OF CHASSIS NEAR G-BOX, INVESTIGATED AND FOUND	
Ⓢ	Ⓢ	LO-210	CHECK AND REPORT ON THE CAUSE OF	3
Ⓢ	Ⓢ	VO-976445	VIP 8MM JOINER	1
Ⓢ	Ⓢ	VO-969289	VIP 8MM JOINER	1
Ⓢ	Ⓢ	VO-992247	SWIVEL	1
Ⓢ	Ⓢ	MK-NARV56306	CABLE TIE 1=10PK	1
Ⓢ	Ⓢ	VO-976446	VIP 12MM JOINER	1
Ⓢ	Ⓢ	VO-969290	VIP 12MM JOINER	1
Ⓢ	Ⓢ	VO-85013941	COMPRESSOR EXCH	1
Ⓢ	Ⓢ	VO-471708	SEAL RING	1
Ⓢ	Ⓢ	VO-992065	O-RING	1
Ⓢ	Ⓢ	VO-23137065	EXHAUST PIPE 360mm long	1
Ⓢ	Ⓢ	LO-250	REPLACE SPLIT EXHAUST FLEX	0.5
Ⓢ	Ⓢ	VO-955986	O-RING M12 (VIP	1
Ⓢ	Ⓢ	AU2- WUR089010810	BRAKE CLEAN	2
Ⓢ	*	91	WORKSHOP CONSUMABLES	

Ⓢ Ⓢ 2018-09-22 - Mileage: 521683 - Order nr: 2197633

Ⓢ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	3.5
Ⓢ	*	93	ENGINE OIL & GREASE	
Ⓢ	*	94	WASTE DISPOSAL	
Ⓢ	Ⓢ	VO-85136742	FILTER KIT (18B)	1
	Ⓢ		Carried out basic service as per specifications.	
Ⓢ	*	91	CONSUMABLES	

Ⓢ Ⓢ 2018-06-26 - Mileage: 0 - Order nr: 8264078

Ⓢ	Ⓢ	LO-350	NO POWER AT OUT LETS IN DASH	0.65
	Ⓢ		TEST POWER OUT LET NO POWER	
Ⓢ	Ⓢ	VO-20378934	FUSE 10 AMP	3

PC	Type	Code	Description (Original)	#
①	*	VO-948883	DOWDY WASHER	2
①	*	91	WORKSHOP CONSUMABLES	
S ⓘ 2019-01-24 - Mileage: 585361 - Order nr: 8269843				
①	*	M	PLEASE FILL IN	
	☑		Contact: KARL - 0417 627 342	
①	①	LO-260	RECTIFY FAN NOT CUTTING IN CORRECTLY	1
①	①	LO-220	RECTIFY OIL TEMP FLICKERING	0.8
①	*	91	WORKSHOP CONSUMABLES	
S ⓘ 2019-01-03 - Mileage: 571978 - Order nr: 8269259				
①	①	VO-1774400	Basic service. Chassis lubrication and o	2.7
①	①	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
	☑		area	
①	①	VO-2330600	Fuel filter, replace (one)	0.3
①	①	VO-2331100	Filter, water separator, replace	0.3
①	①	VO-2582200	Filter, AdBlue, replace	0.2
①	①	VO-5616600	Air drier cassette, replace	0.3
①	①	LO-311	BATTERY SLOW TO CRANK	1
①	①	LO-561	SECONDARY AIR SYSTEM AIR LEAK	0.5
①	*	VO-85136742	FILTER KIT	1
①	*	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
①	*	VO-21516229	FILTER	1
①	*	VO-23260134	AIR DRYER FILTER "FH4	1
①	*	AU2-20935640	Volvo MAINT N200	2
①	*	97	ENVIRONMENTAL CHARGE	
①	*	VO-21848341	DRAIN VALVE	1
①	*	91	WORKSHOP CONSUMABLES	

S ⓘ 2018-10-04 - Mileage: 530876 - Order nr: 8266955

PC	Type	Code	Description (Original)	#
①	②	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
①	②	VO-2330600	Fuel filter, replace (one)	0.3
②	②	VO-2331100	Filter, water separator, replace	0.3
③	②	VO-5616600	Air drier cassette, replace	0.4
③	Ⓜ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
③	Ⓜ	VO-85136742	FILTER KIT	1
③	②	LO-251	EXHAUST BRAKE SQUEELING WHEN	4
③	②	LO-210	ENGINE FAN COMING ON RUNNING	3
③	Ⓜ	VO-21613426	THERMOSTAT	1
③	②	LO-250	Replace bottom boost hose	0.3
③	②	LO-640	Rectify power steering leak	1
③	*	820	Replace missing washer bottle lid	
③	Ⓜ	VO-85003294	EXCH THERMO FAN	1
③	Ⓜ	VO-990950	NUT M8 FL LOCKING	4
③	Ⓜ	MK-NARV56306	CABLE TIE 1=10PK	1
③	Ⓜ	VO-20479636	SEALING STRIP	1
③	Ⓜ	VO-1547254	THERMOSTAT SEAL	2
③	Ⓜ	VO-82268664	COVER	1
③	Ⓜ	VO-21312237	CHARGE AIR HOSE	1
③	Ⓜ	VO-994385	BOLT M8*45 FL	2
③	Ⓜ	VO-20855371	GASKET	6
③	Ⓜ	VO-22718180	KIT	1
③	Ⓜ	VO-1161929	JOINTING PASTE	1
③	Ⓜ	VO-21433769	SEALING RING	2
③	Ⓜ	VO-20938963	SEAL	1
③	Ⓜ	VO-20784537	GASKET	1
③	Ⓜ	VO-22206133	GASKET	1
③	Ⓜ	VO-420643	TURBO DRAIN GKT	1
③	Ⓜ	VO-85103205	PAINT GREEN (VOLVO)	1
③	Ⓜ	AU2- WUR089010810	BRAKE CLEAN	2

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	VO-21032572	CLAMP,UREA HOSE	2
Ⓢ	Ⓢ	VO-21429181	HOSE (urea)	1
Ⓢ	Ⓢ	VO-3985511	CLAMP	1
Ⓢ	Ⓢ	VO-984724	M6*12 FL BOLT	2
Ⓢ	Ⓢ	LO-640	GRIDING NOISE ON PS WHEN TURNING	2
Ⓢ	Ⓢ	VO-85122800	1L DEXRON3 ATF	1
Ⓢ	Ⓢ	OTH-AB15	ADBLUE 15L	4
Ⓢ	Ⓢ	VO-22851845	PUMP UNIT	1
Ⓢ	Ⓢ	VO-22203918	COMBINED TANK UNIT	1
Ⓢ	Ⓢ	VO-20734499	ANTI-TAMPER SEALIN	4
Ⓢ	Ⓢ	VO-21106105	HOUSING	1
Ⓢ	Ⓢ	VO-21280355	CONNECTOR	1
Ⓢ	Ⓢ	VO-984975	CABLE TERMINAL	4
Ⓢ	Ⓢ	LO-236	Straighten cross over bracket as	2
Ⓢ	Ⓢ	MK-NARV56308	CABLE TIE 1=25 PK	1
Ⓢ	Ⓢ	VO-980464	STRIP CLAMP - CABLE TIE	5
Ⓢ	Ⓢ	VO-82269261	FILTER/MAGNET	1
Ⓢ	Ⓢ	VO-20428158	CABLE TIE	6
Ⓢ	*	91	CONSUMABLES	

🔍 2019-04-05 - Mileage: 618273 - Order nr: 2202176

Ⓢ	Ⓢ	LO-331	STARTER MOTOR - REPLACE	2
Ⓢ	Ⓢ	VO-85020789	EXCH STARTER MOTOR	1
	📋		NEW SERIALĂ V47529 M009T66771ZX	
Ⓢ	*	91	CONSUMABLES	

🔍 2019-03-26 - Mileage: 613644 - Order nr: 8271518

Ⓢ	*	M	PLEASE FILL IN	
	📋		Contact:KARL 0417 627 342	
Ⓢ	Ⓢ	VO-1774400	Basic service, Chassis lubrication and o	2.7

PC	Type	Code	Description (Original)	#
①	✎	VO-20464675	V-RIBBED BELT 10PK1545	1
①	✎	VO-22275091	V-RIBBED BELT	1
①	✎	VO-21819687	BELT TENSIONER	1
①	✎	VO-990037	H/LIGHT BULB H7	1
①	✎	VO-992516	BULB H1 24V 70watt	1
①	②	LO-460	LINK RODS HAVE MOVEMENT	2.5
①	✎	VO-984735	BOLT M8*25 FL	8
①	✎	VO-990950	NUT M8 FL LOCKING	8
①	✎	VO-6861717	ALUMINIUM STRIP	2
①	✎	UNK-NTH62365JF	h11pgj19-2 24v 70w	1
①	✎	UNK-NTH623866JF	bulb 24v 21w	1
①	✎	VO-22318844	STAY	1
①	✎	VO-21182661	LOCK NUT	2
①	✎	VO-947140	NUT M18 LOCK NUT FINE	1
①	*	97	ENVIRONMENTAL CHARGE	
①	*	91	WORKSHOP CONSUMABLES	

⑤ ② 2019-05-01 - Mileage: 633507 - Order nr: 2202744

①	*	SHIFT	SHIFT : DAY	
	②		ENG HRS: 8711 FUEL BURN: 273437	
①	②	LO-258	NOX SENSOR FAULT - 36 HRS TO DE-RATE	2
①	✎	VO-22827993	SENSOR	1
①	✎	OTH-AAB122ML-1/2PP-10	100 MESH FILTER 1/2" 122ML	1
①	✎	OTH-ADBLUE FILTER BRA	ADBLUE PICKUP FILTER BRACKET	1
①	✎	OTH-CP23174-7-304SS	SCREEN 200 MESH SILVER	1
①	✎	OTH-NOR-W3-10	STAINLESS STEEL HOSE CLAMP	2
①	✎	OTH-NYP60608	NYLON ELBOW	2
①	✎	VO-20744595	CONNECTOR	1

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	Ⓢ		area	
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.3
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.3
Ⓢ	Ⓢ	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
Ⓢ	Ⓢ	VO-1752700	Final drive oil, change. Lube area	0.6
Ⓢ	Ⓢ	VO-2141300	Valves and unit injectors, adjust	3
Ⓢ	Ⓢ	VO-2341400	Filter for fuel tank ventilation, replac	0.2
Ⓢ	Ⓢ	VO-2582200	Filter, AdBlue, replace	0.2
Ⓢ	Ⓢ	VO-5616600	Air drier cassette, replace	0.4
Ⓢ	Ⓢ	VO-2630800	Fan belt tensioner, replace	2
Ⓢ	Ⓢ	LO-350	CHECK ALL LIGHTS WORKING INCLUDING	3
Ⓢ	Ⓢ	LO-826	L/H REAR MUD FLAP & CHERVRON REPLACE	0.5
Ⓢ	Ⓢ	LO-810	R/H/R HORIZONTAL CAB SHOCK REPLACE	0.5
Ⓢ	Ⓢ	VO-85136742	FILTER KIT	1
Ⓢ	Ⓢ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Ⓢ	Ⓢ	VO-20779040	AT G/BOX FILTER	1
Ⓢ	Ⓢ	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	16
Ⓢ	Ⓢ	VO-21516229	FILTER	1
Ⓢ	Ⓢ	VO-23260134	AIR DRYER FILTER "FH4	1
Ⓢ	Ⓢ	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
Ⓢ	Ⓢ	VO-21743197	AIR CLEANER	2
Ⓢ	Ⓢ	VO-3944785	COMP AIR FILTER	1
Ⓢ	Ⓢ	VO-23105744	VOLVO MUDFLAP RIBBED	1
Ⓢ	Ⓢ	VO-23452020	CHEVRON L/HAND	1
Ⓢ	Ⓢ	VO-984726	BOLT M6*20 FL	4
Ⓢ	Ⓢ	VO-994847	WASHER M6*18	8
Ⓢ	Ⓢ	VO-990949	NUT M6 FL LOCKING	4
Ⓢ	Ⓢ	VO-22128971	SHOCK ABSORBER	1
Ⓢ	Ⓢ	VO-21766717	IDLER PULLEY	1
Ⓢ	Ⓢ	VO-21479276	BELT TENSIONER	1

PC	Type	Code	Description (Original)	#
③	✱	VO-22480498	ADAPTER	1
③	✱	97	ENVIRONMENTAL CHARGE	
③	✱	VO-22335630	FILLER CAP	1
③	✱	91	WORKSHOP CONSUMABLES	

🔍 2020-01-18 - Mileage: 743279 - Order nr: 4421162

①	✱	INFO	DETAILS	
	📄		KM:743,279km's FUEL BURN:319,943ltr's ENG HRS:10,227hr's	
①	✱	BREAKDOWN	BREAKDOWN	
①	③	LO-510	AIR DRYER FAULT ON DASH	4
①	✱	OTH-L-TCWA	TCWA LATE OPENING FEE - MATT	1
①	✱	VO-23260134	KIT	1
①	✱	91	CONSUMABLES	

🔍 2019-10-10 - Mileage: 697921 - Order nr: 8276835

③	③	VO-1774400	Basic service. Chassis lubrication and o	2.7
③	③	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
	📄		area	
③	③	VO-2331200	Filter, water separator, replace	0.3
③	③	VO-2330600	Fuel filter, replace (one)	0.3
③	✱	97	ENVIRONMENTAL CHARGE	
③	✱	252	RECTIFY ADBLUE LEAKING BEHIND CAB	
①	✱	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
①	✱	VO-85136742	FILTER KIT	1
③	✱	AU2-WUR0578705040	FLAPPY DISC 2 INCH	2
①	✱	91	WORKSHOP CONSUMABLES	

🔍 2019-06-18 - Mileage: 656383 - Order nr: 8273782

③	③	VO-1774600	Annual service	6
---	---	------------	----------------	---

PC	Type	Code	Description (Original)	#
⊖	⊖	VO-82386482	O-RING	1
⊖	⊖	VO-84437717	HOSE	1
⊖	⊖	VO-82693739	ACCUMULATOR	1
⊖	*	91	WORKSHOP CONSUMABLES	
S ⊖ 2020-02-04 - Mileage: 752608 - Order nr: 8279979				
⊖	⊖	VO-1774400	Basic service. Chassis lubrication and o	2.7
	⊖		oil changes included only in some models	
⊖	⊖	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
⊖	⊖	VO-2330600	Fuel filter, replace (one)	0.3
⊖	⊖	VO-2331100	Filter, water separator, replace	0.3
⊖	⊖	LO-810	globe trotter sign in roof broken	3
⊖	⊖	LO-251	engine pipe cracked leaking adblue	1
⊖	⊖	LO-826	rear mud flap missing	0.53
⊖	⊖	VO-85136742	FILTER KIT	1
⊖	⊖	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊖	⊖	VO-82367858	DECAL	1
⊖	⊖	VO-84162956	TRIM PANEL	1
⊖	⊖	LO-922	carry out adjustment of turn table jaws	1
⊖	⊖	VO-84429874	WIND DEFLECTOR KIT	1
⊖	⊖	VO-23105744	VOLVO MUDFLAP RIBBED	1
⊖	⊖	VO-6861717	ALUMINIUM STRIP	2
⊖	⊖	VO-23452020	CHEVRON L/HAND	1
⊖	⊖	VO-990940	NUT M8 FL	5
⊖	⊖	VO-984728	BOLT M6*30 FL	4
⊖	⊖	VO-990949	NUT M6 FL LOCKING	4
⊖	⊖	VO-994847	WASHER M6*18	8
⊖	⊖	VO-984736	BOLT M8*30 FL	5
⊖	⊖	AU2- WUR089010810	BRAKE CLEAN	1
⊖	⊖	VO-23260134	AIR DRYER FILTER "FH4	1

PC	Type	Code	Description (Original)	#
①	✎	VO-977030	O-RING	1
①	✎	VO-20852765	DOWDY WASHER	4
①	✎	VO-982724	DOWDY WASHER	2
②	✎	VO-20562032	LOCK BRACE	1
②	✎	VO-1546531	LOCK BRACE	1
②	✎	VO-994446	BOLT M8*20 FL GR8.8 THREAD LOC	1
①	✎	VO-85103205	PAINT GREEN (VOLVO)	1
①	✎	VO-23149532	BRAKE PAD KIT	1
②	✎	VO-20784537	GASKET	1
①	✎	VO-85020372	TURBOCHARGER, EXCH	1
①	✎	VO-85122800	ATF DEX 3	4
①	✎	VO-6790354	O-RING	1
①	✎	VO-22885952	NUT 3/4" UNF CASTLE	1
①	✎	AU2-9770-5073	HOT SHOT DEGREASER	1
①	*	30	Sublet Alpha Glass	
①	✎	VO-84055744	LAMP	1
②	②	VO-1110200	Road test truck without loaded trailer.	0.3
①	②	LO-255	TURBO COMPRESSOR	1
①	*	91	WORKSHOP CONSUMABLES	

8/8 2020-04-01 - Mileage: 776933 - Order nr: 8281511

①	✎	VO-82385480	O-RING	1
---	---	-------------	--------	---

8/8 2020-03-30 - Mileage: 776928 - Order nr: 8281373

①	②	LO-870	AIR CONDITIONING NOT WORKING	5
	②		BLOWING HOT AIR IN CAB	
①	✎	VO-23515346	VENTILATION FILTER	1
①	✎	VO-23515329	VENTILATION FILTER	1
①	✎	VO-82348991	EVAPORATOR	1
①	✎	VO-82356760	O-RING	1

PC	Type	Code	Description (Original)	#
⊗	⊗	LO-826	l/h front mud guard pole loose	0.3
⊗	*	230	r/h fuel tank cap broken	
⊗	⊗	VO-20545485	DIFF LOCK DIAPHRAGM	1
⊗	⊗	VO-984735	BOLT M8*25 FL	1
⊗	⊗	LO-510	steer calipers ratling	5
⊗	*	3000	FCIOCM MISSING COVER	
⊗	⊗	LO-210	OIL LEAKING AT CONTROL VALVES	1
⊗	⊗	VO-2510400	Gaskets, exhaust manifold, replace	1.4
⊗	⊗	LO-6000	OIL LEAKING AT WEEP HOLE	2.5
⊗	⊗	VO-8171107	GASKET	1
⊗	⊗	VO-82849925	LAMP	1
⊗	⊗	VO-22335631	FILLER CAP	1
⊗	⊗	VO-85109890	REPAIR KIT	2
⊗	⊗	VO-944126	O-RING INJ HARN D9B/D12D/D13	1
⊗	⊗	VO-21999956	COVER	1
⊗	⊗	VO-23013321	CONTROL VALVE	1
⊗	⊗	VO-983472	GREY CABLE TIE 145MM	14
⊗	⊗	VO-20855371	GASKET	6
⊗	⊗	VO-22718180	KIT	1
⊗	⊗	VO-21433769	SEALING RING	2
⊗	⊗	VO-20883450	SEALING RING	1
⊗	⊗	VO-22206133	GASKET	1
⊗	⊗	VO-420643	TURBO DRAIN GKT	1
⊗	⊗	VO-469601	TURBO O-RING	1
⊗	⊗	VO-21940615	SEALING RING	1
⊗	⊗	VO-20526428	VEB SEAL RING	1
⊗	⊗	AU2- WUR0673205010	BROWN LOC 2"	2
⊗	⊗	AU2- WUR089010810	BRAKE CLEAN	2
⊗	⊗	VO-22318844	STAY	1
⊗	⊗	VO-21488833	STEERING PUMP	1

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓜ	VO-22058737	AIR SPRING	2
Ⓢ	Ⓜ	VO-22058741	AIR SPRING	1
Ⓢ	Ⓜ	VO-992247	SWIVEL M16 SMALL	1
Ⓢ	Ⓢ	LO-210	AIR CLEANER ELEMENTS CHANGE	0.4
Ⓢ	Ⓜ	VO-21834205	FILTER	1
Ⓢ	Ⓜ	VO-23294956	FILTER	1
Ⓢ	Ⓜ	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
Ⓢ	*	91	WORKSHOP CONSUMABLES	

Ⓢ Ⓢ 2020-09-04 - Mileage: 836409 - Order nr: 3351259

Ⓢ	Ⓢ	VO-2850600	Crankcase pressure sensor, replace	1.6
Ⓢ	Ⓜ	VO-21634017	PRESSURE SENSOR	1
Ⓢ	Ⓢ	VO-1701000	Connect-disconnect of diagnostic tool	0.2
Ⓢ	Ⓜ	VO-FREIGHT	FREIGHT	20
	Ⓢ		CONNECT VCADS COMPUTER AND READ VEHICLE INFORMATION.	
Ⓢ	*	94	Environmental Levy	
Ⓢ	*	91	Workshop Consumables	

Ⓢ Ⓢ 2020-06-10 - Mileage: 799477 - Order nr: 8283204

Ⓢ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	2.7
	Ⓢ		oil changes included only in some models	
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.3
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.3
Ⓢ	*	97	ENVIRONMENTAL CHARGE	
Ⓢ	*	350	.	
Ⓢ	Ⓢ	LO-460	engage power divider can hear air	1
Ⓢ	Ⓜ	VO-85136742	FILTER KIT	1
Ⓢ	Ⓜ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Ⓢ	Ⓢ	LO-350	r/h tail light not working & front spot	0.5

PC	Type	Code	Description (Original)	#
Ⓢ	Ⓢ	LO-871	A/C NOT COLD	2
Ⓢ	Ⓢ	VO-84014254	SUN VISOR	1
Ⓢ	Ⓢ	VO-82166469	SUN VISOR	1
Ⓢ	Ⓢ	VO-23344247	SUN VISOR KIT	1
Ⓢ	Ⓢ	VO-22131014	SWITCH PANEL	1
	Ⓢ		Removed & replaced external sun visor	
Ⓢ	*	91	WORKSHOP CONSUMABLES	

Ⓢ Ⓢ 2020-10-23 - Mileage: 858522 - Order nr: 2216000

Ⓢ	*	SHIFT	DAY	
Ⓢ	Ⓢ	LO-640	SMALL POWER STEERING LEAKING	3
Ⓢ	Ⓢ	VO-23478738	SERVO PIPE	1
Ⓢ	Ⓢ	VO-85122800	1L DEXRON3 ATF	2
Ⓢ	Ⓢ	VO-23044511	FUEL FILTER	1
Ⓢ	Ⓢ	VO-21177275	SOCKET	1
	Ⓢ		Inspected. Found power steer pipe that runs behind the	
Ⓢ	*	91	CONSUMABLES	

Ⓢ Ⓢ 2020-09-15 - Mileage: 839008 - Order nr: 8285693

Ⓢ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	2.7
	Ⓢ		oil changes included only in some models	
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.3
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.3
Ⓢ	*	97	ENVIRONMENTAL CHARGE	
Ⓢ	Ⓢ	LO-3000	REMOVE & REPLACE ALTERNATOR	2
Ⓢ	Ⓢ	LO-460	CHECK & REPORT ON SUSPENSION	4.8
Ⓢ	Ⓢ	VO-85136742	FILTER KIT	1
Ⓢ	Ⓢ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Ⓢ	Ⓢ	VO-85020836	ALTERNATOR, EXCH	1

PC	Type	Code	Description (Original)	#
⊗	*	91	WORKSHOP CONSUMABLES	
⊗	⊗	<u>2020-12-03 - Mileage: 876603 - Order nr: 8287485</u>		
⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	2.7
	⊗		oil changes included only in some models	
⊗	⊗	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
⊗	⊗	VO-2330600	Fuel filter, replace (one)	0.3
⊗	⊗	VO-2331100	Filter, water separator, replace	0.3
⊗	⊗	VO-5616600	Air drier cassette, replace	0.3
⊗	*	97	ENVIRONMENTAL CHARGE	
⊗	⊗	VO-85136742	FILTER KIT	1
⊗	⊗	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
⊗	⊗	VO-23260134	AIR DRYER FILTER "FH4	1
⊗	⊗	LO-460	JACK SHAFT UNIS U/S	2
⊗	*	40	SUBLET JACK SHAFT UNIS	
⊗	⊗	LO-363	REPLACE WIPERS	0.4
⊗	⊗	VO-23469625	UNI-JOINT 57MM OD	2
⊗	⊗	VO-82485683	WIPER BLADE KIT	2
⊗	⊗	VO-995906	BOLT M14*46 THREAD LOCKER	8
⊗	⊗	VO-25339078	NUT M14 FINE PITCH	8
⊗	*	91	WORKSHOP CONSUMABLES	
⊗	⊗	<u>2020-11-23 - Mileage: 871932 - Order nr: 2216732</u>		
⊗	*	SHIFT	DAY	
⊗	⊗	LO-370	"THROTTLE TEST" MESSAGE COMES ON DASH	1.5
	⊗		AND GEARBOX WILL NEUTRALISE. THIS HAS HAPPENED 3 TIMES - 2	
⊗	*	91	CONSUMABLES	
⊗	⊗	<u>2020-11-09 - Mileage: 867220 - Order nr: 8286854</u>		
⊗	⊗	LO-810	SUN VISOR BROKEN	1

PC	Type	Code	Description (Original)	#
<u>2021-03-12 - Mileage: 920474 - Order nr: 8289741</u>				
Ⓢ	Ⓢ	LO-810	cab air bag leaking	1
	Ⓢ		r/h front	
Ⓢ	Ⓢ	VO-21170611	AIR SPRING	2
Ⓢ	*	91	WORKSHOP CONSUMABLES	
<u>2021-02-17 - Mileage: 907459 - Order nr: 8289145</u>				
Ⓢ	Ⓢ	LO-6000	replace steer wheel bearings	6
Ⓢ	Ⓢ	LO-251	exhaust shroud cracked	0.35
Ⓢ	Ⓢ	VO-20967831	BEARING	2
Ⓢ	Ⓢ	VO-21671923	LOCK NUT	2
Ⓢ	Ⓢ	VO-3986189	O-RING	2
Ⓢ	Ⓢ	VO-21377615	HEAT SHIELD	1
	Ⓢ		SUPPORTED STEER AXLE & REMOVED WHEELS	
Ⓢ	*	91	WORKSHOP CONSUMABLES	
<u>2021-02-16 - Mileage: 907396 - Order nr: 8289144</u>				
Ⓢ	Ⓢ	VO-1774400	Basic service, Chassis lubrication and o	2.7
	Ⓢ		oil changes included only in some models	
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.3
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.3
Ⓢ	*	97	ENVIRONMENTAL CHARGE	
Ⓢ	Ⓢ	VO-5616600	Air drier cassette, replace	0.3
Ⓢ	Ⓢ	VO-85136742	FILTER KIT	1
Ⓢ	Ⓢ	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
Ⓢ	Ⓢ	VO-23260134	AIR DRYER FILTER "FH4	1
Ⓢ	Ⓢ	AU2- WUR089010810	BRAKE CLEAN	1

PC	Type	Code	Description (Original)	#
③	✖	VO-21433769	SEALING RING	2
③	✖	AU2-WLUR0890100045	EXHUAUST PASTE	1
③	✖	VO-994441	BOLT M8*50 FL	1
③	✖	VO-990950	NUT M8 FL LOCKING	1
③	✖	VO-22206133	GASKET	1
③	✖	VO-420643	TURBO DRAIN GKT	1
③	✖	VO-469601	TURBO O-RING	1
③	✖	VO-21940615	SEALING RING	1
③	✖	VO-20532891	GASKET	1
③	✖	VO-21475236	SPARE PART KIT	1
③	*	91	WORKSHOP CONSUMABLES	

③ ③ 2021-05-14 - Mileage: 948750 - Order nr: 8291047

③	*	220	power steer hoses leak repair	
③	*	20	SUBLET - LUBRITE	

③ ③ 2021-05-13 - Mileage: 947752 - Order nr: 8290910

③	③	VO-1774400	Basic service. Chassis lubrication and o	2.7
	③		oil changes included only in some models	
③	③	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
③	③	VO-2330600	Fuel filter, replace (one)	0.3
③	③	VO-2331100	Filter, water separator, replace	0.3
③	✖	VO-85136742	FILTER KIT	1
③	✖	AU2-CAL85121795	VDS 4 ENGINE OIL BULK	33
③	✖	VO-85122800	ATF DEX 3	2
③	③	LO-360	REPLACE U/S BATTERY	0.5
③	③	LO-460	REPLACE DIFF OILS	0.6
③	✖	AU2-CAL85121715	DIFF OIL 85W140 BULK	36
③	✖	AU2-23446985	VOLVO EFB 12V 225A N200	1
③	*	91	WORKSHOP CONSUMABLES	

PC	Type	Code	Description (Original)	#
	☐		the time,	
①	☒	VO-85023456	FAN, EXCH	1
①	☒	VO-21503575	SEALING RING	1
①	☒	MK-NARV56306	CABLE TIE 1=25PC	1
①	☐	LO-A	-	1.87
①	*	91	WORKSHOP CONSUMABLES	

2021-06-09 - Mileage: 960911 - Order nr: 8291620

①	☐	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
	☐		(STD)	
①	☐	VO-1752700	Final drive oil, change. Lube area	0.6
①	☐	LO-3000	FIT NEW THROTTLE PEADLE	0.8
①	☐	LO-311	BATTERIES SLOW TO CRANK	1
①	☐	LO-510	CARRY OUT REPORT ON ALL	0.7
①	*	80	SUBLET REPLACE WINDSCREEN	
①	☐	LO-177	CARRY OUT VEHICLE INSPECTION	1.5
①	☐	LO-460	REAR TAIL LIGHT BRACKET CRACKED	1
①	☐	LO-251	CHECK & REPORT ON EXHAUST	5.5
①	☐	LO-210	CHECK & REPORT ON OIL LEAKING	1.4
①	☐	LO-561	REPLACE AIR DRYER FILTER & RESET	0.5
①	☒	VO-23690622	SERVICE KIT	1
①	☒	VO-20779040	AT G/BOX FILTER	1
①	☒	AU2-CAL85121714	VOLVO SAE50 TRANS BULK	17
①	☒	AU2-CAL85121715	DIFF OIL 85W140 BULK	34
①	☒	AU2-23446985	VOLVO EFB 12V 225A N200	1
①	☒	VO-22318844	STAY	1
①	☒	VO-22058737	AIR SPRING	1
①	☒	AU2- WUR0673205010	BROWN LOC 2"	2
①	☒	VO-20855371	GASKET	6
①	☒	VO-20938963	SEAL	1

PC	Type	Code	Description (Original)	#
⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	3.5
⊗	*	1707300	Service alert system, configuration and	
⊗	*	93A	GREASE	
⊗	*	94	WASTE DISPOSAL	
⊗	⊗	VO-24122024	SERVICE KIT	1
⊗	⊗	AU2-AMP85158448	MACK DEO VDS-4.5 BULK, PER LT	37
⊗	⊗	LO-560	REKIT AIR DRIER - PARTS IN CAB	0.8
⊗	*	260	CHECK BOTTOM RAD HOSES & CLAMPS	
⊗	*	91	CONSUMABLES	

🔍 2021-10-28 - Mileage: 1017973 - Order nr: 8294574

⊗	*	M	PLEASE FILL IN	
	📧		Contact: karl 0417627342	
⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊗	⊗	VO-1751300	Engine, oil and filter, replace. Lube ar	0.4
⊗	⊗	VO-2330600	Fuel filter, replace (one)	0.2
⊗	⊗	VO-2331100	Filter, water separator, replace	0.3
⊗	⊗	VO-1707300	Service alert system, configuration and	0.4
⊗	⊗	VO-24122024	SERVICE KIT	1
⊗	⊗	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	33
⊗	⊗	LO-3000	report on cause of derate in 36	3
⊗	⊗	VO-5616600	Air drier cassette, replace	0.3
⊗	⊗	VO-23690622	SERVICE KIT AIR DRIER	1
⊗	⊗	VO-22827995	SENSOR	1
⊗	⊗	VO-21574984	DOSAGE VALVE	1
⊗	*	97	ENVIRONMENTAL CHARGE	
⊗	*	91	WORKSHOP CONSUMABLES	

🔍 2021-06-30 - Mileage: 961326 - Order nr: 8292048

⊗	⊗	LO-210	engine fan coming on running all	5
---	---	--------	----------------------------------	---

PC	Type	Code	Description (Original)	#
⊕	■	OTH-NLM8NYLOC	NUT M8 NYLOC S/S	8
⊕	■	VO-60113320	WASHER M8x30	8
⊕	■	VO-6861717	ALUMINIUM STRIP	2
⊕	⊙	LO-510	electronic park brake fault	1
⊕	⊙	LO-230	fuel leaking at filter housing bung	0.4
⊕	⊙	LO-561	air leaking at air tank drain cocks	0.35
⊕	⊙	LO-461	2nd drive axle rear air bags leaking	1.2
⊕	■	VO-22058741	AIR SPRING	2
⊕	■	VO-23640316	DRAIN VALVE M22	1
⊕	■	VO-20744692	CAP	1
⊕	■	VO-20378934	FUSE 10 AMP MINI	1
⊕	*	91	WORKSHOP CONSUMABLES	

🔍 2022-02-15 - Mileage: 1067698 - Order nr: 8297141

⊕	*	M	PLEASE FILL IN	
	📄		Contact:KARL - 3268 2266	
⊕	⊙	LO-262	COOLING SYSTEM COOLANT	1
⊕	■	VO-21884469	FILLER CAP	1
⊕	*	91	WORKSHOP CONSUMABLES	

🔍 2022-02-11 - Mileage: 1064282 - Order nr: 6054510

	📄		ECM KMS:1063194 FUEL USED: ENG HRS:14628	
⊕	⊙	LO-210	ASSESS ENGINE HUNTING	6
⊕	■	VO-60110514	OBD PLUG	1
⊕	■	VO-20716774	TERMINAL	6
⊕	■	VO-20378932	5A FUSE, MINI	1
⊕	*	91	CONSUMABLES	

🔍 2022-02-10 - Mileage: 1063163 - Order nr: 6054429

	📄		ECM KMS:1063163 FUEL USED: ENG HRS:14626	
--	---	--	--	--

PC	Type	Code	Description (Original)	#
2022-05-26 - Mileage: 1119308 - Order nr: 8299463				
	*	M	PLEASE FILL IN	
			Contact:KARL - 3268 2266	
		VO-1774400	Basic service. Chassis lubrication and o	2.7
		VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
		VO-2331100	Filter, water separator, replace	0.3
		VO-2330600	Fuel filter, replace (one)	0.3
		VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
		VO-1752700	Final drive oil, change. Lube area	0.6
		VO-2141300	Valves and unit injectors, adjust	3
		LO-810	fit weather sheild l/h/s only	0.4
	*	80	SUBLET REPLACE WINDSCREEN	
		VO-5616600	Air drier cassette, replace	0.4
		LO-460	replace r/h rear mud guard only	2
		LO-311	check & report on batteries	0.4
		AU2-AMP23068346	VOLVO VDS 4.5 BULK	33
		VO-24122024	SERVICE KIT	1
		VO-23690622	SERVICE KIT AIR DRIER	1
		VO-20779040	AT G/BOX FILTER	1
		AU2-CAL85121714	TRANS OIL SAE50 BULK	17
		AU2-CAL85121715	DIFF OIL 85W140 BULK	34
		MK-9728-MG650B	MUDGUARD WIDE BLAC	1
		VO-84429874	WIND DEFLECTOR KIT	1
		VO-82359314	GLASS	1
		VO-24112584	DOOR LOCK	1
		VO-82217705	ATTACHMENT KIT	6
		VO-84597792	DOOR HANDLE	1
		VO-23105744	VOLVO MUDFLAP RIBBED	1
		VO-23452020	CHEVRON L/HAND	1
		VO-984736	BOLT M8*30 FL	8

PC	Type	Code	Description (Original)	#
			vehicle will be going for machinery	
		VO-24122024	SERVICE KIT	1
		AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	33
		LO-360	engine light on dash check and report	4.5
		VO-23381562	FILTER	1
		VO-21954674	STRAINER	1
		VO-3944785	COMP AIR FILTER	1
		MK-NARV56306	CABLE TIE 1=25PC	1
		VO-85021151	PUMP UNIT, EXCH	1
			Next Service:add 40,000km 3 months	
			Conncted to laptop,	
			Carried out SCR system build up test, found pressure slow	
			to build up.	
			Removed walkplate, removed pickup in un belly tank, found	
			that the teabag on the filter had been cut off.	
			Removed strainer in inlet pump and found full of debris.	
			Removed and replaced new filters and cleaned pick up.	
			Removed and replaced tank breather filter.	
			Re-checked pump pressure and found still low, Pump needs	
			replacement.	
			Removed and replaced adblue pump assembly, cleared all	
			fault codes and checked operation all OK.	
	*	91	WORKSHOP CONSUMABLES	
2022-06-30 - Mileage: 1129329 - Order nr: 8300382				
	*	M	PLEASE FILL IN	
			Contact: karl 0417627342	
		LO-2000	rectify boost or exhaust leaks under	2
		VO-21312237	CHARGE AIR HOSE	1
	*	91	WORKSHOP CONSUMABLES	

PC	Type	Code	Description (Original)	#
			drive RH front airbag leaking.	
			Checked air fittings on gearbox and air compressor. OK.	
			Held foot on brake and checked for leaks with park brake on and off. OK.	
			Connected laptop and read fault codes. No relevant faults.	
			Removed LH fuel tank walkplate and connected clear hose to fuel return and checked for airtightness. OK. Removed fuel tank pick up and checked gauze filter. OK. Refit pick up.	
			Carried out fuel pressure test. ~340kPa at idle ~460kPa at 1200RPM. Got engine up to operating temp and carried out cylinder balancing test.	
			#5 injector negative compensation >50% after 5min @ idle.	
			checked start up of the engine after it was sitting for 2 days started with in 10 sec. Checked fault codes	
			Rechecked for bubbles in the return when cold and hot	
			Carried out cylinder balance test and number 5 were well out of spec.	
			Checked injectors with cut off test and found engine was smoother when number 5 was shut off	
			Checked fuel feed pressure was within spec	
			Checked history and found this engine imbalance has been going on at least since December 2022	
⊗	*	91	WORKSHOP CONSUMABLES	

🔍 2023-06-08 - Mileage: 1161700 - Order nr: 8308664

⊗	*	ACC	PLEASE FILL IN	
			Contact: Karl 0417 627 342	
⊗	⊗	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊗	⊗	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
⊗	⊗	VO-2330600	Fuel filter, replace (one)	0.3
⊗	⊗	VO-2331100	Filter, water separator, replace	0.3

PC	Type	Code	Description (Original)	#
			CONNECTED LAPTOP AND CARRIED OUT INJECTORS TRIM PROGRAMMING	
			STEAM CLEANED AREA	
			ROAD TESTED TRUCK WITH SENSOR MONITORING ALL WITHIN SPECS	
			CHECKED OVER AFTER ROAD TEST ALL OK.	
			INSPECTED FOUND R/H REAR CAB AIR BAG LEAKING	
			REMOVED AND REPLACED LEAKING AIRBAG	
			BUILT AIR SYSTEM AND CHECKED OPERATION + FOR LEAKS	
			CHECKED CAB RIDE HEIGHT ALL OK.	
			INSPECTED SUSPENSION AIR BAGS FOR LEAKS.	
			FOUND 1ST DRIVE L/H FRONT AIR BAG LEAKING AND 2ND DRIVE	
			R/H FRONT AIR BAG LEAKING. REMOVED & REPLACED BOTH AIR	
			BAGS, CHECKED OPERATION AND FOR LEAKS ALL OK.	
			REMOVED ALL COMPONENTS AROUND ENGINE HARNESS	
			REMOVED & REPLACED ENGINE HARNESS	
			FITTED BACK ALL COMPONENTS AROUND ENGINE HARNESS	
			REPLACED CRANK PRESSURE SENSOR AS OIL WAS LEAKING THROUGH	
			THE CONTACTS.	
⑩	*	91	WORKSHOP CONSUMABLES	

2023-08-18 - Mileage: 1172284 - Order nr: 8311188

⑩	*	M	PLEASE FILL IN	
			Contact:karl 0417 627 342	
⑩	⊙	LO-230	truck hard to start	4
			cranks a long time before it starts	
⑩	⊙	LO-560	air leak on truck	1
			driver saying will drop down over night. check and report	
⑩	*	97	ENVIRONMENTAL CHARGE	
			Checked vehicle for air leaks. No audible leaks.	
			Checked airbags with soapy water.	
			Found 1st drive axle LH front airbag leaking. Found 2nd	

PC	Type	Code	Description (Original)	#
⊗	⌘	VO-85013271	UNIT INJECTOR, EXC	1
⊗	⌘	VO-85013271	UNIT INJECTOR, EXC	1
⊗	⌘	VO-85013271	UNIT INJECTOR, EXC	1
⊗	⌘	VO-85013271	UNIT INJECTOR, EXC	1
⊗	⌘	VO-85013271	UNIT INJECTOR, EXC	1
⊗	⌘	VO-22343361	CABLE HARNESS	1
⊗	⌘	VO-21351717	INJECTOR SLEEVE W/ORING KIT	6
⊗	⌘	VO-1161963	RUBBER GREASE FETT	1
⊗	⌘	MK-NARV56406	CABLE TIE 1=100PK	1
⊗	⌘	VO-21344774	BOLT M10*50 FL	6
⊗	⌘	VO-983472	GREY CABLE TIE 145MM	8
⊗	⌘	MK-NARV56306	CABLE TIE 1=25PC	1
⊗	⌘	VO-21634017	CRANK PRESSURE SENSOR	1
	⌘		2ND DRIVE R/H FRONT	
	⌘		CONNECTED LAPTOP & CHECKED FAULT CODES	
	⌘		read through ro 8311188	
	⌘		attached	
	⌘		FOUND ACTIVE INJECTOR FAULTS	
	⌘		CARRIED OUT INJECTOR SHUT DOWN TEST	
	⌘		CARRIED OUT CYLINDER BALANCE TEST	
	⌘		CARRIED OUT ENGINE COMPRESSION TEST	
	⌘		FOUND #5 INJECTOR NEGATIVE COMPENSATION	
	⌘		DRAINED COOLANT SYSTEM	
	⌘		REMOVED ROCKER COVER	
	⌘		REMOVED ROCKER SHAFT & ALL 6X INJECTORS	
	⌘		EXTRACTED ALL 6X INJECTOR SLEEVES	
	⌘		CLEANED ALL SURFACES	
	⌘		INSTALLED ALL NEW INJECTOR SLEEVES	
	⌘		INSTALLED ALL NEW 6X INJECTORS	
	⌘		FITTED BACK INJECTORS & ROCKER SHAFT	
	⌘		CARRIED OUT VALVE & UNIT INJECTORS ADJUSTMENT	

PC	Type	Code	Description (Original)	#
⊙	Ⓜ	VO-990951	NUT M10 FL LOCKING	1
⊙	Ⓜ	VO-8150740	PIN - SPACER	1
⊙	Ⓜ	VO-22252267	MOUNTING STRAP	1
⊙	Ⓜ	VO-FREIGHT	FREIGHT	104
⊙	Ⓜ	VO-1629499	EXH CLAMP FH	2
⊙	Ⓜ	VO-990951	NUT M10 FL LOCKING	2
⊙	Ⓜ	VO-994195	BOLT M10*50 FL	2
	Ⓜ		email, mollerkt@gmail.com	
	Ⓜ		Next Service:45,000km 3 months	
	Ⓜ		check and report only.	
	Ⓜ		check scr muffler not blocked	
	Ⓜ		as vehicle takes long time to build	
	Ⓜ		road speed & road speed drops off	
	Ⓜ		as soon as hills come up	
⊙	*	91	WORKSHOP CONSUMABLES	

2023-10-17 - Mileage: 1181875 - Order nr: 8312264

⊙	*	ACC	PLEASE FILL IN	
	Ⓜ		Contact:Karl Moller 0417 627 342	
⊙	⊙	LO-210	HARD STARTING ISSUE	13
⊙	⊙	LO-560	AIR LEAKING FROM R/H/S	1
	Ⓜ		REAR CAB AIR BAG	
⊙	*	97	ENVIRONMENTAL CHARGE	
	Ⓜ		REPLACE ALL 6X INJECTORS & TUBES	
⊙	⊙	LO-460	AIR LEAKING AT SUSPENSION AIR BAGS	2
	Ⓜ		1ST DRIVE AXLE L/H FRONT	
⊙	Ⓜ	VO-24182857	AIR SPRING	1
⊙	Ⓜ	VO-22058741	AIR SPRING	1
⊙	Ⓜ	VO-22058737	AIR SPRING	1
⊙	⊙	VO-2860300	Wiring harness, replace. Unit injectors	6
⊙	Ⓜ	VO-85013271	UNIT INJECTOR, EXC	1

PC	Type	Code	Description (Original)	#
	☐		workshop.	
	☐		load test batteries, all ok.	
	☐		Just needs a charge	
	☐		-found negative leads on batteries loose, tighten	
	☐		-checked static current draw, dropped down to 0.1 amsp	
	☐		after a few minutes	
	☐		-cleaned and refitted leads	
	☐		-checked charge rate 28.8 @ 30 amps	
	☐		- put on charge	
	☐		no faults were found at this time.	
①	*	91	WORKSHOP CONSUMABLES	

2024-03-25 - Mileage: 1208961 - Order nr. 8316476

①	*	ACC	PLEASE FILL IN	
	☐		Contact:karl 0417 627 342	
①	①	VO-1774400	Basic service. Chassis lubrication and o	2.7
①	①	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
①	①	VO-2330600	Fuel filter, replace (one)	0.3
①	①	VO-2331100	Filter, water separator, replace	0.3
①	*	97	ENVIRONMENTAL CHARGE	
①	①	LO-210	low power complaint since injectors	6
	☐		and tubes were replaced in october by us. refer history.	
①	①	VO-24122024	SERVICE KIT	1
①	①	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	33
①	①	VO-21383182	SILENCER	1
①	①	VO-8150742	PIN - THREADED	2
①	①	VO-60112471	HEX. SOCKET SCREW	1
①	①	AU2- WUR0664130761	CUT OFF DISC 76MM	1
①	①	VO-984758	BOLT M10*70 FL GR10.9	1
①	①	VO-973430	SPACER SLEEVE	1

Vehicle Service Records (VSR Explorer)

Repair history D-200857

Registration nr: XQ92AO Chassis ID: D-200857 VIN: YV5RG40DXED200857
 Market type: Country: Delivery date: 2015-7-24

PC	Type	Code	Description (Original)	#
<u>2025-08-14 - Mileage: 1219052 - Order nr: 8328325</u>				
⊕	*	ACC	PLEASE FILL IN	
⊕	⊗	LO-311	BATTERIES GOING FLAT	4
	⊗		travel to customers yard, pick up vehicle and return to	
⊕	⊗	LO-810	fit wide angle mirror rhs	0.5
	⊗		part is in the storgae locker top shelf back of cab	
⊕	⊗	LO-810	replace wether shields in the cab	0.8
	⊗		Contact:KARL - 3268 2266 0417 627 342 Kms: 1,219,052kms. Hrs:	
	⊗		16,795hrs.	
⊕	⊗	AU2- WUR089010810	BRAKE CLEAN	1
	⊗		Removed old weather sheild clean up	
	⊗		door frame fit new weather shield	
	⊗		Removed back of mirror.	
	⊗		Removed mirror.	
	⊗		Unplugged.	
	⊗		Plugged new mirror in.	
	⊗		Installed new mirror.	
	⊗		Reinstalled back plastic.	



UD TRUCKS



Volvo Commercial Vehicles - Brisbane
Brisbane North
PARTS TAX INVOICE

** Reprint **

Invoice to:

Page No..... 1

Invoice number.... 6124318 - 004100

Invoice Date..... 24/01/18

Customer Ref..... [REDACTED]

Terms..... CASH (0)

ABN Number.....

Our reference.... 6124318

Advisor was

Jose Fuentes (41)

Remarks.....

Deliver To:

A201

Loc	Partnumber	Description	List Price	Disc Code	Qty Del	Qty B/O	Amount
30002	VO 22332594	LAMP	250.41	0-07	1.0		225.37

Total Net..... 225.37

Sub Total Surcharge

Freight/Opening Fee

Deposits/Other.....

GST..... 22.54

TOTAL 247.91

Launched at the Brisbane truck show
24 months, 500,000 km warranty
On parts and labour in our workshops
Starts on the 1st of June 2017

CASH PAYMENT

Feb -
Visa
24/1/18

Bank Details: BSB 244-000 Account 100588074

Volvo Group Australia Pty Ltd
ABN 27 000 761 250650 Macarthur Avenue, Pinkenba 4008
PO Box 3915, MT OMMANEY, QLD 4074Tel : 07 3710 3710
Fax : 07 3200 1187

www.vcvbrisbane.com.au

Parts Hotline - 13000PARTS



Volvo Commercial Vehicles - Brisbane Brisbane North

WORKSHOP TAX INVOICE

Invoice To:



Page no.: 1

Invoice number: 8261479 004100
Invoice Date: 28/03/18

Customer Ref:

Due Date:
Terms: CASH (0)
ASH Number:

Our reference: 8261479 - 004100
Advisor was: Mark Cowell (40)

Remarks:

Vehicle Details

Reg Number: QV11CK VOLVO (0) FH (4 6*4)
Chassis No: 200857
Owner/Len: 440,200 Engine Hrs: 6,066
Contract:
VIN: YV5RG40DXFD200857
Fleet:

Operation / Part Number	Description	List Price	Nett Price	Quantity Invoiced	B/Ord	Amount
1774400	Basic service.					378.00
2331100	Filter, water separator, replace					42.00
2330600	Replace fuel filter					42.00
1751300	Engine, oil and filter, replace, full area					56.00
VO FK188	*FILTER KIT	142.00	142.00	1.0		142.00
AL2 CAL85121795	VOS 4 ENGINE OI	5.87	5.87	3300		193.71
97	ENVIRONMENTAL CHARGE					19.50
Subtotal: 001 Order Job 001:						873.21
VO 84433698	AIRBAG MOD (91)			1.0		Warranty
8842000	Airbag module, replace					
Subtotal: 002 Campaign C0022:						0.00
363	REPLACE WIPERS					42.00
VO 82480683	WIPER BLAIN KIT	36.18	36.18	2.0		72.36
Subtotal: 003 Order Job 003:						114.36
350	L/H TAIL LIGHT BRACKET LOOSE					56.00
FITTED TWO NEW BOLTS AND SECURED TAIL LIGHT MOUNTING						
VO 984869	BOLT M14*20 1	6.60	6.60	2.0		13.20
VO 994522	NUT M14 FLANGED	7.65	7.65	2.0		15.30

Volvo Group Australia Pty Ltd
ABN 27 000 781 258

650 Macarthur Avenue, Pinkenba 4008
PO Box 3915, MT OMMANEY, QLD 4074

Tel: 07 3710 3710
Fax: 07 3280 1807

www.vcvbrisbane.com.au

Parts Hotline - 13000PARTS



Volvo Commercial Vehicles - Brisbane
Brisbane North

WORKSHOP TAX INVOICE

Invoice to



Page no.....: 2

Invoice number....: 8261479 - 004100

Invoice Date.....: 20/03/18

Customer Ref.....:

Operation / Part Number	Description	List Price	Nett Price	Quantity Invoiced	Quantity B/Ond	Amount
Subtotal: 004 Order Job 004:						74.50
91	WORKSHOP CONSUMABLES					30.80
Launched at the Brisbane Truck show						
24 months 500,000 km warranty						
On parts and labour in our workshops						
Starts on the 1st of June 2017						
Sub Total Parts..						425.57
Sub Total Labour..						616.00
Sub Total Other..						50.30
Sub Total Package:						
GST.....						100.99
TOTAL						1202.16



Customer Acceptance:

The Terms and Conditions detailed on the reverse of this document apply: Bank Details: BSB 244-000 Account 100288074

Volvo Group Australia Pty Ltd
ABN 27 000 761 260

650 Macarthur Avenue, Pinkenba 4008
PO Box 9015, MT OMMANEY, QLD 4074

Tel : 07 3710 3710
Fax : 07 3200 1907

www.vcybrisbane.com.au

Parts Hotline - 13000PARTS



Volvo Commercial Vehicles - Brisbane Brisbane North

WORKSHOP TAX INVOICE

Invoice To :

Page no. 1



Invoice number... 8266955 - 004100
Invoice Date... 04/10/18

Customer Ref....

Due Date.....
Terms..... CASH (0)

Our reference... 8266955 - 004100
Advisor was.....
Brian Cairns

Vehicle Details

Reg Number: X09270 WXVQ (D) F11 C4 6M4
Chassis No: 200817
Odometer... 530,876 Engine Hrs: 7,311
Contract...
VIN... YV5RG40DXED200857
Fleet...

Remarks...
REPAIRED 04/10/18

PA - V/C

Operation / Part Number	Description	List Price	Nett Price	Quantity -- Invc'd B/Ord	Amount
510	CHECK AND RECTIFY AIR LEAK FROM VALVE INSIDE OF CHASSIS NEAR G-BOX. INVESTIGATED AND FOUND 1X AIR PIPE RUBBED THROUGH. CUT AWAY TIES AND REPAIRED. RESECURED AND CHECKED FOR LEAKS.				140.00
VO 969246	VIP 8MM JOINER	20.12	20.12	1.0	20.12
VO 969249	VIP 8MM JOINER	33.13	33.13	1.0	33.13
VO 992247	SWIVE	26.56	26.56	1.0	26.56
MC KARB65006	CABLE TIE 1-10P	3.53	3.53	1.0	3.53
VO 976446	VIP 12MM JOINER	25.79	25.79	1.0	25.79
VO 969290	VIP 12MM JOINER	27.60	27.60	1.0	27.60
Subtotal: 001 Order Job 001:					276.72
250	REPLACE SPLIT EXHAUST FITX. REPLACED PIPE AS REQUIRED.				70.00
VO 2313/065	EXHAUST PIPE	273.48	273.48	1.0	273.48
Subtotal: 002 Order Job 002:					343.48
210	CHECK AND REPORT ON THE CAUSE OF HOT OIL LEAK AT THE COMPRESSOR. CHECKED AND FOUND THE AIR COMPRESSOR LEAKING OIL FROM THE CYLINDER HEAD. REPLACED THE COMPRESSOR AND CHECKED OPERATION.				420.00
VO 85013941	COMPRESSOR EXCH SERIAL NO: 45295	2413.80	2413.80	1.0	2413.80
VO 471/08	SEAL RING	4.56	4.56	1.0	4.56
VO 997065	O-RING	15.40	15.40	1.0	15.40
VO 955006	O-RING MGP VEP	4.09	4.09	1.0	4.09
AL2 WUR089010010	BRAKE CLEAN	8.45	8.45	2.0	16.90

PAYMENT

Volvo Group Australia Pty Ltd
AHN 27 000 761 258

850 Macarthur Avenue, Pinkenba 4008
PO Box 3016, MT OMMANEY, QLD 4074

Tel : 07 3710 3710
Fax : 07 3200 1007

www.vcvbrisbane.com.au



UD TRUCKS



Volvo Commercial Vehicles - Brisbane Brisbane North

WORKSHOP TAX INVOICE

Invoice To :

Page no.....2



Invoice number... B266955 - 004100

Invoice Date... 01/10/18

Customer Ref.....

Operation /Part Number	Description	List Price	Nett Price	Quantity Invoiced B/Ord	Amount
---------------------------	-------------	---------------	---------------	----------------------------	--------

Subtotal: 003 Order Job 003. 2874.75

91 WORKSHOP CONSUMABLES 31.50

Launched at the Brisbane Truck show
24 months 500,000 km warranty
On parts and labour in our workshops
Starts on the 1st of June 2017

Sub Total Parts... 2864.95
Sub Total Labour... 630.00
Sub Total Other... 31.50
GST... 362.65

TOTAL 3879.10

Paid by Visa

Customer Acceptance

The Terms and Conditions stated on the reverse of this document apply. Bank Details: BSB 265-000 Account 100500074

Volvo Group Australia Pty Ltd
ABN 27 000 761 260

650 Macarthur Avenue, Pinkenba 4008
PO Box 3915, MT GAMMANLY, QLD 4076

Tel : 07 3710 3710
Fax : 07 3260 1097

www.vcvbrisbane.com.au

Truck Centre (WA) Pty. Ltd.

ABN 15 426 470 002
 PO Box 77, Guildford WA 6055
 Admin/Finance : 08 9213 2600
 Fax : 08 9217 3625
 Website: www.truckcentrewa.com.au



WORKSHOP TAX INVOICE

Invoice To:



Page No..... 1 / 1

Invoice number... 2197633 - 000001

Invoice Date..... 24/09/18

Customer Ref..... PAYMENT RSC 22/09/

Exp Date.....

Terms..... CASH

Our reference.... 2197633 - 000001

Adviser was.....

Vikrant Deshpande

Remarks.....

Vehicle Details

Reg Number: XQ92AD (0) VOLVO FH 14 6+4
 Chassis No: 200B57
 Odometer... 521,607 Engine Hrs: 7,181
 Contract...
 VIN YV5K640UX8D200B57
 Fleet

Operation / Part Number	Description	List Price	Sell Price	Quantity Invoiced	Quantity B/Ord	Amount
1774400	BASIC SERVICE					574.00
WD 85136742	*FILTER KIT (188	145.00	145.00	1.0		145.00
	Carried out basic service as per specifications.					
93	ENGINE OIL & GREASE					210.00
94	WASTE DISPOSAL					35.00
	Subtotal: 001 BASIC SERVICE:					984.00
93	CONSUMABLES					34.44
WE'RE NOW ONLINE FOR YOUR NEXT BOOKING!						
Book your truck into our service dept simply with our new, easy to use app. Available via Google Play & iTunes Store search 'Truck Centre WA - booking app'						
Sub Total Parts...						145.00
Sub Total Labour...						574.00
Sub Total Other...						293.44
GST.....						101.82
T O T A L						1120.26

SPARE PARTS/WORKSHOP BOOKING

- * Where the parts required by the customer of changing the oil and oil filter are shown as recommended in the vehicle's manual, please ensure they are correctly fitted to the engine.
- * The only parts in the goods issues in the form of our specifications.
- * Orders of substitute parts accepted for 14 days from date of delivery, no penalty.
- * Orders of substitute parts after 14 days, 10% penalty.
- * Orders of substitute parts after 14 days, 20% penalty.
- * Orders of substitute parts after 14 days, 30% penalty.
- * Special log in and log out and delivery charges will apply if required.
- * Additional charges may apply for delivery of substitute parts.

Bank Details : Truck Centre WA Pty Ltd BSB 036 406 Acc 122 774

Albany Bunbury Geraldton Guildford Kewdale Port Hedland Spearwood



ABN: 64 472 284 302

Cloncurry Workshop

Lot 2, Hensley Dr
CLONCURRY QLD 4624



kennysautoelectrical@dodo.com.au

All hours

(07) 4789 4649



www.kennysautoelectrical.com.au



Connect on FACEBOOK
@KennysAutoElectrical

Townsville Workshop

& Postal Address

74-76 Northern Links Cct
BOHLE QLD 4818

CASH SALE
CASH SALE

PLEASE PAY BY

21/12/2018

AMOUNT

\$0.00

INVOICE DATE

21/12/2018

TAX INVOICE NO. 33866

Order No.:

Site: XQ92AO 540 Volvo

Description

[REDACTED]

[20/12/2018] - Work Note

Travelled to job site to inspect tail lights dropping out. Arrived and checked operation. Everything working okay. Driver was moving around his trailers and they dropped out. Checked tubes - all good. Jacked cab and checked feeds into and coming out of reducer. Found faulty reducer. Customer coming to workshop in the morning to get replaced.

[21/12/2018] - Work Note

Proceed to site/job and inspect short in trailer wiring. Inspected trailer wiring and diagnosed short in top rear left marker light. Check over harness. Repaired broken and cut wiring on marker lights. Replaced deutsch plug in tail lights and secured any loose wiring.

Rego:XQ92AO

KM:569502

Item	Quantity	Unit Price	Total
6 WAY DT KIT W/ SOLID TERMINALS	1.00	\$22.72	\$22.72
Shop Supplies/ Consumables	5.00	\$1.10	\$5.50
Townsville Labour	6.50 hrs	\$100.00	\$650.00

PLEASE NOTE: We have new banking details as of 01st May 2018. Please update your system with the Payment Details below.

"Our workmanship and staff are valuable to us, as is a satisfied customer to our business. If this fails at any time please let us know." Thank you.

Sub-Total ex GST	\$678.22
GST	\$67.82
Total inc GST	\$746.04
Amount Applied	\$746.04
Balance Due	\$0.00



Annual service

Truck Centre (WA) Pty Ltd Kewdale

City	Kewdale	Customer	[REDACTED]
Date:	01/2018	Address	[REDACTED]
Repair Order No.	2190767		
Mileage	402,513	Model	FH (4)
Chassis ID	0 200837	Engine	013C940
Registration No.	OV11CL	Axle Configuration	6'4

- Not applicable	1 Repair recommended	2 Repair immediately	3 Checked, without notes
------------------	----------------------	----------------------	--------------------------

Road test

- ☒ 1. Function check of parking brake
- ☒ 2. Check warning and control lamps
- ☒ 3. Check seat belt
- ☒ 4. Check after start
- ☒ 5. Check during road test
- ☒ 6. Check after road test
- ☒ 7. Connect/disconnect PC
- ☒ 8. Check height regulation for air suspension

External check

- ☒ 9. Check lighting and reflectors
- ☒ 10. Check engine oil level
- ☒ 11. Check fluid levels in windscreen and headlamp washer reservoirs
- ☒ 12. Check refrigerant tank, condenser, pipes and hoses
- ☒ 13. Check fluid level in clutch fluid reservoir
- ☒ 14. Check coolant frost protection and fluid level
- ☒ 15. Check radar sensor
- ☒ 16. Check sealing on servo pump, oil containers, oil hoses and steering fluid
- ☒ 17. Check tyre pressure
- ☒ 18. Check tyre wear
- ☒ 19. Check fuel tank, hoses, air vent pipe and connections
- ☒ 20. Check air intake and air deflector
- ☒ 21. Check pivot play, V-hub

- ☒ 22. Check rear shock absorbers
- ☒ 23. Check ball joints - dri, leakage, attachment, fluid level, components and battery bus
- ☒ 24. Check of AdBlue system
- ☒ 25. Check rear wheels
- ☒ 26. Check rear wheel bearings
- ☒ 27. Check alignment of trailing axle or seized driven axle
- ☒ 28. Check silencer for rust/damage

Engine bay

- ☒ 29. Check drive belts and belt tensioners
- ☒ 30. Check A/C - compressor for A/C unit
- ☒ 31. Check of electrical connections and cables for alternator, starter motor and powerwing unit
- ☒ 32. Check engine mountings
- ☒ 33. Check radiator, hoses and pipes
- ☒ 34. Check hoses and pipes for the intercooler
- ☒ 35. Check radiator fan, fan shroud and fan ring with rubber seal
- ☒ 36. Check engine, engine powered power take-off and compressor for leakage
- ☒ 37. Check fuel piping and lines
- ☒ 38. Check for exhaust leakage
- ☒ 39. Check air pipe between air intake and turbo
- ☒ 40. Check engine mount baffles
- ☒ 41. Power steering system, oil level check

Lubrication, oil and fluid level check

- ☒ 42. Cab lubrication
- ☒ 43. Coupling lubrication
- ☒ 44. Fifth wheel lubrication
- ☒ 45. Rod end pin lubrication
- ☒ 46. Check oil level in gearbox
- ☒ 47. Check sealing of retarder
- ☒ 48. Check sealing on the gearbox and power take-off, and check cables
- ☒ 49. Check ventilation for gearbox and PTO
- ☒ 50. Check oil level in retarder
- ☒ 51. Check propeller shafts and universal joints, slide joints and support bearings
- ☒ 52. Check sealing of rear axle and intercooler
- ☒ 53. Check rear axle ventilation
- ☒ 54. Check oil level in rear axle

Front suspension, steering gear

- ☒ 55. Check steering link system
- ☒ 56. Check king pin bearings
- ☒ 57. Check front shock absorbers
- ☒ 58. Check front wheels
- ☒ 59. Check front wheel bearings

Check underneath the vehicle

- ☒ 60. Check clutch wear
☒ 61. Check exhaust pipe and silencer or particulate filter
☒ 62. Check anti-roll bar
☒ 63. Check springs and U-bolts
☒ 64. Check chassis frame and crossmembers
☒ 65. Check compressed air lines and hoses
☐ 66. Check bogie air
☒ 67. Check air suspension bellows
☒ 68. Check sealing on the vehicle speed sensor
☒ 69. Check brake linings
☒ 70. Check brake calipers and brake discs
☒ 71. Check brake cylinders, levers and pins
☒ 72. Check brake lever travel

Finish

- ☒ 73. Finish

Clutch status**Clutch**

X1	25.5
X2	24.7
Y	0.8

X1		
X2		
Y		

Battery status**Battery**

Battery	Test code
Inner / Front battery	5.00
Outer / Rear battery	5.00

Brakes and then**Brake linings**

Start with the front and move towards the rear		Front								Rear
Thickness in mm	Right	85.2	86.8	77.2						

IMPACT 4.04.00, 01/01/18

Thickness in mm	Left	86.8	85.2	82.9						

Brake levers

Start with the front and move towards the rear		Front								Rear
Stroke in mm	Right									
Stroke in mm	Left									

Tyre wear

Start with the front and move towards the rear		Front								Rear
Tyre rest thread depth in mm	Right	11		14	10					
				14	10					
				14	10					
Tyre rest thread depth in mm	Left	11		14	10					

- M EXTERNAL SUNVISOR BROKEN LHS
- MH LH BULB/LED INDICATOR AND (LED STRIP)
- * M RHF FOG LIGHT INOP + BROKEN LENS
- CM LH TAIL BRACKET BENT + LENS BROKEN
- M RH BOTTOM STEP SHROUD BROKEN OFF
- L RH STEER MUDGUARD BROKEN
- MH COMPRESSOR HEAD LEAKING OIL
- * M - 2X BOLTS MISSING RH FENG
- LM FRONT CRANK SEAL WEAPIN
- LM STEERING BOX BOTTOM NUT WET
- MH MUFFLER PIPE WELD CRACK (AD BLUE LEAK)
- M DRIVERS MIRROR TAPED ON


Truck Centre (WA) Pty. Ltd.

ABN 16 120 470 825
 PO Box 77, Guildford WA 6053
 Suburban Office : 08 9251 2500
 Fax Office : 08 9277 3829
 Website : www.truckcentrewa.com.au



Proforma Invoice

Estimate For :



Page no : 1

Estimate Number : 2190/67 000001

Estimate Date :

Expiry Date :

Customer Ref : (000)

Terms : (000)

AIN Number :

Vehicle Details

Reg Number: QV110L (0) VOLVO FH 4 6*4

Chassis No: 200857

Odometer : 402,513

Contract :

VIN : YV5N1400X10200857

Fleet :

Advisor : Mr. [Redacted]

Daniel Contino

Remarks :

Operation / Part Number	Description	List Price	Nett Price	Quantity	Amount
501F1	SHIFT : NIGHT TIRE LBS- 5538 FREE BURN- 174,960 TCM KM- 402,513 [Redacted]				
	Subtotal: 001 Order Job 001:				0.00
560	CARRY OUT AIRRIDER REKIT AND CALIBRATION				145.00
VR 22223804	KIT	121.43		1.0	121.43
	Subtotal: 002 Order Job 002:				266.43
1706700	30 Months (CO) download and oil sample Only valid for Australian market				
VR 8394887	WARRANTY KIT (96)			1.0	Warranty
	Subtotal: 003 Order Job 003:				0.00
* 177P1DEC15BASIC SERVICE SPECIAL VOLVO	JULY TO DEC 2017 OFFER				170.90
*VR 16183	FILTER KIT ** Package **			1.0	
	Subtotal: 004 Order Job 004:				170.90
VR	EXCESS/MAJORS				15.00

CASH PAYMENT

Albany
 27 Pershing Road
 Albany 6330
 T: 08 9344 3470
 F: 08 9344 3465

Bunbury
 1st Fl Westover Dr
 Bunbury 8230
 T: 08 9724 8000
 F: 08 9724 8061

Geraldton
 1st Fl 2428 Barker St
 Geraldton 6530
 T: 08 9384 3500

Guildford
 Vehicle Sales/Admin
 78-84 Koonen Hwy
 South Guildford 6050
 P: 08 9252 2800
 F: 08 9277 3829

Kewdale
 507 Albany Hwy
 Kewdale 6105
 T: 08 9252 3752
 F: 08 9252 3763

Port Hedland
 15 Flinders Dr
 Woodhead 6721
 T: 08 9177 3006
 F: 08 9177 3786

Spencer
 11 Abigail Rd
 Port Spencer 5600
 T: 08 9434 8700
 F: 08 9434 8701

RTA : AU2084

RTA : AU14948

RTA : AU33570

RTA : AU42617

APPROVED

5



Estimate For:

Estimate Number: 2190767 DWG001

Estimate Date

Entry Date

Customer No. _____ EASY

[illegible]

**** 24 MONTHS WARRANTY ON FITTED PARTS ****
If our workshop fits genuine parts in your Mack or Volvo, we'll double the warranty from 12 to 24 months and we'll also cover the warranty on the labour. Offer effective 1.6.17. Conditions apply.

Allany
27 Hudson Road
Weymouth 01978
T: (617) 924-3229
F: (617) 924-3475

ATA-AU2004-4

Bunbury
 Lot 35 Wetherby Dr
 Perth 6020
 P. on 0724 0800
 F. on 0724 0507

ETA: 6514940

Gerdöten
 Lot 2026 Ramen St
 Hagen 6020
 T 06 9022 2008

Guildford
Vehicle Sales/Adm.
 75 Mt. Vernon Hwy.
 North Guilford, BC019
 P. On 425-3 2800
 F. 425-3277 ext. 301

Kawato
161/ Alameda St
Kawato, UT 84037
P: 801/962-2222
F: 801/962-2243

HTA / ALL3070

Port Hedland
 371 Moorpark Rd
 Westport WA 6721
 T: 081 971 72 2000
 E: 081 971 72 2000

ETA: A042817

Sperrywood
 87. Mayan Rd.
 Miami, FL 33133
 P: (305) 462-5411
 F: (305) 462-1025

800-10-100-416-878
P.O. Box 75, Quakertown, PA 18951
Administration : (610) 761-2300
Fax : (610) 761-2300
Website : www.fkcc.org



Invoice to:

KEWDALE E. WA. 6105

Page No. 1 1 1
Invoice Number: 1546091 000001
Invoice Date: 09/03/19
Customer Ref:
Terms: CASH

Deliver To:
CASH ACCOUNT - PARTS REMOVAL

KENDALE WA 98145
Deliv by: COUNTRY PICKUP 6105

Our reference... 1546001
Advisors was
William Perez
Remarks...
Paid in full \$1886.27

Loc	Partnumber	Description	List Price	Disc Code	Qty Ord	Qty B/O	Amount
257A	VO 22647976	GEAR SELECTOR	1642.06	0-06	1.0		1642.06
						Total Net.....	1642.06
						GST.....	164.21
						Total	1806.27

Commonwealth Fund

TRUCK CENTRAL WA PTY
KIMBERLEY WA
TERMINAL 46185900
REFERENCE 023780

CUSTOMER LISTING

CARD NO: 4140-296211
 EXPIRY DATE:
 Visa Credit
 CREDIT
 PURCHASE \$1805.22
 TOTAL BAL \$1805.22

APPROVED
AUTH NO: 02-923
AID: A0000000037010
BTCH# TUR:00800-00000
CASH#01 00000000000000000000
09 MAR 2019 10:14
THANK YOU

SPACE PARTITIONING WITH BRICKS

During the past several years, the following have been the most common and effective in terms of increasing the number of students who are successful in completing the mathematics course:

- *Use a study or learning contract that sets a goal for the student.*
- *Require students to complete assignments on time or receive consequences.*
- *Monitor and encourage good study habits, both at home and in class.*
- *Monitor and encourage good class participation.*
- *Give all students a chance to be successful and achieve a passing grade in the course.*
- *Require students to complete assignments and submit them on time.*

Back Details: Truck Control WA Pty Ltd 1888 036 408 Acc 123 774

Address:
21 Parkside Road
Wilmington, DE 19804
+1 610 364-2670
F 02 364 3425

HYA - A110000

Address:
100 W. Washington St.
Rm. 1000
Chicago, IL 60601
Tel: 312/329-1000

RTA/ALH4500

Chemisches
von 2026 bis 2027
Gemeinschaft der
1. 2026 bis 2027

Gulfport
Vehicle Sales/Leases
 78 G. Eastern Hwy
 Gulfport, MS 39201
 P. 601/557-7000
 F. 601/557-7000

0-500 0277-0617

Keywords:
 5HT_{2A} antagonist, anxiety, depression, mood, panic disorder, serotonin

0174 • J. Neurosci., September 24, 2008 • 28(39):9673–9682

[illegible]

1176 AUGUST

Equine world
37 August 84
Horse Lake 6103
© UB 3434 6623

1997

Truck Centre (WA) Pty. Ltd.

ABN 13 636 474 871
PO Box 77, Quindalup WA 6025
Administration : 08 9290 2688
Finance : 08 9277 3025
Website : www.truckcentrewa.com.au



PARTS TAX INVOICE

Invoice to:

33
CASH ACCOUNT - PARTS KEWDALE

KEWDALE WA 6105

Page No. 1 / 1

Invoice number... 1546091 - 000001

Invoice Date... 09/03/19

Customer Ref.....

Terms..... CASH

Deliver To:

CASH ACCOUNT - PARTS KEWDALE

KEWDALE WA 6105

Deliv by: COUNTER PICKUP

Our reference... 1546091

Advisor was

William Perez

Remarks.....

Paid to full \$1806.27

LOC	Partnumber	Description	List Price	Disc Code	Qty Del	Qty B/O	Amount
257A	VO 22547976	GEAR SELECTOR	1642.06	0-06	1.0		1642.06
Total Net.....							1642.06
GST.....							164.21
TOTAL							1806.27

CASH PAYMENT

Parts/Service For
Valve -

SPARE PARTS/WORKSHOP INVOICE

Always the goods supplied for the purpose of repairing the goods concerned shall be subject to a three month return policy unless stated otherwise. Goods supplied for the purpose of selling are not subject to this policy.

This policy only applies to goods supplied for the purpose of selling. Goods supplied for the purpose of repairing are not subject to this policy.

Goods supplied for the purpose of repairing are not subject to this policy unless otherwise stated.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Prices of finished goods after 11.50pm: 12% weekly.

Bank Details: Truck Centre WA Pty Ltd BSB 030 406 Acc 122 774

Albany	Bunbury	Geraldton	Guthrie	Kewdale	Port Hedland	Spearwood
27 Portman Road Weymouth 8300 P: 08 9444 3470 F: 08 9444 3426	Unit 25 Westbank Drive Perth 6000 P: 08 9324 8806 F: 08 9324 8807	Unit 26 Westbank Drive Perth 6000 P: 08 9324 8806 F: 08 9324 8807	Vehicle Sales/Advice 25 G. Eastern Hwy South Perth 6150 P: 08 9277 3025 F: 08 9277 3026	Unit 11 Albany Rd Kewdale 6105 P: 08 9452 5452 F: 08 9452 5453	13 Manlymore Rd Wagholah 6721 P: 08 9372 2086 F: 08 9372 2087	31 Main Rd Spearwood 6113 P: 08 9434 3622 F: 08 9434 3623
RTA: ALJ00064	RTA: ALJ00064			RTA: ALJ00064	RTA: ALJ00064	

Printed by: (signature)

Truck Centre (WA) Pty. Ltd.

ABN 18 128 416 678
PO Box 77, Guildford WA 6050
Alday/Bunbury : 08 9253 3600
Fremantle : 08 9277 3189
Website : www.truckcentre.com.au



WORKSHOP TAX INVOICE

Invoice To :

004521

Page no..... 1 / 1

Invoice number.... 2202176 - 000001

Invoice Date..... 08/04/19

Customer Ref..... PAYMENT REC 05/04/

Due Date.....

Terms..... CASH

Our reference.... 2202176 - 000001

Advisor was.....

Condor Jackson

Remarks.....

Vehicle Details

Reg Number: KQ52AO (D) VOLVO FH (4 6*4

Chassis No: 200657

Odometer... 616,273 Engine Hrs: 8,505

Contract...

VIN TVSR0400XKD00057

Fleet

Operation / Part Number	Description	Unit Price	Net Price	Quantity	Invoiced R/Ord	Amount
331	STARTER MOTOR - REPLACE - INTERNALLY FAILED. Test starting multiple times, clicked 3x times, disconnected the negative battery terminal. Unplug and unbolts to starter motor. Swap signal plug from old to new starter and fit to truck. Reconnect battery terminal. Start truck, all OK					296.00
VO 80020789	EXCH STARTER MD NEW SERIAL# V47529 M009TGE77128 OLD SERIAL# V14076 M009TGE771	1127.53	1127.53	1.0		1127.53
	Subtotal: 02% STARTER MOTOR NOISY/CLICKING:					1423.53
91	CONSUMABLES					17.76
WE ARE NOW OPEN AT 6 AM EVERYDAY!						
We are pleased to advise that we are now open at 6.00 AM everyday for your convenience! Book today!						
Sub Total Parts...						1127.53
Sub Total Labour...						296.00
Sub Total Consumables...						17.76
GST.....						144.13
TOTAL						1585.42

SPARE PARTS/WORKSHOP INVOICE

- * Where the quote is issued for the purpose of supplying the parts and labour only and not for the purpose of supplying the parts and labour only and not for the purpose of supplying the parts and labour only.
- * This invoice is the property of the company and must be returned to the company with the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.
- * Return of the invoice to the company will be taken as an indication of acceptance of the parts and labour only.

Bank Details : Truck Centre WA Pty Ltd BSB 036 488 Acc 122 774

Alday Bunbury Geraldton Guildford Kewdale Port Hedland Spearwood

Truck Centre (WA) Pty. Ltd.

8470 19 120 425 6277
 1011 Ave. N.E., Grand Rapids, MI 49503
 Registration: 800 426 3550
 Fax: 616 937 7026
 Website: www.rockwellautomation.com



Workshop Estimate

Received 12 June 2006; accepted 12 June 2006

Page no. 1 / 2

PAULINE M. HANCOCK, ... 0269651 - 400607

02/05/19

Expiry Date: 31/05/16

Customer: DeC... 3202744

Term..... CASI

网络地址: <http://www.163.com>

Indirizzo: 00144 Roma

References

學期時分已過半，15時許，適逢下課。

RECEIVED: JANUARY 10, 1997

Ullrich et al. *Proc* 2001127

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 101–108

Continued...

YIN +1+2+3+ YV54C603XRT2G68A7

$$S^2 = \frac{1}{n} \sum_{i=1}^n (x_i - \bar{x})^2$$

Operation /Part Number	Description	List Price	Disc Code	Quantity	Amount
---------------------------	-------------	---------------	--------------	----------	--------

80284-100176-100178-100179-100180-100181-100182-100183-100184-100185-100186-100187-100188-100189-100190-100191-100192-100193-100194-100195-100196-100197-100198-100199-100200-100201-100202-100203-100204-100205-100206-100207-100208-100209-100210-100211-100212-100213-100214-100215-100216-100217-100218-100219-100220-100221-100222-100223-100224-100225-100226-100227-100228-100229-100230-100231-100232-100233-100234-100235-100236-100237-100238-100239-100240-100241-100242-100243-100244-100245-100246-100247-100248-100249-100250-100251-100252-100253-100254-100255-100256-100257-100258-100259-100260-100261-100262-100263-100264-100265-100266-100267-100268-100269-100270-100271-100272-100273-100274-100275-100276-100277-100278-100279-100280-100281-100282-100283-100284-100285-100286-100287-100288-100289-100290-100291-100292-100293-100294-100295-100296-100297-100298-100299-100300-100301-100302-100303-100304-100305-100306-100307-100308-100309-100310-100311-100312-100313-100314-100315-100316-100317-100318-100319-100320-100321-100322-100323-100324-100325-100326-100327-100328-100329-100330-100331-100332-100333-100334-100335-100336-100337-100338-100339-100340-100341-100342-100343-100344-100345-100346-100347-100348-100349-100350-100351-100352-100353-100354-100355-100356-100357-100358-100359-100360-100361-100362-100363-100364-100365-100366-100367-100368-100369-100370-100371-100372-100373-100374-100375-100376-100377-100378-100379-100380-100381-100382-100383-100384-100385-100386-100387-100388-100389-100390-100391-100392-100393-100394-100395-100396-100397-100398-100399-100400-100401-100402-100403-100404-100405-100406-100407-100408-100409-100410-100411-100412-100413-100414-100415-100416-100417-100418-100419-100420-100421-100422-100423-100424-100425-100426-100427-100428-100429-100430-100431-100432-100433-100434-100435-100436-100437-100438-100439-100440-100441-100442-100443-100444-100445-100446-100447-100448-100449-100450-100451-100452-100453-100454-100455-100456-100457-100458-100459-100460-100461-100462-100463-100464-100465-100466-100467-100468-100469-100470-100471-100472-100473-100474-100475-100476-100477-100478-100479-100480-100481-100482-100483-100484-100485-100486-100487-100488-100489-100490-100491-100492-100493-100494-100495-100496-100497-100498-100499-100500-100501-100502-100503-100504-100505-100506-100507-100508-100509-100510-100511-100512-100513-100514-100515-100516-100517-100518-100519-100520-100521-100522-100523-100524-100525-100526-100527-100528-100529-100530-100531-100532-100533-100534-100535-100536-100537-100538-100539-100540-100541-100542-100543-100544-100545-100546-100547-100548-100549-100550-100551-100552-100553-100554-100555-100556-100557-100558-100559-100560-100561-100562-100563-100564-100565-100566-100567-100568-100569-100570-100571-100572-100573-100574-100575-100576-100577-100578-100579-100580-100581-100582-100583-100584-100585-100586-100587-100588-100589-100590-100591-100592-100593-100594-100595-100596-100597-100598-100599-100600-100601-100602-100603-100604-100605-100606-100607-100608-100609-100610-100611-100612-100613-100614-100615-100616-100617-100618-100619-100620-100621-100622-100623-100624-100625-100626-100627-100628-100629-100630-100631-100632-100633-100634-100635-100636-100637-100638-100639-100640-100641-100642-100643-100644-100645-100646-100647-100648-100649-100650-100651-100652-100653-100654-100655-100656-100657-100658-100659-100660-100661-100662-100663-100664-100665-100666-100667-100668-100669-100670-100671-100672-100673-100674-100675-100676-100677-100678-100679-100680-100681-100682-100683-100684-100685-100686-100687-100688-100689-100690-100691-100692-100693-100694-100695-100696-100697-100698-100699-100700-100701-100702-100703-100704-100705-100706-100707-100708-100709-100710-100711-100712-100713-100714-100715-100716-100717-100718-100719-100720-100721-100722-100723-100724-100725-100726-100727-100728-100729-100730-100731-100732-100733-100734-100735-100736-100737-100738-100739-100740-100741-100742-100743-100744-100745-100746-100747-100748-100749-100750-100751-100752-100753-100754-100755-100756-100757-100758-100759-100760-10

本区分为两个自然区，即山区和丘陵平原区。山区包括本区北部、东部和南部，丘陵平原区包括本区中部和西部。

THIS ESTIMATE INCLUDES ALL PARTS AND

LAURENCE HARTFORD TO THOMAS, THESE PARTS

WE OBTAINED THESE. ANY ADDITIONAL

PAKISTAN ON BALANCE OF PAYMENTS POSITION

Copyright © 2005 by The McGraw-Hill Companies, Inc.

TO THE EDITOR: We read with interest the article by

10. 王明賢：《我國工業保險之研究》，《民生》2卷1期。

Subtotal: 001 Order Sub 001:

0.00

2348 *Chrysomelidae: Chrysomelinae: Eumecurus*

234.001

Indirizzo: 10121 Roma, Via del Corso, 323 Tel. 06/478371

294.00

258 Remove Airline, clean out,
install a 1/2" blue breather mod on pick up and install
with a filter - Pressure codes for Airline. Also replace
RXX sensors as active codes. Carry out leakage test & Airline
pump test
Notes: Airline pump & leakage valve quoted because it fails
test.

000000 000000

Q70 148122ML-1/2HP-100	100 MESH FILTER 1/2"	47.58	5-99	1.0	17.30
Q70 AB14	ADHESIVE 15L	27.45	5-25	4.0	109.00
Q70 ADHESIVE FILTER BRACKET	ADHESIVE PICKUP FILTER	92.80	5-99	1.0	87.00
Q70 1731174-7-50455	GREEN 200 MESH 811.0	34.00	6-99	1.0	35.00

[illegible]

Truck Centre (WA) Pty. Ltd.

1000 1000 0000
PO Box 17, Cammeray WA 6045
Australia
Tel: 08 922 2264
Fax: 08 922 2265
Website: www.truckcentre.com.au



Workshop Estimate

Estimate For:

Page 1 of 1

Estimate Number: 0260651 - 000001
Estimate Date: 01/05/16
Expiry Date: 31/05/16
Customer Ref: 2202744

Operation	Part Number	Description	Unit Price	Disc Code	Quantity	Amount
	006 9001-10	STAINLESS STEEL HOSE	9.00	5-09	2.0	18.00
	006 9001-10	NYLON KLEIN	6.50	5-09	2.0	13.00
	006 9001-10	CONNECTOR	19.16	0-09	1.0	19.16
	006 9001-10	CLAMP, ORCA ROSE	1.40	0-09	2.0	2.80
	006 9001-10	HOSE (normal)	10.88	0-09	1.0	10.88
	006 9001-10	CLAMP	4.26	0-10	1.0	4.26
	006 9001-10	M6*12 IN BOLT	0.35	0-08	2.0	0.70
	006 9001-10	WASHER	0.04	0-06	1.0	0.04
	006 9001-10	PUMP UNIT	1314.46	0-06	1.0	1314.46
	006 9001-10	DISC VALVE	0.00	0-06	1.0	0.00
	006 9001-10	COMBINED TANK UNIT	150.49	0-06	1.0	150.49
		last day in stock				
	006 9001-10	ANTI-TAMPER ISOLIN	0.45	0-08	4.0	1.80
	006 9001-10	SCOOTING	13.57	0-09	1.0	13.57
	006 9001-10	CONNECTOR	20.38	0-08	1.0	20.38
	006 9001-10	CABLE TERMINAL	1.52	0-09	4.0	6.08

Subtotal: 003 Order Job 003: 1877.00

004 Blighted fuel cross over bar in damaged by roof and hitting machine

Subtotal: 004 Order Job 004: 306.00

01 CONSUMABLES 109.00

we are now open at 9 AM EVERYDAY

Sub Total Parts...	2092.00
Sub Total Labour...	1779.00
Sub Total Other...	100.00
GST...	465.00

We are pleased to advise that we are now open at 9.00 AM everyday for your convenience! Back today!

TOTAL 4136.00

Adelaide 1000 1000 0000 Tel: 08 922 2264 Fax: 08 922 2265	Brisbane 1000 1000 0000 Tel: 07 555 5555 Fax: 07 555 5556	Gold Coast 1000 1000 0000 Tel: 07 555 5555 Fax: 07 555 5556	Perth 1000 1000 0000 Tel: 08 922 2264 Fax: 08 922 2265	Sydney 1000 1000 0000 Tel: 02 922 2264 Fax: 02 922 2265	Melbourne 1000 1000 0000 Tel: 03 922 2264 Fax: 03 922 2265	Geelong 1000 1000 0000 Tel: 03 922 2264 Fax: 03 922 2265
---	---	---	--	---	--	--


Truck Centre (WA) Pty. Ltd.

ABN 49 438 438 875
PO Box 77, Guildford WA 6055
Administration : 08 9332 6004
Fax : 08 9332 6004
Website : www.truckcentre.com.au



Proforma Invoice

Estimate For :



Page no. 1 / 1

Estimate Number : 2202744 000001

Estimate Date : 02/05/14

Expiry Date :

Customer Ref : X1092A1

Terms : Cash

Vehicle Details

Reg Number : XC92ND (0) VOLVO FH (4 6*4

Chassis No : 200857

Odometer : 633,507

Contract :

VIN : YV6RG40DX10200857

Fleet :

Advisor was :

Daniel Coutinho

Remarks :

Operation / Part Number	Description	List Price	Disc Code	Quantity	Amount
-------------------------	-------------	------------	-----------	----------	--------

SHIPT : SHIPT : DAY
END HRS : 8/11 TIME BURN : 273437

NOTE: PLEASE PRINT TECH TOOL REPORT AND ATTACH TO JOB CARD.

Subtotal: 001 Order Job 001

0.00

208 NOX SENSOR FAULT - 36 HRS TO DE HALL - CODES

296.00

EC10M - C109115 X37

EC10M - C109115 X1

(HAS HIT A FEW ROCKS ON THE WAY OVER)

EMS - P116300 X1

Connect laptop and check codes - Found Nox sensor fault act valve and pressure pressure leakage. Also informed on fuel cross over fuel tank bracket bent. Supplied ESTE 200651 949000 ahead

Subtotal: 002 Order Job 002

296.00

640 GRINDING NOISE ON PS WHEN TURNING
RIGHT HAND TURNS
OVER LAST HAS REPAIRED THE HUMP

296.00

VO 80127800 TL DEXRON2 ATF

20.00 0.00

1.0

20.00

Inspected and found power steering fitting in chassis

Albany
117 Henderson Street
Widby WA 6550
P: 08 9944 3400
F: 08 9944 3425

RTA : A030099

Burby
1st Fl Westfield City
Burby VIC 3083
P: 08 9774 0000
F: 08 9774 0007

RTA : A014040

Devonport
1st Fl 2028 Barker St
Devonport TAS 7310
P: 08 9965 0000
F: 08 9965 1000

Guildford
Vehicle Sales/Adm
70 Gr Eastern Hwy
Guildford WA 6122
P: 08 9332 6004
F: 08 9332 6020

RTA : A033000

Kewdale
507 Albany Hwy
Kewdale WA 6105
P: 08 9332 6004
F: 08 9332 6020

RTA : A033000

Port Hedland
111 Port Hedland St
Port Hedland WA 6721
P: 08 9412 2000
F: 08 9412 2000

RTA : A042017

Speerswood
31 Speerswood St
Speerswood VIC 3040
P: 08 9412 2000
F: 08 9412 2000

RTA : A042017

Truck Centre (WA) Pty. Ltd.

ABN 10 120 419 829
PO Box 17, Guildford WA 6050
Administration : 08 9253 1000
Facsimile : 08 9473 1020
Website : www.truckcentrewa.com.au



Proforma Invoice

Estimate For :

Page no. = 2 / 3



Estimate Number: 2202744 000001
Estimate Date: 02/05/19
Expiry Date:
Customer Ref: X04240

Operation / Part Number	Description	List Price	Disc Code	Quantity	Amount
	loose Retightened filling cleaned and topped up fluid				
	Check over after road test - OK				

Subtotal: 003 Order Job 003:

316.73

258 REMOVE AD BLUE TANK AND CLEAN OUT
Carry out Adblue breather mod on pick up and install external filter. Pressure codes for adblue. Also replace NOX sensor as active codes. Carry out Dosage test & Adblue pump test. Adblue pump intermittently losing pressure. R&R Adblue pump. Carry out dosing test - all ok. Deleted codes, test drove & check over - All ok.

VO 22827993	SENSOR	808.01	0.00	1.0	766.37
	NEW SERIAL # 107180201001277				
OTH AAB127M1	1/2" 100 MESH FILTER 1/2"	47.50	5.99	1.0	47.50
OTH ADBL01 FILTER BRACKET	ADBLUE PICKUP FILTER	82.80	5.99	1.0	66.74
OTH CP23174	7 304SS SCREEN 200 MESH SILV	35.08	5.99	1.0	35.08
OTH NCR W3-10	STAINLESS STEEL HOSE	3.37	5.99	2.0	6.74
OTH NYP60608	NYLON ELBOW	6.58	5.99	2.0	12.00
VO 20744595	CONNECTOR	19.16	0.00	1.0	19.16
VO 21032572	CLAMP UNIA HOSE	1.40	0.00	2.0	2.80
VO 21429181	HOSE (copper)	10.88	0.00	1.0	10.88
VO 3088511	CLAMP	4.26	0.10	1.0	4.26
VO 0804724	M6*12 FL BOLT	0.55	0.00	2.0	1.10

UNLESS REQUESTED

OTH AAB15	ADBLUE 15L	27.45	5.25	4.0	98.82
VO 22851845	PUMP UNIT	1314.46	0.00	1.0	1248.74
	NEW SERIAL # 044002160 23783				
VO 22203918	COMBINED TANK UNIT	358.49	0.00	1.0	340.57
VO 20734499	ANTI TAMPER SEAL IN	0.45	0.00	4.0	1.80
VO 21106105	HOUSING	13.57	0.00	1.0	12.71
VO 21780355	CONNECTOR	20.38	0.00	1.0	16.30
VO 080975	CABLE TERMINAL	1.62	0.00	4.0	6.08
PK NAV56308	CABLE TIE 1-25 PK	4.35	1.07	1.0	4.35
VO 080464	STRIP CLAMP - CABLE	0.83	0.10	5.0	4.15

Aburay
27 Freshwater Road
Wilyup 6150
P 08 9444 9420
F 08 9444 9425

Bunbury
Lot 25 Westside Dr
Murray 6230
P 08 9724 0000
F 08 9724 0007

Geraldton
1st 2628 Bunker Rd
Geraldton 6730
P 08 9282 3500
F 08 9282 3502

Guildford
Vehicle Sales/Admin
56 Gt Eastern Hwy
South Guildford 6050
P 08 9253 2600
F 08 9277 3020

Kewdale
1077 Ansonby Rd
Kewdale 6105
P 08 9392 5257
F 08 9392 5253

Perth Roadside
10 Freshwater Rd
Westfield 6170
P 08 9172 2800
F 08 9172 7000

Spearwood
11 Midland Rd
Spearwood 6108
P 08 9434 8022
F 08 9434 8230

RTA - A1130004

RTA - A1130004

RTA - A1130004

RTA - A1130004

02/05/19

Truck Centre (WA) Pty. Ltd.

ABN 18 120 878 878
 PO Box 77, Guildford WA 6055
 Administration 40 6253 2688
 Fax/Facsimile 40 6277 4671
 Website: www.truckcentrewa.com.au



Proforma Invoice

Estimate For :



Page no 3 / 3

Estimate Number : 2202744 000001
 Estimate Date : 02/06/19
 Expiry Date :
 Customer Ref : XG2240

Operation / Part Number	Description	List Price	Disc Code	Quantity	Amount
VO R2963261	FILTER/MAGNET	40.62	0-06	1.0	38.59
VO 20428158	CABLE TIE	0.84	0-10	0.0	5.04

Subtotal: 004 Order Job 004: 3935.86

230 Straighten cross over bracket as bent. 296.00

Subtotal: 005 Order Job 005: 296.00

91 CONSUMABLES 100.00

WE ARE NOW OPEN AT 6 AM EVERYDAY!

We are pleased to advise that we are now open at 6.00 AM everyday for your convenience! Book today!

Sub Total Parts...	2777.59
Sub Total Labour...	297.00
Sub Total Other...	100.00
GST	494.47
T O T A L	5439.06

Abany
 27 Fremont Road
 Wilby WA 6170
 P: 08 9614 1475
 F: 08 9614 3426

RTA: A1138966

Bunbury
 1st Fl, 25 Warwick Ave
 Bunbury WA 6230
 P: 08 9224 0688
 F: 08 9224 0687

RTA: A114886

Geraldton
 Unit 2025 Burke St
 Geraldton WA 6730
 P: 08 9201 2555
 F: 08 9224 2558

Guildford
 Vehicle Sales/Admin
 76 St Vincent Place
 South Guildford WA 6125
 P: 08 9253 2030
 F: 08 9277 4209

Kewdale
 600 Ardenbury Rd
 Kewdale WA 6105
 P: 08 9252 5252
 F: 08 9252 5253

RTA: A1133070

Port Hedland
 13 Fitzgerald St
 Workipool WA 6721
 P: 08 9112 3466
 F: 08 9112 2488

RTA: A1142017
 Locality

Spearwood
 21 Mount Rd
 Spearwood WA 6110
 P: 08 9424 4422
 F: 08 9424 5288

Locality

Truck Centre (WA) Pty. Ltd.

ABN 15 120 470 879
 PO Box 77, Guildford WA 6055
 Administration : 08 9252 2100
 Fax: 08 9271 3470
 Website : www.truckcentrewa.com.au



WORKSHOP TAX INVOICE

Invoice To :



Page No.....1 / 2

Invoice number.....4421162 - 000004

Invoice date.....20/01/20

Customer Ref.....



Due Date.....

Terms.....CASH

Our reference.....4421162 - 000004

Advisor WAS.....

Mathew McCondy

Remarks.....

Vehicle Details

Reg Number: XG92AQ (0) VOLVO FH (4 6*4)
 Chassis No: 200857
 Odometer.: 743,279 Engine HRS: 10,227
 Contract.:
 VIN : YV5RG40HXED200857
 Fleet : :

Operation / Part Number	Description	List Price	Nett Price	Quantity Invoiced	B/Ord	Amount
-------------------------	-------------	------------	------------	-------------------	-------	--------

INFO DETAILS
 KM:743,279km's FUEL BURN:319,943ltr's ENG HRS:10,227Hr's

REMARKS
 OFFSITE WORK NO.
 DESTINATION: Geraldton workshop
 AFTER HOURS: YES
 CALL OUT TIME 1600
 DATE 18-01-20

PAID 2'000 ON CASH

SUBTOTAL: 000 ORDER JOB 001

0.00

510 AIR DRYER FAULT ON DASH

600.00

(VIN 1-7CWA) 7CWA LATE OPEN

200.00 200.00

1.0

200.00

VG 23250134 KIT

130.00 130.00

1.0

130.00

Vehicle presented with warning on dash for airdryer.
 Carried out checks and found cartridge overdue for replacement. Replaced with new filter and reset warning.

SUBTOTAL: 002 Order Job 002:

930.00

31 CONSUMABLES

10.00

Truck Centre (WA) Pty. Ltd.

ABN 19 126 476 878
PO Box 77, Guildford WA 6121
Administration : 08 9253 2583
Facilities : 08 9277 3323
Website: www.truckcentrewa.com.au



WORKSHOP TAX INVOICE

Invoice To :



Page no.....: 2 / 2

Invoice number...: 4421162 - 000000

Invoice Date.....: 20/01/20

Customer Ref.....:

Operation	List	Nett	Quantity	
Work Order	Price	Price	Invoiced B/Ord	Amount
WE'RE NOW ONLINE FOR YOUR NEXT BOOKING!				
Book your truck into our service dept simply with our new, easy to use app. Available via Google Play & iTunes Store. Search 'Truck Centre WA - booking app'			Sub Total Parts..:	330.00
			Sub Total Labour..:	600.00
			Sub Total Other..:	16.00
			GST.....:	96.61
			T O T A L	1042.61



ARCclick
Licence # AU05738
ABN 44 010 009 462
**ACTION
AUTO ELECTRICS**
Pty Ltd

52 Savage St Pinkenba, QLD 4008 | PO BOX 124 Pinkenba, QLD 4008
PHONE: 61 (07) 3673 3200 | FAX: 61 (07) 3623 3211
EMAIL: actions@actionauto.com.au | www.actionauto.com.au

PLEASE PAY BY

30/03/2020

AMOUNT

\$317.03

INVOICE DATE

27/02/2020

TAX INVOICE NO. 421020

Date: 27/02/2020
Job No.: 52555
Order No.: XQ92AO
Job Name:
Site: XQ92AO

Description

Registration number:

XQ92AO

Vehicle Identification Number (VIN)

YV5RG40DXED200857

Description:

2014 VOLVO FH SERIES PRIME MOVER

(26/02/2020) - Work Note

Travel to the site, check and repair trailer light operation.

Found plug and base required replacing at "B" trailer connection.

Replaced and tested lights, some lights not operational.

Found 1 side clearance light out on "A" trailer.

Tested input supplies, all okay.

Remove and replaced faulty light as required.

On Site (Pinkenba)

Part #	Item	Quantity	Unit Price	Total
H2053	LAMP LED CLEARANCE RED/AMBER	1.00	\$39.08	\$39.08
MP7	PLUG 7 POLE TRAILER METAL	1.00	\$19.13	\$19.13
MB7	SOCKET 7 POLE TRAILER METAL	1.00	\$20.00	\$20.00
	SUNDRIES	1.00	\$16.00	\$16.00
	On Site Labour	1.50 hrs	\$130.00	\$195.00
Service Fee				\$15.00
Labour				\$195.00
Materials				\$78.21
Sub-Total ex GST				\$288.21
GST				\$28.82
Total				\$317.03

HEAVY EQUIPMENT SPECIALISTS
24 HOUR ON SITE SERVICE



Arcstick
CERTIFIED
Licence # AU06738
ADN 44 010 000 462
ELECTRICS
Pty Ltd

52 Savage St Pinkenba, QLD 4008 | PO BOX 124 Pinkenba, Ql 4008
PHONE: 61 (0) 7 3623 3200 | FAX: 61 (0) 7 3623 3211
EMAIL: actiona@actionauto.com.au | www.actionauto.com.au

PLEASE PAY BY

30/03/2020

AMOUNT

\$317.03

INVOICE DATE

27/02/2020

TAX INVOICE NO. 421020

Thank you for your business.
Please leave us a review on google.

[Click here to leave a review!](#)

Sub-Total ex GST	\$288.21
GST	\$28.82
Total inc GST	\$317.03
Amount Applied	\$0.00
Balance Due	\$317.03

How To Pay



Credit Card (MasterCard or Visa)

Pay Online: actionautoelectrics.smartcoupons.com.au/pay/online/

Please call 61 7 3623 3200 to pay over the phone.



Direct Deposit

Bank	Commonwealth Bank of Australia
Acc. Name	Action Auto Electrics
BSB	094-145
Acc. No.	10362040

INVOICE NO. 421020

HEAVY EQUIPMENT SPECIALISTS
24 HOUR ON SITE SERVICE



ARCclick
Licence # AU08738
ABN 44 010 000 462
Pty Ltd

57 Savage St Pinkenba, QLD 4008 | PO BOX 124 Pinkenba, QLD 4008
PHONE: 61 (07) 3623 3200 | FAX: 61 (07) 3623 3211
EMAIL: actiona@actionauto.com.au | www.actionauto.com.au

PLEASE PAY BY

30/03/2020

AMOUNT

\$317.03

INVOICE DATE

27/02/2020

TAX INVOICE NO. 421020

Date: 27/02/2020
Job No.: 52595
Order No.: XQ92AO
Job Name:
Site: XQ92AO

Description

Registration number

XQ92AO

Vehicle Identification Number (VIN)

YV5RG40DXED200657

Description

2014 VOLVO FH SERIES PRIME MOVER

(26/02/2020) - Work Note

Travel to the site, check and repair trailer light operation.

Found plug and base required replacing at "B" trailer connection.

Replaced and tested lights, some lights not operational.

Found 1 side clearance light out on "A" trailer.

Tested input supplies, all okay.

Remove and replaced faulty light as required.

On Site (Pinkenba)

Part #	Item	Quantity	Unit Price	Total
H2053	LAMP LED CLEARANCE RED/AMBER	1.00	\$39.08	\$39.08
MP7	PLUG 7 POLE TRAILER METAL	1.00	\$19.13	\$19.13
MB7	SOCKET 7 POLE TRAILER METAL	1.00	\$20.00	\$20.00
	SUNDRIES	1.00	\$15.00	\$15.00
	On Site Labour	1.50 hrs	\$130.00	\$195.00
Service Fee				\$15.00
Labour				\$195.00
Materials				\$78.21
Sub-Total ex GST				\$288.21
GST				\$28.82
Total				\$317.03



ARCtick
CERTIFIED
Licence # AU06738
ABN 44 010 009 462
Pty Ltd

52 Savage St Pinkenba, QLD 4008 | PO BOX 124 Pinkenba, QLD 4008
PHONE: 61 (07) 3623 3200 | FAX: 61 (07) 3623 3211
EMAIL: actiona@actionauto.com.au | www.actionauto.com.au

PLEASE PAY BY

30/03/2020

AMOUNT

\$517.03

INVOICE DATE

27/02/2020

TAX INVOICE NO. 421020

Thank you for your business.

Please leave us a review on google.

[Click here to leave a review!](#)

Sub-Total ex GST	\$288.21
GST	\$28.82
Total inc GST	\$317.03
Amount Applied	\$0.00
Balance Due	\$317.03

How To Pay



Credit Card (MasterCard or Visa)

Pay Online actionautoelectric.com.au/online-payment/

Please call 07 3623 3200 to pay over the phone.



Direct Deposit

Bank Commonwealth Bank of Australia

Acc. Name Action Auto Electric

BSB 064-145

Acc. No. 10160040

INVOICE NO. 421020