

TAX INVOICE NUMBER L70241

5-7 CAPELLI ROAD WINGFIELD SA

5013

For Enquiries

PHONE A/C 02-87880000 PHONE SERVICE 08-81696400

Customer Feedback

PHONE 1300 137 838

EMAIL customerfeedback@crown.com

Customer No. Reference No. 313534

ORDER DATE	ORDER NO.	INVOICE DATE	JOB LOCATION	JOB ADDRESS
13/09/2023	.nick	18/09/2023	*GEPPS CROSS SA	7 O'Connor Court
FLEET No.	SERIAL NUMBER	MODEL NUMBER		GEPPS CROSS SA
	5A533674R	TRADEIN	BREAKDOWN SERVICE CHARGES	5094

1.45045		QTY.	UNIT PRICE	TOTAL PRICE
LABOUR	320	1.5		292.50
<i>l</i> 2381033	320	1	2,737.11	2,737.11
ENVIRONMENTAL CHARGE		1	17.75	17.75
SUNDRIES AND CONSUMABLES		1	27.65	27.65
		ENVIRONMENTAL CHARGE	ENVIRONMENTAL CHARGE 1	ENVIRONMENTAL CHARGE 1 17.75

Supply Value	\$ 3,075.01	GST RATE 10.0 %	GST AMOUNT		307.50
			TOTAL INVOICE AMOUNT	AUD	3,382.51

Payment due date is 18/10/2023.

Please pay on this invoice. No statement will be issued. Additional Surcharge on Credit Card payments

- Visa/Master Credit Card 1.1%

FOR ALL DIRECT DEPOSITS
Please remit funds to Crown Equipment Pty Ltd
Bank Name: National Australia Bank
BSB No: 082-276

Account No: 509265108

Please email remittance advice to banking@crown.com or fax remittance advice to (02) 8788-0642.

Page 1 of 1



SERVICE JOB REPORT

Crown Equipment Pty Ltd ABN 79 000 514 858

5-7 CAPELLI ROAD WINGFIELD SA

5094

5013

Invoice to: SJ Enterprises 7 O'Connor Court GEPPS CROSS SA

Job Address:

7 O'Connor Court GEPPS CROSS SA

5094

Job Number: X 7559359

Date: 13/09/2023

Time: 10:23 Order Number: .nick

13 - BREAKDOWN SERVICE

Model: SX3030TT-4250

Serial Number: 5A533674R

Fleet Number:

Reference No.: L70241

PART NUMBER	DESCRIPTION	QTY	LOCATION <
00000	LABOUR	1.50	
005769-A03-01	12381033	1.00	320
WASTE-01	ENVIRONMENTAL CHARGE		
SUPPLIES-01	SUNDRIES AND CONSUMABLES		
	TOTAL LABOUR HOURS	1.50	

SERVICE REQUEST:

Fault Diagnosis:

CHG External Battery/Charges, 40B2 Battery Cell (2 or More), Performance, Battery Not Lasting.

Repair Notes:

Pick up new battery and installed ad quoted

CUSTOMERS NAME: Nick Sok

SIGNATURE:

	BATTERY DETAILS	CHARGER DETAILS			
	BATTERY #1	BATTERY #2	MANUFACTURER	Na	
MODEL	005769-a03-01	Na	MODEL	Na	
SERIAL	I231033	Na	SERIAL	Na	
AMP HRS	300	Na	TEST TAG DATE	Na	
DATE CODE	Sept23	Na	HOUR METER		
SPECIFIC GRAVITY	.000	.000			
VOLT STATIC	25.6	.0	2774		
VOLT U/LOAD	.0	.0			

SERVICEMAN	LABOUR	TRAVEL	TOTAL	WARRANTY TYPE	FAILURE CODE	FAIR WEAR
3346	1.0	.5	1.5		40B	Y
				OFFICE USE ONLY:		
TOTAL	1.0	.5	1.5			



Service Job Inspection Report

Battery - 24 Volt

Customer: Job Number: X 7559359

Customer:						Job Number: X 7559359			
DESCRIPTION	INSP	ACT	DESCRIPTION	INSP	ACT	DESCRIPTION	INSP	ACT	
VISUAL INSPECTION			-Specific Gravity						
Inter-cell Connector Covers	✓		-Cell Voltage						
Vent Caps	•		Cell 9						
-Seals	✓		-Specific Gravity						
-Cracks	•/		-Cell Voltage						
Inter-cell Connectors	•		Cell 10						
-Corrosion	✓		-Specific Gravity						
-Tightness	· /		-Cell Voltage						
Battery Terminals	•		Cell 11						
-Tightness	✓		-Cell Voltage						
-Corrosion			-Specific Gravity						
Cell Leaks	√		Cell 12						
Cell Cracks	√		-Specific Gravity						
Battery Cables	\checkmark		-Cell Voltage						
-Insulation Cuts/Tears/Exposed	_								
-Cable Flexibility	√								
Battery Connector and Tips	\checkmark								
-Damaged Tips									
	V								
-Broken or Cracked Housing	✓,								
-Weak Tension Springs	✓								
Electrolyte									
-Electrolyte For Clarity	✓_								
-Level in Each Cell	✓.								
Battery Watering System	\checkmark								
Battery Blinky	\checkmark								
BATTERY CLEANING									
Clean/Neutralize Top of Batter	\checkmark								
Dry/Wipe Off Top Of Battery	\checkmark								
BATTERY MEASUREMENTS Cell 1									
-Specific Gravity									
-Cell Voltage									
Cell 2									
-Specific Gravity -Cell Voltage									
Cell 3									
-Cell Voltage									
-Specific Gravity									
Cell 4									
-Cell Voltage									
-Specific Gravity									
Cell 5									
-Specific Gravity									
-Cell Voltage									
Cell 6									
-Specific Gravity									
-Cell Voltage									
Cell 7									
-Specific Gravity									
-Cell Voltage									
Cell 8									

Component identification and location with regards to appropriate inspection and action codes:

BATTERY MEASUREMENTS, Cell 1, Specific Gravity, Na.

BATTERY MEASUREMENTS, Cell 1, Cell Voltage, Na.

BATTERY MEASUREMENTS, Cell 2, Specific Gravity, Na.

BATTERY MEASUREMENTS, Cell 2, Cell Voltage, Na.

BATTERY MEASUREMENTS, Cell 3, Cell Voltage, Na.

BATTERY MEASUREMENTS, Cell 3, Specific Gravity, Na.



Service Job Inspection Report

Battery - 24 Volt

Customer: Job Number: X 7559359

BATTERY MEASUREMENTS, Cell 4, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 4, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 5, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 5, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 6, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 6, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 7, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 7, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 8, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 8, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 9, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 9, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 10, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 10, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 11, Cell Voltage, Na. BATTERY MEASUREMENTS, Cell 11, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 12, Specific Gravity, Na. BATTERY MEASUREMENTS, Cell 12, Cell Voltage, Na.



TAX INVOICE NUMBER L69492

5-7 CAPELLI ROAD WINGFIELD SA

5013

For Enquiries

PHONE A/C 02-87880000 PHONE SERVICE 08-81696400 02-87880000 FAX ACCOUNTS 08-83594542

Customer Feedback

PHONE 1300 137 838

EMAIL customerfeedback@crown.com 313534

Customer No.

Reference No.

ORDER DATE	ORDER NO.	INVOICE DATE	JOB LOCATION	JOB ADDRESS
9/08/2023	Na	17/08/2023	*GEPPS CROSS SA	7 O'Connor Court
FLEET No.	SERIAL NUMBER	MODEL NUMBER		GEPPS CROSS SA
	5A533674R	TRADEIN	PREVENTATIVE MAINTENANCE CHARGES	5094

PART NUMBER	DESCRIPTION	LOC	QTY.	UNIT PRICE	TOTAL PRICE
00001	LABOUR	320			254.60
	Nick Sok				
	Please note that a				
	service charge has been				
	made on this invoice as				
	per your PMP agreement.				
VASTE-01	ENVIRONMENTAL CHARGE		1	16.75	16.75
UEL-01	FUEL SURCHARGE		1	3.25	3.25
SUPPLIES-01	SUNDRIES AND CONSUMABLES		1	25.40	25.40

Supply Value	\$ 300.00	GST RATE 10.0 %	GST AMOUNT		30.00
			TOTAL INVOICE AMOUNT	AUD	330.00

Payment due date is 16/09/2023.

Please pay on this invoice. No statement will be issued. Additional Surcharge on Credit Card payments

- Visa/Master Credit Card 1.1%

FOR ALL DIRECT DEPOSITS
Please remit funds to Crown Equipment Pty Ltd National Australia Bank 082-276 Bank Name:

BSB No: Account No: 509265108

Please email remittance advice to banking@crown.com or fax remittance advice to (02) 8788-0642.

Page 1 of 1

NOTE: This invoice includes a Fuel Surcharge due to the ongoing spike in fuel prices across the country.



SERVICE JOB REPORT

Crown Equipment Pty Ltd ABN 79 000 514 858

5-7 CAPELLI ROAD WINGFIELD SA

5013

Job Number: X 7493446

Date:

09/08/2023

Time:

14:13

Order Number:

Na

34 - PREVENTIVE MAINT.

Model:

SX3030TT-4250

Serial Number:

5A533674R

Fleet Number:

Reference No.: L69492

PART NUMBER	DESCRIPTION	QTY	LOCATION <
00001	LABOUR	1.40	
WASTE-01	ENVIRONMENTAL CHARGE		
FUEL-01	FUEL SURCHARGE		
SUPPLIES-01	SUNDRIES AND CONSUMABLES		
	TOTAL LABOUR HOURS	1.40	

SERVICE REQUEST:

Repair Notes:

Located unit and brought to work area. Blew out unit and greased all appropriate locations. Battery had no water in and failed load test, quote to be sent for replacement. Edge of load wheels damaged and ripping off. Safety and function tes ted, wiped down, and returned to service.

Job Address:

5094

7 O'Connor Court GEPPS CROSS SA

CUSTOMERS NAME: Nick

SIGNATURE:

DATE: 09/08/2023

	BATTERY DETAILS	CHARGER DETAILS			
	BATTERY #1	BATTERY #2	MANUFACTURER		
MODEL	Crown		MODEL		
SERIAL	E1958296		SERIAL		
AMP HRS	300		TEST TAG DATE		
DATE CODE	5/19		HOUR METER		
SPECIFIC GRAVITY	.000	.000			
VOLT STATIC	24.5	.0	2774		
VOLT U/LOAD	19.3	.0			

SERVICEMAN	LABOUR	TRAVEL	TOTAL	WARRANTY TYPE	FAILURE CODE	FAIR WEAR
2373	1.1	.3	1.4			Υ
				OFFICE USE ONLY:	BL	
TOTAL	1.1	.3	1.4			



Crown Equipment Pty Ltd ABN 79 000 514 858

5-7 CAPELLI ROAD WINGFIELD SA

5013



SERVICE JOB REPORT

Job Number: X 7493446

Date: 09/08/2023

Time: 14:13 Order Number: Na



Service Job Inspection Report

ST/SX 3000 Series

Customer: Job Number: X 7493446

DESCRIPTION	INSP	ACT	DESCRIPTION	INSP	ACT	DESCRIPTION	INSP	ACT
VISUAL INSPECTION			Power Cable Connections Secure	√		Travel Alarm (Optional)		
Oil Leaks	✓		Wiring Conditions	<i>\</i>		Flashing Light (Optional)	1	
Mast Assembly & Guard	1		Wiring Connections Secure	V		ATTACHMENTS	•	
Load Backrest (Optional)	1		Wiring Harness Condition	1		Operation	1	
Forks & Latches	1		Remote Coil Cord & Switch Cond	'		Leaks	1	
Limit Switch	1		CONTACTOR PANEL & POWER	CONTA	С	Condition	1	
Lift Chain & Mounts	1		Line Contactor Tip Condition	\checkmark		CUSTOMER CARE	•	
Control Arm & Handle	1		Pump Contactor Tip Condition	V		Wipe Off Truck	1	
Tyre & Wheel Condition	•		TRACTION CONTROLLER	·		Clean Area	1	
-LH Load Wheel	1		Creep Speed	✓			•	
-LH Caster (Optional)	1		Plugging	1				
-Drive Tyre & Lug Bolts	· /		Blow Dust Off Panel	✓				
-RH Caster (Optional)	./		CONTROL HANDLE	·				
-RH Load Wheel	· /		Switch Condition	✓				
Safety Decals & Capacity Plate	· · /		Switch Adjustment	1				
Bent or Damage Parts	v /		Potentiometer	1				
Tape, String, etc. Around Driv	v /		Spring Return	1				
Battery Cable Condition (Truck	V		BRAKES	•				
Battery Connector Condition (T	V		Adjustment	1				
Battery Retainers	V		Friction Plate	1				
•	✓		Rotor	1				
CLEAN & LUBRICATE Blow Off Truck	_		Hub Key	·/				
Lubricate	✓		Mounting Screws	•/				
	,		Electrical Connection	./				
-Lubricate Mast & Roller Assem	✓,		Switch	./				
-Caster Wheels	✓,		MAST ASSEMBLY	•				
-Steer Bearing	✓,		Roller & Tracking - Wear or Da	./				
-Control Handle Coil Springs	✓,		Lift Chain Condition - Wear	1				
-Lubricate Lift Chains	✓_		Lift Chain Adjustment	./				
-Load Wheel Bearings	✓,		Lift Cylinder & Mount Conditio	1				
-Mast Free Lift Stud (TT)	✓.		Mounting Bolts to Power Unit S	./				
Apply Armorall or Clear Guard	\checkmark		Control Cables & Hoses	1				
HYDRAULIC SYSTEM			Limit Switch	•/				
Pump & Motor Mounting Secure	\checkmark		Load Backrest Secure (Optional	./				
Oil Level & Condition	✓		Poly Stops	./				
Hoses & Fitting Condition	\checkmark		FREEZER CONDITION (Optiona	1)				
Leaks-Cylinder, etc.	\checkmark		Heater Operation	,	NA			
Breather Cap	\checkmark		Wiring Condition		NA			
Suction & Return Filters	\checkmark		OPERATIONAL CHECK & TEST	DRIVE				
Brush & Armature Condition	\checkmark		BDI or Hour Meter (Optional)	./				
Blow Brush Dust From Motor	\checkmark		Horn	·/				
DRIVE UNIT			Safety Reversing Switch	· /				
Fluid Level	\checkmark		Lift - Lower Operation	./				
Leaks	\checkmark		Power Disconnect	·/				
Motor Mounting Secure	\checkmark		Verify Brake Operation	·/				
Brush & Armature Condition	\checkmark		Stopping Distance	./				
Mounting to Power Unit Secure	\checkmark		Brake Switch	./				
Blow Brush Dust From Motor	✓		Limit Switch Cut-Out	./				
Steer Bearings	\checkmark		Travel Speeds	·/				
Wheel Lug Bolts	✓		Rated Capacity	v				
POWER CABLES & CONTROL	WIRING		Charger	v				
Power Cable Conditions	1		y -	٧				

Component identification and location with regards to appropriate inspection and action codes:

FREEZER CONDITION (Optional), Heater Operation, Not Applicable.

FREEZER CONDITION (Optional), Wiring Condition, Not Applicable.