



Booking Code
354427

Inspector: RAYMOND
Date: 23/08/2012

State Roads

We take a closer look

N.S.W. : 1300 737450

VIC : 03 98508000

QLD : 07 55681621

www.stateroads.com.au

Sydney - Gosford - Newcastle - Wollongong - Canberra - Goulburn - Melbourne - Geelong Brisbane
- Gold Coast - Tweed Heads

INDEPENDENT

Email: adminsdney@stateroads.com

Pre Sale Vehicle Inspection Report

This report was compiled for
CUSTOM FLEET

Location inspected
HOMEBUSH

Vehicle Details: Inspection Type: - PRE SALE DEALER REPORT

Make HOLDEN	Model HOLDEN VE P/CAR		
Badged COMMODORE OMEGA	Registration Number AW59NO	State Registered UNREG	Expiry / Date on label 20/08/2012
Body Colour BLUE	Aust Compliance 13/08/08	Build date 08/08	Odometer km 89246
Vin Number 6G1EK85B29L216643			

Engine Number
LE0082190013

Number of Cylinders 6 Petrol Diesel LPG
Number of Doors 4 Automatic Manual

THE ONUS OF THE VEHICLES AUTHENTICITY/VERIFICATION IS SOLELY THE RESPONSIBILITY OF THE PURCHASER.

VIN AND ENGINE NUMBERS CAN BE CHECKED FOR TAMPERING, HOWEVER, NOT GUARANTEED. ENGINE NUMBER WILL ONLY BE RECORDED OF THE ENGINE IF CLEARLY VISIBLE, OTHERWISE COPIED FROM REGISTRATION RECORDS IF AVAILABLE

Inspection and assessment has been by visual and noise appreciation only and no adjustments have been made nor components dismantled to confirm diagnosis. Whilst every care is taken StateRoads Vehicle Inspection cannot report about a defect if we cannot see it or it does not appear during the inspection. It is in the opinion of our experienced inspectors that the items are in the condition indicated on this report. Should there be a concern with the accuracy of this report contact StateRoads prior to any work being carried out.

THIS REPORT IS NOT A WARRANTY OR GUARANTEE, IT IS ONLY INTENDED FOR THE PERSON(S) NAMED ABOVE AND IS NOT TO BE RELIED UPON BY ANY OTHER PERSON(S) OR PURPOSE.

WHAT WE DON'T CHECK - Fuel & oil consumption, Vehicle onboard computers / Modules are not read for any fault codes stored (optional), timing belts, alarm/security system, trip meters/computers, navigation equipment/GPS, operation of TV, cassette or compact disc players, automatic switching of wipers and lights, body work water leaks. We only visually inspect the components that are accesable on the report checklist, further inspection and/or a full comprehensive inspection may be recommended for any concerns found, This report is a general visual short report only and not to be mistaken for a comprehensive report. A comprehensive inspection needs to be booked through the relevant stateroads office and a suitable time allocated by both parties.

ENGINE BAY

C = Consistent With Mileage

N = Needs Service / Repair

	C	N		C	N		C	N
Engine Oil Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Coolant level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Radiator&Heater Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Oil Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Coolant Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Water pump/cooling fan	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Oil Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Coolant Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Drive Belts/Pulleys	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fumes/Smoke	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Mountings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Emission Control (visual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Operational Noises	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Fuel System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Wiring/Secured	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Battery/Clamp/Tray	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Alternator/Charging System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Exhaust Flange/Manifold	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments [No engine bay oil leakage found at time of inspection<>](#)
[Engine runs and sounds good also showing no internal running faults<>](#)
[Engine service due reminder illuminated on dash board<>](#)

STEERING / SUSPENSION / BRAKES

Steering Components	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Ball Joints/Control Arms	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Wheel Bearing Movement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Shocks/Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Front Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rear Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Tyres (Roadworthy)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Wheels/Rims	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Driveshafts/CV Joints	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Universal Joints	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Mufflers/Pipe	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Transmission/Driveline Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake Discs/Rotors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake Pads	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake Lines/Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Differential (Visual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Transmission (Visual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	4WD Transfer Case	<input type="checkbox"/>	<input type="checkbox"/>

Comments [Undercarriage is in good original condition showing no major wear or faults, Showing typical wear for mileage<>](#)
[Brake disc rotors have wear lips, and will need machining or replacing at next brake service or at RWC check<>](#)
[Brake pads% low,will need early replacement<>](#)

INTERIOR & ROAD TEST

Seat Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Seat Mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Window Operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Seats and Trim	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Washers/Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air Conditioner	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Instrument Warning Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Instrument Gauges/Speedo	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Radio	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Heater/Demister	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Indicator Cancel/Return	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Park Brake	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Driveline/Diff	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Steering/Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Exhaust Smoke	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Speedo/Odometer	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cruise Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments [This car drives and performs well, no mechanical faults in drive-line were detected during test drive<>](#)
[Interior trim and carpet is in good and clean condition<>](#)

Vehicles with no number plates and / or unregistered will not be driven or road tested.

Vehicles are inspected to NSW roadworthy requirements, please be aware that roadworthy requirements can vary state to state.


BODY PANELS

C = Consistent with mileage

N = Needs Service / Repairs

	C N		C N		C N
Windscreen (Roadworthy)	<input checked="" type="checkbox"/> <input type="checkbox"/>	Light /Indicator Lenses	<input checked="" type="checkbox"/> <input type="checkbox"/>	Exterior Mirrors	<input checked="" type="checkbox"/> <input type="checkbox"/>
Front Bumper	<input checked="" type="checkbox"/> <input type="checkbox"/>	Rear Bumper	<input checked="" type="checkbox"/> <input type="checkbox"/>	Door Handle	<input checked="" type="checkbox"/> <input type="checkbox"/>

NOTE: DUE TO SOME VEHICLES BEING WET OR DIRTY NOT EVERY SMALL DENT OR SCRATCH MAY BE NOTED INDIVIDUALLY



- Cosmetic Refinish = Green
- Minor Scratches or Dents = Grey
- Damage / Larger Dents = Black
- Previous Body repairs = Pink
- Rust = Red

Added Notes

Vehicle shows no evidence of body repairs, paint thickness is consistent with factory original thickness<>
 Minor chips/sandblasting to windscreen<>
 Shopping type dents/chips/scratches/marks to various panels <>
 Minor scuff marks at bumpers and side panels<>

Body panels have been tested and paint / coating thickness measured with a electronic meter to detect repairs. Minor repairs and imperfections which appear satisfactory may not be recorded with this inspection. It is the purchasers responsibility to carry out a final visual inspection on the vehicle as the vehicle condition may have changed since this inspection We advise purchasers to always check with relevant authorities (Revs, Rta, Vic roads etc) for any previous write-off history

Inspection Report Summary

Body Rating:

Mechanical Rating:

Interior Rating:

80%**80%****80%**

General Overview:

THIS VEHICLE IS IN GOOD GENERAL CONDITION FOR ITS AGE AND MILEAGE

VEHICLE REQUIRES SERVICING / REPAIRS AS MENTIONED IN REPORT

*This vehicle has been rated taking into consideration the mileage displayed, the vehicle age and the condition of the vehicle as inspected - The higher rating = better the condition.

All vehicles are inspected as presented, please ensure that you are aware of the vehicles options and features example: Air bag quantity, Engine specifications, cruise control etc, as this can vary from model to model as an option.

Please ensure to read this report in full including any added notes which may point out any repairs, servicing, faults, problems. Further explanation of the report can be made by speaking direct with your inspector.

BEWARE Always check for a clear title before paying for a vehicle especially on private sales.

N.S.W. R.E.V.S 133 220

Victoria

VIC ROADS 13 1171

Queensland R.E.V.S. 07 32461599

Or online at www.revs.nsw.gov.au