

Vehicle multi-system ODO test report

Repair Shop

Shop Name:PRECISION MOTORWORKS ADELAIDE

Address:5b Thomas str Cavan SA

Zip Code:5094

Telephone:

Email:

SN:979860256571

Test Time:2024-05-01 09:35:02



Vehicle Information

Year:2017

Make:BMW

Model:M140i

VIN:WBA1S92030VD06418

Odometer:81233 km

Vehicle Software Version:V10.03

Diagnostic Application Version:V8.00.223

Inspection Result

System Name	Mileage
IC (Instrument Cluster - INSTR)	81233km; 81236km; 81236km
Total Distance (Instrument Cluster)	81233km
Absolute Odometer From The RAM	81236km
Supplies The Absolute Odometer From The EEPROM	81236km
ECM (Engine Control Module - DME/DDE)	81233km
Kilometre Reading	81233km
TCM (Transmission Control Module - EGS)	81232km
Kilometre Reading	81232km
ABS (Anti-Lock Braking System - DSC)	281970km; 281960km; 275460km
Kilometre Reading/Mileage,Last Initialisation	281970km

Kilometre Reading/Mileage,Last Warning	281960km
Kilometre Reading (Mileage),Penultimate Warning	275460km
CAS (Car Access System - CAS/FEM/BDC)	--
EME2 (Electrical Machine Electronics 2)	--
TCU (Telematic Control Unit - TEL/ULF/ULF-SBX)	--
EPS (Electronic Power Steering)	--
PMA (Parking Assistant)	--
CVM (Convertible-Top Module)	--
EME (Electrical Machine Electronics)/RLM_1R (Tail Light Module, Outer Right)	--
LMV/VTG (Transfer Case)	--
ECM2 (Engine Control Module 2 - DME2)	--