

CarHistory Dealer Report & PPSR Certificate

Report generated on 15/05/2024

REPORT ID

13023102

VIN	6G1EK5E49CL718881
Make	HOLDEN
Model	COMMODORE
Variant/series	OMEGA (LPG)VE II MY12.5
Body	4D SEDAN
Transmission	6 SP AUTOMATIC
Year (first retail date)	2013
Colour	BLUE



*Picture provided is a sample only

QUICK SUMMARY



No stolen status reported



Written-off status reported



No financial interests reported



No odometer rollback reported



Vehicle registered

VEHICLE DETAILS

✔ Vehicle registered

VEHICLE REGISTRATION

Registration plate	1ZS6HH
Registration state	VIC
Registration expiry date	15-07-2024

FIRST SALE INFORMATION

First sale date	30-04-2013
Postcode of first sale	3056
First buyer type	NON-PRIVATE

ENGINE DETAILS

Engine number	LWR130560125
Engine size	3.6L
Cylinders/rotors	LPG6
Fuel type	LIQUID PETROLEUM GAS
Power (KW)	180
Torque (Nm)	320

VEHICLE RATINGS

ANCAP safety rating	-
Overall green rating	-
Air pollution rating	-
Greenhouse rating	-



CarHistory notes:

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

REPORTED ODOMETER HISTORY

✔ No odometer rollback reported

LAST REPORTED ODOMETER READING


Kilometres	23,299
Date reported	18/07/2014

READING ENTERED BY YOU

Kilometres	244,912
Date reported	15/05/2024

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

Kilometres	Date reported	Alerts
244,912	15/05/2024	
23,299	18/07/2014	
15,202	25/02/2014	



CarHistory notes:
CarHistory relies on data received from third parties. We recommend you review the vehicle's log book and service history to determine the accuracy of the vehicle's odometer reading.

REPORTED SALES LISTINGS

No known sales listings for this vehicle.

CarHistory notes:
Reported sales listings are sales advertisements derived from various ecommerce sites and provide an indication of how often the vehicle has been listed for sale.

FINANCE CHECK

✓ No financial interests reported

PPSR has reported that this vehicle is not encumbered.

CarHistory notes:
Financial encumbrance information is sourced via the PPSR. Refer to the PPSR Certificate below.

WRITTEN-OFF CHECK

❗ Written-off status reported

PPSR has reported that this vehicle has been written-off.

Written-off	<ul style="list-style-type: none"> Hail Driver side Light structural Hail Driver front Heavy panel Hail Passenger front Heavy panel
--------------------	--

	Hail Passenger side Light structural Hail Passenger rear Heavy structural Hail Driver rear Heavy structural Hail Roof Heavy structural
Date recorded	05 Feb 2020
State recorded	VIC
Type	Inspected

Written-off	Hail Driver side Light structural Hail Driver front Heavy panel Hail Passenger front Heavy panel Hail Passenger side Light structural Hail Passenger rear Heavy structural Hail Driver rear Heavy structural Hail Roof Heavy structural
Date recorded	02 Feb 2020
State recorded	VIC
Type	Repairable Write-off



CarHistory notes:

Written-off information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

STOLEN CHECK

No stolen status reported

PPSR has reported that this vehicle is not stolen.



CarHistory notes:

Stolen information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

ACCESS YOUR REPORT ONLINE

To allow an individual to view this report online, simply provide them with the following link:

<https://secure.carhistory.com.au/vcn?vcn=A1-KKBD>

GENERAL DISCLAIMERS

This report has been supplied on the [Terms and Conditions](#) set out on the CarHistory website, and accepted by you before you purchased this report.

The data used to compile this report has been sourced from various independent and Government sources, as a result CarHistory can accept no responsibility for the accuracy or completeness of information.

PPSR CERTIFICATE

The following certificate has been issued by the Australian Financial Security Authority.



15/05/2024

Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act 2009*

Search certificate number: 6473679373910001

Search number: 647367937391

This search certificate reflects the data contained in the PPSR at 15/05/2024 13:27:58 (Canberra Time).

Search Criteria Details

Serial number search type: VIN
Motor vehicle: 6G1EK5E49CL718881
PPSR registration state searched: Current

PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

Additional Motor Vehicle Details – NEVDIS

Identifier number:	6G1EK5E49CL718881	Identifier type:	VIN
Vehicle type:	CAR / SMALL PASSENGER VEHICLE	Make:	HOLDEN
Body type:	CAR/SEDAN	Model:	COMMODORE
Colour:	BLUE	Engine number:	LWR130560125
Registration plate number:	1ZS6HH	State vehicle registered:	VIC
Registration expiry:	15 Jul 2024		
Year of manufacture:	2013	Year/Month of compliance:	2013-03

Important NEVDIS notifications about the Vehicle

Written-off:

VIC, 05 Feb 2020, Inspected

- H03D [Hail | Driver side | Light structural]
- H02A [Hail | Driver front | Heavy panel]
- H01A [Hail | Passenger front | Heavy panel]
- H06D [Hail | Passenger side | Light structural]
- H05C [Hail | Passenger rear | Heavy structural]
- H04C [Hail | Driver rear | Heavy structural]
- H08C [Hail | Roof | Heavy structural]

VIC, 02 Feb 2020, Repairable Write-off

- H03D [Hail | Driver side | Light structural]
- H02A [Hail | Driver front | Heavy panel]

This search certificate reflects the data contained in the PPSR at 15/05/2024 13:27:58 (Canberra Time).

- H01A [Hail | Passenger front | Heavy panel]
- H06D [Hail | Passenger side | Light structural]
- H05C [Hail | Passenger rear | Heavy structural]
- H04C [Hail | Driver rear | Heavy structural]
- H08C [Hail | Roof | Heavy structural]

Stolen:

- Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

<https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf> (Note: you will need to provide the vehicle registration plate number to search this site).

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the main source of NEVDIS data and the primary point of contact for enquiries, errors, and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at www.ppsr.gov.au). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at <https://transact.ppsr.gov.au/pps/Home>. There is no fee, however this process will not provide any update to the information in the original search.

Privacy and Terms and Conditions

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au.

This search certificate reflects the data contained in the PPSR at 15/05/2024 13:27:58 (Canberra Time).

End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: www.ppsr.gov.au

GPO Box 1944 Adelaide SA 5001

1300 00 77 77