

K & S CORPORATION LIMITED
Work Order History Report

Asset	W/O No	Description	Done	Reading
1335		KSF - PERTH LOCAL		
D2553	IVECO STRALIS AT460 6X4 PRIME MOVER			
1209655		repair elect fault to trailer lights - repaired repaired wiring -/- repaired attached in documents	10/06/2021	Kilometres
1215436		RR 208918 - Engine light coming on.topped up low coolant wear in turntable jaws - replaced jaw kit - attachment in documents	13/07/2021	117,450 Kilometres
1210887		Roadworthy Inspection - 6 Month - Prime Mover WAcarrried out as per service sheet carried out brake test and passedattachment in documents	14/07/2021	117,450 Kilometres
1219369		RR208962 - airbag remote u/s -/- ===== Replaced air bag remotewiper blades u/s ===== Replaced wiper bladeattached to documents	30/07/2021	118,633 Kilometres
1219722		RR 208958 - ECAS warning light coming on shows 21 and 30. -/- - door pin switch u/s - replaced - Airbag suspension not working. -/- - replaced leaking air fitting - Check interior door handle. -/- - repaired door linkages -/- - attachment in documentsRR 208962 - Air bag remote not working we cant control airbag. -/- replaced air suspension remote	5/08/2021	Kilometres
1221504		RR 208980 - check brakes - grabbing -/- - adjusted and checked brakes - ok - Wiper blades need to be changed. - changed wiper blades - attachment in documents	25/08/2021	Kilometres
1231047		A Service - 20,000KM OR 3 MONTHS - Iveco Stralis - carried out service as per sheet - attachment in documents	11/11/2021	123,330 Kilometres
1234439		RR 209481 - 1. Back right light broken. - replaced light RR 209497 - 2. "Air service reservoir low" and engine sign on dash. - cannot fault 3. Wiper blades need to be replaced.- replaced wiper blades RR 209518 - 4. Indicators broken. - replaced indicator lamp - attachment in documents	11/11/2021	Kilometres
1209048		Turntable Inspection Light - Prime Movers - - installed light - attachment in documents	12/11/2021	Kilometres
1251217		A Service - 20,000KM OR 3 MONTHS - Iveco Stralis- completed service as per sheet on RW W/O # 1245013 - attachment in documents	31/01/2022	126,208 Kilometres
1245013		Roadworthy Inspection - 6 Month - Prime Mover WA - - completed service as per sheet - attachment in documents	31/01/2022	126,208 Kilometres
1240762		RR 49001 - 1. Windscreen wipers not touching windscreen. -/- replaced wiper arms 2. Engine light fault showing.-/- repaired - sublet RR 49002 - 3. Suspension not going to usual height.-/- repaired - sublet 4. Door keep on hinge broken.-/- repaired hinge 5. Oil leak under drivers cabin.-/- spilt from spare engine oil container - attachment in documents	31/01/2022	126,208 Kilometres
1253214		B Service - 80,000kms OR 12 MONTHS - Iveco Stralis - - completed service as per sheet - attached in documents	9/03/2022	127,106 Kilometres
1262346		RR209585 - service brake trailer suzie line u/s -/- replaced suzie lines - attachment in documents	30/03/2022	Kilometres
1271616		A Service - 20,000KM OR 3 MONTHS - Iveco Stralis - completed service as per sheet - attachment in documents	27/07/2022	135,138 Kilometres
1277855		Roadworthy Inspection - 6 Month - Prime Mover WA - completed service as per sheet - attachment in documents	27/07/2022	
1269819		RR 209597 - 1. RHS tail light broken lens/Damage tail light assembly. -/- replaced tail lamp change head light globe - changed - attachment in documents	28/07/2022	135,138 Kilometres
1272292		Air System Maintenance - 240,000km OR 12 Months -- completed service as per sheet - attachment in documents	28/07/2022	135,138 Kilometres
1290808		trailer elect lead u/s - completed - attachment in documents	14/09/2022	Kilometres
1295389		A Service - 20,000kms OR 3 Months - Iveco Straliscpleted as per task sheet brakes checked and passed - attachment in documents	9/11/2022	139,951 Kilometres
1300086		LHS tail lamp u/s - straightened mudguards support completed - attachment in documents	9/11/2022	Kilometres
1309192		driver side door won"t open, light repair- attachment in documents	6/01/2023	Kilometres
1300332		w/o1295389 1. cracked chassis cross member - rebook 2. cab hyd lift / ram worn out bushes - rebook RR 49008 - 3. RHS indicator not working.RR 49010 - 4. LHS front indicator not working.5. Driver side door not opening.RR 209709 - 6. No aircon.7. Drivers seat back broken.completed Roadworthy Inspection - 6 Month - Prime Mover WAcpleted as per task sheet brakes checked and passed attached in documents	8/03/2023	Kilometres
1308760		A Service - 20,000kms OR 3 Months - Iveco Straliscpleted as per task sheet brakes checked and passes attached in documents	8/03/2023	144,748 Kilometres
1312926		w/o1295389 1. cracked chassis cross member - welded cracks 2. cab hyd lift / ram worn out bushes - replaced bushes 3. water leaking on cab floor - replaced driver door seal attached in documents	8/03/2023	144,748 Kilometres
1320376		C Service - 240,000KM OR 24 Months - Iveco Stralis- completed service as per sheet brakes checked and passed attached in documents	20/04/2023	Kilometres
1340673		?INS AUS18766 repair front damage completed attached in documents	11/07/2023	148,940 Kilometres
1340849		RR 209927 - 1. Air leaks from one of the air connections when release brakes .completed attached in documents	12/07/2023	Kilometres
1346130		Roadworthy Inspection - 6 Month - Prime Mover WA- completed service as per sheet attached in documents	16/08/2023	Kilometres
1346271		A Service - 20,000kms OR 3 Months - Iveco Stralis- completed service as per sheet attached in documents	27/09/2023	151,634 Kilometres
1353879			28/09/2023	151,634 Kilometres

1341471	Air System Maintenance - 240,000km OR 12 Months- completed as per task list attached in documents	28/09/2023	151,634 Kilometres
1331602	Change Diff Oil - 200,000km- completed attached in documents	28/09/2023	151,634 Kilometres
1354259	rhs front damage - repaired front bumper - replaced rhs head lights - repaired head light wiring Roadside Breakdown Location: Kewdale Reported Fault: Engine Stopped Cause: Fuel issues Correction: [Remember to use FAILED COMPONENT field!] Reference #: Drivers name & contact: attached in documents	6/10/2023	Kilometres
1375845	Breakdown - Engine Derate - Adblue leak 1. Refit Pipe to adblue filter completed attached in documents	13/02/2024	Kilometres
1375847	documents	13/02/2024	Kilometres
1367205	MTData - full install of refurb unit - report attached in documents	28/02/2024	Kilometres
1378008	Roadworthy Inspection - 6 Month - Prime Mover WA completed as per task sheet brakes checked and passed attached in documents	21/03/2024	160 Kilometres
1366543	A Service - 20,000kms OR 3 Months - Iveco Stralis completed as per task sheet attached in documents	21/03/2024	159,354 Kilometres
1349426	RR209948 Engine light on 2. RR209950 driver side headlight and bumper twisted 3. check drive belts - squealing noise 4. RR209974 overheating 5. head lights not working completed attached in documents	4/04/2024	Kilometres
1384621	RR35358 1. Engine light on dash - complete- attachment in documents	15/05/2024	Kilometres
1331603	Tune Up - 160,000km- completed	13/06/2024	161,200 Kilometres
1393573	A Service - 20,000km OR 3 Months - Iveco Stralis completed as per task sheet attached in documents	20/06/2024	161,342 Kilometres
1396147	active fault light on dash - diagnose fault - - found failed Nox sensor - replaced sensor - attachment in documents	25/06/2024	Kilometres
1396882	RR35302 - 1. Engine light on dash 2. driver side window not working properly 3. driver door hard to open - faulty lock- carried out service as per task sheet- attachment in documents	28/06/2024	162,088 Kilometres
1400337	1. active engine fault code on dash 2. Injector harness seal leaking 3. oil found in engine harness 4. oil found in ECU - require replacing COMPLETED remove /replace ddm ECU, injector & engine harness, reset timing and carry out engine tune up attached in documents	10/08/2024	Kilometres
1404988	1. driver side window not working - replaced faulty door module 2. repair driver seat - repaired seat completed attached in documents	19/08/2024	Kilometres
1406564	RR35303 1. Engine light on 2. licence plate light waring light on - carried out service as per task sheet- attachment in documents	6/09/2024	Kilometres
1405808	Roadworthy Inspection - 6 Months - Prime Mover WA- completed service as per sheet - attachment in documents	6/09/2024	163,432 Kilometres
1407746	B Service - 80,000km OR 12 Months - Iveco Stralis- carried out service as per task sheet- attachment in documents	10/09/2024	163,433 Kilometres
1413481	broken passenger side window - completed- attachment in documents	23/10/2024	Kilometres