

A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 4310217  
 PACLEASE AUSTRALIA  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

**Document No.:** 993859  
**Document Date:** 23/02/2021  
**Repair Order No.:** 324689  
**Rego No.:** XW100I  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 101850  
**Delivery Date:** 31/03/2020  
**Invoice To:** 4310217  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 16275  
**Fleet No.:** PM53  
**Page:** 1 of 2

### B SERVICE

B Service - Carry out B service as per KW/DAF recommendations.  
 ALL defects must be reported in the first hour of the service.  
 CUSTOMER REQUEST: Carry out B service.

### CORRECTION:

CARRIED OUT B SERVICE AS REQ. & REPLACED THE AIR DRYER FILTER.

### DEFECT LIST:

Part Number	Part Description	Quantity
2164462	FUEL FILTER,ELEMENT	1.00
2018671	O-RING	1.00
1982821	DRAIN TAP-PLUG PLUG	1.00
1953595	AIR FILTER ELEMENT INTERIOR CF	1.00
1433649	FUEL FILTER ELEMENT MOIST SEPA	1.00
2234788	OIL FILTER ELEMENT	1.00
A90020	SCREENWASH	1.00
3415493	CASTROL 10W-40 VECTON LONG DRAIN E6/E9	38.00
3377121	CASTROL PREMIUM HEAVY DUTY GREASE	1.00

**Parts Totals: 46.00**

### \*ZNA05

RNR AIR DRIER FILTER  
 CARRIED OUT DURING THE B SERVICE.

Part Number	Part Description	Quantity
-------------	------------------	----------

ISO 9001 A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

**SERVICE JOB SUMMARY**

**Invoice To:** 4310217  
PACLEASE AUSTRALIA  
355 FITZGERALD RD  
DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

<b>Document No.:</b>	<b>993859</b>
Document Date:	23/02/2021
Repair Order No.:	324689
Rego No.:	XW10OI
Make/Model:	2019 DAF CF530 FTT
Vehicle ID No.:	XLRTTM430KG297621
Engine Hours:	
Odometer:	101850
Delivery Date:	31/03/2020
Invoice To:	4310217
Customer ABN:	11005592049
Tax Exempt No.:	
P/Order No.:	16275
Fleet No.:	PM53
Page:	2 of 2

\*ZNA05

1925363

FILTER AIR DRYER + OIL SEP.

1.00

**Parts Totals:****1.00**Miscellaneous Charges

WORKSHOP SUPPLIES

ENVIRONMENTAL CHARGES

Advisor: GEORGE BUHAGIAR

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

**Bank Account Details for Direct Payments:**

Bank: ANZ Branch: Altona North

BSB: 013202 Account No.: 775073766 Account Name: KENWORTH DAF MELBOURNE

A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 4310217  
 PACLEASE AUSTRALIA  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

**Document No.:** 1061261  
**Document Date:** 12/01/2022  
**Repair Order No.:** 333144  
**Rego No.:** XW10OI  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 148886  
**Delivery Date:** 31/03/2020  
**Invoice To:** 4310217  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 19000  
**Fleet No.:** PM53  
**Page:** 1 of 2

### B SERVICE

LABOUR.

CUSTOMER REQUEST: Carry out B service.

CORRECTION: Carry out B service as per checklist. Top up diff oils as required - 2L in each diff. Carry out brake test - Passed

### DEFECT LIST:

- Loading light on air tank not working
- Diff oils low
- Side camera won't turn off
- Warning on dash while driving

Part Number	Part Description	Quantity
1953595	AIR FILTER ELEMENT INTERIOR CF	1.00
1433649	FUEL FILTER ELEMENT MOIST SEPA	1.00
A90020	SCREENWASH	1.00
3415493	CASTROL 10W-40 VECTON LONG DRAIN E6/E9	39.00
3377121	CASTROL PREMIUM HEAVY DUTY GREASE	1.00
3370024	CASTROL AXLE AP 85W140 (EPX 85W-140)	4.00
2277128	FUEL FILTER,ELEMENT SSI	1.00
2234788	OIL FILTER ELEMENT	1.00
2018671	O-RING	1.00
1982821	DRAIN TAP-PLUG PLUG	1.00

**Parts Totals: 51.00**

\*ZNA01

**Warranty Repairs/Service At No Charge**

Requires PSFA 0080094 Vic Software Update

 A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

**SERVICE JOB SUMMARY**

<b>Document No.:</b>	<b>1061261</b>
Document Date:	12/01/2022
Repair Order No.:	333144
Rego No.:	XW10OI
Make/Model:	2019 DAF CF530 FTT
Vehicle ID No.:	XLRTTM430KG297621
Engine Hours:	
Odometer:	148886
Delivery Date:	31/03/2020
Invoice To:	4310217
Customer ABN:	11005592049
Tax Exempt No.:	
P/Order No.:	19000
Fleet No.:	PM53
Page:	2 of 2

**Invoice To:** 4310217  
PACLEASE AUSTRALIA  
355 FITZGERALD RD  
DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

**\*ZNA01****Warranty Repairs/Service At No Charge**

Carried out VIC3 software update as per PSFA 0080094.  
Claim 428076

Miscellaneous Charges  
WORKSHOP SUPPLIES  
ENVIRONMENTAL CHARGES

Advisor: MADELEINE WAHRBICHLER

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

**Bank Account Details for Direct Payments:**

Bank: ANZ Branch: Altona North  
BSB: 013202 Account No.: 775073766 Account Name: KENWORTH DAF MELBOURNE

A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 4310217  
 PACLEASE AUSTRALIA PPFS  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

**Document No.:** 1119565  
**Document Date:** 3/10/2022  
**Repair Order No.:** 340339  
**Rego No.:** XW10OI  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 217140  
**Delivery Date:** 31/03/2020  
**Invoice To:** 4310217  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 21369  
**Fleet No.:** PM53  
**Page:** 1 of 2

### 90DFCPL

Carried out Paclease DAF C-service as per DAF service requirements.

#### Defects:

- Engine light is on
- Power steering fluid low
- Crossmember bolts missing
- J Bracket rubbers moving on RH Fuel tank
- Exhaust leaking at EGR throttle body

Part Number	Part Description	Quantity
1982821	DRAIN TAP-PLUG PLUG	1.00
1953595	AIR FILTER ELEMENT INTERIOR CF	1.00
1933740	AIR FILTER ELEMENT	1.00
0671090384	ECOFILM M 20LT	1.00
3415493	CASTROL 10W-40 VECTON LONG DRAIN E6/E9	39.00
2018671	O-RING	1.00
1433649	FUEL FILTER ELEMENT MOIST SEPA	1.00
3377121	CASTROL PREMIUM HEAVY DUTY GREASE	2.00
2277128	FUEL FILTER,ELEMENT SSI	1.00
A90020	SCREENWASH	1.00
2234788	OIL FILTER ELEMENT	1.00
CAS116944	LABCHECK K KIT	1.00
2122909	FILTER ADBLUE	1.00
1925363	FILTER AIR DRYER + OIL SEP.	1.00

**Parts Totals: 53.00**

### 90DFTUE6

Carried out DAF engine tune-up as per DAF specifications.

Part Number	Part Description	Quantity
-------------	------------------	----------

 A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 4310217  
 PACLEASE AUSTRALIA PPFS  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

<b>Document No.:</b>	<b>1119565</b>
Document Date:	3/10/2022
Repair Order No.:	340339
Rego No.:	XW10OI
Make/Model:	2019 DAF CF530 FTT
Vehicle ID No.:	XLRTTM430KG297621
Engine Hours:	
Odometer:	217140
Delivery Date:	31/03/2020
Invoice To:	4310217
Customer ABN:	11005592049
Tax Exempt No.:	
P/Order No.:	21369
Fleet No.:	PM53
Page:	2 of 2

### 90DFTUE6

2105834	VALVECOV.GASKET	1.00
<b>Parts Totals:</b>		<b>1.00</b>

### 90DDDR

Drained and refilled diffs with DYNA DRIVE

Part Number	Part Description	Quantity
CAS3334801	DYNADRIIVE 80W90 GL4/GL5 20L AU	2.00
<b>Parts Totals:</b>		<b>2.00</b>

### 22MCBLM

#### Warranty Repairs/Service At No Charge

Cross member Bolts have been replaced  
 Checked and found cross member bolts loose and missing. RR all 16 with new with lock tight.  
 442179

### 32TSRFREP

#### Warranty Repairs/Service At No Charge

Replaced Tank strap rubbers— Fuel  
 Checked and found tank rubbers bulging on both side j brackets. Lift tanks rr with new re fit tanks all ok  
 442183

### 99CLEBRHS CR

#### Warranty Repairs/Service At No Charge

COOLANT LEAK - ENGINE BAY RHS - O- ring leaking Check and Repair  
 Checked and found plug leaking on R/H side of engine. Drained coolant. Removed plug found o-ring split. RR o-ring with new. RE fill and top up lost coolant. Bleed system all ok.  
 442184

#### Miscellaneous Charges

WORKSHOP SUPPLIES  
 ENVIRONMENTAL CHARGES

Advisor: MADELEINE WAHRBICHLER

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

#### Bank Account Details for Direct Payments:

Bank: ANZ Branch: Altona North  
 BSB: 013202 Account No.: 775073766 Account Name: KENWORTH DAF MELBOURNE

A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 4310217  
 PACLEASE AUSTRALIA PPFS  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

**Document No.:** 1156754  
**Document Date:** 14/03/2023  
**Repair Order No.:** 345347  
**Rego No.:** XW10OI  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 248747  
**Delivery Date:** 31/03/2020  
**Invoice To:** 4310217  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 22954  
**Fleet No.:** PM53  
**Page:** 1 of 2

### 90DFBPL

Carried out Paclease DAF B-service as per DAF service requirements. Tightened spring hanger bolts as required. Replaced front diff plug as required.

#### Defects:

- Front drive pads low
- RH Spring hanger bolt loose (Tightened)
- Front diff inspection plug rounded (Replaced)

Part Number	Part Description	Quantity
A90020	SCREENWASH	1.00
2277128	FUEL FILTER,ELEMENT SSI	1.00
2234788	OIL FILTER ELEMENT	1.00
1982821	DRAIN TAP-PLUG PLUG	1.00
1953595	AIR FILTER ELEMENT INTERIOR CF	1.00
1433649	FUEL FILTER ELEMENT MOIST SEPA	1.00
3377121	CASTROL PREMIUM HEAVY DUTY GREASE	1.00
3415493	CASTROL 10W-40 VECTON LONG DRAIN E6/E9	38.52
0699112	PLUG	1.00
<b>Parts Totals:</b>		<b>46.52</b>

### 11FDBRKPAD

Removed & replaced front drive axle brake pads as req .

Part Number	Part Description	Quantity
1982826	SET BRAKE PAD	1.00
<b>Parts Totals:</b>		<b>1.00</b>

 A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

**SERVICE JOB SUMMARY**

**Invoice To:** 4310217  
PACLEASE AUSTRALIA PPFS  
355 FITZGERALD RD  
DERRIMUT VIC 3026

**\*\*\* CASH SALE \*\*\***

<b>Document No.:</b>	<b>1156754</b>
Document Date:	14/03/2023
Repair Order No.:	345347
Rego No.:	XW10OI
Make/Model:	2019 DAF CF530 FTT
Vehicle ID No.:	XLRTTM430KG297621
Engine Hours:	
Odometer:	248747
Delivery Date:	31/03/2020
Invoice To:	4310217
Customer ABN:	11005592049
Tax Exempt No.:	
P/Order No.:	22954
Fleet No.:	PM53
Page:	2 of 2

22TTWPREP

Replaced turntable wear plates as req. Parts supplied by Paclease

Miscellaneous Charges

WORKSHOP SUPPLIES

ENVIRONMENTAL CHARGES

Advisor: MADELEINE WAHRBICHLER

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

**Bank Account Details for Direct Payments:**

Bank: ANZ Branch: Altona North

BSB: 013202 Account No.: 775073766 Account Name: KENWORTH DAF MELBOURNE



A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 7400600  
 PACLEASE AUSTRALIA PPFS  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**Document No.:** 1227768  
**Document Date:** 10/01/2024  
**Repair Order No.:** 353626  
**Rego No.:** XW10OI  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 285945  
**Delivery Date:** 31/03/2020  
**Invoice To:** 7400600  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 25740  
**Fleet No.:** PM53  
**Page:** 1 of 2

### 90DFBPL

Carried out Paclease DAF B-service as per DAF service requirements.

#### DEFECTS:

- Spring pin bushes have wear - monitor.
- Front drive wheel bearings sweat/leak.
- All brakes very low & wont last to next service.

Part Number	Part Description	Quantity
2277128	FUEL FILTER,ELEMENT SSI	1.00
2018671	O-RING	1.00
3377121	CASTROL PREMIUM HEAVY DUTY GREASE	1.00
1982821	DRAIN TAP-PLUG PLUG	1.00
2234788	OIL FILTER ELEMENT	1.00
1953595	AIR FILTER ELEMENT INTERIOR CF	1.00
3415493	CASTROL 10W-40 VECTON LONG DRAIN E6/E9	39.00
A90020	SCREENWASH	1.00
1433649	FUEL FILTER ELEMENT MOIST SEPA	1.00
CAS116944	LABCHECK K KIT	1.00
<b>Parts Totals:</b>		<b>48.00</b>

### 05DFLHFDWBREP

Front drive wheel bearing sweat/leak.

Raised vehicle & set on stands.

Stripped front dirve hubs - found bearings on both sides worn.

Replaced wheel bearings on both sides of front drive axle as required.

Reassembled with new brake pads and wear sensors as required.

A DIVISION OF **PACCAR** AUSTRALIA PTY LTD. A.B.N. 43 004 669 667 LMCT 1343  
 355 Fitzgerald Road, Derrimut Victoria 3026 (PO Box 661, Laverton Victoria 3028)  
 Tel: (03) 9396 9100 Fax: 9396 9111 Service & Parts Hotline: 1300 727 944  
 Trading Hours: Mon To Fri 7:00am - 10:00pm Saturdays 8:00am - 1:00pm

ARC NO. AU17468

## SERVICE JOB SUMMARY

**Invoice To:** 7400600  
 PACLEASE AUSTRALIA PPFS  
 355 FITZGERALD RD  
 DERRIMUT VIC 3026

**Document No.:** 1227768  
**Document Date:** 10/01/2024  
**Repair Order No.:** 353626  
**Rego No.:** XW10OI  
**Make/Model:** 2019 DAF CF530 FTT  
**Vehicle ID No.:** XLRTTM430KG297621  
**Engine Hours:**  
**Odometer:** 285945  
**Delivery Date:** 31/03/2020  
**Invoice To:** 7400600  
**Customer ABN:** 11005592049  
**Tax Exempt No.:**  
**P/Order No.:** 25740  
**Fleet No.:** PM53  
**Page:** 2 of 2

### 05DFLHFDWBREP

Part Number	Part Description	Quantity
CBC-400G	BRAKECLEANER AEROSOL 400GM	2.00
2255921	WEAR INDICATOR BRAKE PAD	1.00
1982826	SET BRAKE PAD	1.00
1801594	TAP ROLL BEAR WHEEL SET	2.00
1398725	O-RING	2.00
L0C34238	LOCTITE 5699 GREY MAXX	1.00
1396548	SELFLOCKING NUT	2.00
<b>Parts Totals:</b>		<b>11.00</b>

### 11SBRKPAD

Removed & replaced steer axle brake pads as req .

Part Number	Part Description	Quantity
2255921	WEAR INDICATOR BRAKE PAD	1.00
1982826	SET BRAKE PAD	1.00
<b>Parts Totals:</b>		<b>2.00</b>

### 11RDBRKPAD

Removed & replaced rear drive axle brake pads & wear sensors as required.

Part Number	Part Description	Quantity
2255921	WEAR INDICATOR BRAKE PAD	1.00
1982826	SET BRAKE PAD	1.00
<b>Parts Totals:</b>		<b>2.00</b>

### Miscellaneous Charges

WORKSHOP SUPPLIES  
 ENVIRONMENTAL CHARGES

Advisor: ANTHONY GOULEMAS

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

### Bank Account Details for Direct Payments:

Bank: ANZ Branch: Altona North  
 BSB: 013202 Account No.: 775073766 Account Name: KENWORTH DAF MELBOURNE