

## HINO GT1J CRANE TRUCK (7000L)

<b>MAKE</b>	Hino			
<b>MODEL</b>	GT1J			
<b>YEAR</b>	2000			
<b>VIN No.</b>	JHDGT1JKLXXX10068			
<b>ENGINE No.</b>	J08CF17860			
<b>TARE WEIGHT</b>	7780			
<b>GVM.</b>	13000			
<b>ENGINE CAPACITY</b>	7960.0			
<b>CRANE INSPECTION DATE</b>	16/02/2010			
<b>CRANE SERIAL No.</b>	630238			
<b>e-TAG No.</b>	174710350045			
<b>ID No.</b>	WT4			
<b>Standpipe Repairs</b>	Saxon 07 38811545			
<b>REGISTRATION</b>	<b>BV52QW</b>			
<b>INSPECTION REQUIRED</b>	<b>HVAIS</b>			
<b>REGISTRATION EXPIRY</b>	<b>5/09/2024</b>			
<b>UPDATED</b>	<b>12/02/2024</b>			
<b>DATE</b>	<b>HOURS</b>	<b>JOB / SERVICE TYPE</b>	<b>SERVICE / REPAIR DETAIL</b>	<b>PRE-START FAULTS / COMMENTS</b>
26/06/2013	25967		Purchased from Garys online	
4/09/2013		Auto Electrician	Fit IP65 e stop box with rubber cap toggle switch & e stop Connect wiring and test (e stop used from old control box) Wipe up beacon light to dashboard & fit rocker switch with warning light Fit new LED for PTO Fit new LED side lights and wire up Attend to short circuit in reverse light wiring Repair & test - OK	
8/01/2014	28552	Kms Recorded		
19/06/2014	-	Boilermaker	Realign & reinforce load binder rail on truck	
26/06/2014	32714	Fuel tuck		
22/07/2014	-	Toyota	Control Heater GHFDGD (x1)	
28/08/2014	35437	General	Maintenance for rego, tightened bolts, adjust steering rod.	
28/08/2014	-	Rego Check	Rego Check	

16/10/2014		Auto Electrician	Attend to Hino crane truck - air con not working Check wiring, repair open circuit in wiring loom	NB There is a slight gas shortage - not worth topping up at this stage
28/10/2014	36777	Service	Change Air, Fuel & Oil filters, change engine oil, grease, check all fluid levels, test drive.	
9/06/2015	-	Tyres	x2 Hankook 900R20 AH11 tyres x2 Tube 900X20 TRA78A Wheel Alignment Laser Align Drive Axle x1 tyre off- ok for cap inspection	
17/07/2015	40485	General	Fit new r/h rear tail lamp assembly. (inner lamp fittings brokrn)	
17/08/2015	43867	General	Serviced engine, r & r lube, fuel, air & A/C filters, greased adjusted park brake, general checkover.	
2/09/2015	-	Registration	Registration Check Pink slip Fill Washers & test as not working	
4/09/2015	-	Registration	HVAIS Inspection Carried out Registration paid Expiry: 5/9/2016	
14/10/2015	-	Stickers	x2-150mm T01 Stickers	
9/11/2015	-	Auto Electrician	Proceed to Unanderra workshop - Replace broken estop on crane truck	
29/12/2015	-	Auto Electrician	Proceed to workshop - Attend to truck Start sorting out wiring for Hetronic remote control system	<b>NOTE:</b> Waiting for information from hetronic dealer
31/12/2015		Auto Electrician	Continue with testing & wiring changes on truck Power supply to Hetronic receiver now active - Transpec is closed until 8/1/16 - Waiting for information on how to activate controller - advised Loris Crane still operating in manual mode	
7/01/2016	-	Auto Electrician	Attend to Hyno crane truck T01 - Complete wiring connections for remote control receiver & check operation (Mitch & Aaron tested crane) NB Hydraulic legs for crane are not controlled by remote unit The system key switch has to be set to manual first to operate hydraulic legs & then switched to remote to operate the crane	
11/04/2016		Premium Tyres	6 x Cold cap 11R22.5 XTE2 Case Repair	
22/04/2016	45990	General	Replaced batteries - 2 x 2500488 Cat	
26/05/2016		General	Replaced hydraulic fitting on crane controls	
7/06/2016	47579	General	Replaced beacon & rhs headlight globes.	
30/08/2016	51671	General	Pre checked for rego, greased, light repaired, hydraulic leak on crane fixed.	
31/08/2016	-	Registration	Registration Check	
1/09/2016		General	Fitted missing reflectors, new tyre fitted.(Premium)	
1/09/2016		General	Change rear r/h wheel and have Premium fit new tyre.	

<b>2/09/2016</b>	-	General	Hino Ranger5-8 windscreen fitted	
<b>5/09/2016</b>	-	Registration	Inspection Carried Out Registration Paid New Expiry- 5/9/2017	
<b>7/07/2017</b>	57447	Pre-start		
<b>11/07/2017</b>		Pre-start		
<b>26/07/2017</b>	58122	Pre-start		
<b>16/08/2017</b>		Premium Tyre Servic	Delivery docket : 216551 16/08/2017 Fitter : Brad Position Drive : 3 4 2x Double star 900R20 DSR168 A/P Road Service truck	
<b>17/08/2017</b>	58916	Pre-start		
<b>5/09/2017</b>		Registration	Registration renewed New expiry: 05/09/2018	
<b>13/09/2017</b>	59974	Pre-start		
<b>19/09/2017</b>	62101	Pre-start	Brakes need adjusting, 3 ltrs oil added.	
<b>4/10/2017</b>		General	Removed activation shuttle and clearance plates from PTO and resealed with sealant, tested all ok	
<b>20/10/2017</b>		Pre-start		
<b>15/12/2017</b>	63930	Service	Serviced vehicle, r & r fuel x 2, lube & air filters, greased, cleaned out cab.	
<b>18/12/2017</b>		Premium Tyre	13/12/2017 Position Steer: 1 TU90020 TUBE 900X20 TR78A ZPT CASE REPAIR - TRUCK	
<b>15/02/2018</b>	64918	Pre-start		
<b>20/02/2018</b>	65686	Pre-start		
<b>7/05/2018</b>		Complete Hose	Replaced 2 x leaking hoses from boom of crane to valve bank 4 x SAE 100 R2T-2SN non skive 4 x 1 & 2 wire ferrule non skive 4 x Din light metric (DKL) fem	
<b>11/05/2018</b>	67297	Pre-start		
<b>2/07/2018</b>	68069	General	Tension fan & a/c belts, remove, re-seal & replace hydraulic pump, replace tranny oil, repair Hi-ab control oil leak, repair light, test drive and give checkover - ok.	
<b>3/07/2018</b>	68069	Pre-start		
<b>9/07/2018</b>		Pirtek	Supply new hyd hose	
<b>17/07/2018</b>		Krop Industrial	Abrasive blasting & priming of water tank Abrasive blast prime (PR9)	
<b>27/07/2018</b>	68850	Pre-start		
<b>1/08/2018</b>	69117	Pre-start		
<b>30/08/2018</b>	70707	Pre-start		
<b>6/09/2018</b>		Registration	Registration renewed New Expiry: 05/09/2019	
<b>11/09/2018</b>	71359	Pre-start		
<b>19/09/2018</b>	71700	Pre-start		

<b>28/09/2018</b>	71856	Pre-Start		
<b>21/11/2018</b>	63082	Pre-start		
<b>22/11/2018</b>	72557	Pre-Start	Head board damaged	
<b>28/11/2018</b>	72729	Pre-start		
<b>29/11/2018</b>	72905	Pre-start	No documents	
<b>12/12/2018</b>	73093	Pre-start		
<b>13/12/2018</b>	73378	Pre-start		
<b>12/03/2019</b>		General	Mud Guard supports	
<b>10/04/2019</b>	74074	General	Fit water tank/ fabrication of mounts x8, R/R fuel tanks, fabricated new rear bar/step, fabricated new battery isolation switch mount	
<b>6/05/2019</b>			Converted to WT4 Water Cart 7500 Litres : 06/05/2019	
<b>14/05/2019</b>	0	General	mounting plates for tank	
<b>14/05/2019</b>	0	General	mounting plates for tank	
<b>20/05/2019</b>	74084	General	Finish water cart conversion. Fit reverse light and alarm. Wire up hose reel motor. Fit spring stop adjusters. Secure tool box mesh. Test operation	
<b>1/07/2019</b>	74253	Pre-start		
<b>2/07/2019</b>	74254	Pre-start		
<b>15/07/2019</b>	74264	Pre-start		
<b>16/07/2019</b>	74271	Pre-start		
<b>17/07/2019</b>	74270	Pre-start		
<b>18/07/2019</b>	74292	Pre-start		
<b>24/07/2019</b>	7440	Pre-start		
<b>25/07/2019</b>	7444	Pre-start		
<b>29/07/2019</b>	2222	Pre-start		
<b>30/07/2019</b>	74685	Pre-start		
<b>1/08/2019</b>	74781	Pre-start	Came back from Seymour Whyte with a missing mud flap	
<b>5/08/2019</b>	74805	Pre-start		
<b>8/08/2019</b>	74846	Pre-start		
<b>9/08/2019</b>	74876	Pre-start	No fire extinguisher	
<b>12/08/2019</b>	74897	Pre-start		
<b>13/08/2019</b>	74925	Pre-start		
<b>14/08/2019</b>	74944	Pre-start		
<b>15/08/2019</b>	74970	Pre-start		
<b>16/08/2019</b>	74988	Pre-start		
<b>19/08/2019</b>	74995	Pre-start		

20/08/2019	75029	Pre-start	
20/08/2019	75025	Pre-start	No fire extinguisher Hose split from pump
21/08/2019	74049	Pre-start	
22/08/2019	75079	Pre-start	
26/08/2019	75110	Pre-start	
2/09/2019		Registration	Registration renewed New Expiry: 05/09/2020
2/09/2019	75119	Pre-start	
3/09/2019	7514.2	Pre-start	
4/09/2019	75283	General	Replace missing mud flap, check over of lights fluids ect, greased
6/09/2019	75418	Pre-start	
7/09/2019	75421	Pre-start	
11/09/2019	75869	Pre-start	Back right guard been torn off.
12/09/2019	75877	Pre-start	
30/09/2019	76404	Pre-start	
1/10/2019	76559	Pre-start	
2/10/2019	76720	Pre-start	
3/10/2019	76866	Pre-start	
4/10/2019	77022	Pre-start	
8/10/2019	77179	Pre-start	
10/10/2019	7718	Pre-start	
11/10/2019	7718	Pre-start	
14/10/2019	77181	General	Repair mud flap. Grease and checkover machine
17/10/2019	0	General	mud guard
17/10/2019	0	General	mud guard
18/10/2019	77185	Pre-start	
21/10/2019	77470	Pre-start	
23/10/2019	7752	Pre-start	
24/10/2019	77530	Pre-start	
28/10/2019	77550	Pre-start	
31/10/2019	7762	Pre-start	Couple of small holes in bottom of tank somewhere.
7/11/2019	7767	Pre-start	
8/11/2019	7768	Pre-start	
11/11/2019	7768	Pre-start	
13/11/2019	7769	Pre-start	
23/11/2019	77843	General	Repair and weld 3 splits in water tank, check over, greased, repair hosereal, install 2way radio bracket and wiring

25/11/2019	0	General	uhf aerial	
25/11/2019	0	General	uhf aerial	
26/11/2019	77900	Pre-start		
27/11/2019	77903	Pre-start		
28/11/2019	77904	Pre-start		
9/12/2019	78167	Pre-start		
10/12/2019	78204	Pre-start		
11/12/2019	78246	Pre-start		
12/12/2019	78248	Pre-start		
16/12/2019	78252	Pre-start		
17/12/2019	78281	Urgent	Adjust clutch. Repair fill hosing	
18/12/2019	78269	Pre-start		
19/12/2019	78282	Pre-start		
20/12/2019	78308	Pre-start		
15/01/2020	78693	Pre-start		
22/01/2020	78713	General	Clean and repackaged bearing on hide reel, remove actuator bolts and spay lube for sticking seal.	
26/03/2020	78916	Pre-start		
27/03/2020	78925	General	Replace flat tyre inner drivers rear	
15/04/2020	79224	Pre-start		
16/04/2020	79525	Pre-start		
17/04/2020	79799	Pre-start		
18/04/2020	79933	Pre-start		
20/04/2020	80003	Pre-start		
21/04/2020	80187	Pre-start		
22/04/2020	80388	Pre-start		
23/04/2020	80580	Pre-start		
24/04/2020	80781	Pre-start		
27/04/2020	80868	Pre-start		
28/04/2020	81179	Pre-start		
29/04/2020	81427	Pre-start		
30/04/2020	81675	Pre-start		
2/05/2020	81687	Pre-start		
4/05/2020	81884	Pre-start		
5/05/2020	82082	Pre-start		
6/05/2020	82183	Pre-start		

7/05/2020	82405	Pre-start		
8/05/2020	82557	Pre-start		
9/05/2020	82890	Pre-start		
10/05/2020	82989	Pre-start		
13/05/2020	83422	Pre-start	No fire extinguisher	
14/05/2020	83490	Pre-start	No fire extinguisher	
21/07/2020	83648	Pre-start		
21/08/2020	83848	General	Weld cracks in tank, check over, replaced brake lights, fit 2 way radio, top up engine oil, greased	
31/08/2020	83912	General	Re weld cracks in tank where baffles are inside tank and outside	
4/09/2020	83914	Pre-start		
6/09/2020	8402	Pre-start		
8/09/2020	84274	Urgent	Repair faulty UHF due to faulty earth	
8/09/2020	84276	Pre-start		
10/09/2020	84422	Pre-start		
15/09/2020	84559	General	Service truck & grease	
28/09/2020	84559	General	Check over	
29/09/2020	8455	Pre-start		
13/10/2020	84623	Pre-start		
22/10/2020	846425	Pre-start	Fuse blown in 2way radio	
19/11/2020	84628	Pre-start		
20/11/2020	84629	Pre-start		
2/02/2021	0	Registration	05/09/2020-05/09/2021 , Inspection required (HVAIS-HVIS EXEMPT)	
16/03/2021	84775	General	Remove and repair hose reel / seized bushes, greased, replaced drivers rear brake light	
19/04/2021	84804	Pre-start		
27/04/2021	84803	Pre-start		
2/06/2021	84805	Pre-start		
31/08/2021	85004	Urgent	Replace Spring stoppers. Adjust clutch. Replace over taking stickers. Checkover	
6/09/2021	84990	Registration	05/09/2021-05/09/2022 Inspection Required	
14/12/2021	85401	Pre-start		
23/06/2022	85482	Pre-start		
27/06/2022	85483	Pre-start		

12/07/2022	85514	Pre-start		
12/07/2022	85514	Pre-start		
13/07/2022	85514	Pre-start		
14/07/2022	85520	Pre-start		
18/07/2022	85544	Pre-start		
19/07/2022	85546	Pre-start		
22/07/2022	8554	Pre-start		
26/07/2022	85549	Pre-start		
27/07/2022	85550	Pre-start		
28/07/2022	85551	Pre-start		
29/07/2022	85552	Pre-start		
10/08/2022	85635	Pre-start		
2/09/2022	0	Registration	REGO RENEWED 2022-2023	
9/12/2022	86081	General	Checkover truck. Adjust brakes and grease	
12/12/2022	86090	Pre-start		
13/12/2022	86134	Pre-start		
15/12/2022	86258	Pre-start		
16/12/2022	86308	Pre-start		
17/12/2022	86372	Pre-start		
19/12/2022	86400	Pre-start		
20/12/2022	8641	Pre-start		
21/12/2022	8646	Pre-start		
4/01/2023	86492	Pre-start		
9/01/2023	8658	Pre-start		
9/01/2023	8658	Pre-start		
19/01/2023	8663	Pre-start		
20/01/2023	8668	Pre-start		
23/01/2023	292810	Pre-start		
24/01/2023	292854	Pre-start		
6/02/2023	86810	Pre-start		
7/02/2023	86974	Pre-start		
9/02/2023	87000	Pre-start		
10/02/2023	6701	Pre-start		
13/02/2023	87021	Pre-start		
16/02/2023	87114	Pre-start		
17/02/2023	87286	Pre-start		



<b>18/02/2023</b>	87322	Pre-start	
<b>20/02/2023</b>	87351	Pre-start	Inner door handle on drivers side is broken have to use outer door handle to open
<b>21/02/2023</b>	87386	General	A/C not working low on gas, recharged a/c system
<b>8/03/2023</b>	87439	Pre-start	
<b>9/03/2023</b>	87497	Pre-start	
<b>16/03/2023</b>	87554	Pre-start	Number flare on front faded
<b>17/03/2023</b>	0	Tyres	GOODRIDE 9.00R20 CR976AW 144/142K (ALL/STEER - L) TT, SCRAP TYRES TRUCK, SERVICE CALL OUT NORM HRS
<b>9/05/2023</b>	87838	Pre-start	
<b>11/05/2023</b>	87853	Pre-start	
<b>12/05/2023</b>	87855	Pre-start	
<b>15/05/2023</b>	87862	Pre-start	
<b>23/05/2023</b>	87911	Pre-start	
<b>7/07/2023</b>	87940	Pre-start	
<b>12/07/2023</b>	87945	Pre-start	
<b>2/08/2023</b>	87990	Pre-start	
<b>7/08/2023</b>	88167	Pre-start	
<b>10/08/2023</b>	88308	Pre-start	
<b>14/08/2023</b>	88379	Pre-start	
<b>9/10/2023</b>	88550	Pre-start	Good order
<b>10/10/2023</b>	88559	Pre-start	Secure
<b>11/10/2023</b>	88577	Pre-start	Little ripped on the side
<b>12/10/2023</b>	88590	Pre-start	Yes
<b>17/10/2023</b>	88609	Pre-start	Little rip but good
<b>18/10/2023</b>	88690	Pre-start	Good little rip
<b>19/10/2023</b>	88775	Pre-start	Clean
<b>26/10/2023</b>	0	Tyres	GOODRIDE 9.00R20 CR976AW 144/142K, (ALL/STEER - L) TT, SCRAP TYRES TRUCK, SERVICE CALL OUT NORM HRS
<b>23/11/2023</b>	89361	Pre-start	Okay
<b>12/01/2024</b>	64008	Pre-start	Ok