

35

EMC Electric Vehicles- Pre-Sale Condition Report

Make - AKKE Year - 2020 Colour - WHITE & BLACK
 Model - SPRAY UNIT Body Type 600L TANK 3000W Chassis No - 100795-016

Description	Pass	Repair	Fail	Description	Pass	Repair	Fail	
Cosmetics				Batteries				
Roof	} NA			Battery Type	} NA			
Front Body				Charge				
Windscreen				Water level				
Rear body / tray				Specific gravity				
Paint				Watering system				
Front bumper								
Interior				Electrical				
Rear bumper / safety bar				Wiring (visual check)	✓			
Roof supports				Controller scan				
				Battery gauge	NA			
Floor	} NA			Dash gauges	NA			
Front seat				Front lights	NA			
Rear seat/s				Rear lights	NA			
Pedals				Brake lights	NA			
Seat belts				Blinkers	NA			
Dash				Motor brushes (visual check)	NA			
Switches				Throttle pot	NA			
Park brake lever								
Steering				Brakes				
Upper column	} NA			Discs / drums	} NA			
Middle column				Shoes/ pads				
Steering rack				Callipers (disc only)				
Tie rods				Brake cylinders (drums only)				
Steering wheel				Hydraulic lines (if appl)				
				Brake cables (if appl)				
Front Suspension				Wheels & Tyres				
King pins	} NA			Park brake mechanism	} NA			
Bushes				Front left tyre				
Wheel bearings				Front left rim				
Wheel studs				Front right tyre				
Shocks				Front right rim				
Rear Suspension				Wheels & Tyres				
Leaf springs	} NA			Rear left tyre				
Shocks				Rear left rim				
Bushes				Rear right tyre				
Shackles				Rear right rim				
Axle seals				Wheel nuts				
Diff seals								
backlash				Chassis condition	✓			
				Sub-frames	NA			

Completed by / Name & Sign - Malcolm

Date - 11.2.25

Other comments -

12V & 48V FEEDS REQUIRED TO RUN PUMP & PUMP WORKING OK.