#38

EMC Electric Vehicles- Pre-Sale Condition Report

Make - FMC		Year-	20 72	Colour-	SILUCOL	
Model-Fxoress	2 2018	Body Type	COLF CART	Chassis No	-L4F2558K7N00	3002

Description	Pass Re	pair	Fail	Description	Pass	Repair	Fail	
Cosn	netics			Batter				
Roof				Battery Type				
Front Body	/			Charge	1			
Windscreen	V			Water level	V			
Rear body / tray	V			Specific gravity				
Paint				Watering system	V			
Front bumper	V			Electri	Electrical			
Rear bumper / safety bar	V.			Wiring (visual check)	V			
Roof supports	V			Controller scan				
Interior			Battery gauge	NA				
Floor	V			Dash gauges	V			
Front seat	V			Front lights	1			
Rear seat/s	ALA			Rear lights	~			
Pedals	V			Brake lights	/			
Seat belts	V.			Blinkers	V			
Dash				Motor brushes (visual check)				
Switches	V			Throttle pot				
Park brake lever	ŇA		Brakes					
Steering			Discs / drums Dhumo					
Upper column				Shoes/ pads	₹ NA	1		
Middle column	V			Callipers (disc only)				
Steering rack				Brake cylinders (drums only)	NA			
Tie rods	V			Hydraulic lines (if appl)	NA			
Steering wheel				Brake cables (if appl)	1	/		
	spension			Park brake mechanism	V			
King pins V		Wheels & Tyres						
Bushes		/		Front left tyre				
Wheel bearings				Front left rim	V			
Wheel studs	V			Front right tyre				
Shocks				Front right rim	V			
Rear Suspension			Rear left tyre	V				
Leaf springs	V			Rear left rim	V		-	
Shocks	/			Rear right tyre	/			
Bushes	V			Rear right rim				
Shackles	V			Wheel nuts	1			
Axle seals			- 0					
Diff seals	V			Chassis condition	V			
backlash	V			Sub-frames				

Completed by / Name & Sign – Date – 17, 3, 25 Other comments -	MARON