



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

De-Hire Inspection Check

31/05/2025 / 383031 / Sydney / UE / Battery Electric / FN524157 /
Artemio Drio

Complete

Serial Number	FN524157
Hour Meter Read	10970 hr
Service Job No.	383031
Location	Sydney
Conducted on	31/05/2025 8:39 AM ACST
Conducted By	Artemio Drio

Truck Category

UE



Photo 1

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

Wheels/Tyres

Front Wheels / Tyres

WEAR & TEAR



Photo 7



Photo 8

Rear Wheels / Tyres

WEAR & TEAR



Photo 9

Wheel Bearings

N/A

Machine inoperational .

Chassis/Structure

Overhead Guard

OK

Chassis

OK

Paints scraped off and scratches everywhere . Stickers / decals scratches . Dent on the left side .



Photo 10

Battery Cover

N/A

Driver Seat & Fixing

OK



Photo 11

Panels and Covers (Left & Right)

OK

Accessories (Mirrors, Blue Lights)

WEAR & TEAR

No mirror and blue lights .

Windscreen

N/A

Rear Screen

N/A

Arm Rest

OK



Photo 12

Connection Elements

OK

Drive Unit

Transmission Operation	N/A
Dead battery .	
Transmission Noise & Leaks	N/A
Dead battery .	
Drive Motor Condition	N/A
Dead battery .	
Brake	
Brake Function & Adjustment	N/A
Dead battery .	
Steering	
Steer Motor Operation/Noise	N/A
Dead battery .	
Steering Cylinder	N/A
Steer Axle	N/A
Dead battery .	
Steering Wheel/Controls	OK
Dead battery .	
	
Photo 13	
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	N/A
Dead battery .	
Forks & Fork Carriage	OK



Photo 14



Photo 15

Lift Chains Free & Secondary

Dead battery .

OK



Photo 16



Photo 17



Photo 18

Hydraulic Cylinder Free Lift

OK



Photo 19

Hydraulic Cylinders Secondary Light Right & Left

OK



Photo 20



Photo 21

Hydraulic Hoses Conditions

OK



Photo 22



Photo 23

Reach Carriage & Cylinder

N/A

Sideshift Carriage & Cylinder

N/A

Machine inoperational . Visually ok.



Photo 24



Photo 25

Tilt Function & Cylinders

N/A

Machine inoperational . Visually ok .



Photo 26




Photo 27

Hydraulic System

Valve Block

N/A

Dead battery .

Pump Motor Operation

N/A

Dead battery .

Pump Operation

N/A

Dead battery .

Hydraulic Function Levers

Machine inoperational . Visually ok.

OK



Photo 28



Photo 29

Electric System

Multi-pilot & Solo-pilot

Machine inoperational . Visually ok.

N/A

Strobe & Working Lights / Alarms

Dead battery .

N/A

Drive Display, Console & Instruments

Keyswitch barrel and keys missing .

N/A



Photo 30



Photo 31

Main Contactor & Connectors

Dead battery .

N/A

Charger Condition & Operation

N/A

Battery

Battery Condition & Cables

Battery short as indicated on tag.

WEAR & TEAR



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37

Battery Carriage	OK
Battery Lock System	OK
Additions or Attachments	
Any other related attachments	No
Were any issues identified?	Wear & Tear
Dead battery . Missing keyswitch barel and keys . Dent on chassis . No charger . Decals scratched . Worn front and rear tyres . Missing mirror .	

(Internal) Parts required - BE

Painting
Dent on chassis repair
JH decals on CCW
Front tyres
Rear tyres
Mirror
Key barel
Keys

Media summary




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19




Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26




Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37