



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report.

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

Incoming Inspection Check

07/03/2025 / 90583302 / Sydney / UE / Battery Electric

Incomplete

Serial Number

90583302
12 - NH - KMS - LOW LEVEL ORDER
PICKER

Hour Meter Read

1499 hr



Photo 1

Location

Sydney

Conducted on

07/03/2025 10:04 AM ACDT

Conducted By

Larry Labayo

Truck Category

UE

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

CUSTOMER DAMAGE

WEAR & TEAR

Scratches on front base frame



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12

Include Images of the Front, Rear & Sides of the Unit



Photo 13



Photo 14



Photo 15



Photo 16

Wheels/Tyres

Front Wheels / Tyres

OK

Rear Wheels / Tyres

WEAR & TEAR

Load wheels worn out




Photo 17

Wheel Bearings

WEAR & TEAR

Load wheel worn out

Chassis/Structure

Overhead Guard

N/A

Chassis

OK

Battery Cover

OK

Driver Seat & Fixing

N/A

Panels and Covers (Left & Right)

DAMAGE

Follow me sensor smashed



Photo 18

Accessories (Mirrors, Blue Lights)	OK
Windscreen	N/A
Rear Screen	N/A
Arm Rest	N/A
Connection Elements	OK
Drive Unit	
Transmission Operation	OK
Transmission Noise & Leaks	OK
Drive Motor Condition	OK
Brake	
Brake Function & Adjustment	OK
Steering	
Steer Motor Operation/Noise	OK
Steering Cylinder	OK
Steer Axle	OK
Steering Wheel/Controls	OK
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	N/A
Forks & Fork Carriage	OK
Lift Chains Free & Secondary	N/A
Hydraulic Cylinder Free Lift	OK
Hydraulic Cylinders Secondary Light Right & Left	N/A
Hydraulic Hoses Conditions	OK
Reach Carriage & Cylinder	OK
Sideshift Carriage & Cylinder	OK
Tilt Function & Cylinders	N/A

Hydraulic System	
Valve Block	OK
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK
Electric System	
Multi-pilot & Solo-pilot	OK
Strobe & Working Lights / Alarms	OK
Drive Display, Console & Instruments	OK
Main Contactor & Connectors	OK
Charger Condition & Operation	OK
Battery	
Battery Condition & Cables	OK
Battery Carriage	OK
Battery Lock System	OK
Additions or Attachments	
Any other related attachments	No
Was any wear & tear identified?	Yes

(Internal) Parts required

Load wheel worn. Flat spot



Photo 19



Photo 20

(Internal) Est. Labour Requirements to repair (hrs)

1 hr

Front unit base frame grey paint

(External) Parts Required

Paint grey



Photo 21



Photo 22



Photo 23

(External) Labour Requirements (hrs)	1.5
(External) Est. Labour Cost	225

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23